

22/03/2002

ASS. REC. BY:

REF:

CS3/MSG18015880/U24d302

Special Instruction:

✓

Surveyor:

Mcruis

ASSIGNMENT (Office)

From (Person):

Chris Prewing

of

MSG

Date/Time:

20/8/18 @ 4:12pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLG 4680G

Insured:

SMC 4177C

at Workshop m/s

Z-one Automotive

Tel:

9755 2115

of

1 Kerkki Bld Ave 6 #01-87

Policy No:

A29087620AVW

Claim No:

568673

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/08/2018

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

10:50am @ 20/8/18

Person Contacted:

Yvonne

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SLG 4680G - X
	SMC 4177C - X.
31/8/18	Discontinued.

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLH 46806

at Workshop m/s 2-one

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen. Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 67299

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLG 46806 Yr Regn: 9 116

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)

Make: Toyota hiemer c.c. 1986

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 36018 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 25U 600077585

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 235/55-218

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 7 mm Rear 7 mm

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 26/8/18 D.O.I. 30/8/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

No settling press longer
4500 - 6500

31/8/18 submit PRS Report

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: 120

Transportation: _____

S + RS, SI

Photos

Others 10

TOTAL 130

Report Format : _____

Lump Sum / I.B.I. (\$) _____

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Aug 2018		29 Aug 2018 16:12 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	KARTHIK BALKRISHNAN NATARAJAN, ID: S7887937H, Tel: +6591082721, Email: NOEMAIL		
Main Claimant:	TEO HAN WEE, ID: S7222167B		
Vehicle Reg. No.:	SLG4680G	Date of Loss:	26/08/2018 16:00 - :59 [22 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 568673	Policy/Cover Note No.:	A29087620AVW (Comprehensive) Coverage: 29/06/2018 - 28/06/2019
Vehicle Reg. No. (Insured):	SMC4177C	Policy No. (Claimant):	
		Excess:	
Repairer:	Z-one Automotive Pte Ltd - Kb (HQ) 1 Kaki Bukit Avenue 6, #01-87/85 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/08/2018]		
Driver/Custodian (Insured):	KARTHIK BALKRISHNAN NATARAJAN (40 / Male), NRIC: S7887937H, Tel: +6591082721		
Adj Asg. Remarks:	Liability is down due to BOLA. TP disagree with our SJE list. Proceed to appoint LKK Auto Consultants. Contact Person: Yvonne / 9755 2115 / 6250 2115.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG18015880/Uz4d3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 31-08-2018	
		Code : MSG	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SMC 4177C	Veh. Inspected	SLG 4680G
Policy No.	A29087620AVW	Coverage (\$)	0.00
Claim No.	568673	Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	31/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	26/08/2018	Inspection Date	30/08/2018
Survey held at	Z-ONE AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVE 6, BLK C, #01-52 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

MSME18110861 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 27/08/2018 15:48
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/08/2018 15:48
Date Of Accident	26/08/2018 15:45
Exact Location Of Accident	PIE TWDS CHANGI AIRPORT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG4680G
Insured/Policyholder	
Name Of Registered Owner	TEO HAN WEE
NRIC No	S7222167B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-84485656
Alternative Phone No	OFFICE-84485656

Vehicle Particulars

Manufacturer	TOYOTA
Model	HARRIER
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	M493539
Cover Note Number	

Driver

Name of Driver	TEO HAN WEE
NRIC No	S7222167B
Date Of Birth	27/06/1972
Occupation	INDOOR
Date Of Driving Pass	23/08/2006
Driving Experience	12 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84485656
Fax Number	
Contact Number	OFFICE-84485656
EMail Address	NOEMAIL

Address 94 LORONG G TELOK KURAU
 Postcode 426286
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3
 Passenger 1
 NAME: : UNKNOWN
 GENDER: : MALE
 Passenger 2
 NAME: : UNKNOWN
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON 26/08/2018 AT 15.44PM, I AM DRIVING MY CAR (SLG4680G) ON THE PIE TOWARDS CHANGI AIRPORT. SUDDENLY, I FELT AN IMPACT FROM MY REAR. VEHICLE B (SMC4177C) CANNOT STOP WHEN I STOP BECAUSE THE VEHICLE IN FRONT OF ME STOPPED. THERE IS NO INJURY FROM THIS ACCIDENT.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMC4177C
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver KARTHIK BALKBISHNAN NATARAJAN
 NRIC/Passport Number
 Contact Number
 Address
 Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SKZ517J

Vehicle Make/Model/Colour

Details Of Properties

VEHICLE C

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driving Signature
+ Full Name of the Policyholder
Date & Time:

Expanding Centre's Representative Signature
Name:
Date & Time:

Z - ONE

Sketch Plan #2 Pg. 1

SKETCH PLAN



Vehicle A = SLG 4680G

Vehicle B = SMC 4177C


Vehicle C = SKZ 517J


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 26/08/2018 afternoon 15:44 PM. I am driving my car SLG 4680G on the PIE towards Changi Airport. Suddenly I felt an impact from my rear. The vehicle B SMC 4177C cannot stopped when I stopped because the vehicle in front of me stopped. There is no injury from this accident.

DECLARATION

We declare the foregoing particulars are true to the best of our knowledge.


 Police Officer (Sg. 2511)
 Date & Time


 Driver's Signature
 (If driver is not the registered owner)
 Date & Time


 Reporting Officer's Signature
 Name
 NRIC ID No.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2167B
Vehicle Details	
Vehicle No.:	SLG4680G
Vehicle to be Exported:	No
Intended De-registration Date:	30 Aug 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER PREMIUM 2.0 A
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	3ZRB778309
Chassis No.:	ZSU600077585
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$30,885.00
Original Registration Date:	30 Sep 2016
First Registration Date:	30 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$30,239.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2026
PARF Rebate Amount:	\$22,679.00
Intended COE Rebate Details	
COE Expiry Date:	29 Sep 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$55,201.00
COE Rebate Amount:	\$44,620.00
Total Rebate Amount:	\$67,299.00

The information contained herein is correct as at 30 Aug 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Aug 2018		29 Aug 2018 16:12 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	KARTHIK BALKRISHNAN NATARAJAN , ID: S7887937H, Tel: +6591082721, Email: NOEMAIL								
Main Claimant:	TEO HAN WEE , ID: S7222167B								
Vehicle Reg. No.:	SLG4680G	Date of Loss:	26/08/2018 16:00 - :59 [22 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 568673	Policy/Cover Note No.:	A29087620AVW (Comprehensive) Coverage: 29/06/2018 - 28/06/2019						
Vehicle Reg. No. (Insured):	SMC4177C	Policy No. (Claimant):							
		Excess:							
Repairer:	Z-one Automotive Pte Ltd - Kb (HQ) 1 Kaki Bukit Avenue 6, #01-87/85 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 30/08/2018]								
Driver/Custodian (Insured):	KARTHIK BALKRISHNAN NATARAJAN (40 / Male), NRIC: S7887937H, Tel: +6591082721								
Adj Asg. Remarks:	Liability is down due to BOLA. TP disagree with our SJE list. Proceed to appoint LKK Auto Consultants. Contact Person: Yvonne / 9755 2115 / 6250 2115.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLG4680G (568673)**
[SMC4177C]
TP
TEO HAN WEE
Aug 26 2018 4:00PM
[KARTHIK BALKRISHNAN NATARAJAN]
Z-one Automotive Pte Ltd - Kb

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Video



















































1 per page
☒









































No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/08/18 15:09	Video - Accident <small>From:SC - Reg. No: SMC4177C, Claimant: KARTHIK BALKRISHNAN NATARAJAN</small>	Load MP4	

Photos/Images

3 per page
☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
2	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
3	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
4	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
5	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
6	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
7	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
8	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
9	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
10	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
11	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
12	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
13	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
14	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
15	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
16	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
17	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
18	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
19	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
20	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
21	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
22	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
23	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
24	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
25	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
26	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
27	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
28	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
29	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
30	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
31	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
32	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
33	31/08/18 12:23	General View	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
35	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
36	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
37	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
38	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
39	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
40	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
41	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
42	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
43	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
44	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
45	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
46	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
47	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
48	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
49	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
50	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
51	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
52	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
53	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
54	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
55	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
56	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
57	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
58	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
59	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
60	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
61	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
62	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
63	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
64	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
65	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
66	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
67	31/08/18 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
68	31/08/18 14:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	31/08/18 14:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	31/08/18 14:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	31/08/18 14:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	31/08/18 14:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	31/08/18 14:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	31/08/18 14:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	31/08/18 14:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	31/08/18 14:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	31/08/18 14:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	31/08/18 14:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	31/08/18 14:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	31/08/18 14:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	31/08/18 14:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	31/08/18 14:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	31/08/18 14:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
84	31/08/18 14:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	31/08/18 14:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	31/08/18 14:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	31/08/18 14:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	31/08/18 14:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	31/08/18 14:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	31/08/18 14:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	31/08/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	31/08/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	31/08/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	31/08/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	31/08/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	31/08/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	31/08/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	31/08/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	31/08/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	31/08/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	31/08/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	31/08/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	31/08/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	31/08/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	31/08/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	31/08/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	31/08/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	31/08/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	31/08/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	31/08/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	31/08/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	31/08/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	31/08/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	31/08/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	31/08/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	31/08/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	31/08/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	31/08/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	31/08/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/08/18 15:07	Email - PRI	 Load PDF	
2	29/08/18 15:08	Notice to conduct PRI	 Load PDF	
3	29/08/18 15:09	SKZ517J GIA Rpt From:SC - Reg. No: SMC4177C, Claimant: KARTHIK BALKRISHNAN NATARAJAN	 Load PDF	
4	29/08/18 15:09	SLG4680G GIA Rpt From:SC - Reg. No: SMC4177C, Claimant: KARTHIK BALKRISHNAN NATARAJAN	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18015880/UZ4D3E2

Date: 04/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29087620AVW

Claimant Vehicle No : SLG4680G

Insured Vehicle No : SMC4177C

Date of Loss: 26/08/2018

Nature of Claim: TP

Claim No: 568673

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLG4680G

Make & Model: TOYOTA HARRIER, 2.0 Premium (A)

Engine No: 3ZRB778309

Reg. Date: 30/09/2016 (Man. Year: 2016)

Chassis No: ZSU600077585

Colour: Black

Odometer: 36018 km

Engine Capacity: 1986 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18

Rear Tyre Size: 235/55 R18

Front Left Side: Bridgestone 7 mm

Rear Left Side: Bridgestone 7 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 29/08/2018

Date Inspected: 30/08/2018 Inspected At:

Z-one Automotive Pte Ltd - Kb (HQ)
1 Kaki Bukit Avenue 6, #01-87/85 Autobay
@ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 0.0 days

Adjuster: MARCUS CHUA

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,500.00 -\$6,500.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Sep 2018)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 Premium (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG4680G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >