

ASS. REC. BY

REF

CS/MSG18015881/Uqd3/4

Special Information

957 8

Surveyor
Mennen

Mercus

ASSIGNMENT (Office)

From (Person):

Monica Chung

of

MSG

Date/Time

20/8/18 @ 4:11pm

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBF 6356D

Insured:

8KJ 4858H

at Workshop m/s

Hua Ho

Tel:

62844487

of

Blk 6 Defu Lane 10 # 01-540

Policy No:

S27S1S769SMA

Claim No:

56851S

Sum Insured

Excess

Make of Veh:

(Client's Record)

D.O.A

17/8/18

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement

Date/Time:

10:35am @ 30/8/18

Person Contacted:

Vehicle

IN OUT

Date/Time	Action/Instruction	Estimate
	FBF 6356D - X	
	8KJ 4858H - CS/MSG17009620/Subno	DOA: 5/5/2017
31/8/18 @ 3:55pm	revised to Monica Chung via Mennen.	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18015881/Uqd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 31-08-2018



Code : MSG

1.

Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKJ 4858H	Veh. Inspected	FBF 6356D
Policy No.	S27515769SMA	Coverage (\$)	0.00
Claim No.	568515	Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	31/08/2018

2.

Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3.

Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4.

Description of Damages

--

5.

General Information

Accident Date	17/08/2018	Inspection Date	30/08/2018
Survey held at	HUA HO TRADING BLK 6 DEFU LANE 10 #01-540 SINGAPORE 539537		

5a.

Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rot	Adj Submitted	Ins Auth'd	Status
Main	18 Aug 2018		29 Aug 2018 16:11 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured: Seah Nam Heng , ID: S0207319F	
Main Claimant: PEI WEI SHENG , ID: S9317376G	
Vehicle Reg. No.: FBF6356D	Date of Loss: 17/08/2018 10:00 - :59 [82 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type: TP / 568515	Policy/Cover Note No.: S27515769SMA (Comprehensive) Coverage: 24/07/2018 - 23/07/2019
Vehicle Reg. No. (Insured): SKJ4858H	Policy No. (Claimant):
Excess:	
Repairer: Hua Ho Trading (HQ) Blk 6 Defu Lane 10, #01-540 Defu Industrial Estate Park C, 539187 Defu Lane - Tel: 62844487	
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]	
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/08/2018]	
Driver/Custodian (Insured): Seah Nam Heng (67 / Male) , NRIC: S0207319F	
Adj Asg. Remarks: SJE AGREE LKKK - Henry Ng . Liab not clear. Contact: 62844487	

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 31 Aug 2018

Preliminary Advice

Insured Vehicle No	: SKJ4858H	Accident Date	: 17/08/2018
TP Vehicle No	: FBF6356D	Assignment Date	: 29/08/2018
Make	: YAMAHA YZF-R15	Est. Duration of Repair	: 4.00
Date of Inspection	: 30/08/2018		
Inspection At	: HUA HO TRADING (HQ) BLK 6 DEFU LANE 10, #01-540 DEFU INDUSTRIAL ESTATE PARK C SINGAPORE 539187		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,522.00
Revised Amount	:S\$	1,848.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,848.60

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 7376G

Vehicle Details

Vehicle No.: FBF6356D

Vehicle to be Exported: No

Intended De-registration Date: 30 Aug 2018

Vehicle Make: YAMAHA

Vehicle Model: YZF-R15

Primary Colour: Red

Secondary Colour: White

Manufacturing Year: 2010

Engine No.: 38B1020609

Chassis No.: ME138B01YA2020680

Maximum Power Output: -

Open Market Value: \$2,648.00

Original Registration Date: 05 Oct 2011

First Registration Date: 05 Oct 2011

Transfer Count: 5

Actual ARF Paid: \$398.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 04 Oct 2021

COE Category: D - Motorcycle

COE Period(Years): 10

QP Paid: \$2,109.00

COE Rebate Amount: \$652.00

Total Rebate Amount: \$652.00

The information contained herein is correct as at 30 Aug 2018

OK

[Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	FBF6356D
Vehicle Type:	P00 - Passenger Motorcycle/Autocycle/Moped
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	YAMAHA
Vehicle Model:	YZF-R15
Chassis No.:	ME138B01YA2020680
Propellant:	Petrol
Engine No.:	3881020609
Engine Capacity:	150 cc
Maximum Power Output:	-
Maximum Laden Weight:	330 kg
Unladen Weight:	120 kg
Year Of Manufacture:	2010
Original Registration Date:	05 Oct 2011
Lifespan Expiry Date:	-
COE Category:	D - Motorcycle
Quota Premium:	\$2,109.00
COE Expiry Date:	04 Oct 2021
Road Tax Expiry Date:	04 Oct 2018
Inspection Due Date:	04 Oct 2018
Intended Transfer Date:	27 Aug 2018
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

The current road tax expiry is 04 Oct 2018. You may renew the road tax from 05 Jul 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 04 Oct 2018, late renewal fee(s) will be imposed. Please use [Enquire Road Tax Payable](#) to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 05 Oct 2018 to 04 Apr 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	32.00	-	32.00
Total Amount Payable:			57.00

Amount Payable (From 05 Oct 2018 to 04 Oct 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	64.00	-	64.00
Total Amount Payable:			89.00

You may print this page for reference.

[OK](#)
[Print](#)

Attn: Nene
Heng Ho Trading

MVA318108949 / VAC - Raki Bukit
ENTRY DATE & TIME: 23/08/2018 11:04
SUBMITTED BY: Norhaini Bte Abdul Majid

Your NCD will be affected due to late reporting
Actual e-Filing Submission Date & Time: 23/08/2018 11:13

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/08/2018 11:04
Date Of Accident	17/08/2018 10:10
Exact Location Of Accident	PIE TOWARDS TUAS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	BF6356D
Insured/Policyholder	
Name Of Registered Owner	PEH WEI SHENG
NRIC No	S9317376G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94777749
Alternative Phone No	OTHERS-94777749
Vehicle Particulars	
Manufacturer	YAMAHA
Model	YZF-R15
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	
NO	
If No, Please state action to be taken	
THIRD PARTY	
Vehicle Category	
MOTORCYCLE	
Insurance Company	
Name of Insurance Company	
MSIG INSURANCE (SINGAPORE) PTE. LTD.	
Type Of Coverage	
THIRD PARTY	
Fleet Policy	
NO	
Policy Number	
MSD/VMT/18-380321-CA (TP)	
Cover Note Number	
Driver	
Name of Driver	
PEH WEI SHENG	
NRIC No	
S9317376G	
Date Of Birth	
24/05/1993	
Occupation	
INDOOR	
Date Of Driving Pass	
28/12/2016	
Driving Experience	
1 YEAR AND 7 MONTHS	
Gender	
MALE	
Mobile Number	
(LOCAL) +65-94777749	
Fax Number	
Contact Number	
OTHERS-94777749	
Email Address	
NOEMAIL	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

JLR6513

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

MOTORCYCLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

PEH WEI SHENG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

F8F6356D

Were seat belts worn?


Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police report

DECLARATION

y/We declare the foregoing particulars are true in every respect.

Policyholder's signature _____
Date & Time: 23/8/8 11:10

Driver's Signature: _____
(If driver is not the policyholder)
Date & Time: _____

YACK KAKI BUKIT (PAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67436697 Fax: 67492305
Email: yackb@sinonet.com.sg

Reporting Center Personnel: Signature
Name: _____
SPIC/173 P.6



**SINGAPORE
POLICE FORCE**



J/20180821/7015

1 of 2

POLICE REPORT (NP299)

Report No. J/20180821/7015

Police Station Of Origin
Jurong Police Divisional HQ
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7910000

Date/Time Report Made 21/08/2018 11:46	Vide Report No.	Station Diary No.
Name Of Informant PEH WEI SHENG	Address APT BLK 171 HOUGANG AVENUE 1 #13-1477 SINGAPORE 530171	
ID Type / ID No. NRIC NO / S9317376G	Contact No. Home/Office:	Mobile: 94777749
Nationality SINGAPORE CITIZEN	Email Address welsheng.peh@gmail.com	
Occupation Student	Sex Male	Age 25
Institution/School Name	Date of Birth 24/05/1993	Race Chinese
Date/Time Of Incident 17/08/2018 10:10 - 17/08/2018 10:30	Location Of Incident PAN ISLAND EXPRESSWAY	

Brief details.

A vehicle SKJ 4858H collided with a motorbike JLR 6513. The car make a sudden swerve into my lane. To avoid colliding, i immediately apply both brakes and skidded. The car was shifted to the road shoulder by the owner himself. i was conveyed to the hospital. The malaysian rider only had his head bandaged as he do not wan to be conveyed. A 5 days MC was given by the hospital from 17 Aug 2018 - 21 Aug 2018.

Subjects Involved	
Victim	
Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 21/08/2018 11:46
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp

和 好 贸 易

HUA HO TRADING

新加坡德福工業區C德福十巷大牌6號門牌#01-540
Blk 6, Defu Lane 10, #01-540 Defu Industrial Estate Park C,
Singapore 539187, Tel: 62844487 Fax: 62898180

Dear Sir,

Estimate cost repair for the accident motorcycle Vehicle No: FBF6356D

Items	Price
Left Side Mirror	\$75
Clutch Lever	\$24
Left Handle Bar	\$86
Handle Grid	\$34
Handle Bar End	\$42
Side Stand	\$65
Left Foot Rest	\$88
Left Tail Side Panel	\$60
Signal Light Left Front	\$62
Top Cowling	\$458
Front Fender Muggard	\$88
Left Side Fairing 1 Set	\$368
Inner Top Cowling Panel	\$256
Headlight 1 set	\$320
Cowling Bracket	\$86
Towing Fee	\$60
Labor Charge	\$350
Total	\$2522

2-1704
1070
153360
1848.6

not repair
2/5 #1400/2
4 day.

30/8/18

take photo after repair

3/8/18

HUA HO TRADING

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)










































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Aug 2018		29 Aug 2018 16:11 Edit Adj Rpt	S\$1,400.00 Edit Estimates	S\$1,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Seah Nam Heng , ID: S0207319F								
Main Claimant:	PEI WEI SHENG , ID: S9317376G								
Vehicle Reg. No.:	FBF6356D	Date of Loss:	17/08/2018 10:00 - :59 [82 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 568515	Policy/Cover Note No.:	S27515769SMA (Comprehensive) Coverage: 24/07/2018 - 23/07/2019						
Vehicle Reg. No. (Insured):	SKJ4858H	Policy No. (Claimant):							
		Excess:							
Repairer:	Hua Ho Trading (HQ) Blk 6 Defu Lane 10, #01-540 Defu Industrial Estate Park C, 539187 Defu Lane - Tel: 62844487								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 28/09/2018]								
Driver/Custodian (Insured):	Seah Nam Heng (67 / Male), NRIC: S0207319F								
Adj Asg. Remarks:	SJE AGREE LKKK - Henry Ng. Liab not clear. Contact: 62844487								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBF6356D (568515)
[SKJ4858H]
TP
PEI WEI SHENG
Aug 17 2018 10:00AM
[Seah Nam Heng]
Hua Ho Trading

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	28/08/18 15:59	Accident Statement <small>From: SC - Reg. No: SKJ4858H, Claimant: SEAH NAM HENG</small>	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	31/08/18 15:55	Adjuster Immediate Advice	1	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/09/18 07:39	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	07/09/18 07:39	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	07/09/18 07:39	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	07/09/18 07:39	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	07/09/18 07:39	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	07/09/18 07:39	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	07/09/18 07:39	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	07/09/18 07:39	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	07/09/18 07:39	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	07/09/18 07:39	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	07/09/18 07:39	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	07/09/18 07:39	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	07/09/18 07:39	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	07/09/18 07:39	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	07/09/18 07:39	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	07/09/18 07:39	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	07/09/18 07:39	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	07/09/18 07:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	07/09/18 07:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	07/09/18 07:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	07/09/18 07:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	07/09/18 07:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	07/09/18 07:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	07/09/18 07:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	07/09/18 07:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	07/09/18 07:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	07/09/18 07:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
28	07/09/18 07:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
29	07/09/18 07:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	07/09/18 07:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
31	07/09/18 07:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
32	07/09/18 07:40	General View		Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
33	07/09/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
34	07/09/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
35	07/09/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
36	07/09/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
37	07/09/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
38	07/09/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
39	07/09/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
40	07/09/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
41	07/09/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
42	07/09/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
43	07/09/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
44	07/09/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
45	07/09/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
46	07/09/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
47	07/09/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
48	07/09/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
49	07/09/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
50	07/09/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
51	07/09/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
52	07/09/18 07:40	General View	 Load JPG	<input checked="" type="checkbox"/>
53	07/09/18 07:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	07/09/18 07:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	07/09/18 07:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	07/09/18 07:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	07/09/18 07:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	07/09/18 07:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	07/09/18 07:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	07/09/18 07:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	07/09/18 07:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	07/09/18 07:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	07/09/18 07:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	07/09/18 07:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	07/09/18 07:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	07/09/18 07:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	07/09/18 07:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	07/09/18 07:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	07/09/18 07:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	07/09/18 07:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/08/18 15:59	PRI & THIRD PARTY REPORT From: SC - Reg. No: SKJ4858H, Claimant: SEAH NAM HENG	 Load PDF	
2	29/08/18 11:45	SJE AGREE LKKK - Henry Ng	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18015881/UQD3Q2

Date: 10/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: S27515769SMA

Claimant Vehicle No: FBF6356D

Insured Vehicle No: SKJ4858H

Date of Loss: 17/08/2018

Nature of Claim: TP

Claim No: 568515

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBF6356D

Make & Model: YAMAHA YZF-R15, 150cc (M)

Engine No: 38B1020609

Reg. Date: 05/10/2011 (Man. Year: 2010)

Chassis No: ME138B01YA2020680

Colour: Black

Odometer: 0 km

Engine Capacity: 150 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 80/90-17

Rear Tyre Size: 120/70-17

Front Left Side: Dunlop 6 mm

Rear Left Side: IRC 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,112.00	1,533.60	578.40	27.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	410.00	315.00	95.00	23.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,522.00	1,848.60	673.40	26.70
Approved Total (Overridden) (\$\$)		1,400.00		
Nett Amount (\$\$)	2,522.00	1,400.00	1,122.00	44.49

INSPECTION

Date of Assignment: 29/08/2018

Date Inspected: 30/08/2018 Inspected At:

Hua Ho Trading (HQ)
Blk 6 Defu Lane 10, #01-540 Defu
Industrial Estate Park C
Singapore 539187

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Sep 2018)	
Parts:	N/A	YAMAHA YZF-R15 150cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBF6356D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LEFT SIDE MIRROR	Broken	75.00 F	*75.00 FL
2	1		*CLUTCH LEVER	Bent / Cut	24.00 F	*24.00 FL
3	1		*LEFT HANDLE BAR	Bent	86.00 F	*86.00 FL
4	1		*HANDLE GRID	Torn	34.00 F	*34.00 FL
5	1		*HANDLE BAR END	Cut	42.00 F	*42.00 FL
6	1		*SIDE STAND	Bent	65.00 F	*65.00 FL
7	1		*LEFT FOOT REST	Cut	88.00 F	*88.00 FL
8	1		*LEFT TAIL SIDE PANEL	Cracked	60.00 F	*60.00 FL
9	1		*SIGNAL LIGHT LEFT FRONT	Broken	62.00 F	*62.00 FL
10	1		*TOP COWLING	Deep Cut	458.00 F	*458.00 FL
11	1		*FRONT FENDER MUGGARD	Repair	88.00 F	*- FL
12	1		*SET LEFT SIDE FAIRING	Deep Cut	368.00 F	*368.00 FL
13	1		*INNER TOP COWLING PANEL	Cracked	256.00 F	*256.00 FL
14	1		*SET HEADLIGHT	Serviceable	320.00 F	*- FL
15	1		*CLOWING BRACKET	Bent	86.00 F	*86.00 FL
Sub Total (\$\$)					2,112.00	1,704.00
- List Item Discount on L Items 0.00/10.00% (\$\$)					0.00	170.40
Total Parts (\$\$)					2,112.00	1,533.60

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING FEE	New	60.00	35.00
2	LABOUR CHARGE	New	350.00	280.00
Gross Labour Cost (S\$)			410.00	315.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >