

CS3 / ICS18015890 / G24d302

NAME OF
MEMBER

GA

ASSIGNMENT (Office)

From (Person)

Janice Goh

at

ICS

Date/Time

28/8/18 @ 5.36pm

Estimated Cost

Bill to

OD

(TP)

WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

SKL 2383M

Insured

SLP 7926G

at Workshop no

Mcwell Ventures

Tel

93893004

of

8 Kerkai Bkt Ave 4 # 01-47

Policy No

Claim No

DMPC1800345H/DL

Sum Insured

Excess

Make of Veh

D.O.A

28/08/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement

Date/Time

9:20am 20/8/18

Person Contacted

Alan

Vehicle

(IN)

OUT

Date/Time	Action/Instruction (X) Estimate
	SKL 2383M - X
	SLP 7926G - X
	Dismantle part : 31-08-2018

0000/0000 0000

ASS. REC. BY:

Xel

REF: ICS

65618

x

(-2021)

PRS

ASSIGNMENT

From Date: 30/8/18

Estimated Cost

OR ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKL 2383M

at Workshop n/s Mcwell Ventures

of 8 Kerli Bkt Ave 4 #01-47/48

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Alan @ 93893004

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value:

\$64K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lump Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS lwp

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKL 2383M

Regn:

08 Sep 2011

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Bmw 320i

C.C.

1995

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

62606

T/Radio:

Insured / Std / NI / NA

Eng/No:

WBA DV 320 70E 4918 29

G/No:

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F: 225/40ZR18

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

30-08-18

Survey held at

W/S

4pm

Des. of Damages: Frt / Rear / ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$2000 - \$3000

1/9/18

submit PRS Report

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

G + RS, SI

Photos

Others

TOTAL

100

100

10

210

Nivitha (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Tuesday, 28 August 2018 5:36 PM
To: Charles Hoon; assignments
Cc: ECICS Claims
Subject: RE: PROPERTY DAMAGE CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 25 AUGUST 2018 AT ABOUT 10:00HRS INVOLVING MOTOR VEHICLES NO(S). SKL2383M AND SLP7926G ALONG ROCHOR ROAD [our ref: AP/2018/000146] [your ref: to be advised]
Attachments: ltr to 3P & ECICS- (28 Aug 18).pdf; GIA - SKL2383M.PDF

Without Prejudice

Hi Charles

Thank you for your email.

We are not agreeable with your surveyor list and we will appoint LKK for the SJE.

Aside to LKK

Please assist to arrange for survey.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: Charles Hoon [mailto:charles@aplp.com.sg]
Sent: Tuesday, 28 August, 2018 5:18 PM
To: ECICS Claims
Subject: RE: PROPERTY DAMAGE CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 25 AUGUST 2018 AT ABOUT 10:00HRS INVOLVING MOTOR VEHICLES NO(S). SKL2383M AND SLP7926G ALONG ROCHOR ROAD [our ref: AP/2018/000146] [your ref: to be advised]

Dear Janice,

WITHOUT PREJUDICE

We refer to your email below.

Our clients do not agree to your list of surveyors.

We are instructed to propose the use of one of the motor surveyors named below to conduct the joint pre-repair survey as a single joint expert:

- a. Alan Cheong
- b. TT Rajan
- c. Oh Han Cheong
- d. Andrew How
- e. Dave Ho Joo Koong
- f. Lee Kok Weng
- g. Seah Kwang Boon
- h. Lee K.W.
- i. Willy Goh
- j. Zali Saidi

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors.

Regards,

Charles Hoon

AP Law Practice

9 Temasek Boulevard #09-01 Suntec Tower 2 Singapore 038989

T: 64071429 F: 64071427 E: charles@aplp.com.sg

Singapore UEN No.: 53380739E

This email transmission is confidential and intended only for the addressee(s). It may contain information which is privileged as between solicitor and client or protected by litigation privilege. If you are not the intended recipient, please delete this message and all attachments and inform us by return email. No part of this message should be disclosed to any party, copied or used for any purpose. Thank you for your co-operation.

From: ECICS Claims <claims@ecics.com.sg>

Sent: Tuesday, 28 August 2018 3:41 PM

To: Charles Hoon <charles@aplp.com.sg>

Cc: ECICS Claims <claims@ecics.com.sg>

Subject: RE: PROPERTY DAMAGE CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 25 AUGUST 2018 AT ABOUT 10:00HRS INVOLVING MOTOR VEHICLES NO(S). SKL2383M AND SLP7926G ALONG ROCHOR ROAD [our ref: AP/2018/000146] [your ref: to be advised]

Without prejudice

Dear Charles

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert.

- 1. LKK
- 2. JP knight
- 3. Formteam
- 4. Appraisal Associates
- 5. Autoprobe
- 6. Raleigh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Thank you.

Regards,

Janice Goh

Claims Division

DID: +65 6303 0182

FAX: +65 6338 9267

ECICS Limited
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: Charles Hoon [<mailto:charles@aplp.com.sg>]

Sent: Tuesday, 28 August, 2018 10:26 AM

To: ECICS Claims

Subject: PROPERTY DAMAGE CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 25 AUGUST 2018 AT ABOUT 10:00HRS INVOLVING MOTOR VEHICLES NO(S). SKL2383M AND SLP7926G ALONG ROCHOR ROAD [our ref: AP/2018/000146] [your ref: to be advised]

Attn: Motor Claim Department

Dear Sirs,

Please find attached, our letter of even date.

Regards,

Charles Hoon

AP Law Practice

9 Temasek Boulevard #09-01 Suntec Tower 2 Singapore 038989

T: 64071429 F: 64071427 E: charles@aplp.com.sg

Singapore UEN No.: 53380739E

This email transmission is confidential and intended only for the addressee(s). It may contain information which is privileged as between solicitor and client or protected by litigation privilege. If you are not the intended recipient, please delete this message and all attachments and inform us by return email. No part of this message should be disclosed to any party, copied or used for any purpose. Thank you for your co-operation.

follow us on  facebook follow us on  twitter visit our website  **ecics.com.sg** **ECICS**
INSURANCE
INTEGRITY

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Nivitha (LKK Auto)

From: Charles Hoon <charles@aplp.com.sg>
Sent: Wednesday, 29 August 2018 5:32 PM
To: Catherine Chong (LKK Auto); 'ECICS Claims'; 'assignments'
Cc: Alan Chua
Subject: RE: PROPERTY DAMAGE CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 25 AUGUST 2018 AT ABOUT 10:00HRS INVOLVING MOTOR VEHICLES NO(S). SKL2383M AND SLP7926G ALONG ROCHOR ROAD [our ref: AP/2018/000146] [your ref: to be advised]

Dear Catherine,

We refer to your email below.

Please note that our clients' vehicle may be inspected at:

McWell Ventures Pte Ltd
8 Kaki Bukit Ave 4
#01-47/48 Premier@Kaki Bukit
S415875
Contact: Alan (93893004)

Please note that our clients' vehicle will only be available for the pre-repair survey within the next two (2) working days. Our client shall proceed to repair their vehicle thereafter without further notice or reference to you.

Regards,

Charles Hoon

AP Law Practice

9 Temasek Boulevard #09-01 Suntec Tower 2 Singapore 038989

T: 64071429 F: 64071427 E: charles@aplp.com.sg

Singapore UEN No.: 53380739E

This email transmission is confidential and intended only for the addressee(s). It may contain information which is privileged as between solicitor and client or protected by litigation privilege. If you are not the intended recipient, please delete this message and all attachments and inform us by return email. No part of this message should be disclosed to any party, copied or used for any purpose. Thank you for your co-operation.

From: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>
Sent: Wednesday, 29 August 2018 2:58 PM
To: 'ECICS Claims' <claims@ecics.com.sg>; Charles Hoon <charles@aplp.com.sg>; 'assignments' <assignments@lkkauto.com>
Subject: RE: PROPERTY DAMAGE CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 25 AUGUST 2018 AT ABOUT 10:00HRS INVOLVING MOTOR VEHICLES NO(S). SKL2383M AND SLP7926G ALONG ROCHOR ROAD [our ref: AP/2018/000146] [your ref: to be advised]

Dear Janice,

Thank you for your email.

Dear Charles,

Kindly provide us the workshop detail.

9.20am
veh ✓
Alan
eslx
BA



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD

Ref : CS3/ICS18015890/Gz4d3

10 EUNOS ROAD 8

SINGAPORE POST CENTRE #09-04A SINGAPORE 408600

Date : 31-08-2018



Code : ICS

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLP 7926G	Veh. Inspected	SKL 2383M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	JANICE GOH	Assign Date	31/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	25/08/2018	Inspection Date	30/08/2018
Survey held at	MCWELL VENTURES PTE LTD 51 UBI AVE 1 #01-05/06 PAYA UBI IND. PARK SINGAPORE 408933		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
 B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
 THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
 C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/08/2018 12:53
Date Of Accident	25/08/2018 10:00
Exact Location Of Accident	ALONG ROCHOR ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKL2383M
Insured/Policyholder	
Name Of Registered Owner	SIU YEE MAY MAY
NRIC No	S7176561Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91250126
Alternative Phone No	OTHERS-91250126

Vehicle Particulars

Manufacturer	BMW
Model	320 CIA CABRIOLET
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800079439
Cover Note Number	

Driver

Name of Driver	SIU YEE MAY MAY
NRIC No	S7176561Z
Date Of Birth	28/07/1971
Occupation	INDOOR
Date Of Driving Pass	07/09/2001
Driving Experience	16 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91250126
Fax Number	
Contact Number	OTHERS-91250126
Email Address	NOEMAIL

Address	BLK 79 MARINE DRIVE #25-26
Postcode	440079
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED STATEMENT RECORDED BY LILY - PROGRESSIVE AUTOMOTIVE PTE LTD 67415336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	REQUEST FROM OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP7926G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claim process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GI& Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms) which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


27/8/18

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NIC/TIN No.:

Sketch Plan #2

SKETCH PLAN



Vehicle No

A -

B -

Legend



Vehicle



Bike

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling and filtering to the right and all of a sudden, the car hit and bang my right side front door.

DECLARATION

I/We declare the foregoing particulars are true in every respect. Please be advised that your insurer may have a 14 day clause whereby the claim against own policy must be made within the stipulated timeframe from the date of occurrence. Kindly check your policy for more details.

Policyholder's Signature

Date & Time:

27/8/18

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/PRN No:

Owner IC & LIC



Email: alanchua@mcwellventures.com



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)

Midnight Accident

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Sep 2018 12:24 Edit Reg		28 Aug 2018 00:00 Edit Adj Rpt	\$50.00 Edit Estimates	\$50.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: -, Co. Reg. No.: -, Email: EMAIL@EMAIL.COM									
Main Claimant: -									
Vehicle Reg. No.: SKL2383M		Date of Loss: 25/08/2018 00:00 - :59 [83 Months and 17 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): SLP7926G		Policy No. (Claimant):							
		Excess:							
Repairer: Mcwell Ventures Pte Ltd (HQ) 8 Kakui Bukit Ave 4, #01-47/48 Premier@Kaki Bukit, 415875 Kaki Bukit - Tel:									
Handling Insurer: ECICS Limited (HQ) - Tel: 63374779 /6303 0178									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 11/09/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents





*SKL2383M
[SLP7926G]

TP

Aug 25 2018 12:00AM

[-]

Mcwell Ventures Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View View in Browser	
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	01/09/18 09:38	General View		 Load JPG	<input checked="" type="checkbox"/>		
2	01/09/18 09:38	General View		 Load JPG	<input checked="" type="checkbox"/>		
3	01/09/18 09:38	General View		 Load JPG	<input checked="" type="checkbox"/>		
4	01/09/18 09:38	General View		 Load JPG	<input checked="" type="checkbox"/>		
5	01/09/18 09:38	General View		 Load JPG	<input checked="" type="checkbox"/>		
6	01/09/18 09:38	General View		 Load JPG	<input checked="" type="checkbox"/>		
7	01/09/18 09:38	General View		 Load JPG	<input checked="" type="checkbox"/>		
8	01/09/18 09:38	General View		 Load JPG	<input checked="" type="checkbox"/>		
9	01/09/18 09:38	General View		 Load JPG	<input checked="" type="checkbox"/>		
10	03/09/18 09:06	Dismantled Parts		 Load JPG	<input checked="" type="checkbox"/>		
11	03/09/18 09:06	Dismantled Parts		 Load JPG	<input checked="" type="checkbox"/>		
12	03/09/18 09:06	Dismantled Parts		 Load JPG	<input checked="" type="checkbox"/>		
13	03/09/18 09:06	Dismantled Parts		 Load JPG	<input checked="" type="checkbox"/>		
14	03/09/18 09:06	Dismantled Parts		 Load JPG	<input checked="" type="checkbox"/>		
15	03/09/18 09:06	Dismantled Parts		 Load JPG	<input checked="" type="checkbox"/>		
16	03/09/18 09:06	Dismantled Parts		 Load JPG	<input checked="" type="checkbox"/>		
17	03/09/18 09:06	Dismantled Parts		 Load JPG	<input checked="" type="checkbox"/>		
18	03/09/18 09:06	Dismantled Parts		 Load JPG	<input checked="" type="checkbox"/>		
19	03/09/18 09:06	Dismantled Parts		 Load JPG	<input checked="" type="checkbox"/>		
20	03/09/18 09:06	Dismantled Parts		 Load JPG	<input checked="" type="checkbox"/>		
21	03/09/18 09:06	Dismantled Parts		 Load JPG	<input checked="" type="checkbox"/>		
22	03/09/18 09:06	Dismantled Parts		 Load JPG	<input checked="" type="checkbox"/>		
23	03/09/18 09:06	Dismantled Parts		 Load JPG	<input checked="" type="checkbox"/>		
24	03/09/18 09:06	Dismantled Parts		 Load JPG	<input checked="" type="checkbox"/>		

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>	
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/ICS18015890/GZ4D3E2

Date: 05/09/2018

REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle No: SKL2383M

Insured Vehicle No:

SLP7926G

Date of Loss: 25/08/2018

Nature of Claim:

TP

Claim No:

N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKL2383M

Make & Model: BMW 320i, 2.0 (A)

Engine No: BDA265I891N46B20

Reg. Date: 08/09/2011 (Man. Year: 2011)

Chassis No: WBADV32070E491829

Colour: White

Odometer: 62606 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40Z R18

Rear Tyre Size:

225/40Z R18

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/08/2018

Date Inspected: 30/08/2018 Inspected At:

Mcwell Ventures Pte Ltd (HQ)
 8 Kakui Bukit Ave 4, #01-47/48
 Premier@Kaki Bukit
 Singapore 415875

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 Sep 2018)	
Parts:	N/A	BMW 320I 2.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKL2383M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >