

CS/ALG18015891/Kvd3

SURVEYOR

menner

Kenneth

ASSIGNMENT (Office)

From (Person)

Mikheo Sing

ALG

Date/Time

30/8/18 @ 9.50am

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle: No

FD 9728H

Insured:

SJL 8694M

at Workshop with

GA Motor

Tel:

64539903

of

Blk 32, Sin Ming Drive # 01-331

Policy No

2100109347

Claim No

9780712869SG

Sum Insured

Excess

Make of Veh:

(Client's Record)

D.O.A.

24/8/18

CA / REV / REP. / REV 24 HRS

1up)

H.O.D. Endorsement

Date/Time

9.55am 30/8/18

Person Contacted:

Mrs. Tan

Vehicle

IN/OUT

Date/Time	Action/Instruction	Estimate
	FD 9728H - x	
	SJL 8694M - CC3/ALG13001085/RS-292	DOA: 11/11/2013
9/10/18	@ 1216pm Mrs Tan said pending Kenneth to offer repair cost	
11/10	11pm @ 2100 email & confirm (Recd 1281, 381)	

004173 wof

ASS. REC. BY:

REF: AIG

ASSIGNMENT

From Date: 30/8/18

Estimated Cost

On: TP WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: FD 9728H

at Workshop no/s GA Motor

of Blk 32 Sin Ming Drive # 01-331

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$3200

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{up}

10/22

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: 1-D 9728H Yr Regn: 06, 85

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha RXS C.C. 115

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 73662 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: 52A . 001124

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: Metzler 2.75 R18

R: Pir 3.00 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / SUMI /

TOYO / YOKO or

Front

R/Bal. 2 mm

L/Bal. mm

D.O.A. 24/8/18

Survey held at

Rear

R/Bal. 5 mm

L/Bal. 5 mm

D.O.I. 30/8/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Ad 8011 body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

3/18 File pass to Nivore

RECEIVED 11 OCT 2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 11/10 - typist

Report Format: Melimen

Lump Sum / I.B.I. (\$) 21000

Days Of Repair: 4

Resurvey No. of Trip: -

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS, \$

Photos

Others

TOTAL

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Assigned	Status
Main	24 Aug 2018 Edit Reg		31 Aug 2018 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	TAN AH TEE, ID: S0268185D		
Main Claimant:	TAN YOY SENG, ID: S0203868D		
Vehicle Reg. No.:	FD9728H	Date of Loss:	24/08/2018 00:00 - :59
Claim Type:	TP / 9780712869SG	Policy/Cover Note No.:	2100109347 (Comprehensive)
Vehicle Reg. No. (Insured):	SJL8694M	Policy No. (Claimant):	
		Excess:	
Repairer:	Ga Motor (HQ) Blk 32 Sin Ming Drive, #01-331, 575706 Sin Ming - Tel: 64539903		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 11/09/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/AIG18015891/Kvd3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 31-08-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJL 8694M	Veh. Inspected	FD 9728H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MITHOOSINGH	Assign Date	31/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	24/08/2018	Inspection Date	30/08/2018
Survey held at	GA MOTOR BLK 32 SIN MING DRIVE #01-331 SINGAPORE 575706		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

- Pre repair inspection request - FD9728H VS SJL8694M (OI) DOA 24/08/2018

From: Mithoosingh, Aashweenjeetkaur
To: admin-a@lkkauto.com, assignments@lkkauto.com
Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Manessa, Md Isahak, Mohd Imran, Lim, Sheng Yang, Azlan, Syazairndia, Chan, Yoke Shi
Sent: 30/8/2018 9:50:12 AM
Attachments:  **PR-97807128695G003-29.08.18.HJ**

Hi,

Please refer to the enclosed request from Centro-Legal Law Corporation.

Claim no : 97807128695G003
Case Owner : MING YAO LEE

If you have any queries/concerns, please let us know.
Kindly assist to assign Kenneth Kong as Single Joint Expert as requested.

Thanks and regards,

Aashweenjeet Kaur (Aashween)
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: GA MOTOR [mailto:gamotor@gmail.com]
Sent: Thursday, August 30, 2018 9:40 AM
To: Mithoosingh, Aashweenjeetkaur
Subject: Re: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJL8694M AND FD9728H ON 24/08/2018

Hi,

Please arrange Kenneth Kong (LKK Auto Consultants Pte Ltd) for the pre-repair inspection survey.
Thanks

On Wed, Aug 29, 2018 at 3:03 PM Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com> wrote:

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการส่งข้อความปลอดภัยที่เข้ารหัสไว้ เพื่ออ่านมันได้คุณต้องเปิดแนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2018-09-05 15:03 +08 to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the individual(s) named. If you have received this email in error or simply delete it.

Secured by Proofpoint Encryption. Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

Best Regards,
Tan Sin Huat
GA MOTOR
BLK 32 SIN MING DRIVE
#01-331 SINGAPORE 575706

Tel: +65 64539903
Fax: +65 64539904

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments

are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Aashweenjeetkaur.Mithoosingh@aig.com

To: gamotor@gmail.com

Cc: Lily.Tan@aig.com, Andy-SY.Fong@aig.com, Baljit.Kaur@aig.com, Lee-

Ying.Chin@aig.com, NoorMariessa.AbuKassim@aig.com, Imran.Ishak@aig.com, ShengYang.Lim@aig.com, Syazairdina.Azlan@aig.com, yokeashil.chen@aig.com

Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJL8894M AND FD9728H ON 24/08/2018

Date: Wed, 29 Aug 2018 07:03:45 +0000

Without Prejudice

Your Reference : CLLC.0905.2018.L1 / FD9728H

Our Reference : 9780712869SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Fong Soon Yee	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Aashweenjeet Kaur (Aashween)

AIG

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services

Centro-Legal Law Corporation

ADVOCATES AND SOLICITORS

Your ref

SJL8694M

Our ref

CLLC.0905.2018 LI / FD9728H

29 AUGUST 2018

AIG ASIA PACIFIC INSURANCE PTE LTD
 78 Shenton Way #07-16 AIG Building
 Singapore 079120
 Fax: 6835 7416

BY FAX & EMAIL

Attn: **Officer-In-Charge**
 Dear Sirs,

NOTICE TO INSURANCE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF RE-ACTION PROTOCOL FOR NIMA CASE

We act for TAN YOY SENG, the owner of motor vehicle FD9728H, who has appointed us to act on his behalf to claim against your insured's vehicle no **SJL8694M** in regards to the road traffic accident on 24.08.2018

Please be informed that the said motor vehicle can be inspected at:-

GA MOTOR

BLK 32 SIN MING DRIVE #01-331
 Singapore 575706

Tel: 6453 9903 / 6453 9904 Fax : 6453 9904

Kindly contact: **Mrs Tan / Tel: 6453 9903**

Please note that if you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,

CENTRO-LEGAL LAW CORPORATION
 Cc **Mrs Tan**

Email : gamotor@gmail.com / Fax : 6453 9904

[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
 Owner ID: 3868D

Vehicle Details

Vehicle No.: FD9728H
 Vehicle to be Exported: No
 Intended De-registration Date: 31 Aug 2018
 Vehicle Make: YAMAHA
 Vehicle Model: RX11
 Primary Colour: Black
 Manufacturing Year: 1985
 Engine No.: 52A001124
 Chassis No.: 52A001124
 Maximum Power Output: -
 Open Market Value: \$0.00
 Original Registration Date: 21 Jun 1985
 First Registration Date: 21 Jun 1985
 Transfer Count: 7
 Actual ARF Paid: \$0.00

Intended PARF Rebate Details

PARF Eligibility: No
 PARF Eligibility Expiry Date: -
 PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Oct 2022
 COE Category: D - Motorcycle
 COE Period(Years): 10
 PQP Paid: \$1,895.00
 COE Rebate Amount: \$789.00
 Total Rebate Amount: \$789.00

Message

Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.

This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.

This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.

For more information, please visit <http://www.nea.gov.sg/mtcincentive> or contact NEA at 1800-2255-632.

The information contained herein is correct as at 31 Aug 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/08/2018 12:46
Date Of Accident	24/08/2018 12:30
Exact Location Of Accident	SIN MING ROAD & SHUNFU ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FD9728H
Insured/Policyholder	
Name Of Registered Owner	TAN YOY SENG
NRIC No	S0203868D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90408941
Alternative Phone No	OTHERS-90408941

Vehicle Particulars

Manufacturer	YAMAHA
Model	RX11
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	A 27675247 TPY
Cover Note Number	

Driver

Name of Driver	TAN YOY SENG
NRIC No	S0203868D
Date Of Birth	13/03/1953
Occupation	OUTDOOR
Date Of Driving Pass	04/07/1983
Driving Experience	35 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90408941
Fax Number	
Contact Number	OTHERS-90408941
Email Address	NOEMAIL



**SINGAPORE
POLICE FORCE**



T/20180824/2091

1 of 3

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

Report No. T/20180824/2091

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 24/08/2018 15:20	Vide Report No.:	Station Diary No.: 30
--	------------------	--------------------------

Informant's Particulars				
Name of Informant: TAN YOY SENG		Address: APT BLK 833 ANG MO KIO AVENUE 6 #06-5145 SINGAPORE 560633		
ID Type / ID No.: NRIC NO / S0203868D		Contact No.: Home/Office: Mobile: 90408941		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 65	Date of Birth: 13/03/1953	Type of Informant: Rider	
Race: Chinese		Language:		Institution / School Name:
Occupation: DELIVERYMAN		Driving Licence Information: Class: 2B,3,4 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 24/08/2018 12:30	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 SIN MING ROAD UPPER THOMSON ROAD				
Weather: Clear		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FD9728H	Motorcycle					0
SJL8694M						0



GA MOTOR

Block 32, Sin Ming Drive, #01-331, Singapore 575706

TEL: 64539903, 64539904 FAX: 64539904

Importer & Exporter - New & Used Motorcycles. Spare Parts & Accessories.

Dealer of Honda, Yamaha, Suzuki and Vespa, etc. Repair & Service all motorcycles, scooters.



Date: 28-08-2018

Estimated repair list for the accident motorcycle Yamaha RX115 Vehicle No. FD9728H

1 pc	Handle bar	B ₁	\$80.00	✓
1 pc	Brake lever	B ₂	\$25.00	✓
1 set	Mirror	CM	\$50.00	✓
1 set	Top brake pump	RM	\$160.00	✓
1 pc	Signal light (right)	CM	\$35.00	✓
1 pc	I. U. unit	RM	\$156.00	✓
1 pc	I.U. bracket	R	\$35.00	X
1 pc	Head light	RM	\$120.00	✓
1 pc	Head light bracket	R	\$95.00	X
1 pc	Seat	(T ₁)	\$120.00	X NC
2 pcs	Front fork inner tube	TT	\$240.00	✓
1 set	Fork oil seal & fork oil	RM	\$55.00	✓ 50/100 27.50
1 pc	Bottom steering stem	RM	\$140.00	✓
1 set	Steering cone & bearing	RM	\$60.00	✓
1 pc	Bottom brake pump	RM	\$220.00	✓
1 pc	Brake hose	RM	\$60.00	✓
1 pc	Front disc plate	WAP	\$185.00	✓
1 set	Front sport rim	WAP	\$360.00	✓
1 pc	Front mudguard	CM	\$95.00	✓
1 set	Front footrest & footrest rubber	RM	\$80.00	✓
1 pc	Brake padel	RM	\$70.00	✓
1 pc	Rear box	CM	\$160.00	✓
1 pc	Exhaust pipe	RM	\$450.00	✓
	Towing		\$30.00	✓
	Labour		\$300.00	1801

Total :

\$3381.00

Not Withstand

21 Day @ 2100h

After Paint

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Aug 2018 Edit Reg		30 Aug 2018 00:00 Edit Adj Rpt	S\$2,100.00 Edit Estimates	S\$2,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TAN AH TEE , ID: S0268185D								
Main Claimant:	TAN YOY SENG , ID: S0203868D								
Vehicle Reg. No.:	FD9728H	Date of Loss:	24/08/2018 00:00 - :59 [398 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 9780712869SG	Policy/Cover Note No.:	2100109347 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJL8694M	Policy No. (Claimant):							
		Excess:							
Repairer:	Ga Motor (HQ) Blk 32 Sin Ming Drive, #01-331, 575706 Sin Ming - Tel: 64539903								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 11/09/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FD9728H (9780712869SG)
[SJL8694M]
TP
TAN YOY SENG
Aug 24 2018 12:00AM
[TAN AH TEE]
Ga Motor

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Assessment Reports															1 per page			☒		
No.	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail			Print		
1	04/09/18 11:30		Accident Statement From: SC - Reg. No: SJLB694M, Claimant: TAN AH TEE															Load HTM		
Photos/Images															3 per page			☒		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	11/10/18 10:27		General View															Load JPG ☒		
2	11/10/18 10:27		General View															Load JPG ☒		
3	11/10/18 10:27		General View															Load JPG ☒		
4	11/10/18 10:27		General View															Load JPG ☒		
5	11/10/18 10:27		General View															Load JPG ☒		
6	11/10/18 10:27		General View															Load JPG ☒		
7	11/10/18 10:27		General View															Load JPG ☒		
8	11/10/18 10:27		General View															Load JPG ☒		
9	11/10/18 10:27		General View															Load JPG ☒		
10	11/10/18 10:27		General View															Load JPG ☒		
11	11/10/18 10:27		General View															Load JPG ☒		
12	11/10/18 10:27		General View															Load JPG ☒		
13	11/10/18 10:27		General View															Load JPG ☒		
14	11/10/18 10:27		General View															Load JPG ☒		
15	11/10/18 10:27		General View															Load JPG ☒		
16	11/10/18 10:27		General View															Load JPG ☒		
17	11/10/18 10:27		General View															Load JPG ☒		
18	11/10/18 10:27		General View															Load JPG ☒		
19	11/10/18 10:27		General View															Load JPG ☒		
20	11/10/18 10:27		General View															Load JPG ☒		
21	11/10/18 10:27		General View															Load JPG ☒		
22	11/10/18 10:27		General View															Load JPG ☒		
23	11/10/18 10:27		General View															Load JPG ☒		
24	11/10/18 10:27		General View															Load JPG ☒		
25	11/10/18 10:27		General View															Load JPG ☒		
26	11/10/18 10:27		General View															Load JPG ☒		
27	11/10/18 10:27		General View															Load JPG ☒		
28	11/10/18 10:27		General View															Load JPG ☒		
29	11/10/18 10:32		General View															Load JPG ☒		
30	11/10/18 10:32		General View															Load JPG ☒		
31	11/10/18 10:32		General View															Load JPG ☒		
32	11/10/18 10:32		General View															Load JPG ☒		
33	11/10/18 10:32		General View															Load JPG ☒		

Assessment Reports			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	11/10/18 10:32	General View	 Load JPG	☒
35	11/10/18 10:32	General View	 Load JPG	☒
36	11/10/18 10:33	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/08/18 12:38	TP GIA AND POLICE REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18015891/KVD3Q2

Date: 23/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 2100109347

Claimant Vehicle No: FD9728H

Insured Vehicle No: SJL8694M

Date of Loss: 24/08/2018

Nature of Claim: TP

Claim No: 9780712869SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FD9728H

Make & Model: YAMAHA RX11, 115cc

Engine No: 52A001124

Reg. Date: 21/06/1985 (Man. Year: 1985)

Chassis No: 52A001124

Colour: Black

Odometer: 73662 km

Engine Capacity: 115 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 2.75 R18

Rear Tyre Size: 3.00 R18

Front Left Side: Metzeler 2 mm

Rear Left Side: Pirelli 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,051.00	2,498.90	552.10	18.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	330.00	210.00	120.00	36.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,381.00	2,708.90	672.10	19.88
Approved Total (Overridden) (S\$)		2,100.00		
Nett Amount (S\$)	3,381.00	2,100.00	1,281.00	37.89

INSPECTION

Date of Assignment: 30/08/2018

Date Inspected: 30/08/2018 Inspected At:

Ga Motor (HQ)
Blk 32 Sin Ming Drive, #01-331
Singapore 575706

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent	80.00 F	*80.00 FL
2	1		*BRAKE LEVER	Bent	25.00 F	*25.00 FL
3	1		*SET MIRROR	Cut	50.00 F	*50.00 FL
4	1		*SET TOP BRAKE PUMP	Dented	160.00 F	*160.00 FL
5	1		*SIGNAL LIGHT (RIGHT)	Cracked	35.00 F	*35.00 FL
6	1		*LU UNIT	Dented	156.00 F	*156.00 FL
7	1		*LU BRACKET	Repair	35.00 F	*- FL
8	1		*HEAD LIGHT	Dented	120.00 F	*120.00 FL
9	1		*HEAD LIGHT BRACKET	Repair	95.00 F	*- FL
10	1		*SEAT (Torn)	Not Consistent With The Impact	120.00 F	*- FL
11	2		*FRONT FORK INNER TUBE	Twisted	240.00 F	*240.00 FL
12	1		*SET FORK OIL SEAL & FORK OIL (50%)	Necessary	55.00 FS	*27.50 FS
13	1		*BOTTOM STEERING STEM	Distorted	140.00 F	*140.00 FL
14	1		*SET STEERING CONE & BEARING	Necessary	60.00 F	*60.00 FL
15	1		*BOTTOM BRAKE PUMP	Dented	220.00 F	*220.00 FL
16	1		*BRAKE HOSE	Dented	60.00 F	*60.00 FL
17	1		*FRONT DISC PLATE	Warped	185.00 F	*185.00 FL
18	1		*SET FRONT SPORT RIM	Warped	360.00 F	*360.00 FL
19	1		*FRONT MUDGUARD	Cracked	95.00 F	*95.00 FL
20	1		*SET FRONT FOOTREST & FOOTREST RUBBER	Bent	80.00 F	*80.00 FL
21	1		*BRAKE PADEL	Distorted	70.00 F	*70.00 FL
22	1		*REAR BOX	Cut	160.00 F	*160.00 FL
23	1		*EXHAUST PIPE	Dented	450.00 F	*450.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,051.00	2,773.50
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	274.60
Total Parts (\$\$)	3,051.00	2,498.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING	New	30.00	30.00
2	LABOUR	New	300.00	180.00
Gross Labour Cost (S\$)			330.00	210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >