

3003260

ASS. REC. BY:

REF: CS3/LPC/18015893/Grd3 n2

Surveyor

Guo Qiang

ASSIGNMENT (Office)

From (Person)

Ong Li Li

of

LPC

Date/Time

21/8/18 @ 4:55pm

Estimated Cost

Bill to:

OD (TV) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ 2844L

Insured:

G88 7479Y

at Workshop m/s

Hup Juy Street

Tel:

96773832

of

Blk1 Kaki Blk Ave 6 #01-35

Policy No:

Claim No:

18/18/18/VCS/020862

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

28/8/18

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

10.02am @

Person Contacted:

Mr. Tan

Vehicle IN/OUT

(OUT)

Date/Time	Action/Instruction (X) Estimate
	G88 7479Y - NA/MSG/18015893/18/18/18 D.O.A: 28/8/18
	SLQ 2844L - NA/MSG/18015893/18/18/18 D.O.A: 28/8/18
	Submit Pres report

PRS
XAL

REF:

0993C /

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: Hup ley Huat
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SUQ 2844L Yr Regn: 03 Jul 2017
 Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Mazda 5 c.c. 1998
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: 21821 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JM6CW1071H0125825
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD / A/Rim or _____
 Tyre Size: F: 205/55R16
 R: 11

(Policy Condition)

C	
N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Bal. or Market Value: _____
 IDAC Accident Rport.: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 03-09-18
 Survey held at W/S 12pm
 Des. of Damages: Fr Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>\$3000 - \$4000</u>

RECEIVED 15 OCT 2018

Date/Time, File Pass to? : Preli. Report

Days Of Repair: 4

1) typist : Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: : Site Insp (\$)

Transportation:

Report Format :

: Interview (\$)

) Photos

Lump Sum / I.B.I: (\$)

: Tech. Invs (\$)

) Others

: Weekend (\$)

TOTAL

450



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CS3/LPC18015893/Grd3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 31-08-2018	
		Code : LPC2	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	GBB 7479Y	Veh. Inspected	SLQ 2844L
Policy No.		Coverage (\$)	0.00
Claim No.	18/18/18/VCO5/020862	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	31/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	28/08/2018	Inspection Date	03/09/2018
Survey held at	HUP LEY HUAT MOTOR SPRAY PAINTING SVS BLK 1 KAKI BUKIT AVE 6, #01-35 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Wednesday, 29 August 2018 4:55 PM
To: Chris Tan; assignments@lkkauto.com; Catherine Chong (LKK Auto)
Cc: hup Ley Huat
Subject: RE: Your Ref: LCH.ct/2KB02-80775.18 Our Ref: 18/18/18/VC05/020862 Accident involving GBB7479Y and SLQ2844L on 28/8/2018
Attachments: 80775.ltr.pdf

*10:02am
VMI
Mr. Tan.*

Without Prejudice

Dear Chris

We are not agreeable with your proposed list of surveyors and we shall proceed to appoint our surveyor to conduct the pre-repair survey.

Dear Catherine/Nivitha

Please arrange survey.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Chris Tan [mailto:mail@cheonghoh.sg]
Sent: Wednesday, 29 August, 2018 4:50 PM
To: ONG LI LI
Cc: hup Ley Huat
Subject: Re: Your Ref: LCH.ct/2KB02-80775.18 Our Ref: 18/18/18/VC05/020862 Accident involving GBB7479Y and SLQ2844L on 28/8/2018

Dear Li Li

Enclosed pls see our letter dated 29 August 2018 for your information and reply.

Regards,
Chris Tan
Cheonghoh Law Corporation
Blk 53 Chin Swee Road #03-05
Singapore 160053
Tel: 63378700
Fax: 63373700

On 29 Aug 2018, at 2:11 PM, ONG LI LI <llong@lonpac.com> wrote:

Without Prejudice
Save as to Costs

Dear Sir/Mdm

We refer to your fax of 29.08.2018.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick <input type="checkbox"/>
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

<20862 (2).pdf>

Cheonghoh Law Corporation

(Incorporated with limited liability) Blk 53 Chin Swee Road #03-05 . Singapore 160053
Co. Reg No.201108070G Tel: 63378700 Fax: 63373700 E-mail: mail@cheonghoh.sg

In reply, please quote our Reference Number

Our Ref: LCH.ct/2KB02-80775.18
Your Ref: 18/18/18/VC05/020862

29 August 2018

Lonpac Insurance Berhad
300 Beach Road #17-04/07
The Concourse
Singapore 199555
Attn: Ong Li Li

BY EMAIL ONLY
Fax No: 62962706

Dear Sirs

ACCIDENT INVOLVING VEHICLES NO SLQ 2844 L AND GBB 7479 Y ON 28 AUGUST 2018 AT/ALONG JUNCTION OF EUNOS ROAD 1 AND EUNOS AVE 7 - MC/MC

We refer to the above matter and to your email of even date.

Pursuant to the NIMA protocol of the Practice Directions Amendment No. 1 of 2016, we have our client's instructions to reject your list of appointed surveyors as stated in your said email.

We are further instructed to append below our client's 10 proposed surveyors as follows:

- 1) Fong Kok Heng
- 2) Danny Yap
- 3) Willy Goh
- 4) Francis Ng
- 5) Dennis Yap
- 6) Louis Ng
- 7) Michael Yap
- 8) LimYong Tian
- 9) Patrick Ng
- 10) Philip Foo


If you are not agreeable to our list of surveyors above, kindly appoint your surveyor to proceed with the pre-repair survey of our client's vehicle at our client's repairer workshop as follows :-

Hup Ley Huat Motor Spray Painting Services
Blk 1 Kaki Bukit Avenue 6 #01-35
Singapore 417883

Person to contact : Mr Tan Boon Seng (contact no. 96773832)

Thank you.

Yours faithfully



Lee Cheong Hoh
CHEONGHOH LAW CORPORATION

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0993C
Vehicle Details	
Vehicle No.:	SLQ2844L
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Sep 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA5 WAGON 2.0 AT EU6
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	PE10503328
Chassis No.:	JM6CW1071H0125825
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$17,821.00
Original Registration Date:	03 Jul 2017
First Registration Date:	03 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$17,821.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Jul 2027
PARF Rebate Amount:	\$13,365.00
Intended COE Rebate Details	
COE Expiry Date:	02 Jul 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$55,000.00
COE Rebate Amount:	\$48,551.00
Total Rebate Amount:	\$61,916.00

The information contained herein is correct as at 04 Sep 2018

OK




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Ref: CS3/LPC18015893/Grd3n2 Date: 16-10-2018 Code: LPC2	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	GBB 7479Y	Veh. Inspected	SLQ 2844L
Policy No.		Coverage (\$)	0.00
Claim No.	18/18/18/VC05/020862	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	29/08/2018
2. Vehicle Particulars & Condition			
Make & Model	MAZDA 5	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6CW1071H0125825	Colour	WHITE
Odometer	21821 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	TOYO	6 mm
L/H Front Tyre	205/55 R16	TOYO	6 mm
R/H Rear Tyre	205/55 R16	TOYO	6 mm
L/H Rear Tyre	205/55 R16	TOYO	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.			
5. General Information			
Accident Date	28/08/2018	Inspect Date / Time	03/09/2018 (12:00 PM)
Survey held at	HUP LEY HUAT MOTOR SPRAY PAINTING SVS BLK 1 KAKI BUKIT AVE 6, #01-35 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/LPC18015893/Grd3n2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.