

REF CS/ASM18015897/R/V0302

Ref. of Assignment

Sgt/Voyant

Resul

ASSIGNMENT (Office)

From (Person)

Peter Wang

ASM(CAXA)

Date/Time

29/8/2018

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

SJA 9898T

Insured

at Workshop n/a

cycle & Cemicole

Tel

9186 5113

of

188 pandan loop

Policy No

Claim No

S8M007FR

Sum Insured

Excess

\$500.00

Make of Veh

(Client's Record)

D.O.A

25/8/18

CA / REV

REP. / REV 24 HRS

Date/Time

12.56pm 30/8/18

Person Contacted

Kerlyn

R.O.D. Endorsement

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJA 9898T - CCG / AIG 15605203 / Ape 3q2 DOA: 20/3/15

31/8/18

Revert via SMART claim

3/9/18

Rece authorise from Peter Wang via SMART claim

3/9/18

Informed Kerlyn c/A ex \$500 by email

9/10/18

final fig \$4731.20 (Ref 4067-39, 46/3) confirmed by email

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OOT / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJA 9898Tat Workshop mis CBC

of _____

Insured: ASM / AXA

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 60K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJA 9898T Yr Regn: 2011 / JunType: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: MERCEDES BENZ E200 C41 c.c 1796Colour: BLUE A/C: Insured / Std / NI / NASp. Reading: 120095 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD 2120482A390599Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 245/45 ZR17R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FALKEN

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 25/08/18 D.O.I. 30/08/18Survey held at CBC (PL)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 15 NOV 2018

Date/Time, File Pass to?

☐ : Preli. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) 15/11 - typistDays Of Repair: 6Resurvey No. of Trip: -Survey Fee: 200

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

) \$ + RS \$ _____

☐ : Interview (\$ _____)

) Photos _____

☐ : Tech. Invs (\$ _____)

) Others _____

☐ : Weekend (\$ _____)

) _____

TOTAL

200Report Format: SMART claimLump Sum / I.B.I. (\$) 473620



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18015897/R1vd3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 31-08-2018



Code : ASM

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SJA 9898T
Policy No.	Coverage (\$)	0.00
Claim No. S8M00TFR	Excess (\$)	0.00
Assign From SMARTCLAIM (PETER WANG)	Assign Date	31/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

5. General Information

Accident Date	25/08/2018	Inspection Date	30/08/2018
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		

5a. Remarks

- A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Re:SJA 9898T-IA SUBMITTED INCLUDE SUPPLEMENTARY

Type

🔗 Question

Message

Noted to proceed. However, why is supplementary so late, almost 1.5mths. Was it submitted and inspected before the repair?

Reply *

Dear Sir/Madam,
Kindly be informed we only received this supplementary on 5th Oct 2018, our surveyor verified damages and submitted for your approval on 11th Oct 2018.Thanks Veron Chen

Cancel Reply

Reply Now



Re:SJA 9898T-IA SUBMITTED INCLUDE SUPPLEMENTARY

Type

🔗 Question

Message

Noted to proceed. However, why is supplementary so late, almost 1.5mths. Was it submitted and inspected before the repair?

Reply

Kindly be advised we only
received this ~~sup~~ supplement on
5th Oct 2018, our surveyor
verified damage and submitted
for your approval on 9th Oct 2018.

New Message

Type *

☒ Message

Subject *

SJA 9898T-IA SUBMITTED INCLUDE SUPPLEMENTARY

Message *

Dear Sir/Madam,

IA submitted include supplementary. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair.

Best Regards Veron Chen

Cancel

Send



Auto
Consultants
Pte Ltd

31, UBI AVE 1, #01-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408033 TEL : (065) 62563561 FAX : (065) 62564318

Immediate Advice

To : AXA Insurance Pte Ltd

Date:9/10/2018

Survey details

Date of loss	25/8/2018
Date of appointment	29/8/2018
Date of survey	30/8/2018
Location of survey	CYCLE & CARRIAGE IND (1986) PTE LTD

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SJA 9898T
Make and Model	MERCEDES BENZ
Date of registration	16/6/2011
Excess	\$500
Market Value	\$60,000.00
Part Rebate	\$47,707.00
Nett Loss	\$12,293.00

Repair details

Initial Estimate	\$8,798.59 (Incl.supplementary \$31.20)
------------------	---

Proposed/Revised repair cost:

Parts	\$31.20
"Check items (Estimated)	
Labour	\$4,700.00
Total	\$4,731.20 (Incl.supplementary \$31.20)
Lump Sum (Estimated)	

Number of days of repair	6 days (est)
--------------------------	--------------

Remarks:

The vehicle sustained damages at the o/s rear portion

Damages Consistent
Repair Cost Economical

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 3 September 2018 10:51 AM
To: Kerlyn Ong (kerlyn.ong@cyclecarriage.com.sg)
Cc: SUR
Subject: SJA 9898T-DOA: 25/8/2018 (AXA OD)

Dear Kerlyn,

As instructed by our client, please proceed to repair the insured vehicle **SJA 9898T (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Authorized

Type

🔗 Question

Message

Pls proceed to authorize repair. Excess: \$500.

Reply

New Message

Type *

☒ Message

Subject *

IA SUBMITTED FOR SJA 9898T

Message *

Dear Sir/Madam,

Please be informed that IA submitted. We have Not Authorize repair. Kindly let us have your approval please.Thanks Veron Chen

Cancel

Send



Public
Consultants
Pte Ltd

11 MARINE CORPUS DRIVE, INDUSTRIAL PARK, SINGAPORE 409902 TEL : (65) 62963562 FAX : (65) 62964119

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 31/8/2018

Survey details

Date of loss	25/8/2018
Date of appointment	29/8/2018
Date of survey	30/8/2018
Location of survey	CYCLE & CARRIAGE IND (1986) PTE LTD

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SJA 9898T
Make and Model	MERCEDES BENZ
Date of registration	16/6/2011
Excess	\$500
Market Value	\$60,000.00
Part Rebate	\$47,707.00
Nett Loss	\$12,293.00

Repair details

Initial Estimate	\$8,767.39
------------------	------------

Proposed/Revised repair cost:

Parts	
"Check items (Estimated)	
Labour	\$4,700.00
Total	\$4,700.00
Lump Sum (Estimated)	

Number of days of repair	6 days (est)
--------------------------	--------------

Remarks:

The vehicle sustained damages at the
o/s rear portion.

Damages Consistent
Repair Cost Economical




Service Request Details

Claim

S8M00TFR

Reference

None 

Loss Date

August 25, 2018

Request Date

August 29, 2018

Due Date

September 5, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SJA9898T

Make

MERCEDES

Model

E200

Service Address

188 PANDAN LOOP, ., 128378

Primary Contact/Insured

TANOTO SHIPYARD PTE LTD

1 JALAN SAMULUN, 629119, Singapore

GCINS@SINGNET.COM.SG

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

Wkshop: C&C @ Pandan Excess: \$500 Pending company authorization letter To survey WP

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)

[New Message](#)

VISHNU BATHAM Shekhar

From: Kerlyn Ong Kai Li <kerlyn.ong@cyclecarriage.com.sg>
Sent: Monday, August 27, 2018 5:09 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: SJA9898T
Attachments: img-827170524-0001.pdf

Categories: Shekhar

Dear Officer,

Please arrange to survey under own damage claim

Your Sincerely,

Kerlyn Ong
Service Advisor - Body Care & Repair
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
188 Pandan Loop Service Center
Mobile: 91865113 | DID: 67714420 | Fax: 68721272
Website: www.mercedes-benz.com.sg

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Information	
Owner ID Type:	Company
Owner ID:	3005G
Vehicle Details	
Vehicle No.:	SJA9898T
Vehicle to be Exported:	No
Intended De-registration Date:	31 Aug 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E 200CGI
Primary Colour:	Blue
Manufacturing Year:	2010
Engine No.:	27186030191377
Chassis No.:	WDD2120482A390599
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$53,923.00
Original Registration Date:	16 Jun 2011
First Registration Date:	16 Jun 2011
Transfer Count:	0
Actual ARF Paid:	\$53,923.00
Intended PARF/COE Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Jun 2021
PARF Rebate Amount:	\$32,353.00
Intended COE Details	
COE Expiry Date:	15 Jun 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$57,100.00
COE Rebate Amount:	\$15,354.00
Total Rebate Amount:	\$47,707.00

The information contained herein is correct as at 31 Aug 2018

OK

60,000
47,707

12,293



redefining / insurance

AXA Insurance Pte Ltd
☎ 1800 880 4888 (Within Singapore)
(65) 6880 4888 (International)
✉ (65) 6880 4740
✉ customer.care@axa.com.sg
🌐 www.axa.com.sg

TANOTO SHIPYARD PTE LTD
1 JALAN SAMULUN
SINGAPORE 629119

Renewal

date
21/05/2018

your servicing distributor
**G & C GENERAL INSURANCE AGENCY /
01730**

your servicing distributor contact
91000500

Policy Schedule

Your SmartDrive Comprehensive Flexi

Your policy snapshot

Policyholder name	TANOTO SHIPYARD PTE LTD	Policy number	VA1 / GA042912
Cover	Comprehensive	FIN / NRIC	198703005G
Period of Insurance	from 16/06/2018 to 15/06/2019 (both dates inclusive)		

Premium breakdown

Gross Premium after 50% NCD	SGD 1,241.82
7% GST	SGD 86.93
Final Premium	SGD 1,328.75

Your benefits highlights

(refer to Policy Wording for full terms and conditions)

SmartDrive Comprehensive Flexi Benefits

- 24/7 Towing & Transportation in Singapore or Overseas
- Windscreen Replacement with Excess OR Repair your windscreen at your preferred location and get \$50 cash reward with no excess
- Loss or Damage
- Legal Liability
- Workshop of Your Choice
- Medical and dental expenses up to \$1,000 per person for you, your named drivers and your immediate family members
- Reimbursement of 110% of your car's market value in the event of total loss due to flood (without Basic Own Damage Excess)

Add-on Benefits

- Personal accident benefit of up to \$ 50,000.00 for you and your named drivers

Vehicle details

Make & Model of Vehicle	MERCEDES E200 CGI	Year of manufacture	2010
Vehicle registration number	SJA9898T	Type of Use	Private use
Body type	SALOON	Engine capacity (c.c.)	1796
Seating capacity (excl driver)	4	Engine number	27186030191377
Off-Peak car	No	Chassis number	WDD2120482A390599

Insured's Estimated Market Value	Market Value at the time of Loss (including accessories and spare parts)
Limitation to use	As per Certificate of Insurance
Finance Loan Company	CITIBANK SINGAPORE LIMITED

Excess applicable (refer to Policy Wording for other applicable Excesses)

Basic Own Damage Excess	SGD 500.00
Windscreen Excess	SGD 100.00

Drivers details

Licence Number: **F0859028K**

Name:

TANOTO WILLIE

Birth Date: **20 Aug 1984**

Issue Date: **25 Mar 2017**

Valid Till **24/03/2022**



FOR C&C USE ONLY



002669006E

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class	Description	Effective Date
Class 3	Motor cars with unladen weight $\leq 3000\text{kg}$ with ≤ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq 2500\text{kg}$	03 Mar 2007

FOR C&C USE ONLY

NP 425A



Licence No: F0859028K

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/08/2018 15:56
Date Of Accident	25/08/2018 14:45
Exact Location Of Accident	ALONG BALESTIER ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJA9898T
Insured/Policyholder	
Name Of Registered Owner	TANOTO SHIPYARD PTE LTD
Co Reg No	198703005G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62647300

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E200

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VA/GA042912
Cover Note Number	

Driver

Name of Driver	TANOTO WILLIE
NRIC No	F0859028K
Date Of Birth	20/08/1984
Occupation	INDOOR
Date Of Driving Pass	03/03/2007
Driving Experience	11 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81574451
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	NO 1 JALAN SAMULUN
Postcode	629119
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO MOTORCYCLIST
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : JOAN TANDRA GENDER: : FEMALE
Passenger 2	NAME: : SUSANNA GENDER: : FEMALE
Passenger 3	NAME: : ASHTON TANOTO GENDER: : MALE
Passenger 4	NAME: : KAYLA TANOTO GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER POLICE REPORT NO: T/20180825/7016.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBN2238X
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

MOTORCYCLE

Name of Driver

LIM TECK LIANG

NRIC/Passport Number

S8022624A

Contact Number

91034444

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Kerlyn Ong Kai Li

DID : 6771 4420 HP : 912- 5133

Email : kerlyn.ong@cyclocarrier

Cycle & Carriage Insurance

Customer Service Centre - P



Policyholder's Signature

Date & Time 27/08/2018 1412

Driver's Signature

(If driver is not the policyholder)

Date & Time 27/08/2018 1412

Reporting Centre Personnel's

Name: KERLYN

NRIC/FIN No.:

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

refer to police report no. T/2018 0825/7016

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

(Please contact your insurance company for any further details)

Kerlyn Ong Kai Li

DID : 6771 4420 HP : 9186 5113

Email : kerlyn.ong@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Policyholder's Signature

Date & Time 27/08/2018 1412



Driver's Signature

(If driver is not the policyholder)

Date & Time 27/08/2018 1412

Reporting Centre Personnel's

Name: KERLYN

NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20180825/7016

1 of 4

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20180825/7016

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 25/08/2018 18:11	Vide Report No.: E/20180825/0139	Station Diary No.:
--	-------------------------------------	--------------------

Informant's Particulars

Name of Informant: TANOTO WILLIE			Address: 9 ROBIN LANE SINGAPORE 258239		
ID Type / ID No.: FIN NO / F0859028K			Contact No.: Home/Office: Mobile: 81574451		
Nationality: INDONESIAN			Email: wtanoto@gmail.com		
Sex: Male	Age: 34	Date of Birth: 20/08/1984	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: BANK EXECUTIVE			Driving Licence Information: Class: 3 Date of Expiry: 24/03/2022		

General Information of the Accident

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 25/08/2018 14:45	Type of Location: Straight Road
Location: BALESTIER ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBN2238X	Motorcycle			Blue	Slightly Damaged	0
SJA9898T	Car	MERCEDES BENZ	E200	Blue	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180825/7016

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 4

Report No. T/20180825/7016

CONTINUATION OF REPORT

Rider			
Name	Lim Teck Liang	ID No.	S8022624A
Related Vehicle	FBN2238X (Motorcycle)	Contact No.	91034444
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
Driver			
Name	TANOTO WILLIE	ID No.	F0859028K
Related Vehicle	SJA9898T (Car)	Contact No.	81574451
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: 24/03/2022
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

The accident occurred on Balestier Road, heading towards Lavender Road. This is in front of a shop called Avantgarde Curtain, at 334 Balestier Road.

I was on the middle lane of the 3-lane road, trying to filter to the right-most lane. Traffic was very heavy and slow moving. I estimate that it could not have been more than 5 or 10 kilometres per hour. The right lane was clear to me and the next closest vehicle in the lane is the motorcycle I collided with. I estimate him to be approximately 7-8 vehicles distance away from me at the time I was entering the lane. He was wearing a bright pink Food Panda uniform and as such was very visible.

Judging that the lane was clear, I signalled right and moved slowly into the lane. In the course of doing so, I heard a bang near the right-back passenger car door and stopped my vehicle immediately. When I got out of the car, the motorcycle was down, but the rider was standing and helping his bike up. The rider claimed to be injured and immediately called for an ambulance for himself. Both of us jointly checked him for injuries and the only visible one was a scratch on his right index finger. However, he said his back, which is suffering from a chronic injury he says he has been seeing a specialist for, was aching and he needed to go to the hospital. He continued to be mobile, was independently taking photographs of the accident site, spoke on the phone several times and we exchanged information and contact details. I was physically fine and needed no medical attention.

There was a 30-40 cm scratch across the right back car door and this was the main visible damage for my car. For his motorbike, I could only see a scratch on an emblem on the left side. There were no other damages to other vehicles or public property as the collision only involved two parties. There was no resulting debris on the road.



**SINGAPORE
POLICE FORCE**



T/20180825/7016

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 4

Report No. T/20180825/7016

CONTINUATION OF REPORT

I have some photos of the vehicles and of the rider immediately after the accident. I do not have an in-vehicle camera.

I called 999 and was informed that the emergency services have already been notified and the ambulance came by in maybe 10-15 minutes and the traffic police 10 or so minutes after that. The paramedics checked the rider and he repeated to them what he had told me and afterwards he proceeded to board the ambulance after collecting his valuables. The traffic police officer came by just as the ambulance was about to leave, spoke to the rider for a couple of minutes, and then directed me to move the vehicle to the leftmost lane of Balestier Road. I left the scene after the traffic police officer issued me with a case card and told me to come here to the police station to make a police report.



**SINGAPORE
POLICE FORCE**



T/20180825/7016

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

4 of 4

Report No. T/20180825/7016

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
SHAHRUL NIZAM BIN SAMARRI
Contact No.: 65476904

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
25/08/2018 18:11

Classification Of Case:



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorized Dealer
Company No. 196400367W
GST Reg No. MR-8502111-X

ESTIMATE FOR SJA9898T

Tanoto Shipyard Pte Ltd

No. 1 Jalan Samulun
Singapore 629119

Work: 62647300

Vehicle & Document Information

WIP No 26421
Reg No/Reg Date SJA9898T / 16/06/2011
Date In/Mileage / 0
Chassis No WDD2120482A390599
Engine No 27186030191377
Make/Model MB/E 200 CGI SEDAN (W212)
Colour/Trim 023 359 Tansanite B/ 042 201 Black

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	27/08/2018/ 17:04	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST				
Customer Request				
M BPNSUN				
POLICY NO/ACC DATE : VA1/GA042912 // 25/08/2018				
DRIVE IN/EXCESS : 27/08/2018 // \$500				
DATE IN/DATE SURVEY:				
BY/AUTHORIZED ON :				
A BPILAB				
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				2880.00
A BPIRES				1800.00
RESPRAY RH/ REAR DOOR, RH/ REAR FENDER & REAR BUMPER				
A BPILAB			0.10	380.00
USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT				
A BPILAB				120.00
CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT				
M RH/ REAR DOOR	1.00	2125.25	00.00	2125.25
M RH/ REAR DOOR WEATHERSTRIP	1.00	280.72	00.00	280.72
M RH/ REAR DOOR SIDE WINDOW FIXED	1.00	120.85	00.00	120.85
M GLAZING REPAIR KIT	1.00	154.72	00.00	154.72
M RH/ REAR DOOR WINDOW GUIDE RAIL	1.00	164.19	00.00	164.19
M RH/ REAR DOOR ORNAMENTAL COVER	1.00	85.80	00.00	85.80
M RH/ REAR DOOR SEALING RAIL	1.00	135.77	00.00	135.77
M RH/ REAR DOOR CHROME MOULDING	1.00	91.20	00.00	91.20
M LH/ REAR BUMPER CHROME MOULDING	1.00	128.17	00.00	128.17
M RH/ REAR BUMPER CHROME MOULDING	1.00	128.17	00.00	128.17
M CTR/ REAR BUMPER CHROME MOULDING	1.00	172.55	00.00	172.55

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Kerlyn Ong Kai Li

Confirmed & accepted by "Without Prejudice" basis

DID : 6771 4420 HP : 9186 5113

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Email : kerlyn.ong@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Acknowledged by Repairer

Authorized signatory and company stamp

Total Payable 9,381.11

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128376
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SJA9898T

AXA INSURANCE PTE LTD
MOTOR CLAIM DEPARTMENT
8 SHENTON WAY #24-01
SINGAPORE 068811

Work: 62647300

Vehicle & Document Information

WIP No **26421**
Reg No/Reg Date **SJA9898T / 16/06/2011**
Date In/Mileage **03/09/2018 / 120095**
Chassis No **WDD2140482A390599**
Engine No **27186030191377**
Make/Model **MB/E 200 CGI SEDAN (W212)**
Colour/Trim **023 359 Tansanite 8/ 042 201 Black**

SJA9898T

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
CS100001	Cash	11/09/2018/ 10:01		301 / Kerlyn Ong	10.00	3.12	00.00	31.20
Description of Goods / Services								
X RIVET								

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

SUPPLEMENTARY

Confirmed & accepted by

7% GST on **Nett 31.20**
2.18
Total Payable 33.38

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 126378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SJA9898T

AXA INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT
8 SHENTON WAY #24-01
SINGAPORE 068811

Work: 62647300

Vehicle & Document Information

WIP No **26421**
Reg No/Reg Date **SJA9898T / 16/06/2011**
Date In/Mileage **03/09/2018 / 120095**
Chassis No **WDD240482A390599**
Engine No **27186030191377**
Make/Model **MB/E 200 CGI SEDAN (W212)**
Colour/Trim **023 359 Tansanite 8/ 042 201 Black**

Account No	Terms	Date/Time Printed	CSE	Operator	
CSI00001	Cash	11/09/2018/ 10:02	K0	301 / Kerlyn Ong	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount

Z REQUEST

Customer Request
MIRBRSON

POLICY NO/ACC DATE : VA1/GA042912 // 25/08/2018
DRIVE IN/EXCESS : 27/08/2018 // \$500
DATE IN/DATE SURVEY: 30/08/2018 1710 // LKK - RASUL
BY/AUTHORIZED ON : 03/09/2018 // LKK - Veron Chen

A BPILAB					2400.00
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.					
A BPIRES					1800.00
RESPRAY RH/ REAR DOOR, RH/ REAR FENDER & REAR BUMPER					
A BPILAB				0.10	380.00
USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT					
A BPILAB					120.00
CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT					
X BPNEXC					-500.00
INSURANCE EXCESS					
X RIVET	10.00	3.12	00.00		31.20 (A)

Finalization

Confirmed & accepted by

7% GST on **Nett 4,231.20**
296.18
Total Payable 4,527.38

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 9 October 2018 11:27 AM
To: 'Kerlyn Ong'
Cc: SUR
Subject: RE: SJA 9898T-DOA: 25/8/2018 (AXA OD)

Dear Kerlyn,

Confirmed \$4731.20 before excess \$500 and GST @ 6 working days.

Kindly forward invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Kerlyn Ong <kerlyn.ong@cyclecarriage.com.sg>
Sent: Friday, 5 October 2018 3:24 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SJA 9898T-DOA: 25/8/2018 (AXA OD)

Dear Veron,

Please refer to attachment.

Your Sincerely,

Kerlyn Ong
Service Advisor - Body Care & Repair
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
188 Pandan Loop Service Center
Mobile: 91865113 | DID: 67714420 | Fax: 68721272
Website: www.mercedes-benz.com.sg

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Friday, 5 October, 2018 2:52 PM
To: Kerlyn Ong
Cc: SUR
Subject: RE: SJA 9898T-DOA: 25/8/2018 (AXA OD)

Dear Kerlyn,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Monday, 3 September 2018 10:51 AM

To: Kerlyn Ong (kerlyn.ong@cyclecarriage.com.sg) <kerlyn.ong@cyclecarriage.com.sg>

Cc: SUR <sur@lkkauto.com>

Subject: SJA 9898T-DOA: 25/8/2018 (AXA OD)

Dear Kerlyn,

As instructed by our client, please proceed to repair the insured vehicle **SJA 9898T (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

Workshop invoice linked - Kindly advise final report and invoice

Type

🔗 Question

Message

Thanks

Reply




Mercedes-Benz

60117690

3019561027
Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

TAX INVOICE

Invoice Name & Address		Owner Name & Vehicle Info	
AXA INSURANCE PTE LTD		Cust No/Name	/Tanoto Shipyard Pte Ltd
MOTOR CLAIM DEPARTMENT		Reg No/Reg Date	SJA9898T / 16/06/2011
8 SHENTON WAY #24-01		Date In/Mileage	03/09/2018/ 120095
SINGAPORE 068811		Chassis No	WDD2120482A390599
Contact No		Engine No	27186030191377
		Make/Model	MB/E 200 CGI SEDAN (W212)
		Colour/Trim	023 359 Tansanite B, 042 201 Black

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
CSI00001	Cash	26/10/2018/ 10:00	K0	301 / Kerlyn Ong	26421	28147204

Description of Goods / Services	Qty	Unit Price S\$	Amount S\$
Z REQUEST			
Customer Request			F.O.C
M BPNSUN			
POLICY NO/ACC DATE : VA1/GA042912 // 25/08/2018			
DRIVE IN/EXCESS : 27/08/2018 // \$500			
DATE IN/DATE SURVEY: 30/08/2018 1710 // LKK - RASUL			
BY/AUTHORIZED ON : 03/09/2018 // LKK - Veron Chen			
A BPILAB			2400.0
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.			
A BPIRES			1800.0
RESpray RH/ REAR DOOR, RH/ REAR FENDER & REAR BUMPER			
A BPILAB		0.10	380.0
USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			
A BPILAB			120.0
CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT			
X BPNEXC			-500.0
INSURANCE EXCESS			
X RIVET	10.00	3.12	31.2



Parts	31.20	Nett	4,231.2
Labour	4,700.00	7% GST on	296.1
Standard Menu	0.00		
Specialist Job	0.00	Total Payable	4,527.3
Diagnostics Job	0.00	Paid	0.0
Sundry/Others	-500.00	Total Due	4,527.3
Total(w/o GST)	4,231.20		

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



WE DRIVE FIRST CLASS

Pandan Loop Service Center
188 Pandan Loop

TO: AXA INSURANCE SINGAPORE PTE LTD

MOTOR VEHICLE CLAIM
SATISFICATION/DISCHARGE VOUCHER


NAME OF INSURED: Tanoto Shipyard Pte Ltd
MOTOR POLICY NO: VA1/GA042912
REGISTRATION NO: SJA9898T
ACCIDENT DATE: 25/082018
WIP NO.: 26421

REPAIRER NAME: CYCLE & CARRIAGE INDUSTRIES PTE LTD (CCI)
MERCEDES-BENZ SERVICE CENTRE
188 PANDAN LOOP SINGAPORE 128378

I/We certify that the vehicle has been fully repaired to my entire satisfaction and the payment of CCI's charges that are claimable under the policy will be deemed as full and final settlement of my claim.

I/We hereby release CCI from all liabilities in respect of damages to my/our motor vehicle.


SIGNATURE OF INSURED:





DATE: 11 Sep 2018.





TANOTO SHIPYARD PRIVATE LIM TED
NO. 1 JALAN SAMULUN SINGAPORE 629119 TEL : 6264 7300 FAX : 6264 7724
RCB No. 198703005G

31 August 2018

To whom it may concern:

AUTHORISATION TO DRIVE VEHICLE: SJA9898T

Please be informed that Mr. Willie Tanoto (F0859028K) was authorised by the company to drive the aforementioned vehicle on 25 August 2018.

Your attention to the above is greatly appreciated. Thank you.

Yours faithfully,

For & on behalf of

TANOTO SHIPYARD PTE LTD

Managing Director
Tanoto Iskandar



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18015897/R1vd3e2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN : PETER WANG

Date : 16-11-2018



Code : ASM

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SJA 9898T
Policy No.	VA/GA042912	Coverage (\$)	0.00
Claim No.	S8M00TFR	Excess (\$)	0.00
Assign From	PETER WANG	Assign Date	29/08/2018

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ E 200CGI	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WDD2120482A390599	Colour	BLUE
Odometer	120095	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/45Z R17	FALKEN	6 mm
L/H Front Tyre	245/45Z R17	FALKEN	6 mm
R/H Rear Tyre	245/45Z R17	FALKEN	6 mm
L/H Rear Tyre	245/45Z R17	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	25/08/2018	Inspection Date	30/08/2018
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		

5a. Remarks

A)THE MARKET VALUE IS S\$60,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJA 9898T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RH/ REAR DOOR (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	2,125.25	-
1	RH/ REAR DOOR WEATHERSTRIP (SN) (CONSISTENT)	SERVICEABLE	280.72	-
1	RH/ REAR DOOR SIDE WINDOW FIXED (SN) (CONSISTENT)	SERVICEABLE	120.85	-
1	GLAZING REPAIR KIT (SN) (CONSISTENT)	SERVICEABLE	154.72	-
1	RH/ REAR DOOR WINDOW GUIDE RAIL (SN) (CONSISTENT)	SERVICEABLE	164.19	-
1	RH/ REAR DOOR ORNAMENTAL COVER (SN) (CONSISTENT)	SERVICEABLE	85.80	-
1	RH/ REAR DOOR SEALING RAIL (SN) (CONSISTENT)	SERVICEABLE	135.77	-
1	RH/ REAR DOOR CHROME MOULDING (SN) (CONSISTENT)	SERVICEABLE	91.20	-
1	LH/ REAR BUMPER CHROME MOULDING (SN) (CONSISTENT)	SERVICEABLE	128.17	-
1	RH/ REAR BUMPER CHROME MOULDING (SN) (CONSISTENT)	SERVICEABLE	128.17	-
1	CTR/ REAR BUMPER CHROME MOULDING (SN) (CONSISTENT)	SERVICEABLE	172.55	-
10	RIVET @\$3.12 (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	31.20	31.20
			3,618.59	31.20
LABOUR				
	DISASSEMBLE ND REPLACE ATTACHED DAMAGED PARTS & REFINISH. INCLUSIVE OF THE REPAIR OF RH/ REAR DOOR.		2,880.00	2,400.00
	RESPRAY RH/ REAR DOOR, RH/ REAR FENDER & REAR BUMPER.		1,800.00	1,800.00
	USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD.		380.00	380.00
	CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE.		120.00	120.00
			5,180.00	4,700.00
GRAND TOTAL			8,798.59	4,731.20
RECOMMENDED COST OF REPAIRS				4,731.20

Report Ref No. CS/ASM18015897/R1vd3e2



LESS EXCESS			-500.00
NETT LIABILITY			4,231.20

Report Ref No. CS/ASM18015897/R1vd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.