

INSURANCE

INS. CASE OWNER

CC6 / AIG1801 5904, Aubby

LKK

IDAC

Surveyor:

Arian

DOI:

ASSIGNMENT

20/8/18

Date / Time:

20/8/18

Registered in Meritex:

20/8/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLX 1023J

Claim No.:

066886778556

Name of Insured:

1271 LEHANN PLK

Policy No.:

999994007

Insured Tel No.:

HP:

Make / Model:

Honda

Excess Sec II :SS

D.O.A.:

20/8/18

Place of Accident:

RD 1 upp SEKAMPOON KO

Is driver the owner? ( YES / NO )

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

TAN KIE THONG

OI GIA REPORT YES / NO : TP GIA REPORT YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: % Final ? Yes / No

STY 67850



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

people



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time

18/8/18  
TM

STY 67850  
SLX 1023J  
20/08/2018 08:58 (at 00:00) / 2/18

A is liable to B  
B is liable to C



10-08-18 Issue APPROVAL TO REPAIR TP CLAIM  
21-08-18 EMAIL WSP TO REPAIR TP CLAIM

Reject Case  
By: [Signature]  
Approved by: [Signature]  
Date: 21/08/18

STAGE	DATE / PIC
Non-Reporting ltr (1st)	
Non-Reporting ltr (2nd)	
Non-Reporting ltr (Final)	
Notification ltr (if non-pickup)	
Call OE	
After call ltr to OE	
Documentation Check List:	Handler Typist
Notification ltr (if non-pickup)	
After call ltr to OE	
Authorisation To Act	
Release Voucher	
Final Repair Bill	
Car Rental Invoice	
Towing Invoice	
LTA / GIA :	
Medical Bill	
PIR	
Mandate/Reject Instruction	
LOD	
Payment Breakdown Form	
Post-Repair Photos	
Others:	

<b>PRELIMINARY ADVICE</b>	Date/Time:	Sent By:	Confirm with:	Email	Call
<b>FINALIZATION</b>	Date/Time:	Repair Cost:	(\$)	( days) Reduction:	%
<b>FINAL SETTLEMENT</b>	Date/Time:	Confirm with:	Email	Call	
Final Liability:	% 0	(Agreed / Assessed) BOLA S/N No.:	289	If NO or B 28. Ass. Ln :	
Repair Cost:	\$5				
Loss of Rental (LOR):	\$5	( days)			
Loss of Use (LOU):	\$5	(S x days)			
Loss of Income (LOI):	\$5	(S x days)			
LOR only	<input type="checkbox"/>	LOU only	<input type="checkbox"/>	LOR + LOU	<input type="checkbox"/>
LOR + LOI	<input type="checkbox"/>	[Tick only one]			
GIA/LTA Search	\$5				
Medical	\$5				
Disbursement:	\$5	(e.g. Tow/ Independent )			
Legal Cost	\$5				
<b>Total:</b>	\$5	<b>Global Sum \$5:</b>			
<b>FINAL PAYMENT</b>	Date/Time:	Confirm with:	Email	Call	
Payee 1:	\$5	Name 1:			
Payee 2: (Strike if N.A.)	\$5	Name 2:			
Payee 3: (Strike if N.A.)	\$5	Name 3:			

COPY SENT  
20/8/18

REF:

ISS. REC. BY: Adrian King**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: **Yes** or **No**  
 GIA / PR Seer: \_\_\_\_\_ Consistent?: **Yes** or **No**  
 Est. Repairs: 3 days Res.: **Yes** or **No**  
 Lum Sum: 20 % 3 Val: **Yes** or **No**

CA / REV / REP. / 24 HRS

Vehicle: **IN** / **OUT**

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SJY6785D Yr Regn: \_\_\_\_\_ /  
 Type:  Car /  M.Cycle /  Bus /  Van /  Lorry /  Taxi /  Prime Mover /

Truck / Trailer or

Make: Toyota Vios. c.c. \_\_\_\_\_  
 Colour: Grey. A/C: **Insured** / **Std** / **NI** / **NA**  
 Sp. Reading: 126515. T/Radio: **Insured** / **Std** / **NI** / **NA**

Eng/No: \_\_\_\_\_

C/No: \_\_\_\_\_

Gen. Cond:  Good /  Fair /  Poor /  BurntSteering:  In order /  Jammed /  Leaked /  Burnt orBrake:  In order /  Jammed /  Leaked /  Burnt orModi:  Nil /  S/Rim /  STD A/Rim or

Tyre Size: F: 185/60 R15  
 R: 185/60 R15.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Achilles.

Front 06 mm R/Bal. 06 mm  
 L/Bal. 06 mm Rear 06 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 30/08/18

Survey held at People.Des. of Damages: **Frt** / **Rear** /  **N/S** /  **U/C** /  **Rooftop** orThe **U/C** / **Chassis frame** / **Body Structure** affected due to collision.

Date / Time Action / Instruction

TP Allg.46 + 1000 (220 + 1126.00 57/-)

Date/Time: File Pass to?

 : Prel. Report

①

 : Final Report

Date/Time: File Return to?

②

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Report Format \_\_\_\_\_

Lump Sum / (L.B.): (\$ \_\_\_\_\_)

Add Fee:  Site Insp (\$ \_\_\_\_\_) Interview (\$ \_\_\_\_\_) Tech. Insp (\$ \_\_\_\_\_) Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

① + RB. \_\_\_\_\_

Photos \_\_\_\_\_

Other \_\_\_\_\_

TOTAL \_\_\_\_\_



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG18015904/Aub3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 31-08-2018



Code : AIG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLX 1023J	Veh. Inspected	SJY 6785D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	31/08/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	30/08/2018	Inspection Date	30/08/2018
Survey held at	PEOPLE'S VEHICLE RECOVERY SERVICE BLK 3023-A, UBI ROAD 1 #01-60 SINGAPORE 408717		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

# PEOPLE'S VEHICLE RECOVERY SERVICE

BLK 3023-A UBI ROAD 1 #01-60 SINGAPORE 408717  
 Tel No. : 67433246/ 67438552 Fax No. : 67430013  
 E-Mail : peoplevehicle@gmail.com  
 Tax Reg. No. : M90001895E Buss. Reg. No. : 31800200X

**AIG ASIA PACIFIC INSURANCE PTE LTD**  
 7A SHENTON WAY #07-16  
 CHARTIS BUILDING (S) 079120

*Thin Thin*

Attention : Motor Claim Department  
 Contact : 6419 1828 Fax No. : 6415 3727

**Estimate : ES18038**

Date : 10/10/2018  
 Vehicle Num. : SJY 6785 D  
 Make/Model : TOYOTA VIOS  
 Chassis/Eng# :  
 Accident Date : 30/08/2018  
 Claim No. : TP 315-18  
 Reference : SLX 1023 J  
 Policy No. : NTUC 5097862233

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

<b>LIST ITEMS :</b>				
1.	1	DOOR PROTECTOR R/H FRT <i>cut</i>		95.00 ✓
2.	1	DOOR PROTECTOR CHROME R/H FRT <i>per</i>		28.00 ✓
3.	1	DOOR PROTECTOR R/H REAR <i>cut</i>		75.00 ✓
4.	1	DOOR PROTECTOR CHROME R/H REAR <i>per</i>		28.00 ✓
List Total S\$ :				222.00
25.00% Discount S\$ :				55.50
				<hr/>
				166.50
<b>SPECIAL NETT ITEMS :</b>				
1.	1	SPORT RIM R/H REAR <i>cut</i>	<i>380</i>	<del>480.00</del> 380 ✓
Special Nett Total S\$ :				480.00
<b>LABOUR :</b>				
COMPUTERIZED WHEEL ALIGHTMENT				80.00 ✓
SPRAY PAINTING ACCIDENT EFFECT PARTS				<del>900.00</del> 500 ✓
REMOVE & REPLACE ACCIDENT DAMAGED PARTS				
TO KNOCK REAR ARCH PANEL R/H AND BOTH DOOR R/H				<i>780</i>
Labour Total S\$ :				<hr/>
				1,530.00

SingDollars : Two Thousand One Hundred Seventy-Six & Cents Fifty Only

E. & O.E.

Total S\$ : 2,176.50

LKK Auto Consultants hence notify the Repairer of the following:  
 • In resurvey before/after spray painting  
 • Parts prices are subject to confirmation  
 • This estimate is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*total: 1326.5*  
*4/5: 1050*  
*032p*

PEOPLE'S VEHICLE RECOVERY SERVICE

Computer Generated Invoice. No Signature Required

## Asher Sng (LKKAuto)

---

**From:** Chan, Kian-Meng <Kianmeng.Chan1@aig.com>  
**Sent:** Monday, 10 June 2019 9:06 AM  
**To:** Asher Sng (LKKAuto)  
**Cc:** Admin A  
**Subject:** RE: 0668817788SG-003 // SJY6785D // DOA: 30/08/2018

**Follow Up Flag:** Follow up  
**Flag Status:** Completed

Dear Asher,

Kindly assist to reject claim as SJY6785D was the proximate cause of the accident.

Best regards,  
Chan Kian Meng  
AIG  
Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way, #08-16, Singapore 079120  
Tel +(65) 6419 1678  
[KianMeng.Chan1@aig.com](mailto:KianMeng.Chan1@aig.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** Asher Sng (LKKAuto) [mailto:AsherSng@lkkauto.com]  
**Sent:** Saturday, June 08, 2019 5:37 PM  
**To:** Chan, Kian-Meng  
**Cc:** Admin A  
**Subject:** [EXTERNAL] RE: 0668817788SG // SJY6785D // DOA: 30/08/2018

This message is from an external sender; be cautious with links and attachments.

Hi Kian Meng,

**ACCIDENT INVOLVING SLX 1023J (OI) & SJY 6785D (TP) & SLR 4696D (OTHER) ON 30/08/2018**

We refer to the above matter.

Based on the above accident scenario third party collided into insured in which insured collided into other party.

We are of the opinion that BOLA 28(g) is applied and insured shall not be liable for the accident.

In view of the above, we are intending to reject TP claim.

**For your approval/ comments/ instruction.**

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shu Pei (LKKAuto)

**Sent:** Monday, 3 June 2019 7:45 PM

**To:** Chan, Kian-Meng <[Kianmeng.Chan1@aig.com](mailto:Kianmeng.Chan1@aig.com)>

**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Asher Sng (LKKAuto) <[AsherSng@lkkauto.com](mailto:AsherSng@lkkauto.com)>

**Subject:** RE: 0668817788SG // SJY6785D // DOA: 30/08/2018

Dear Sir / Madam,

Thank you for your email.

Please note that: -

<b>LKK ref</b>	<b>Officer in charge</b>
CC6/AIG18015904/Aeb3	Asher

*To check availability of the case handler, you may contact the undersigned*

Best Regards,

Shu Pei | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: [shupe@lkkauto.com](mailto:shupe@lkkauto.com) | fax: 6741-4108

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Chan, Kian-Meng <[Kianmeng.Chan1@aig.com](mailto:Kianmeng.Chan1@aig.com)>

**Sent:** Monday, 3 June 2019 4:49 PM

**To:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** 0668817788SG // SJY6785D // DOA: 30/08/2018

Dear LKK,

Kindly advise handler.

Best regards,

Chan Kian Meng

**AIG**

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way, #08-16, Singapore 079120

Tel +(65) 6419 1678

[KianMeng.Chan1@aig.com](mailto:KianMeng.Chan1@aig.com) | [www.aig.sg](http://www.aig.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**Asher Sng (LKKAuto)**

---

**From:** Asher Sng (LKKAuto)  
**Sent:** Friday, 21 June 2019 10:32 AM  
**To:** peoplevehicle@gmail.com  
**Subject:** RE: ACCIDENT INVOLVING SJY 6785D & SLX 1023J ON 30/08/2018  
**Attachments:** OI SKETCH PLAN.pdf

Hi Sir/Mdm,

We refer to the above matter.


**ACCIDENT INVOLVING SJY 6785D (TP) & SLX 1023J (OI) & SLC 4696D (OTHER) ON 30/08/2018**

We attached here with a copy of our insured's accident statement and our insured police report for your easy reference.

Our principal has reiterated that the accident was caused due to the entire negligence of your client make a lane change to the right and collided into our insured in which collided into other party.

We are of the opinion that liability is not in your client's favor.

Under such a circumstances, we regret to inform you that we have our principal instruction to deny liability and unable to look into your client's claim.



Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [asher.sng@lkkauto.com](mailto:asher.sng@lkkauto.com) | fax: 6741-4108

8lk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Asher Sng (LKKAuto)  
**Sent:** Tuesday, 2 April 2019 4:01 PM

To: 'peoplevehicle@gmail.com' <peoplevehicle@gmail.com>  
Subject: ACCIDENT INVOLVING SJY 6785D & SLX 1023J ON 30/08/2018

**'WITHOUT PREJUDICE'**  
**SAVE AS TO COSTS**

Your Ref: SJY 6785D  
Our Ref: CC6/AIG18015904/Aeb3

Dear Sirs,

ACCIDENT INVOLVING SJY 6785D & SLX 1023J ON 30/08/2018

We refer to the above matter.

Please be informed that liability is unclear for this matter. Our insured driver reported that your client encroach into his path and collided onto the right rear portion of our insured vehicle. Enclosed herewith in this email is a copy of our insured's accident report for your perusal.

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, we would like to request a copy of video footage/witness statement/scene photos(if any) in order for us to look into the matter.

We shall revert upon hearing from you.

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Aug 2018 <a href="#">Edit Reg</a>		30 Aug 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$1,050.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,050.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>123 Leasing Pte Ltd</b> , Co. Reg. No.: -								
Main Claimant:	<b>TAN WELL ENGINEERING PTE LTD</b> , Co. Reg. No.: 199307554H								
Vehicle Reg. No.:	<b>SJY6785D</b>	Date of Loss:	30/08/2018 11:00 - :59 [95 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 06688177885G</b>	Policy/Cover Note No.:	0999994697 (Comprehensive) Coverage: 15/03/2018 - 14/03/2019						
Vehicle Reg. No. (Insured):	<b>SLX1023J</b>	Policy No. (Claimant):	5097662233						
Repairer:	<b>People's Vehicle Recovery Service (HQ)</b> Blk 3023A Ubi Rd 1, #01-60, 408717 Ubi - Tel: 67433246								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Chan, Kian-Meng</b> ] Kianmeng.Chan1@aig.com								
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ADRIAN LING</b> ] ... [Final Rpt due 11/09/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
• AIG_SG (04/09/2018): No OI GIA Report (SLX1023J VS SJY6785D)									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJY6785D (0668817788SG)  
[SLX1023J]  
TP  
TAN WELL ENGINEERING PTE LTD  
Aug 30 2018 11:00AM  
[123 Leasing Pte Ltd]  
People's Vehicle Recovery Service

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View <span style="border: 1px solid black; padding: 0 2px;">View in Browser</span> <span style="font-size: 0.8em;">v</span>
<b>Photos/Images</b>					3 per page <span style="font-size: 0.8em;">v</span> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	09/11/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>
2	09/11/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>
3	09/11/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>
4	09/11/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>
5	09/11/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>
6	09/11/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>
7	09/11/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>
8	09/11/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>
9	09/11/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>
10	09/11/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>
11	09/11/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>
12	09/11/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>
13	09/11/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>
14	09/11/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>
15	09/11/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>
16	09/11/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>
17	09/11/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>
18	09/11/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>
19	09/11/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>
20	09/11/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>
21	09/11/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>
22	09/11/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>					1 per page <span style="font-size: 0.8em;">v</span> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	31/08/18 11:52	TP GIA REPORT		Load PDF	
2	21/06/19 12:00	APPROVAL TO REJECT TP CLAIM		Load PDF	
3	21/06/19 12:00	EMAIL WSP TO REJECT TP CLAIM		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	03/09/18 13:50	SLR 4696D - GIA report		Load PDF	
2	06/09/18 15:24	OI GIA REPORT		Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199807196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18015904/AEB3Q2

Date: 01/07/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994697  
**Claimant Vehicle No :** SJY6785D **Insured Vehicle No :** SLX1023J  
 Date of Loss: 30/08/2018 Nature of Claim: TP Claim No: 0668817788SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SJY6785D**  
 Make & Model: TOYOTA VIOS, 1.5 E (A) Engine No: 1NZY106347  
 Reg. Date: 23/09/2010 (Man. Year: 2010) Chassis No: MR053HY9305169739  
 Colour: Grey Odometer: 126515 km  
 Engine Capacity: 1497 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15  
 Front Left Side: Achilles 6 mm Rear Left Side: Achilles 6 mm  
 Front Right Side: Achilles 6 mm Rear Right Side: Achilles 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	646.50	546.50	100.00	15.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,530.00	780.00	750.00	49.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,176.50</b>	<b>1,326.50</b>	<b>850.00</b>	<b>39.05</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,050.00</b>		
<b>(S\$)</b>	2,176.50	1,050.00	1,126.50	51.76
<b>+ GST 7.00/7.00% (S\$)</b>	152.36	73.50	78.86	51.76
<b>Nett Amount (S\$)</b>	<b>2,328.86</b>	<b>1,123.50</b>	<b>1,205.36</b>	<b>51.76</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

## INSPECTION

Date of Assignment: 30/08/2018  
 Date Inspected: 30/08/2018 Inspected At: People's Vehicle Recovery Service (HQ)  
 Blk 3023A Ubi Rd 1, #01-60  
 Singapore 408717  
 Estimated Period of Repair: 3.0 days

---

**Adjuster:** ADRIAN LING

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*DOOR PROTECTOR R/H FRT	Cut	95.00 FL	*95.00 FL	
2	1		*DOOR PROTECTOR CHROME R/H FRT	Necessary	26.00 FL	*26.00 FL	
3	1		*DOOR PROTECTOR R/H REAR	Cut	75.00 FL	*75.00 FL	
4	1		*DOOR PROTECTOR CHROME R/H REAR	Necessary	26.00 FL	*26.00 FL	
5	1		*SPORT RIM R/H REAR	Cut	480.00 FS	*380.00 FS	
					<b>Sub Total (S\$)</b>	<b>702.00</b>	<b>602.00</b>
					<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	<b>55.50</b>	<b>55.50</b>
					<b>Total Parts (S\$)</b>	<b>646.50</b>	<b>546.50</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	COMPUTERIZED WHEEL ALIGNMENT	New	80.00	80.00
2	SPRAY PAINTING ACCIDENT EFFECT PARTS	New	900.00	500.00
3	REMOVE & REPLACE ACCIDENT DAMAGED PARTS TO KNOCK REAR ARCH PANEL R/H AND BOTH DOOR R/H	New	550.00	200.00
			<hr/>	
			<b>Gross Labour Cost (S\$)</b>	<b>780.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >