

ISS. REC. BY: Adrian Ling

REF: CC3/ALG180159071 Ard3n2

Merimen

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. 2100 498 796

Claims No. 357989479556

Sum Insured: \_\_\_\_\_ Excess: \$800

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 160K.

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 04883 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLK7104M. Yr Regn: 2017 June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A6 c.c. 1798

Colour: Grey. A/C: Insured / Std / NI / NA

Sp. Reading: 30803 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WAUZ22493HN045101

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R17

R: 225/55R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIR) / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. \_\_\_\_\_ D.O.I. 30/08/18

Survey held at Premium.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	OD ALG.
	SLK 7104M-X
7/11/18	Confirm with Mr Bo \$5717.72, 4 Days Pd: \$5151.20, 47%.
RECEIVED 12 NOV 2018	

Date/Time, File Pass to?

☐

Preli. Report

1) typist

☒

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

200

10

210

Report Format: OD

Lump Sum / L.B.I.: (\$ 5717.72)

## Janice Lee (LKKAuto)

---

**From:** Janice Lee (LKKAuto)  
**Sent:** Wednesday, November 07, 2018 10:15 AM  
**To:** Boo seng yak; Adrian Ling (LKKAuto); SUR; Carrine Leong; jiajee.yap@premiumauto.com.sg; Chang Chee Sing  
**Subject:** RE: FINAL REVISION - SLK7104M - OD AIG - SURVEYED 30 AUG 18

Dear Mr. Boo,

Confirm \$5,717.72 @ 4 days

\*Kindly send us the DV and Invoice for our early closure

Thank you.

Best Regards,

**Jannice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Boo seng yak [mailto:boojohnny@gmail.com]  
**Sent:** Tuesday, October 16, 2018 4:13 PM  
**To:** Adrian Ling (LKKAuto) <[adrianling@lkkauto.com](mailto:adrianling@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; Carrine Leong <[carrine.leong@premiumauto.com.sg](mailto:carrine.leong@premiumauto.com.sg)>; jiajee.yap@premiumauto.com.sg; Chang Chee Sing <[claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg)>  
**Subject:** FINAL REVISION - SLK7104M - OD AIG - SURVEYED 30 AUG 18

Hi Adrian and all,

Revised estimate and photographs attached.

Please confirm repair cost of \$5717.52 @ 4 days of repairs due to parts ordering of cancelled items by surveyor.

Your early closure is well appreciated.

Best regards - jb

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	23/08/2018 10:56
Date Of Accident	21/08/2018 08:10
Exact Location Of Accident	MOUNTBATTEN ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK7104M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN LI XIN MICHELLE
NRIC No	S8537030H
Email Address	MEECHELLETAN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97383959
Alternative Phone No	OTHERS-97383959

### Vehicle Particulars

Manufacturer	AUDI
Model	A6 1.8 TFSI S-TRONIC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100498796-01
Cover Note Number	

### Driver

Name of Driver	TAN LI XIN MICHELLE
NRIC No	S8537030H
Date Of Birth	19/11/1985
Occupation	INDOOR
Date Of Driving Pass	13/08/2009
Driving Experience	9 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97383959
Fax Number	
Contact Number	OTHERS-97383959
Email Address	MEECHELLETAN@GMAIL.COM

Address	35 AMBER ROAD
	#03-15
Postcode	439945
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

WAS AT A TRAFFIC JUNCTION WHEN OUR CARS WERE STATIONARY. VEHICLE SLB1981J, HAD MOVED SLOWLY AND I HAD FOLLOWED. HOWEVER, SLB1981J HAD SUDDEN BRAKED AND I HAD BRAKED TOO. UNFORTUNATELY AS I COULD NOT STOP IN TIME HENCE, I HAD ACCIDENTALLY KNOCKED INTO SLB1981J BACK. THE DRIVER, KENNETH THONG, S7426840D, CAME DOWN TO ACCESS THE SITUATION AND WE HAD EXCHANGED CONTACT DETAILS. HOWEVER, THE PASSENGER OF SLB1981J, KENNETH THONGS'S WIFE HAD CAME OUT OF THE CAR AND YELLED AT ME DEMANDING I SHOULD HAVE STOPPED IN TIME AND QUESTIONED MY DRIVING SKILLS.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLB1981J
Vehicle Make/Model/Colour	VOLKSWAGEN GOLF 230TSI
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KENNETH THONG
NRIC/Passport Number	S7426840D
Contact Number	90279878
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLB1981J

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

23/8/18

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


23/8/18



Reporting Centre Personnel's Signature  
Name: Tony Hoong  
NRIC/FIN No.: G204707K

## Sketch Plan #2

### SKETCH PLAN




### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Was at a traffic junction when our cars were stationary. Vehicle SLB 1981J had moved slowly and I had followed. However, SLB 1981J had suddenly ~~jumped~~ <sup>braked</sup> and I had braked too. Unfortunately, as I could not stop in time, hence I had accidentally knocked into SLB 1981J back.


The driver, Kenneth Thong S74268400, came down to assess the situation and we had exchanged contact details. However, ~~there~~ the passenger of SLB 1981J, Kenneth Thong's wife, had come out of the car and yelled at me, demanding that I should have stopped in time and questioned my driving skills.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature

Date & Time:  
23/8/18

  
Driver's Signature  
(If driver is not the policyholder)

Date & Time:  
23/8/18



Reporting Centre Personnel's Signature  
Name: Tom Foong  
NRIC/FIN No.: 62040 Rxx

Accident Photo



**REPUBLIC OF SINGAPORE DRIVING LICENCE**

Licence Number **S8537030H**

Name  
**TAN LI XIN, MICHELLE  
(CHEN LIXIN)**

Birth Date **19 Nov 1985**  
Issue Date **13 Aug 2006**

001773803C




**REPUBLIC OF SINGAPORE**  
**IDENTITY CARD NO. S8537030H**



Name  
**TAN LI XIN MICHELLE  
(CHEN LIXIN)**  
**陳俐心**

Race  
**CHINESE**

Date of birth  
**19-11-1985**

Country/Place of birth  
**SINGAPORE**

Sex  
**F**

S8537030H





**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)**

Class 3 Motor Cars=< 3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg

PASS DATE **13 Aug 2009**

Licence No: S8537030H

NP 428A



5612180



NRIC No: S8537030H



Date of issue  
**14-06-2016**

Address  
**35 AMBER ROAD  
#03-15  
SINGAPORE 439945**



# CERTIFICATE OF INSURANCE

## AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : TAN LI XIN MICHELLE (CHEN LIXIN)  
Period of Insurance : 24 Jan 2018 To 23 Jan 2019  
Engine No. : CYG016797  
Chassis No. : WAUZZZ4G3HN045101

Vehicle No. : SLK7104M  
Policy No. : 2100498796-01  
Endorsement No. :  
Issued Date : 15 Dec 2017

### ABOUT THE COVER

Make/Model : AUDI A6 1.8 TFSI ULTRA  
Engine Capacity/Tonnage : 1,798.00 CC  
Driver Restriction : NA  
Sum Insured : Market Value  
Off Peak Car : No  
First Year of Registration : 2017  
Insuring with COE/PARF : Yes

#### Person or Classes of Persons Entitled to Drive\* :

a) The Policyholder  
b) Any other person who is driving on the Policyholder's order or with his/her permission  
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.  
You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

#### Limitation as to use\* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

### EXCESS

#### Section 1

Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

#### Section 2

Property Damage - \$0

Windscreen : \$100

#### Named Driver and Excess (where applicable)

TAN LI XIN MICHELLE (CHEN LIXIN) - \$800 (Own Damage)

### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.com.sg](http://www.aig.com.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HONG LEONG FINANCE LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125216

PREMIUM LEASING - CW  
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE  
SINGAPORE 159938  
Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.  
AUTHORISED REPRESENTATIVE

SSPOCC

**IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.****What can the 24-hour AIG Auto Emergency Hotline provide for you?**

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

**What should I do in the event of an accident?**

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party(ies) to AIG immediately.

**If no one is injured in the accident:**

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

**If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:**

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

**LOSS OF USE CAR REPLACEMENT BENEFIT**

**Applicable only if this benefit is included in your motor insurance.** Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

**Steps to activate Loss of Use Car Replacement Benefit and Important Information**

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **5** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

**Rental Car Company: Popular Rent A Car Pte. Ltd.**

**Activation Hotline: 67428888**

**501 Guillemard Road Singapore 399840**

**Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm**

\*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

**IMPORTANT NOTICE**

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/OD/0961/2018/NK  
Date : 23-Aug-18

Vehicle NOT IN workshop. Kindly arrange for survey.

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Tan Li Xin Michelle  
Address : 35 Amber Road  
#03-15  
Singapore 439945  
Telephone : HP +65 97383959  
Type of Claim : Own Damage Claims  
Policy No. : 2100498796-01  
Vehicle No : **SLK 7104 M**  
Model Code : AUDI A6 1.8 TFSI S TRONIC  
Model / Year : Jan-17  
Engine No : CYG016797  
Chassis No : WAUXXX4G3HN045101  
Mileage :  
Date In :  
Liability : -  
Excess Cost : -  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 21-Aug-18  
Place of Accident : Mountbatten Road

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLK 7104 M

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	✓ /
2	To dismantle and renew front bumper. Reorganise front crash managements components. Reinstall all parts removed.	\$ <del>1,050.00</del>	500 /
3	To respray front bumper.	\$ <del>900.00</del>	550 /
4	To carry out diagnostic checks.	S/N \$ 192.00	✓ /
TOTAL LABOUR CHARGES		: \$ <u>2,622.00</u>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLK 7104 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>replaced</i>	\$ 2,650.00 ✓	2120
2	FRONT BUMPER FIXING PARTS	\$ 507.00 x	} x
3	FRONT BUMPER SECURING STRIP	2 \$ 12.00 x	
4	FRONT BUMPER GRILLE LOWER CENTRE <i>cracked</i>	\$ 112.00 ✓	89.20
5	LOCKING CLIPS <i>New</i>	14 \$ 48.00 ✓	38.68
6	FRONT BUMPER BRACKETS LH / RH	2 \$ 64.00 +	} x
7	CLOSING ELEMENT	\$ 188.00 x	
8	FRONT BUMPER CENTRE PC	\$ 216.00 +	
9	FRONT BUMPER SPOILER <i>New</i>	\$ 817.00 x	
10	RADIATOR GRILLE <i>cracked</i>	\$ 1,697.00 ✓	1357.60
11	RADIATOR GRILLE COVER <i>New</i>	\$ 32.00 ?	X
12	AIR GUIDE GRILLE <i>cracked</i>	\$ 434.00 x	347.20
13	FRONT BUMPER COVER LH <i>New</i>	\$ 44.00 x	} x
14	FRONT BUMPER FOAM	\$ 203.00 +	
15	REINFORCEMENT BEAM	\$ 702.00 x	
16	FRONT BUMPER SENSOR	\$ 196.00 x	
17	FRONT NO PLATE <i>Bent</i>	S/N \$ 25.00 ✓	25.06
18	SUNDRIES <i>New</i>	\$ 300.00 ?	18.64
TOTAL SPARE PARTS CHARGES		: \$ 8,247.00	
TOTAL LABOUR CHARGES		: \$ 2,622.00	
GRAND TOTAL		: \$ 10,869.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : *Adrian King*  
Surveyed Date : *30/08/18*  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : *Authorised Repairs, 03 Days*

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant

**Janice Lee (LKKAUTO)**

---

**From:** Boo seng yak <boojohnny@gmail.com>  
**Sent:** Tuesday, October 16, 2018 4:13 PM  
**To:** Adrian Ling (LKKAUTO); SUR; Carrine Leong; jiajee.yap@premiumauto.com.sg; Chang Chee Sing  
**Subject:** FINAL REVISION - SLK7104M - OD AIG - SURVEYED 30 AUG 18  
**Attachments:** PA09612018 - SLK 7104 M - Audi A6 1.8 TFSI S FRONT OD (AIG).xls; WhatsApp Image 2018-09-18 at 3.14.03 PM (1).jpeg; WhatsApp Image 2018-09-18 at 3.14.03 PM.jpeg

Hi Adrian and all,

Revised estimate and photographs attached.

Please confirm repair cost of \$5717.52 @ 4 days of repairs due to parts ordering of cancelled items by surveyor.

Your early closure is well appreciated.

Best regards - jb

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/OD/0961/2018/NK  
Date : 23-Aug-18

Vehicle NOT IN workshop. Kindly arrange for survey.

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

You recommend 3 days

We took 4 days with parts order

jb - 16 Oct 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Tan Li Xin Michelle  
Address : 35 Amber Road  
#03-15  
Singapore 439945  
Telephone : HP +65 97383959  
Type of Claim : Own Damage Claims  
Policy No. : 2100498796-01  
Vehicle No : **SLK 7104 M**  
Model Code : AUDI A6 1.8 TFSI S TRONIC  
Model / Year : Jan-17  
Engine No : CYG016797  
Chassis No : WAUXXX4G3HN045101  
Mileage :  
Date In :  
Liability : -  
Excess Cost : -  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 21-Aug-18  
Place of Accident : Mountbatten Road

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLK 7104 M

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00	\$ 480.00
2	To dismantle and renew front bumper. Reorganise front crash managements components. Reinstall all parts removed.	\$	1,050.00	\$ 500.00
3	To respray front bumper.	\$	900.00	\$ 550.00
4	To carry out diagnostic checks.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 2,622.00</u>	<u>\$ 1,722.00</u>

# Premium Automobiles

55-Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLK 7104 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 2,650.00	\$ 2,120.00
2	FRONT BUMPER FIXING PARTS	\$ 507.00	
3	FRONT BUMPER SECURING STRIP	2 \$ 12.00	
4	FRONT BUMPER GRILLE LOWER CENTRE (Nec)	\$ 112.00	\$ 89.20
5	LOCKING CLIPS (Nec)	14 \$ 48.00	\$ 38.08
6	FRONT BUMPER BRACKETS LH / RH	2 \$ 64.00	
7	CLSOING ELEMENT	\$ 188.00	
8	FRONT BUMPER CENTRE PC	\$ 216.00	
9	FRONT BUMPER SPOILER	\$ 817.00	
10	RADIATOR GRILLE	\$ 1,697.00	\$ 1,357.60
11	RADIATOR GRILLE COVER	\$ 32.00	
12	AIR GUIDE GRILLE (LHS lower grille - see Photo)	\$ 434.00	\$ 347.20
13	FRONT BUMPER COVER LH	\$ 44.00	
14	FRONT BUMPER FOAM	\$ 203.00	
15	REINFORCEMENT BEAM	\$ 702.00	
16	FRONT BUMPER SENSOR	\$ 196.00	
17	FRONT NO PLATE	S/N \$ 25.00	\$ 25.00
18	SUNDRIES	\$ 300.00	\$ 18.64
	TOTAL SPARE PARTS CHARGES	: \$ 8,247.00	\$ 3,995.72
	TOTAL LABOUR CHARGES	: \$ 2,622.00	\$ 1,722.00
	GRAND TOTAL	: \$ 10,869.00	\$ 5,717.72

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

## Telefax

to **AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
Motor Claims Dept  
**Your Ref: SLK7104M**

Norah Khai  
6768 9828  
6841 1183

Body Repair

PA/OD/0961/2018/TF  
20 Sept 2018

from  
Telephone +65-  
Telefax +65-  
Mobile +65-  
Our department  
Your Claim Ref  
Our Ref  
Date

total pages


### RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

**Make & Model** : Audi A6 1.8 TFSI S tronic  
**Vehicle Chassis No.** : WAUZZZ4G3HN045101  
**Vehicle Regn No.** : **SLK7104M**  
**Vehicle Mileage** : 31994KM  
**Vehicle Owner** : Ms. Tan Li Xin Michelle  
**Certificate No** : 1800016196 *wrong*  
**Policy Excess** : S\$856.00(inclusive of 7% GST)  
**Accident Date** : 21 August 2018  
**Place** : MOUNTBATTEN ROAD  
**Repair Cost** : \$ 5,261.96  
**WIP No.** : 22093  
**Repairer's Name** : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd  
Showroom  
9 Leng Kee Road  
Singapore 159090  
Telephone (65) 6566 1111  
Telefax (65) 6471 3733

Service & Parts Centres  
55 Ubi Road 1  
Singapore 408699  
Telephone (65) 6366 2323  
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

**Owner / Insured Signature** :   
**Time** : 10.30pm  
**Date** : 21/9/18

# Premium Automobiles

**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
**Attn: Motor Claims Dept**  
**Yr Ref: SLK 7104 M**

Norah Khai  
6768 9911  
6841 1183  
Nora.khai@premiumauto.com.sg  
Body & Paint Dept  
PA/OD/0961/2018/MAS

10 Nov 2018

from  
Telephone +65-  
Telefax +65-  
EMail  
Our department  
Our Ref  
Your Ref  
Date

Dear Sir,

**RE: INSURANCE CLAIM FOR SLK 7104 M, Audi A6 1.8 TFSIS-Tro**

With reference to the above-mentioned vehicle, no **SLK 7104 M**, claimant,  
**Ms. Tan Li Xin Michelle**, please find the related document per attached.

1. A copy of the Original invoice no. 85013115 – S\$5,261.96
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai  
Claims Dept

Encls

AIG – SLK 7104 M

total pages

Premium Automobiles Pte Ltd  
Showroom  
9 Leng Kee Road  
Singapore 159090  
Telephone (65) 6566 1111  
Telefax (65) 6471 3733

Service & Parts Centres  
55 Ubi Rd 1  
Singapore 408699  
Telephone (65) 6336 2323  
Telefax (65) 684 11183

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Aug 2018		31 Aug 2018 12:30 <a href="#">Edit Adj Rpt</a>	<b>S\$5,717.72</b> <a href="#">Edit Estimates</a>	<b>S\$5,717.72</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	TAN LI XIN MICHELLE, ID: S8537030H, Tel: +6597383959, Email: MEECHELLETAN@GMAIL.COM								
Vehicle Reg. No.:	SLK7104M	Date of Loss:	21/08/2018 08:00 - :59 [18 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 3579894795SG	Policy/Cover Note No.:	2100498796 (Comprehensive)						
		Excess:	S\$800.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mohd Zawaye, Norsazani] Norsazani.Zawaye@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 11/09/2018]								
Driver/Custodian:	TAN LI XIN MICHELLE (32 / Female), NRIC: S8537030H, Tel: +6597383959								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (03/09/2018): SLK7104M / OD / 21/08/2018 / Coverage &amp; Excess update</li> </ul>									
<input type="checkbox"/> <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLK7104M (3579894795SG)  
 OD  
 Aug 21 2018 8:00AM  
 [TAN LI XIN MICHELLE]  
 Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		Use Viewer	
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	03/09/18 09:03	General View														Load JPG	<input checked="" type="checkbox"/>	
2	03/09/18 09:03	General View														Load JPG	<input checked="" type="checkbox"/>	
3	03/09/18 09:03	General View														Load JPG	<input checked="" type="checkbox"/>	
4	03/09/18 09:03	General View														Load JPG	<input checked="" type="checkbox"/>	
5	03/09/18 09:03	General View														Load JPG	<input checked="" type="checkbox"/>	
6	03/09/18 09:03	General View														Load JPG	<input checked="" type="checkbox"/>	
7	03/09/18 09:03	General View														Load JPG	<input checked="" type="checkbox"/>	
8	03/09/18 09:03	General View														Load JPG	<input checked="" type="checkbox"/>	
9	03/09/18 09:03	General View														Load JPG	<input checked="" type="checkbox"/>	
10	03/09/18 09:03	General View														Load JPG	<input checked="" type="checkbox"/>	
11	03/09/18 09:03	General View														Load JPG	<input checked="" type="checkbox"/>	
12	03/09/18 09:03	General View														Load JPG	<input checked="" type="checkbox"/>	
13	03/09/18 09:03	General View														Load JPG	<input checked="" type="checkbox"/>	
14	03/09/18 09:03	General View														Load JPG	<input checked="" type="checkbox"/>	
15	03/09/18 09:03	General View														Load JPG	<input checked="" type="checkbox"/>	
16	03/09/18 09:03	General View														Load JPG	<input checked="" type="checkbox"/>	
17	03/09/18 09:03	General View														Load JPG	<input checked="" type="checkbox"/>	
18	03/09/18 09:03	General View														Load JPG	<input checked="" type="checkbox"/>	
19	03/09/18 09:03	General View														Load JPG	<input checked="" type="checkbox"/>	
20	03/09/18 09:03	General View														Load JPG	<input checked="" type="checkbox"/>	
21	03/09/18 09:03	General View														Load JPG	<input checked="" type="checkbox"/>	
22	03/09/18 09:03	General View														Load JPG	<input checked="" type="checkbox"/>	
23	03/09/18 09:03	General View														Load JPG	<input checked="" type="checkbox"/>	
24	03/09/18 09:03	General View														Load JPG	<input checked="" type="checkbox"/>	
25	03/09/18 09:03	General View														Load JPG	<input checked="" type="checkbox"/>	
26	05/11/18 13:01	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>	
27	05/11/18 13:01	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>	
Documentation															1 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	03/09/18 09:02	SLK 7104M EST														Load PDF		
2	03/09/18 09:02	Certificate of Insurance														Load PDF		
3	03/09/18 09:02	SLK 7104M NRIC & DL														Load PDF		
4	03/09/18 09:02	Singapore Accident Statement														Load PDF		
5	15/11/18 09:43	WORKSHOP INVOICE														Load PDF		
6	15/11/18 09:43	DISCHARGE VOUCHER														Load PDF		

## Linked Accident Report Documents

			View	Use Viewer
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	23/08/18 11:44	Accident Statement	Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print

1	23/08/18 11:37	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
2	23/08/18 11:37	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
3	23/08/18 11:37	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
4	23/08/18 11:37	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
5	23/08/18 11:37	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
6	23/08/18 11:37	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
7	23/08/18 11:37	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
8	23/08/18 11:37	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
			1 per page		<input checked="" type="checkbox"/>
<b>Documentation</b>					
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	23/08/18 11:25	Sketch Plan	1	Load JPG	<input checked="" type="checkbox"/>
2	23/08/18 11:25	Sketch Plan #2	1	Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

## LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120

Our File No: CC3/AIG18015907/ARD3N2

Date: 15/11/2018

## REFERENCE

Insured/Claimant: TAN LI XIN MICHELLE Policy No: 2100498796  
Date of Loss: 21/08/2018 Nature of Claim: OD Claim No: 3579894795SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLK7104M Engine No: CYG016797  
Make & Model: AUDI A3, 1.8 TFSI (A) Chassis No: WAUZZZ4G3HN045101  
Reg. Date: 24/01/2017 (Man. Year: 2016) Odometer: 30803 km  
Colour: Grey  
Engine Capacity: 1798 cc  
Market Value/New Car Price: S\$160,000.00  
Price:  
Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/55R17 Rear Tyre Size: 225/55R17  
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,247.00	3,995.72	4,251.28	51.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,622.00	1,722.00	900.00	34.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,869.00	5,717.72	5,151.28	47.39
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	10,069.00	4,917.72	5,151.28	51.16
+ GST 7.00/7.00% (S\$)	704.83	344.24	360.59	51.16
Nett Amount (S\$)	10,773.83	5,261.96	5,511.87	51.16

## INSPECTION

Date of Assignment: 31/08/2018

Date Inspected: 30/08/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,650.00 FS	*2,120.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	507.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	12.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE LOWER CENTRE	Cracked	112.00 FS	*89.20 FS
5	14		*LOCKING CLIPS	Necessary	48.00 FS	*38.08 FS
6	2		*FRONT BUMPER BRACKETS LH/RH	Not Necessary	64.00 FS	*- FS
7	1		*CLOSING ELEMENT	Not Necessary	188.00 FS	*- FS
8	1		*FRONT BUMPER CENTRE PC	Not Necessary	216.00 FS	*- FS
9	1		*FRONT BUMPER SPOILER	Not Necessary	817.00 FS	*- FS
10	1		*RADIATOR GRILLE	Cracked	1,697.00 FS	*1,357.60 FS
11	1		*RADIATOR GRILLE COVER	Not Necessary	32.00 FS	*- FS
12	1		*AIR GUIDE GRILLE	Cracked	434.00 FS	*347.20 FS
13	1		*FRONT BUMPER COVER LH	Not Necessary	44.00 FS	*- FS
14	1		*FRONT BUMPER FOAM	Not Necessary	203.00 FS	*- FS
15	1		*REINFORCEMENT BEAM	Not Necessary	702.00 FS	*- FS
16	1		*FRONT BUMPER SENSOR	Not Necessary	196.00 FS	*- FS
17	1		*FRONT NO PLATE	Bent	25.00 FS	*25.00 FS
18	1		*SUNDRIES	Necessary	300.00 FS	*18.64 FS
Total Parts (S\$)					8,247.00	3,995.72

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER.REORGANISE FRONT CRASH MANAGERMENTS COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY FRONT BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (S\$)			2,622.00	1,722.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >