

ASS. REC. BY:

REF:

CS3/MSG18015952/G24d32²

Instruction:

Surveyor:

menmen

From (Person):

Elaine Ngu

of

MSG

Date/Time:

30/8/18 @ 3:08pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SLN3614T

Insured:

SLL9570G

at Workshop m/s:

Zolcar Auto

Tel:

91461186

of

8 keiki Bkt Ave 4 # 06-21

Policy No.:

71600806QMY

Claim No.:

568621

Sum Insured:

Excess:

Make of Veh.:

D.O.A

24/8/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

5:02pm @ 31/8/18

Person Contacted:

Marc

Vehicle:

IN OUT

Date/Time

Action/Instruction (X) Estimate

SLN3614T-X

SLL9570G-X

3/9/18

Dismanjled.

Surveys

PRS.
Xal.

REF:

M&G

C3055R /

ASSIGNMENT

From: Date:

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 8LN 3614T
at Workshop m/s Zolar Auto
of No. 8 Kaki Bukit Ave 4 #06-21.

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

31/8/2018

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: 8LN36147 Yr Regn: 28 Apr 2017

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Merce E220D cc 1950

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 97839 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD 2130042A 2222 06

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55 R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 31-08-18

Survey held at W/S 3:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The ☒ J/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PRS. \$3000 - \$4000

4/9/18 Submit PRS Report

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG18015952/Gz4d3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 31-08-2018



Code : MSG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLL 9570G	Veh. Inspected	SLN 3614T
Policy No.	71600806QMY	Coverage (\$)	0.00
Claim No.	568621	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	31/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	24/08/2018	Inspection Date	31/08/2018
Survey held at	ZOLAR AUTO SERVICES NO.8 KAKI BUKIT AVENUE 4 PREMIER (GATE 2) #06-21 SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Aug 2018		30 Aug 2018 15:08 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	Chua Kian Tiong, ID: S1314023E		
Main Claimant:	TITANIUM LIMOUSINES PTE. LTD., Co. Reg. No.: 201213055R		
Vehicle Reg. No.:	SLN3614T	Date of Loss:	24/08/2018 15:00 - :59 [15 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 568621	Policy/Cover Note No.:	71600806QMY (Comprehensive) Coverage: 15/03/2018 - 14/03/2019
Vehicle Reg. No. (Insured):	SLL9570G	Policy No. (Claimant):	
		Excess:	
Repairer:	Zolar Auto Services (kaki Bukit#06-21) (HQ) No. 8 KakiBukit Avenue 4,, Premier (Gate 2) #06-21, 415875 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 31/08/2018]		
Adj Asg. Remarks:	SJE DISAGREE APPOINT LKK AND CONTACT MARC @9146 1186 Liability (Non-reporting)		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/08/2018 14:55
Date Of Accident	24/08/2018 15:10
Exact Location Of Accident	FAR EAST PLAZA SERVICE ROAD EXIT TO SCOTTS ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN3614T
Insured/Policyholder	
Name Of Registered Owner	TITANIUM LIMOUSINES PTE. LTD.
Co Reg No	201213055R
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96884514
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	E220D
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5089460350-01
Cover Note Number	
Driver	
Name of Driver	MOHAMED SUFFIAN BIN KASSANI
NRIC No	S7001744Z
Date Of Birth	19/01/1970
Occupation	OUTDOOR
Date Of Driving Pass	02/01/1998
Driving Experience	20 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96884514
Fax Number	
Contact Number	
Email Address	NOEMAIL

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Titanium
LIMOUSINES PTE LTD
CO. REG. NO. 201210001N

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3055R
Vehicle Details	
Vehicle No.:	SLN3614T
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Sep 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E220D AUTO
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	65492080098193
Chassis No.:	WDD2130042A222206
Maximum Power Output:	143.0 kW (191 bhp)
Open Market Value:	\$53,741.00
Original Registration Date:	28 Apr 2017
First Registration Date:	28 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$53,734.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Apr 2027
PARF Rebate Amount:	\$40,300.00
Intended COE Rebate Details	
COE Expiry Date:	27 Apr 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,621.00
COE Rebate Amount:	\$43,787.00
Total Rebate Amount:	\$84,087.00

The information contained herein is correct as at 03 Sep 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Aug 2018		30 Aug 2018 15:08 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	Chua Kian Tiong, ID: S1314023E		
Main Claimant:	TITANIUM LIMOUSINES PTE. LTD., Co. Reg. No.: 201213055R		
Vehicle Reg. No.:	SLN3614T	Date of Loss:	24/08/2018 15:00 - :59 [15 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 568621	Policy/Cover Note No.:	71600806QMY (Comprehensive) Coverage: 15/03/2018 - 14/03/2019
Vehicle Reg. No. (Insured):	SLL9570G	Policy No. (Claimant):	
		Excess:	
Repairer:	Zolar Auto Services (kaki Bukit#06-21) (HQ) No. 8 KakiBukit Avenue 4,, Premier (Gate 2) #06-21, 415875 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 31/08/2018]		
Adj Asg. Remarks:	SJE DISAGREE APPOINT LKK AND CONTACT MARC @9146 1186 Liability (Non-reporting)		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLN3614T (568621)**
[SLL9570G]
TP
TITANIUM LIMOUSINES PTE. LTD.
Aug 24 2018 3:00PM
[Chua Kian Tiong]
Zolar Auto Services (kaki Bukit#06-21)

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

Letters/Correspondences

1 per page ☒

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	30/08/18 11:01	Non Reporting Letter to OI	Load HTM	

Photos/Images

3 per page ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/09/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
2	04/09/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
3	04/09/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
4	04/09/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
5	04/09/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
6	04/09/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
7	04/09/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
8	04/09/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
9	04/09/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
10	04/09/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
11	04/09/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
12	04/09/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
13	04/09/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
14	04/09/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
15	04/09/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
16	04/09/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
17	04/09/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
18	04/09/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
19	04/09/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
20	04/09/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
21	04/09/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
22	04/09/18 10:33	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
23	04/09/18 10:33	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
24	04/09/18 10:33	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
25	04/09/18 10:33	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
26	04/09/18 10:33	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
27	04/09/18 10:33	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
28	04/09/18 10:33	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
29	04/09/18 10:33	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
30	04/09/18 10:33	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
31	04/09/18 10:33	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
32	04/09/18 10:33	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page ▾	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
33	04/09/18 10:33	Dismantled Parts	Load JPG	
34	04/09/18 10:33	Dismantled Parts	Load JPG	
Documentation			1 per page ▾	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	30/08/18 11:10	SJE DISAGREE LKK	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18015952/GZ4D3S2
Date: 05/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 71600806QMY
Claimant Vehicle No : SLN3614T **Insured Vehicle No :** SLL9570G
Date of Loss: 24/08/2018 **Nature of Claim:** TP **Claim No:** 568621

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN3614T**
 Make & Model: MERCEDES-BENZ E220, 2.0 (A) Engine No: 65492080098193
 Reg. Date: 28/04/2017 (Man. Year: 2017) Chassis No: WDD2130042A222206
 Colour: Black Odometer: 97839 km
 Engine Capacity: 1950 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55R17 Rear Tyre Size: 225/55R17
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 30/08/2018
 Date Inspected: 31/08/2018 Inspected At: Zolar Auto Services (kaki Bukit#06-21) (HQ)
 No. 8 KakiBukit Avenue 4., Premier (Gate 2) #06-21
 Singapore 415875
 Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG**Manager:** Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

REPAIR DETAILS

Reference	
Part Source:	MRM-SG Version: 1.0 (Last Synchronised: 05 Sep 2018)
Parts:	143 MERCEDES-BENZ E220 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN3614T)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >