

ASS. REC. BY:

REF:

CS/ICS18015462/Plgdbz

Special Instruction:

Surveyor

Rasul

ASSIGNMENT (Office)

From (Person)

Merimen

Janice Goh

of

ICS

Date/Time

29/8/18 @ 3:25pm

Estimated Cost:

Bill to:

OD/TP WS/TP RES/OD RES/EVA/INV/MY/CS

To Inspect Vehicle No.

FY 28762

Insured:

SLH 62817

at Workshop m/s

HKL Lim Teem

Tel:

9242 3895

of

B11C1008, Bkt merah lene 3 #01-24

Policy No:

Claim No:

DMPC 1800341H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/08/2018

CA / REV / REP. / REV 24 HRS

lup

31/8/18 @ 3:30pm - 6pm

H.O.D. Endorsement:

Date/Time:

29/8/18 @ 3:31pm

Person Contacted:

Keong

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	FY 28762 - NBA/MSG18015701/Y DOA: 24/8/18
	SLH 62817 - NBA/MSG18015701/Y DOA: 24/8/18
03/9/18 @ 5:14pm	revised to Janice Goh via Merimen.
05/10/18 @ 2:20pm	confirmed with Keong is \$800 by email. (led \$1357, 63%)

08/11/83 wof
ASS. REC. BY: *Penn*

REF: ICS

8435F

COE Regn: 2019/mar

ASSIGNMENT

From: Date: 31/08/18

Estimated Cost:

OP ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FY 2876Z

at Workshop m/s HKL Lim Team

of BIK 1008, Blet meruh tone 3 # 01-24

Insured:

Policy No.

Claims No.

Sum Insured: - Excess:

(Client's Record)

3:30pm - 6pm

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 1400

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS *up*

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: FY 2876Z Yr Regn: 2004 / mar

Type: M.Car ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: YAMAHA 4BR 125 c.c. 125

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 47466 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: LB8PCJLB240220128

Gen. Cond: Good ☒ Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 275-18

R: 90/90-18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or MAXXIS

Front

Rear

R/Bal. 3 mm R/Bal. 3 mm

L/Bal. mm L/Bal. mm

D.O.A. 24/08/18 D.O.I. 30/08/18

Survey held at HKL

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 09 OCT 2018

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 4

Resurvey No. of Trip:

Survey Fee:

250

1) 09/10 *up*

☐ : Final Report

Date/Time, File Return to?

Transportation:

2)

S + RS, SI

Photos

Others

10

Report Format : 7P

Lump Sum / I.B.A. (\$) - 800

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

TOTAL

260

Catherine Chong (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Wednesday, 29 August, 2018 3:22 PM
To: hklлимteam@gmail.com; assignments
Cc: ECICS Claims
Subject: FW: FY2876Z / SKH6281T on 24/08/2018 Arrange Surveyor
Attachments: FY2876Z 9.jpg; FY2876Z 3.jpg; FY2876Z 4.jpg; FY2876Z 1.jpg; FY2876Z 2.jpg; FY2876Z 5.jpg; FY2876Z 6.jpg; FY2876Z 7.jpg; FY2876Z 8.jpg

Without Prejudice

Hi James

Thank you for your email.
We will arrange LKK for the PRS

Aside to LKK

Please assist to arrange TP PRS.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: HKL Lim Team Motorsport [mailto:hklлимteam@gmail.com]
Sent: Wednesday, 29 August, 2018 12:42 PM
To: ECICS Claims
Subject: FY2876Z / SKH6281T on 24/08/2018 Arrange Surveyor

Hi to whom it may concern,


Do arrange surveyor for this case, and let me know the officer in charge for this.

--
Thank You.

Best Regards


James Lim (Keong)

Tel: +65 9242 3895



BLK 1008 #01-24 Bukit Merah Lane 3, Singapore 159722

Tel: +65 6275-6656, 6275-6566 Fax: 6272-9291



This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Shiau Chan (LKKAUTO)

From: HKL Lim Team Motorsport <hkllimteam@gmail.com>
Sent: Friday, 5 October 2018 2:20 PM
To: Shiau Chan (LKKAUTO)
Subject: Re: VEHICLE FY 2876Z (DOA: 24/08/2018)

Agree

On Fri, Oct 5, 2018 at 2:05 PM Shiau Chan (LKKAUTO) <siewsc@lkkauto.com> wrote:

Dear Keong,

As spoken with you.

Based on our surveyor's estimate marking, the estimate repair cost at Lump Sum \$800.00.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

--

Thank You.

Best Regards

James Lim (Keong)

Tel: +65 9242 3895

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 03 Sep 2018

Preliminary Advice

Insured Vehicle No	: SKH6281T	Accident Date	: 24/08/2018
TP Vehicle No	: FY2876Z	Assignment Date	: 31/08/2018
Make	: YAMAHA YBR125	Est. Duration of Repair	: 4
Date of Inspection	: 31/08/2018		
Inspection At	: HKL LIM TEAM MOTORSPORT		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s & rear portion & o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,157.00
Revised Amount	:S\$	997.80
Check Items (Estimated)	:S\$	72.00
Total	:S\$	1,069.80

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8435F
Vehicle Details	
Vehicle No.:	FY2876Z
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Sep 2018
Vehicle Make:	YAMAHA
Vehicle Model:	YBR125
Primary Colour:	Black
Manufacturing Year:	2004
Engine No.:	JYM154FMI04400118
Chassis No.:	LBPPCJLB240220128
Maximum Power Output:	-
Open Market Value:	\$1,296.00
Original Registration Date:	10 Aug 2004
First Registration Date:	10 Aug 2004
Transfer Count:	6
Actual ARF Paid:	\$195.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2019
COE Category:	D - Motorcycle
COE Period(Years):	5
PQP Paid:	\$1,237.00
COE Rebate Amount:	\$142.00
Total Rebate Amount:	\$142.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 03 Sep 2018

OK

1400
142
1258

> [Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details

Vehicle No. :	FY2876Z
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	YAMAHA
Vehicle Model :	YBR125
Chassis No. :	LBPPCJLB240220128
Propellant :	Petrol
Engine No. :	JYM154FMI04400118
Engine Capacity :	124 cc
Maximum Power Output :	-
Maximum Laden Weight :	-
Unladen Weight :	106 kg
Year Of Manufacture :	2004
Original Registration Date :	10 Aug 2004
Lifespan Expiry Date :	-
COE Category :	D - Motorcycle
PQP Paid :	\$1,237.00
COE Expiry Date :	31 Mar 2019
Road Tax Expiry Date :	09 Feb 2019
Inspection Due Date :	09 Feb 2019
Intended Transfer Date :	28 Aug 2018
CO2 Emission :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use [Enquire Road Tax Payable](#) for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

[OK](#)

[Print](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/08/2018 18:02
Date Of Accident	24/08/2018 14:10
Exact Location Of Accident	ALONG DEPOT ROAD TOWARDS TELOK BLANGAH ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FY2876Z
Insured/Policyholder	
Name Of Registered Owner	THENESH S/O MANIAM
NRIC No	S9648435F
Email Address	DANGERBOI21@GMAIL.COM
Mobile Phone No	(LOCAL) +65-83895317
Alternative Phone No	OTHERS-83895317

Vehicle Particulars

Manufacturer	YAMAHA
Model	YBR125-124CC (M)
Exact Purpose for which vehicle was being used at time of accident	GOING BACK HOME
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	MSD/VMT/18-380867-CA
Cover Note Number	

Driver

Name of Driver	THENESH S/O MANIAM
NRIC No	S9648435F
Date Of Birth	17/12/1996
Occupation	OUTDOOR
Date Of Driving Pass	18/12/2015
Driving Experience	2 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83895317
Fax Number	
Contact Number	OTHERS-83895317
Email Address	DANGERBOI21@GMAIL.COM

Address	BLK 141 JALAN BUKIT MERAH #03-1198
Postcode	160141
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CLEMENTI NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: NO. 20 CLEMENTI AVENUE 5 , POSTCODE: 129858 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8729999 - FAX NO: 67748639
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT T/20180824/2142

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKH6281T
Vehicle Make/Model/Colour	BMW
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	THENESH S/O MANIAM
Approximate Age	
Injuries Sustain	SLIGHT INJURY
Injured person in which vehicle?	FY2876Z
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

28/08/2018
Reporting Centre Personnel's Signature
Name: 
NRIC/FIN No.:

SKETCH PLAN

A) KY 2816Z
B) SKH 6281T




DEPOT ROAD
TOWARDS TUKU BLANGIAH

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


P/S Report to Police Report
7/20180824/2142

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: Rozali Waffoon
NRIC/FIN No.: _____



SINGAPORE POLICE FORCE

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999



T/20180824/2142

1 of 3

Report No. T/20180824/2142

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:
24/08/2018 20:36

Vide Report No.:

Station Diary No.:
221

Informant's Particulars

Name of Informant:
THENESH S/O S MANIAM

Address:
APT BLK 141 JALAN BUKIT MERAH #03-1198 SINGAPORE
160141

ID Type / ID No.:
NRIC NO / S9648435F

Contact No.:
Home/Office: Mobile: 83895317

Nationality:
SINGAPORE CITIZEN

Email:

Sex: Male Age: 21 Date of Birth: 17/12/1996

Type of Informant:
Rider

Race:

Indian

Language:
English

Institution / School Name:

Occupation:
DELIVERY RIDER

Driving Licence Information:
Class:

Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 24/08/2018 14:10	Type of Location: Straight Road
Location: Along Road 1 DEPOT ROAD				
Towards Telok Blangah				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FY2876Z	Motorcycle	YAMAHA	YBR125	Black	Slightly Damaged	0
SKH6281T	Car	BMW	320I	Blue	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FY2876Z	MSIG INSURANCE (SINGAPORE) PTE. LTD.	MSDTMT18380867	31/03/2018	30/03/2019



**SINGAPORE
POLICE FORCE**



T/20180824/2142

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

2 of 3

Report No. T/20180824/2142

CONTINUATION OF REPORT

Brief Details.

On the above mentioned date, time and location, I was riding my motorbike bearing the said registration plate number heading back home. At the point of time, I was travelling along lane 2 and came to a complete stop when the lights turned red.

When my motorbike was in stationery mode, one car which came from the back collided into my motorbike. Due to the impact, my motorbike wobble however I managed to stabilize it. The car came straight and bang into my motorbike again. Due to the 2nd impact, I lost control of my bike and fell off the bike.

Ambulance later was at scene and I was conveyed to SGH for medical treatment. I was then given 3 days MC in regards to the accident. This is not the first time such accident happened to me and I have all the particulars of the driver.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999



T/20180824/2142

3 of 3

Report No. T/20180824/2142

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

D /

Staff Sgt CLEMENT CHEE WEI JUN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / AEIT /
Sr Staff Sgt ONG YONG HOCK
Contact No.: 65476436

Signature Of Informant:

Date/Time:
24/08/2018 20:36

Classification Of Case:

Authentication Stamp

NP168

SN 37

SIGNATURE



HKL LIM TEAM MOTORSPORT

Blk 1008 #01-24, Bukit Merah Lane 3, Singapore 159722
Email: support@hklimmotorsport.com.sg

Tel: 6275 6656, 6275 6566, 62727292 Fax: 6272 9291
Website: www.hklimmotorsport.com.sg

FY2876Z

- 1 FRONT FORK ASSY LH / RH
- 2 FRONT FORK UNDER BRACKET
- 3 STEERING CONE BEARING
- 4 FRONT FENDER
- 5 FRONT WHEEL RIM
- 6 FRONT WHEEL SHALF
- 7 FRONT WHEEL BEARING 2PCS
- 8 HANDLE BAR
- 9 HANDLE BAR GRIP
- 10 WINDSHIELD
- 11 FRONT NO PLATE
- 12 BRAKE LEVER
- 13 SIDE MIRROR LH / RH
- 14 HEADLIGHT
- 15 FRONT FOOT REST BAR
- 16 FUEL TANK
- 17 EXHAUST GASKET
- 18 EXHAUST COVER
- 19 REAR SIGNAL LH / RH
- 20 REAR FENDER
- 21 REAR NO PLATE
- 22 LABOUR

SUR

\$180.00	repair (80)
\$120.00	X SUR
\$80.00	X SUR
\$70.00	CRA
\$150.00	repair
\$35.00	X
\$40.00	X SUR
\$80.00	X
\$20.00	X SUR
\$35.00	CRA
\$12.00	SUR
\$20.00	SUR
\$40.00	SUR
\$180.00	SUR
\$80.00	X SUR
\$150.00	PT
\$180.00	X SUR
\$60.00	SUR
\$80.00	CRA
\$80.00	X SUR
\$15.00	PT
\$450.00	250

TOTAL

\$2,157.00

Melrosey - \$180 X SUR

From 2337
Hp 90010068

4 days

4/5

31/08/18 @ 1630

Resay after repair

3/9/18

...CLAIM SUBFOLDER...(Pending for Survey Report)




















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Oct 2018 10:02 Edit Reg		29 Aug 2018 00:00 Edit Adj Rpt	S\$800.00 Edit Estimates	S\$800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: -, Co. Reg. No.: -, Email: EMAIL@EMAIL.COM									
Main Claimant: THENESH S/O MANIAM , ID: S9648435F									
Vehicle Reg. No.: FY2876Z		Date of Loss: 24/08/2018 14:00 - :59 [168 Months and 14 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / DMPC1800341H		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): SKH6281T		Policy No. (Claimant):							
		Excess:							
Repairer: Hkl Lim Team Motorsport (HQ) BLK 1008 #01-24 BUKIT MERAH LANE 3, 159722 Bukit Merah - Tel: 62756656/62756566/62727292									
Handling Insurer: ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Janice Goh - 6303 0182]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 11/09/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FY2876Z (DMPC1800341H)
[SKH6281T]
TP
THENESH S/O MANIAM
Aug 24 2018 2:00PM
[-]
Hkl Lim Team Motorsport

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Assessment Reports									1 per page		<input checked="" type="checkbox"/>	
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	03/09/18 17:14		Adjuster Immediate Advice						1	Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
2	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
3	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
4	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
5	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
6	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
7	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
8	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
9	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
10	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
11	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
12	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
13	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
14	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
15	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
16	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
17	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
18	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
19	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
20	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
21	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
22	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
23	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
24	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
25	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
26	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
27	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
28	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
29	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
30	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
31	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
32	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
33	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	
34	09/10/18 13:51		General View						1	Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	09/10/18 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>
36	09/10/18 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>
37	09/10/18 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>
38	09/10/18 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>
39	09/10/18 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>
40	09/10/18 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>
41	09/10/18 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>
42	09/10/18 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>
43	09/10/18 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>
44	09/10/18 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>
45	09/10/18 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>
46	09/10/18 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>
47	09/10/18 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>
48	09/10/18 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>
49	09/10/18 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>
50	09/10/18 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>
51	09/10/18 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>
52	09/10/18 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>
53	09/10/18 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18015962/R1QD3E2

Date: 22/10/2018

REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle
No : FY2876Z

Insured Vehicle No : SKH6281T

Date of Loss: 24/08/2018

Nature of Claim: TP

Claim No: DMPC1800341H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FY2876Z

Make & Model: YAMAHA YBR125, 124cc (M)

Engine No: JYM154FMI04400118

Reg. Date: 10/08/2004 (Man. Year: 2004)

Chassis No: LBPPCJLB240220128

Colour: Red

Odometer: 47466 km

Engine Capacity: 124 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 2.75-18

Rear Tyre Size: 90/90-18

Front Left Side: Maxxis 3 mm

Rear Left Side: Maxxis 3 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,887.00	747.80	1,139.20	60.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	450.00	250.00	200.00	44.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,337.00	997.80	1,339.20	57.30
Approved Total (Overridden) (S\$)		800.00		
Nett Amount (S\$)	2,337.00	800.00	1,537.00	65.77

INSPECTION

Date of Assignment: 29/08/2018

Date Inspected: 31/08/2018 Inspected At:

Hkl Lim Team Motorsport (HQ)
BLK 1008 #01-24 BUKIT MERAH LANE 3
Singapore 159722

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 22 Oct 2018)	
Parts:	N/A	YAMAHA YBR125 124cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FY2876Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FORK ASSY LH / RH	Scratched	180.00 FS	*80.00 FS
2	1		*FRONT FORK UNDER BRACKET	Serviceable	120.00 F	*- FL
3	1		*STEERING CONE BEARING	Necessary	80.00 F	*80.00 FL
4	1		*FRONT FENDER	Cracked	70.00 F	*70.00 FL
5	1		*FRONT WHEEL SHALF	Serviceable	35.00 F	*- FL
6	2		*FRONT WHEEL BEARING	Serviceable	40.00 F	*- FL
7	1		*HANDLE BAR	Serviceable	80.00 F	*- FL
8	1		*HANDLE BAR GRIP	Serviceable	20.00 F	*- FL
9	1		*WINDSHIELD	Cracked	35.00 F	*35.00 FL
10	1		*FRONT NO PLATE	Scratched	12.00 F	*12.00 FL
11	1		*BRAKE LEVER	Scratched	20.00 F	*20.00 FL
12	1		*SIDE MIRROR LH / RH	Scratched	40.00 F	*40.00 FL
13	1		*HEADLIGHT	Scratched	180.00 F	*180.00 FL
14	1		*FRONT FOOT REST BAR	Serviceable	80.00 F	*- FL
15	1		*FUEL TANK	Bent	150.00 F	*150.00 FL
16	1		*EXHAUST GASKET	Serviceable	180.00 F	*- FL
17	1		*EXHAUST COVER	Scratched	60.00 F	*60.00 FL
18	1		*REAR SIGNAL LH / RH	Cracked	80.00 F	*80.00 FL
19	1		*REAR FENDER	Serviceable	80.00 F	*- FL
20	1		*REAR NO PLATE	Bent	15.00 F	*15.00 FL
21	1		*METER ASSY	Serviceable	180.00 F	*- FL
22	1		*FRONT WHEEL RIM	Repair	150.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,887.00	822.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	74.20
Total Parts (\$\$)	1,887.00	747.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	450.00	250.00
Gross Labour Cost (S\$)			450.00	250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >