

Mehmen

Marcus

ASSIGNMENT (Office)

From (Person):

Mithoo Singh

of

AIG

Date/Time:

3/18/18 @ 12:04pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKA 2148J

Insured:

SLQ 9892B

at Workshop m/s:

Imperium Automotive

Tel:

9748 9940

of

25 Kelki Blot Rd 4 # 01-49

Policy No:

1700032370

Claim No:

3838 506 891 SG

Sum Insured:

Excess:

Make of Veh:

D.O.A.

30/08/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

1:32pm @ 3/18/18

Person Contacted:

8heun

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKA 2148J - X
	SLQ 9892B - X

(08/11/13) wef

ASS. REC. BY: marcus

REF:

A16/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKA 2148Jat Workshop m/s imperium

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GA / PR Seen: 2 Consistent? : Yes or NoEst. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKA 2148J Yr Regn: 1, 11Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or nMake: Toyota Vios c.c. 1497Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 94605 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053HY/9305174665Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/60 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 30/8/18 D.O.I. 31/8/18

Survey held at _____

Des. of Damages: Rear / Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

6/9/18 12A16577
contact L/S @ 3800 with Shawn. (Red 3567.88, 4890)

RECEIVED 06 SEP 2018

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 5

1)

☐ : Final ReportResurvey No. of Trip: 1

Date/Time, File Return to?

2) 6/9 - typistAdd Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

Report Format: merimenLump Sum / I.B.I. (\$) 3800/2

250

20

270



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/AIG18015963/Uvd3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 31-08-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLQ 9892B	Veh. Inspected	SKA 2148J
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MITHOOSINGH	Assign Date	31/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	30/08/2018	Inspection Date	31/08/2018
Survey held at	IMPERIUM AUTOMOTIVE 25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Aug 2018 Edit Reg		31 Aug 2018 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	YAP WEE TAI WILLIE, ID: S8013752D		
Main Claimant:	LOH WEI NAN, ID: S8370333D		
Vehicle Reg. No.:	SKA2148J	Date of Loss:	30/08/2018 18:00 - :59
Claim Type:	TP / 3838506891SG	Policy/Cover Note No.:	1700032370 (Comprehensive)
Vehicle Reg. No. (Insured):	SLQ9892B	Policy No. (Claimant):	
		Excess:	
Repairer:	Imperium Automotive - Kaki Bukit (HQ) 25 Kaki Bukit Road 4, #01-49 Synergy@KB, 417800 Kaki Bukit - Tel: 97489940		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 11/09/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (03/09/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

- Pre repair inspection request - SKA2148J VS SLQ9892B (OI) DOA: 30/08/2018

From: Mithoosingh, Aashweenjeetkaur
To: admin-a@kkauto.com, assignments@kkauto.com
Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Azlan, Syazairdina, Chan, Yoke Shi
Sent: 31/8/2018 12:04:57 PM
Attachments:  tmpA205.tif

Hi,

Please refer to the enclosed request from **JusEquity Law Corporation**.

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours.

If you have any queries/concerns, please let us know.

Kindly assist to assign Marcus Chua as Single Joint Expert as requested.

Thanks and regards,

Aashweenjeet Kaur (Aashween)
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: juseq@singnet.com.sg [mailto:juseq@singnet.com.sg]
Sent: Friday, August 31, 2018 11:59 AM
To: Mithoosingh, Aashweenjeetkaur
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLQ9892B AND SKA2148J ON 30/08/2018

Your ref: SLQ9892B
Our ref: JEQ/SKA2148J/IMP

Dear Sir/madam,

We refer to your email today.

Our client is agreeable to appoint the following surveyor as our single joint expert.

Mr. Marcus Chua-LKK Auto Consultants Pte Ltd

Please be informed that our client's vehicle is available for inspection at the understated workshop:-

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 #01-49,

Synergy@KB

Singapore 417800

Tel: 9748 9940 Fax: 6346 7213

Alfred Ng
Executive
On behalf of Mr Michael Yap
M/s JusEquity Law Corporation
No. 171 Chin Swee Road
#02-01/02/06 Singapore 169877
Tel: 6536 9339
Fax: 6536 5368

IMPORTANT NOTICE:

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.

From: Mithoosingh, Aashweenjeetkaur
Sent: Fri, 31 Aug 2018 03:23:45 +0000
To: juseq@singnet.com.sg
Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Azlan,

Syazairdina, Chan, Yoke Shi

Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLQ9892B AND SKA2148J ON 30/08/2018

Without Prejudice

Your Reference : JEQ/SKA2148J/IMP
Our Reference : SLQ9892B

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Fong Soon Yee	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Aashweenjeet Kaur (Aashween)
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/08/2018 17:54
Date Of Accident	30/08/2018 12:50
Exact Location Of Accident	BUKIT TIMAH RD JUST BEFORE HOOPER RD TOWARD CITY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKA2148J
Insured/Policyholder	
Name Of Registered Owner	LOH WEI NAN
NRIC No	S8370333D
Email Address	AHNAN83@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90906355
Alternative Phone No	OTHERS-90906355

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS-1.5 E (A)
Exact Purpose for which vehicle was being used at time of accident	GOING TO LUNCH
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800070690
Cover Note Number	

Driver

Name of Driver	LOH WEI NAN
NRIC No	S8370333D
Date Of Birth	12/11/1983
Occupation	OUTDOOR
Date Of Driving Pass	07/02/2009
Driving Experience	9 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90906355
Fax Number	
Contact Number	OTHERS-90906355
Email Address	AHNAN83@GMAIL.COM

Address	APT BLK 426B YISHUN AVENUE 11 #05-118
Postcode	762426
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	THOMSON NPP 25 SIN MING ROAD
Police Station Address	ROAD: 25 SIN MING ROAD #01-180 , POSTCODE: 570025 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLQ9892B
Vehicle Make/Model/Colour	KIA / NIRO / BLACK
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	YAP WEE TAI, WILLIE
NRIC/Passport Number	S8013752D
Contact Number	97356902
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

24/08/2018

Driver's Signature
(If driver is not the policyholder)
Date & Time:

24/08/2018

Reporting Centre Personnel's Signature
Name: BRIAN LIM
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180830/2146

1 of 4

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

Report No. T/20180830/2146

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 30/08/2018 17:12	Vide Report No.:	Station Diary No.: 50
--	------------------	--------------------------

Informant's Particulars

Name of Informant: LOH WEI NAN			Address: APT BLK 426B YISHUN AVE 11 #05-118 SINGAPORE 762426	
ID Type / ID No.: NRIC NO / S8370333D			Contact No.:	Mobile: 90906355
Nationality: SINGAPORE CITIZEN			Home/Office:	
			Email:	
Sex: Male	Age: 34	Date of Birth: 12/11/1983	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation: SALES PERSON			Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 30/08/2018 12:50	Type of Location: Straight Road
Location: Along Road 1 BUKIT TIMAH ROAD towards City (Before Hooper Road)				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKA2148J	Car	TOYOTA	VIOS E AUTO	Silver	Slightly Damaged	0
SLQ9892B	Car	KIA	NIRO HYBRID 1.6 GDI DCT SUNROOF	Grey		0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



**SINGAPORE
POLICE FORCE**



T/20180830/2146

2 of 4

Report No. T/20180830/2146

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKA2148J	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1800070690	20/06/2018	19/06/2019

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	LOH WEI NAN		ID No.	S8370333D
Related Vehicle	SKA2148J (Car)		Contact No.	90906355
Hospital/Clinic	L&L FAMILY MEDICINE CLINIC		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	30/08/2018		Date Discharge	30/08/2018
No. of Days granted Medical Leave	03		Degree of Injury	NIL
Driver				
Name	YAP WEE TAI WILLIE		ID No.	S8013752D
Related Vehicle	SLQ9892B (Car)		Contact No.	97356902
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

Brief Details.

On 30th August 2018 at 1250hrs, I was driving my vehicle registration SKA2148J along Bukit Timah Road towards City. I was driving in the middle lane. While I was driving, there was a vehicle ahead of me making stopped. I managed to stop on time and was in the stationary position.

Then, there was an impact from my rear vehicle. I alighted and realised that there was another vehicle registration number: SLQ9892B (V2) had collided to my rear portion.

I managed to exchange particulars and I went to seek medical attention due to the strong impact. I was given 3 days MC.

I am lodging this report for insurance claimed.



**SINGAPORE
POLICE FORCE**



T/20180830/2146

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

3 of 4

Report No. T/20180830/2146

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20180830/2146

4 of 4

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

Report No. T/20180830/2146

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /

Sr Staff Sgt MOHAMAD FARID BIN JAMAL

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

30/08/2018 17:12

Officer In Charge Of Case:

TP / AEIT /

Sr Staff Sgt ONG YONG HOCK

Contact No.: 65476436

Classification Of Case:



SINGAPORE
POLICE FORCE

SN 070

Authentication Stamp

NP168

SIGNATURE

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 #01-49 Synergy @ KB Singapore 417800
Tel: 9478 9940 Fax: 6346 7213

Vehicle No: SKA2148J

Model: Toyota Vios

Not Authorized
2/5 + 3800/1
3.18/18
Lg
take up after repair

QTY	List Price:
1	Rear boot
1	Rear boot rubber
1	Rear boot lock
1	Rear boot lock catch
1	Rear boot emblem "Logo"
1	Rear boot emblem "VIOS"
1	Rear boot emblem "E"
1	Rear boot emblem "Limited Edition"
1	Rear boot moulding
2	Rear taillamp- RH/LH @ 481.65
2	Rear taillamp side holder clips @ 12.90
2	Rear taillamp panel housing- RH/LH @ 105.00
1	Rear bumper
2	Rear bumper reflector- RH/LH @ 106.25
2	Rear bumper bracket- RH/LH @ 95.50
2	Rear bumper side holder- RH/LH @ 82.50
2	Rear bumper side retainer- RH/LH @ 89.65
6	Rear bumper clip @ 4.50
1	Rear end panel
1	Rear end panel garnish
2	Rear end panel garnish clip @ 4.50
1	Rear spare tire panel
1	Rear spare tyre panel cardboard
2	Rear spare tyre panel foam- RH/LH @ 126.20
1	Rear spare tyre screw carrier
1	Rear exhaust silencer
2	Rear exhaust mounting

Less 25%

Special Nett Items:

1	Rear number plate with casing
1	Rear bumper reverse sensor

Labour Charges:

Panel beating, cut, weld, remove and replacing above parts
Spray painting
To checking rear electrical wiring
To remove, refix cushion and inner trim

ESTIMATE PARTS AND LABOUR GRAND TOTAL

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey & re-estimate spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Prices \$

3rd/5th	665.90	✓
to n	162.84	✓
tw	289.50	✓
11	48.85	X
re	42.60	✓
NF	68.20	X
re	46.30	✓
NF	58.30	X
11	286.95	X
fra	963.30	✓
11	25.80	X
11	210.00	X
no/pe	459.75	✓
one	212.50	✓
11	191.00	X
11	165.00	X
Sub	179.30	✓
re	27.00	✓
11	777.25	✓
tw	89.65	✓
11	9.00	X
11	781.65	X
to A	156.50	✓
11	252.40	X
11	39.20	X
11	489.10	X
11	46.00	X

6743.84

-1685.96

Subtotal 5057.88

11 50.00 X

one/shd 280.00 200

Subtotal 330.00

1000.00 680

800.00 780

80.00 30

100.00 60

Subtotal 1980.00

\$ 7367.88

4804.4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18015963/UVD3N2

Date: 10/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700032370
 Claimant Vehicle No: SKA2148J Insured Vehicle No: SLQ9892B
 Date of Loss: 30/08/2018 Nature of Claim: TP Claim No: 3838506891SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKA2148J Engine No: 1NZY123215
 Make & Model: TOYOTA VIOS, 1.5 E (A) Chassis No: MR053HY9305174665
 Reg. Date: 27/01/2011 (Man. Year: 2010) Odometer: 94605 km
 Colour: Grey
 Engine Capacity: 1497 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60R15 Rear Tyre Size: 185/60R15
 Front Left Side: Achilles 6 mm Rear Left Side: Achilles 6 mm
 Front Right Side: Achilles 6 mm Rear Right Side: Achilles 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,387.88	3,254.29	2,133.59	39.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,980.00	1,550.00	430.00	21.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,367.88	4,804.29	2,563.59	34.79
Approved Total (Overridden) (S\$)		3,800.00		
Nett Amount (S\$)	7,367.88	3,800.00	3,567.88	48.42

INSPECTION

Date of Assignment: 31/08/2018
 Date Inspected: 31/08/2018 Inspected At: Imperium Automotive - Kaki Bukit (HQ)
 25 Kaki Bukit Road 4, #01-49
 Synergy@KB
 Singapore 417800
 Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent/Buckled	665.90 FL	*665.90 FL
2	1		*REAR BOOT RUBBER	Torn	162.84 FL	*162.84 FL
3	1		*REAR BOOT LOCK	Twisted	289.50 FL	*289.50 FL
4	1		*REAR BOOT LOCK CATCH	Not Necessary	48.85 FL	*- FL
5	1		*REAR BOOT EMBLEM LOGO	Necessary	42.60 FL	*42.60 FL
6	1		*REAR BOOT EMBLEM VIOS	Not fitted	68.20 FL	*- FL
7	1		*REAR BOOT EMBLEM E	Necessary	46.30 FL	*46.30 FL
8	1		*REAR BOOT EMBLEM LIMITED EDITION	Not fitted	58.30 FL	*- FL
9	1		*REAR BOOT MOULDING	Not Necessary	286.95 FL	*- FL
10	2		*REAR TAILLAMP-RH/LH	Cracked	963.30 FL	*963.30 FL
11	2		*REAR TAILLAMP SIDE HOLDER CLIPS	Not Necessary	25.80 FL	*- FL
12	2		*REAR TAILLAMP PANEL HOUSING-RH/LH	Repair	210.00 FL	*- FL
13	1		*REAR BUMPER	Dented/Deformed	459.75 FL	*459.75 FL
14	2		*REAR BUMPER REFLECTOR-RH/LH	Cracked	212.50 FL	*212.50 FL
15	2		*REAR BUMPER BRACKET-RH/LH	Not Necessary	191.00 FL	*- FL
16	2		*REAR BUMPER SIDE HOLDER-RH/LH	Not Necessary	165.00 FL	*- FL
17	2		*REAR BUMPER SIDE RETAINER-RH/LH	Bent	179.30 FL	*179.30 FL
18	6		*REAR BUMPER CLIP	Necessary	27.00 FL	*27.00 FL
19	1		*REAR END PANEL	Dented	777.25 FL	*777.25 FL
20	1		*REAR END PANEL GARNISH	Twisted	89.65 FL	*89.65 FL
21	2		*REAR END PANEL GARNISH CLIP	Not Necessary	9.00 FL	*- FL
22	1		*REAR SPARE TYRE PANEL	Repair	781.65 FL	*- FL
23	1		*REAR SPARE TYRE PANEL CARDBOARD	Torn	156.50 FL	*156.50 FL
24	2		*REAR SPARE TYRE PANEL FOAM-RH/LH	Not Necessary	252.40 FL	*- FL
25	1		*REAR SPARE TYRE SCREW CARRIER	Not Necessary	39.20 FL	*- FL
26	1		*REAR EXHAUST SILENCER	Repair	489.10 FL	*- FL
27	2		*REAR EXHAUST MOUNTING	Not Necessary	46.00 FL	*- FL
28	1		*REAR NUMBER PLATE WITH CASING	Not fitted	50.00 FS	*- FS
29	1		*REAR BUMPER REVERSE SENSOR	Cracked/Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,073.84	4,272.39
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,685.96	1,018.10
Total Parts (\$\$)	5,387.88	3,254.29

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,CUT,WELD,REMOVE AND REPLACING ABOVE PARTS	New	1,000.00	680.00
2	SPRAY PAINTING	New	800.00	780.00
3	TO CHECKING REAR ELECTRICAL WIRING	New	80.00	30.00
4	TO REMOVE,REFIX CUSHION AND INNER TRIM	New	100.00	60.00
Gross Labour Cost (S\$)			1,980.00	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >