Surveyor: Tanjh | REF: ASM (AXA)

ASSIGNMENT

From: | Date: 05/9/2018

Estimated Cost:

OD / TPY WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKV 7683 L

at Workshop m/s Volkswagen

of 1 Kampong Ampat off Macpherson Rd

Insured:

Policy No.

Claims No. -

Sum Insured: | Excess:

(Client's Record)

Make of Veh:

(Policy Condition) 10am

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value: 465K.

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: | Person Contacted:

Veh No: SKV 7683L Yr Regn: 2015 Sep

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Volkswagen Golf c.c 1395

Colour Silver A/C: Insured / Std / NI / NA

Sp.Reading 73702. T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVWZZZAUZFW456359

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17.

R: 〃 〃

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	5/9/18

Survey held at VW Kg Ampat @1030.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Report Format : -

Lump Sum / I.B.I: ($)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation: ___S + RS, ___SI

Photos

Others

TOTAL