MVA118107856 / VAC - Bukit Batok ENTRY DATE & TIME: 20/08/2018 16:58 SUBMITTED BY: LYNDA NG AH HIANG

SINGAPORE ACCIDENT STATEMENT

- IMPORTANT NOTICE 1. Please report correctly the details of the accident to speed up the claims process.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

aforesaid.	t to the archiving of this report at the centre and to copies of the report of the rep				
A CONTRACTOR OF THE STATE OF TH	20/08/2018 16:58				
	19/08/2018 12:50				
Date Of Accident	JURONG WEST ST 42				
Exact Location Of Accident	SINGAPORE				
Country/State of Loss	ETAILS OF OWN VEHICLE				
NAME OF THE OWNER OF THE OWNER OF THE OWNER, WHEN THE OWNER OF THE OWNER, WHEN	SLE4708Y				
Vehicle Fegistration Number					
Insured/Policyholder	AKY LEASING				
Name Of Registered Owner	53339339J				
Co Reg No	NOEMAIL				
Email Address	(LOCAL) +65-90040805				
Mobile Phone No	OFFICE-90040805				
Alternative Phone No					
Vehicle Particulars	HONDA				
Manufacturer	VEZEL				
Model					
Exact Purpose for which vehicle was being used a time of accident					
Are you claiming under your own insurance policy	NO .				
for repair to your verticle:	THIRD PARTY				
If No, Please state action to be taken	PRIVATE CAR				
Vehicle Category	ODERATIVE LTD				
Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD				
Name of Insurance Company	COMPREHENSIVE				
Type Of Coverage	NO				
Fleet Policy	5082467039-02(CLASSIC)				
Policy Number					
Cover Note Number					
Driver	ANG KIAN YONG				
Name of Driver	S8612436Z				

S8612436Z NRIC No 01/05/1986

Date Of Birth INDOOR Occupation 07/03/2008

10 YEARS AND 5 MONTHS Date Of Driving Pass

Driving Experience MALE

(LOCAL) +65-90040805 Gender

Mobile Number Fax Number

Contact Number EMail Address

NOEMAIL

Address

BLK 561B JURONG WEST ST 42 #12-1159

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Weather Conditions

CLEAR

Road Sulface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

YES

Was any other material or property damaged? I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

POLICE STATION NAME [OTHER]

JURONG WEST NPC

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLS REFER ATTACHED ACCIDENT REPORT FROM THE DRIVER. POLICE REPORT NO. T/20180819/2102

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

WILL EMAIL IF REQUIRED

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBG3123Z

Vehicle Make/Model/Colour

Details Of Properties

COMMERCIAL VEHICLE

Vehicle Category Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information. provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 26/8/2018

Driver's Signature (If driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature

OAR (VAC)

Name:

NRIC/FIN No .:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While nescring to park to the empty carports slot beside me located on Blk 560 divons West Street UA2, and floor, bibb 31332 knock onto SLE 47684 left bumper and go off. It was captured on SLE 47084 for cam and police report mas made on 19/15/2018 indicate the flog Waft and the left bumper drop off.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

IDAC BUKIT BATOK (VAC)

Policyholder's Signature Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:





1 of 3

Report No. T/20180819/2102

Police Station Of Origin: Jurong West N.P.C 700 Corporation Road SINGAPORE 649818 Tel No: 1800-2689999

REPORT OF A TRAFFIC ACCIDENT Date/Time Report Made: 19/08/2018 21:20			Vide Report No.:	Station Diary No. 185			
Informan	rs Particu	lars -	er med eg skrivere er en en en kompeten synes skriver og fra en	Control of the second of the s			
Name of Informant: ANG KIAN YONG			Address: APT BLK 561B JURONG WEST STREET 42 #12-1159 SINGAPORE 642561				
ID Type / ID No.: NRIC NO / S8612436Z		36Z	Contact No.: Home/Office:	Mobile: 90040805			
Nationality: SINGAPORE CITIZEN			Email:				
Sex: Male	Age:	Date of Birth: 01/05/1986	Type of Informant: Driver	Institution / School Name:			
Race: Chinese			Language: Chinese	Institution / School Name.			
Occupation: CONTRACTOR			Driving Licence Information: Class: 3	Date of Expiry:			

ieneral Information Type of Accident:	nation of the Acciden Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 19/08/2018 12:50	Type of Location Car Park
	ST STREET 42			
Weather:		Road Surface:		Road Speed Limit:
Clear Traffic Flow:		Traffic Control:		Traffic Volume: No Traffic
Type of Colli Moving Vehi	sion: cle Against - Parked Ve	ehicle		Anyone conveyed by ambulance: No

Details of Ve			Model	Color	Condition	No of Passenge
Vehicle No.	Type	Make	N. R. C. St. C. St. Company of Property of the Company of the Comp	Silver		0
GBG3123Z	Lorry	NISSAN	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5	Silver		
SLE4708Y	Car	HONDA	VEZEL 1.5X	Wnite	Seriously Damaged	0





Police Station Of Origin: Jurong West N.P.C

700 Corporation Road SINGAPORE 649818

Tel No: 1800-2689999

CONTINUATION OF REPORT

2 of 3 Report No. T/20180819/2102

Details of Perso	n Involved	CARLELLA	Beid Links	and the second		
Any Pedestrian I	nvolved: No					
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA			
Driver.			e salescare a			
Name	ANG KIAN YONG			ID No		S8612436Z
Related Vehicle	NIL		Contact No.		90040805	
Hospital/Clinic	NIL.			Class of Driving Licence & Expiry Date		Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Disc	harge	NIL		
No. of Days granted Medical Leave NIL			Degree of	Injury	NIL	

Brief Details.

On the 19/08/208 at about 1250hrs, I realized that my vehicle (SLE4708Y) was damaged on the front left. The bumper was dented and fort light was damaged. Thereafter, I made a check on the in-cam recording and realized that a lorry (GBG3123Z) actually collided onto my vehicle. The recording shows that the lorry was trying to park into the lot that was located beside me but collided onto my vehicle when he was reversing.





Police Station Of Origin: Jurong West N.P.C 700 Corporation Road SING

Report No. T/20180819/2102

700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999 CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: J / Sgt 1 LIM JUNJIE	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 19/08/2018 21:20
Officer In Charge Of Case: TP / HRT / Sr Staff Sgt ESTHER CHCNG Contact No.: 65476368	Classification Of Case:
Authentication Stamp	