

ASS. REC. BY:

REF:

CS/FCL18016033 /Anbn2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

CWS

From (Person):

Jaunne Yang

of

FCI

Date/Time:

3/18/18 @ 12:37pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SJA 878K

Insured:

SHD 3427S

at Workshop m/s:

Prime Motor

Tel:

67479241

of

1 Kaki Bkt Ave 6 # 01-43

Policy No.:

Claim No.:

D18006495MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/8/2018

CA / REV / REP. / REV 24 HRS

lup

3/9/18

H.O.D. Endorsement:

Date/Time:

1:10pm @ 3/18/18

Person Contacted:

Sukyi

Vehicle (IN) OUT

Date/Time

Action/Instruction (✓) Estimate

3/18/18

sukyi arrange on 3/9/18, as she went admin to sunny

SJA 878K - NS/GNC0902167A/Cn

DLA: 03-11-2009

SHD 3127S - CS/FCL18011267 /And3

DLA: 18062018

4/9/18

Informed FCI pending workshop est by email

REF:

ASS. REC. BY: Adrian King

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: STA8781C Yr Regn: 2016 / Dec.Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz E220 C.C. 1950Colour: Black A/C: Insured / Std / NI / NASp. Reading: 52542 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD2130042A122981Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 245/40R19R: 245/40R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Itabirend.

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 03/09/18Survey held at Prime.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Cap13/5/19 Adrian confirmed LS \$5300 (Red 20,428, 7990)14/5/19 Email preli revised to FCI

RECEIVED 14 MAY 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

14/5 - typist

Report Format :

CWSLump Sum / I.B.I. (\$) 5300/2Days Of Repair: 4Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Phone:

Other:

TOTAL

15/15 = 225170 + 225505034529



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18006495MFSH

Our ref: CS/FC118016033/Avb

Date : 14/5/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJA 878K


We thank you for your instruction on 31/8/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 3/9/2018 at the premises of M/s PRIME MOTOR WORKS and have the following to report:-

Workshop Estimate Amount	: S\$25,728.00
Revised Estimate Amount	: S\$5,300.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s portion and undercarriage



Comments/Present Status:

Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	30-08-2018	Our Ref No. D18006495MFSH
Accident Date	29-08-2018	Claim Type. Third Party
Insured Vehicle	SHD3427S	Third Party Vehicle. SJA878K
Survey Location	1 KAKI BUKIT AVE 6 BLK C #01-43 BLK C @AUTOBAY	
Contact Person.	REENA/ SUKYI	
Contact No.	67479241/ 0	Fax No. 67417276
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PRIME MOTOR WORKS	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 14 May 2019 9:15 AM
To: 'Claim Workflow System'
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006495MFSH/1, SJA 878K
Attachments: SJA 878K PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SJA 878K
Date of survey: 3/9/2018
Number of days : 4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 4 September 2018 9:50 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006495MFSH/1, SJA 878K

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SJA 878K on 3/9/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 31 August 2018 12:44 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18006495MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer arrange survey on 03/09/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Friday, 31 August 2018 12:37 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; JOANNEYONG@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18006495MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 4 September 2018 9:50 AM
To: 'Claim Workflow System'
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006495MFSH/1, SJA 878K

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SJA 878K on 3/9/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 31 August 2018 12:44 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006495MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer arrange survey on 03/09/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 31 August 2018 12:37 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; JOANNEYONG@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006495MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 1958H

Vehicle Details

Vehicle No.: SJA878K
Vehicle to be Exported: No
Intended De-registration Date: 30 Aug 2018
Vehicle Make: MERCEDES BENZ
Vehicle Model: E220D AUTO
Primary Colour: Black
Manufacturing Year: 2016
Engine No.: 65492080053125
Chassis No.: WDD2130042A122981
Maximum Power Output: 143.0 kW (191 bhp)
Open Market Value: \$58,245.00
Original Registration Date: 14 Dec 2016
First Registration Date: 14 Dec 2016
Transfer Count: 1
Actual ARF Paid: \$66,841.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 13 Dec 2026
PARF Rebate Amount: \$50,130.00

Intended COE Rebate Details

COE Expiry Date: 13 Dec 2026
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$46,229.00
COE Rebate Amount: \$38,300.00
Total Rebate Amount: \$88,430.00

The information contained herein is correct as at 30 Aug 2018

OK

PRIME MOTOR WORKS

BLOCK 1, KAKI BUKIT AVENUE 6, #01-43, SINGAPORE 417883

TEL: 6747 9241 FAX: 6741 7276 HP: 9067 8767

EMAIL: primemotorworks@hotmail.sg

RCB No: 53177286A

30/08/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 29/08/2018

Estimated repair cost for vehicle no: SJA878K MERCEDES E220 D 2.0 A '16

CHASSIS: WDD2130042A122981

S/N	QTY	ITEMS	U/PRICE	AMOUNT	
1	1	Front R/H Head Lamp <i>2nd time</i>		3467	x
2	1	Front R/H Head Lamp Lower Bracket			x
3	1	Front Bumper <i>Repair front</i>		2023	x
4	1	Front R/H Bumper Side Retainer <i>2nd</i>		35	2
5	1	Front Bumper Centre Lower Chrome Moulding <i>2nd time</i>		487	x
6	1	Front Bumper Sensor <i>2nd time</i>		182	x
7	1	Front R/H Fender <i>Dented</i>		1040	✓
8	1	Front R/H Rim <i>cut</i>	<i>850(SN)1537</i>		✓
9	1	Front R/H Tyre <i>new</i>		380	x
10	1	Front R/H Lower Arm <i>Bent</i>		625	2
11	1	Front R/H Knuckle Arm <i>Bent</i>		1050 1640	2
12	1	Front R/H Knuckle Arm Bearing <i>2nd</i>		554	✓
13	1	Front R/H Upper Arm <i>2nd</i>		836	x
14	1	Front R/H Drive Shaft <i>2</i>			x
15	1	Front R/H Stabilizer Bar <i>2nd</i>		585	x
16	1	Front Steering Rack <i>2nd</i>		9097	x

Subtotal:- \$0.00

5327

478430

SN 850

Labour charges

To remove & refit front steering rack & drive shaft	\$450.00 X
To remove & refit R/H front undercarriage	\$380.00 220
Tuff kote	\$150.00 X.
To check wiring	\$100.00 30
To check wheel alignment computer	\$150.00 80.
Panel beating	\$1,000.00 300
Spray painting	\$1,000.00 400.

1030

Subtotal:- \$3,230.00

Total:- \$3,230.00

25, 728

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:


Date:

Adrian King
2/s 03/09/18.
O.A. King

total: 6674.30
4/s 5.315.



PEOPLES AUTO TRADING
BLK 3007 UBI ROAD 1 #01-400
TEL 6741 4646



COMPUTERIZED ALIGNMENT SPECIALISTS

CUSTOMER	CASH	DATE	Aug 30, 2018 10:07:02 AM
LICENSE NO.	SJA 878 K		
MILEAGE	52535		
REFERENCE	CUSTOM	MODEL	MERCEDES BENZ E CL

Front Wheel	SPECS				DIAGNOSIS				ADJUSTMEN			
	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	0.00	1.00	2.10			2.40				2.30		
PARTIAL TOE	0.00	0.50	1.00		1.70		0.60		0.30		1.90	
SET BACK	---	---	---			0°06"				0°06"		
CAMBER	-1°22"	-0°36"	0°06"		-0°52"		-1°54" 1°02"		-0°48"		-1°56" 1°08"	
CASTER	7°44"	8°44"	9°44"		8°50"		8°58" 0°08"		8°50"		8°58" 0°08"	
KING-PIN	---	---	---		7°30"		7°46" 0°16"		7°30"		7°46" 0°16"	
INCL. ANGLE	---	---	---		6°36"		5°50"		6°40"		5°48"	
Toe-out on turns	---	---	---		---		---		---		---	
STEERING IN	---	---	---		---		---		---		---	
STEERING OUT	---	---	---		---		---		---		---	

Rear Wheel	SPECS				DIAGNOSIS				ADJUSTMEI			
	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	0.00	2.10	4.20			1.90				1.90		
PARTIAL TOE	0.00	1.00	2.10		0.50		1.30		0.50		1.30	
SET BACK	---	---	---			0°12"				0°12"		
CAMBER	0°00"	---	---		-1°18"		-1°36" 0°16"		-1°18"		-1°36" 0°16"	
THRUST ANGLE	-0°08"	0.00	0°08"			-0°02"				-0°02"		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18016033/Avbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 15-05-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3427S	Veh. Inspected	SJA 878K	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006495MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	31/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E220	c.c	1950	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WDD2130042A122981	Colour	BLACK	
Odometer	52542	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 R19	HABILEAD	6 mm	
L/H Front Tyre	245/40 R19	HABILEAD	6 mm	
R/H Rear Tyre	245/40 R19	HABILEAD	6 mm	
L/H Rear Tyre	245/40 R19	HABILEAD	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/08/2018	Inspection Date	03/09/2018	
Survey held at	PRIME MOTOR WORKS BLK 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJA 878K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT R/H HEAD LAMP	NOT NECESSARY	3,467.00	-
1	FRONT R/H HEAD LAMP LOWER BRACKET (NPA)	NOT NECESSARY	-	-
1	FRONT BUMPER	TORN	2,023.00	2,023.00
1	FRONT R/H BUMPER SIDE RETAINER	NECESSARY	35.00	35.00
1	FRONT BUMPER CENTRE LOWER CHROME MOULDING	NOT NECESSARY	487.00	-
1	FRONT BUMPER SENSOR	NOT NECESSARY	182.00	-
1	FRONT R/H FENDER	DENTED	1,040.00	1,040.00
1	FRONT R/H TYRE	NOT NECESSARY	380.00	-
1	FRONT R/H LOWER ARM	BENT	625.00	625.00
1	FRONT R/H KNUCKLE ARM	BENT	1,640.00	1,050.00
1	FRONT R/H KNUCKLE ARM BEARING	NECESSARY	554.00	554.00
1	FRONT R/H UPPER ARM	NOT NECESSARY	836.00	-
1	FRONT R/H DRIVE SHAFT (NPA)	NOT NECESSARY	-	-
1	FRONT R/H STABILIZER BAR	NOT NECESSARY	595.00	-
1	FRONT STEERING RACK	NOT NECESSARY	9,097.00	-
	LESS 10% DISCOUNT		-	-532.70
			20,961.00	4,794.30
SPECIAL NETT ITEMS				
1	FRONT R/H RIM (SN)	CUT	1,537.00	850.00
			1,537.00	850.00
LABOUR				
	TO REMOVE & REFIT FRONT STEERING RACK & DRIVE SHAFT.	NOT NECESSARY	450.00	-
	TO REMOVE & REFIT R/H FRONT UNDERCARRIAGE.		380.00	220.00
	TUFF KOTE.	NOT NECESSARY	150.00	-
	TO CHECK WIRING.		100.00	30.00
	TO CHECK WHEEL ALIGNMENT COMPUTER.		150.00	80.00
	PANEL BEATING.		1,000.00	300.00
	SPRAY PAINTING.		1,000.00	400.00
			3,230.00	1,030.00

Report Ref No. CS/FC118016033/Avbn2



GRAND TOTAL		25,728.00	6,674.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,300.00

Report Ref No. CS/FCI18016033/Avbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.