

12/03/2002

ASS. REC. BY:

REF:

CS3 / ALH18016068 / ACB97

Special Instruction:

SURVIVOR

## ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

ALH

Date/Time:

03/09/2018 3:16pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR 6692B

Insured:

SLP 8756Z

at Workshop m/s

AutoPm

Tel:

9092 7579

of

Bk 8 Kaki Bukit Ave 4 #06-21

Policy No:

0999994784

Claim No:

791977386786

Sum Insured:

Excess:

Make of Veh:

D.O.A

21082018

(Client's Record)

CA / REV / REP. / REV 24 HRS WP

04-09-2018 @ morning

H.O.D. Endorsement:

Date/Time:

03/09/2018 5:11pm

Person Contacted:

Alan

Vehicle IN/OUT

Date/Time	Action/Instruction ( X ) Estimate
	SLR 6692B - X
	SLP 8756Z - X
	Dismantle: 6/9/2018.
	After repair: 7/9/2018

(0001/113) wel  
ASS. REC. BY:

REF: AIG

### ASSIGNMENT

From : Date: **1/9/18**  
Estimated Cost:  
OP: ☒ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV  
To Inspect Vehicle No: **SLR 6692B**  
at Workshop m/s: **Auto Pro**  
of **Blk 8 Kaki Bkt Ave 4 #06-21**  
Insured:  
Policy No:  
Claims No:  
Sum Insured: Excess:  
(Client's Record)  
Make of Veh: **Morning**  
**Alan @ 9092 7279**

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:  
IDAC Accident Rpt: Consistent? : Yes or No  
GIA / PR Seen: Consistent? : Yes or No  
Est. Repairs: **5** days Res.: Yes or No  
Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS **(up)**

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: **SLR6692B** Yr Regn: **2012 Sept.**  
Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: **Toyota Estima.** c.c. **2362**  
Colour: **Grey.** A/C: **Insured / Std / NI / NA**  
Sp. Reading: **87123.** T/Radio: **Insured / Std / NI / NA**

Eng/No:

C/No: **ACR507111529.**

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: F: **215/55R17.**

R: **215/55R17.**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

**Fallcon.**

Front

Rear

R/Bal. **06** mm

R/Bal. **06** mm

L/Bal. **06** mm

L/Bal. **06** mm

D.O.A.

D.O.I. **04/09/18**

Survey held at

**Auto Pro**

Des. of Damages: Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

**TP AIG PRS**

**MV: 78K**  
**PV: 59.7K**  
**Nett: 18.3K**

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: **5**

1)

☐ : Final Report

Resurvey No. of Trip: **2**

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format : **DAR**

Lump Sum / I.B.I. (\$) )




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS3/AIG18016068/Acb	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 04-09-2018	
		Code : AIG	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>			
Insured Veh.	SLP 8756Z	Veh. Inspected	SLR 6692B
Policy No.		Coverage (\$)	0.00
Claim No.	7919773867SG	Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	03/09/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	21/08/2018	Inspection Date	04/09/2018
Survey held at	AUTOPRO - 8 KAKI BUKIT AVE 4 #06-21		
Repairer	-		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLP8756Z AND SLR6692B ON 21/08/2018

From: Chin, Lee-Ying  
To: assignments@lkkauto.com, admin-a@lkkauto.com  
Cc: Fong, Andy-SY  
Sent: Monday, 3 September, 2018 3:16:46 PM  
Attachments: 28082018105103.pdf

Hi LKK,

Kindly assist to survey, owner will leave vehicle at 4pm today.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG  
Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947 | Fax +(65) 6835 7416  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

03092018 @ 5:11pm  
Alan veh in  
04092018 @ morning

**From:** William Lee [mailto:william@roypartners.com.sg]  
**Sent:** Tuesday, August 28, 2018 10:52 AM  
**To:** Gan, Angiegeokling; Fong, Andy-SY; Lim, Sheng Yang; Ng, Hai-Chuan  
**Cc:** 'Ashley'; 'Roy'; 'TeamAutoPro North'  
**Subject:** Our Ref: MKR/404/8188/2018/as.wl; Your Ref: Your insured vehicle no. SLP 8756Z;  
**Importance:** High

Our Ref: MKR/404/8188/2018/as.wl;  
Your Ref: Your insured vehicle no. SLP 8756Z;

Dear Sirs,

**Attn: Motor claims department**

**CLAIMANT:** WISAN WATANIYAKUN (OWNER OF SLR 6692B)  
**ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SLR 6692B AND SLP 8756Z ALONG ECP EXIT 15 ON 21.08.2018 AT ABOUT 1940 HOURS.**

We refer to the above matter.

We act for Wisan Wataniyakun, the owner of motor car No. **SLR 6692B**.

We are instructed by our client to notify you of a road traffic accident on 21.08.2018 at about 7.40 pm along ECP Exit 15 involving our client's motor car registration number **SLR 6692B** and motor car registration number **SLP 8756Z** driven by your insured at the material time. A copy of the Singapore Accident Statement is attached.

As a result of the accident, our client's motor car **SLR 6692B** has been damaged. Before our client proceed to repair the damaged motor car, please let us know within **two (2) working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of our client's motor car **SLR 6692B** at our client's repairer workshop, **M/s Team AutoPro Pte Ltd at No. 8 Kaki Bukit Avenue 4 #06-21 Premier @ Kaki Bukit (Gate 2) Singapore 415875**. Your said surveyor may contact **Mr. Alan at 9092 7279**. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the motor car without further reference to you.

Thanks & regards,

**William Lee**  
M/s Roy & Partners  
101 Cecil Street  
#11-09 Tong Eng Building  
Singapore 069533  
Tel: 6536 8466 Fax: 6536 1963  
Email: [william@roypartners.com.sg](mailto:william@roypartners.com.sg)

6358 1955  
michele

*IMPORTANT NOTE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.*

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	24/08/2018 16:18
Date Of Accident	21/08/2018 19:40
Exact Location Of Accident	ECP EXIT 15
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR6692B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	WISAN WATANIYAKUN
NRIC No	S2717884G
Email Address	WISAN.W@EMAS.COM
Mobile Phone No	(LOCAL) +65-97800391
Alternative Phone No	OTHERS-97800391

#### Vehicle Particulars

Manufacturer	TOYOTA
Model	ESTIMA
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

#### Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT101239
Cover Note Number	

#### Driver

Name of Driver	WISAN WATANIYAKUN
NRIC No	S2717884G
Date Of Birth	14/10/1963
Occupation	INDOOR
Date Of Driving Pass	03/10/2003
Driving Experience	14 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97800391
Fax Number	
Contact Number	OTHERS-97800391
E-Mail Address	WISAN.W@EMAS.COM

Address	3 SIMEI STREET 4 #02-01
Postcode	529862
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : NA GENDER: : FEMALE
Passenger 2	NAME: : NA GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CHANGI NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 9 SIMEI STREET 2 , POSTCODE: 529914 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5872999 - FAX NO: 65872900
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP8756Z
Vehicle Make/Model/Colour	
Details Of Propertles	
Vehicle Category	PRIVATE CAR
Name of Driver	

NRIC/Passport Number

Contact Number 82184559

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/PAN No.:

# Sketch Plan #2 Pg. 1

## SKETCH PLAN

ECP 6X1715

Vehicle A: SLK 692 B

Vehicle B: SLP8756 Z

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report T/20180822/2685

Passenger wife (Female)

daughter (Female)

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/ID No:

CONTINUE ON BACK OF FORM 17

## Common Statement Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20180822/2085

Police Station Of Origin:  
Changi N.P.C  
9 Simei Street 2 SINGAPORE 529914  
Tel No: 1800-5872999

1 of 3

Report No. T/20180822/2085

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/08/2018 17:35		Vide Report No.:		Station Diary No.: 27	
<b>Informant's Particulars</b>					
Name of Informant: WISAN WATANIYAKUN			Address: 3 SIMEI STREET 4 #02-01 SINGAPORE 529862		
ID Type / ID No.: NRIC NO / S2717884G			Contact No.: Home/Office: Mobile: 97800391		
Nationality: THAI			Email:		
Sex: Male	Age: 54	Date of Birth: 14/10/1963	Type of Informant: Driver		
Race: Thai			Language:		Institution / School Name:
Occupation: GENERAL MANAGER (TECHNICAL)			Driving Licence Information: Class: 3 Date of Expiry:		

<b>General Information of the Accident</b>				
Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 21/08/2018 19:40	Type of Location: Straight Road
Location: Along Road 1 EAST COAST EXPRESSWAY EXIT 15				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SLP8756Z	Car				Slightly Damaged	1
SLR6692B	Car	TOYOTA	ESTIMA AERAS G-EDITION 2.4 A	Grey	Slightly Damaged	2

<b>Details of Vehicle Insurance</b>				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date

**SINGAPORE  
POLICE FORCE**

T/20180822/2085

Police Station Of Origin:  
Changi N.P.C  
9 Simei Street 2 SINGAPORE 529914  
Tel No: 1800-5872999

2 of 3

Report No. T/20180822/2085

## CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No	Insurance Company	Insurance No	Effective	Expiry Date
SLR6692B	TOKIO MARINE INSURANCE SINGAPORE LTD.	MT101239	09/04/2018	08/04/2019

**Brief Details.**

On 21st August 2018 at about 7.40pm, I was travelling in my car (SLR6692B) along East Coast Expressway towards Victoria Street. As I was about to exit at Exit 15, I stopped as there was a car in front of me. Suddenly, the car (SLP8756Z) behind me hit the rear of my vehicle. Nobody was injured in the accident.

My car sustained damages on the left rear area. My dashboard camera was not recording at that point of time.

**Driver's particulars:**

Loh Khiam Piew  
S7121243B  
HP: 82184559

Common Statement Pg. 1



SINGAPORE  
POLICE FORCE

Police Station Of Origin:  
Changi N.P.C  
9 Simei Street 2 SINGAPORE 529914  
Tel No: 1800-5872999



T/20180822/2085

3 of 3



Report No. T/20180822/2085

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 2 WONG TARYN ESMERELDA XIN YI	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 22/08/2018 17:35
Officer In Charge Of Case: TP / GIA / Staff Sgt WONG SIEU LUI Contact No.: 65476151	Classification Of Case: 
Authentication Stamp NP158	

Email: [sm@idac.com.sg](mailto:sm@idac.com.sg)

Tel no: 6555 6888 Fax no: 6454 3279

**Personal Particulars of Owner & Driver (Vehicle A)**

Date of Accident: 21/08/2018 (dd/mm/yy) Time of Accident: 19:49 24-HR-FORMAT

Vehicle No.: SLR 6692B Vehicle Make & Model: Toyota Estima

Exact location of Accident: ECP Exit 15

Policyholder's Name / IC No.: Wisan Wattaniyakun / S27178846

Driver's Name / IC No.: \_\_\_\_\_ (As Above) ☒

Driver's Contact No.: 97800391 Company Contact No.: \_\_\_\_\_

Driver's Address: 3 Simai St 4 #02-01 SLS29862

Insurance Company: Takimaru Email address (if any): WISAN.W@EMAS.COM

**Relationship between Owner & Driver:** (Please **CIRCLE** one only)

Owner / Spouse / Children / Friend / Parents / Sibling / Relative / Employee / Hirer or Others specify: \_\_\_\_\_

**What do you wish to claim?** (Please **TICK** one only)

☐ Own Insurance / ☒ Other Vehicle (The one you want to claim against) / ☐ Reporting (For Record Purpose)

**Exact purpose for which the vehicle was being used at time of accident?**

☒ Private use / ☐ Work purpose

**Occupation (nature of job)** ☒ Indoor / ☐ Outdoor

**No. of Passengers (Including Driver):** 03

**Weather condition & Road conditions?** (On the day of accident)

☒ Clear & Dry / ☐ Raining & Wet / ☐ After-Rain & Wet / ☐ Drizzling & Wet / Others: \_\_\_\_\_

**Was there any video captured by your Car Camera?** ☐ Yes / ☒ No

**Any Injuries:** ☐ Yes / ☒ No (If YES) Injured Person's Name: \_\_\_\_\_

Injuries Sustain: \_\_\_\_\_ Injured Person in Which Vehicle: \_\_\_\_\_

**Police Report filed:** ☒ Yes / ☐ No (If YES) Which Police Station: Changi NPC

**The Other Party(s) Details:**

1. Driver's Name / IC No.: \_\_\_\_\_ Vehicle No: SLP 87562

Driver's Contact No: 82184559 Insurance Company (If any): \_\_\_\_\_

2. Driver's Name / IC No.: \_\_\_\_\_ Vehicle No: \_\_\_\_\_

Driver's Contact No: \_\_\_\_\_ Insurance Company (If any): \_\_\_\_\_

\*Independent Witness (If Any): \_\_\_\_\_ Contact No: \_\_\_\_\_

Preferred Workshop Name: \_\_\_\_\_ Contact No: \_\_\_\_\_

\*If no proper documents are produced, IDAC should not file the report. Information will be discarded after one week.



# SINGAPORE POLICE FORCE



T/20180822/2085

1 of 3

Police Station Of Origin:

Changi N.P.C

9 Simei Street 2 SINGAPORE 529914

Tel No: 1800-5872999

Report No. T/20180822/2085

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 22/08/2018 17:35	Vide Report No.:	Station Diary No.: 27
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: WISAN WATANIYAKUN			Address: 3 SIMEI STREET 4 #02-01 SINGAPORE 529862		
ID Type / ID No.: NRIC NO / S2717884G			Contact No.: Home/Office: Mobile: 97800391		
Nationality: THAI			Email:		
Sex: Male	Age: 54	Date of Birth: 14/10/1963	Type of Informant: Driver		
Race: Thai			Language:		Institution / School Name:
Occupation: GENERAL MANAGER (TECHNICAL)			Driving Licence Information: Class: 3 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 21/08/2018 19:40	Type of Location: Straight Road
Location: Along Road 1 EAST COAST EXPRESSWAY				
EXIT 15				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLP8756Z	Car				Slightly Damaged	1
SLR6692B	Car	TOYOTA	ESTIMA AERAS G- EDITION 2.4 A	Grey	Slightly Damaged	2

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



**SINGAPORE  
POLICE FORCE**



T/20180822/2085

3 of 3

Police Station Of Origin:  
Changi N.P.C  
9 Simei Street 2 SINGAPORE 529914  
Tel No: 1800-5872999

Report No. T/20180822/2085

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

G /  
Sgt 2 WONG TARYN ESMERELDA XIN YI

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIA /  
Staff Sgt WONG SIEU LUI  
Contact No.: 65476151

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

22/08/2018 17:35

Classification Of Case:



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7884G
Vehicle Details	
Vehicle No.:	SLR6692B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	04 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	ESTIMA AERAS G-EDITION 2.4 A
Primary Colour:	Grey
Manufacturing Year:	2012
Engine No.:	2AZH830961
Chassis No.:	ACR507111529
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$37,549.00
Original Registration Date:	14 Sep 2012
First Registration Date:	14 Sep 2012
Transfer Count:	1
Actual ARF Paid:	\$37,549.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Sep 2022
PARF Rebate Amount:	\$26,284.00
Intended COE Rebate Details	
COE Expiry Date:	13 Sep 2022
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$85,889.00
COE Rebate Amount:	\$33,407.00
<b>Total Rebate Amount:</b>	<b>\$59,691.00</b>

The information contained herein is correct as at 04 Sep 2018

OK



New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

onefm  
913  
9000 TIMES GREATEST HITS

THE COURT'S ONE FM 91.3  
TOP 913 GREATEST HITS  
OF ALL TIME COUNTDOWN

WHAT'S YOUR NO.1 SONG  
OF ALL TIME?

SUBMIT NOW



Post an Advertisement  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

New 5 Year COE Renewal Toyota Wish 1.8A



\$2800 Downpayment! Monthly  
\$688 Onwards! Lowest 3.68%  
P.a. @ GV Cars Financing!  
GV Credit Pte Ltd StarAd



HIN LUNG AUTO  
Ho Bee Group

30 years  
of car sale

**One Stop Car Hub**  
Finance, Insurance, Workshop  
New and Used Cars

Browse by Category

Save Search

Print

Sort by Date Posted

20 results/page

6 vehicles

Search

estima

Advanced Search

Search

View All

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

estima

Any

Any

2012

Any

Any

Any

Available



☐ Toyota Estima 2.4A Aeras  
Premium Moonroof

\$79,800

\$15,070 /yr

16-Aug-2012

2,362 cc

51,000 km

MPV

Available

Original New Facelift, "One Year In-House Warranty", From \$8,000 Onwards Drive Away, Comes With Official Warranty Certificate For A Peace Of Mind, Accident Free, Wear And Tear Replaced, Able To Try Ma...

Carway

☆ Posted: 04-Sep-2018 Tags: 2012 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota



☐ Toyota Estima 2.4A Aeras G

\$77,800

\$14,380 /yr

26-Sep-2012

2,362 cc

98,452 km

MPV

Available

Well Taken Care Vehicle By Owner And Suitable For Family With Kids For Safety And Comfort, High Loan And High Trade In Available! Call Us Now To Book For Appointment!

ABWIN (1994) Pte Ltd

☆ Posted: 04-Sep-2018 Tags: 2012 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota



☐ Toyota Estima 2.4A Aeras G

\$80,800

\$15,250 /yr

29-Sep-2012

2,362 cc

71,900 km

MPV

Available

Consignment Unit, Well Taken Care Vehicle By Owner And Suitable For Family With Kids For Safety And Comfort, Flexible Loan Packages Catering For All Requirements! Call Us Now To Book For Appointment!

☆ Posted: 01-Sep-2018 Tags: 2012 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota



☐ Toyota Estima 2.4A Aeras  
Premium Moonroof

\$82,800

\$14,890 /yr

15-Nov-2012

2,362 cc

120,400 km

MPV

Available

Down Payment Of 20% With Easy Approval. Monthly Installment From \$1500. The Greatest People's Mover Of All. Reliable With Easy Maintenance. Contact Our Sales Team For More Info At 64721119.

Vincar Pte Ltd

☆ Posted: 20-Aug-2018 Tags: 2012 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota

Car Buying ▶


Car Selling ▶

Car Ownership ▶

Car Aftermarket ▶

On The Move ▶

Lifestyle ▶



☐ Toyota Estima 2.4A Aeras G

\$82,800

\$14,900 /yr

21-Nov-2012

2,362 cc

MPV

Available

Just Arrival! Superb Condition, Very Low Mileage Done. A Fully Equipped MPV With DVD System And Ceiling Monitor. Superbly Maintained By Previous Meticulous Owner That Keeps The Interior And Exterior N...

☆ Posted: 03-Sep-2018 Tags: 2012 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota



☐ Toyota Estima Hybrid 2.4A X

\$78,800

\$14,910 /yr

20-Dec-2012

2,362 cc

70,000 km

MPV

Available

Fuel Type: Petrol-Electric

One Owner, Nice Bidded Number 2323! Excellent Engine And Smooth Transmission, Convenient And Spacious 7 Seaters, Quiet, Comfort Family Car. New Hybrid Battery Change With One Year Warranty. This Is The...

☆ Posted: 01-Sep-2018 Tags: 2012 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Save Search

SHORTLISTED HISTORY

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Compare

View Expired ads

20 results/page

# MOTORCAR (Rear)

Vehicle No: **SLR 66928**

## Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	CUT ✓		
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC ✓		
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	DIS ✓		
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge	LH CUT ✓		
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DM ✓		
1159	993327	Rear End Panel	DD R ✓		
1160	993339	Rear End Panel Top Garnish	CUT ✓		
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	DD ✓		
1182	991328	Tailgate Emblem	NEC ✓		
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	NEC ✓		
1196	994607	Tailgate Glass Sealant	NEC ✓		
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1196	990247	Sticker	NEC ✓		

No of Items: **3**

Assessor: \_\_\_\_\_

TGrim *llm*

25/9/18

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Aug 2018 <a href="#">Edit Reg</a>		03 Sep 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$0.00</b> <a href="#">Edit Estimates</a>	<b>\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

## CLAIM SUBFOLDER DETAILS

[\[Created by adjuster\]](#)

Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K			Date of Loss:	21/08/2018 19:00 - :59 [71 Months and 7 Days From LTA Reg Date (Man Yr)]
Main Claimant:	WISAN WATANIYAKUN, ID: S2717884G			Policy/Cover Note No.:	0999994784 (Comprehensive)
Vehicle Reg. No.:	SLR6692B			Policy No. (Claimant):	
Claim Type:	TP / 7919773867SG			Excess:	
Vehicle Reg. No. (Insured):	SLP8756Z				
Repairer:	Team Autopro Pte Ltd (KAKI BUKIT) No.8 Kaki Bukit Avenue 4, #06-21 Premier@ Kaki Bukit (Gate 2), 415875 Kaki Bukit - Tel: 90927279				
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Olea, Maricel] Maricel.Olea@aig.com				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 13/09/2018]				

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG\_SG (06/09/2018): Request To Upload TP GIA Report

## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									





## Claim Documents

**\*SLR6692B (7919773867SG)**  
**[SLP8756Z]**

TP

**WISAN WATANIYAKUN**

**Aug 21 2018 7:00PM**

**[LCRF PTE LTD]**

**Team Autopro Pte Ltd**

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

**View** [View in Browser](#)

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	06/09/18 09:34	<b>AIG Asia Pacific Insurance Pte. Ltd. (SG)</b> <b>Accident Statement</b> <small>From: SC - Reg. No: SLP8756Z, Claimant: LCRF PTE LTD</small>	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder		Thumbnail	Print
LKK Auto Consultants Pte Ltd (HQ)				
1	05/09/18 12:22	General View	Load JPG	<input checked="" type="checkbox"/>
2	05/09/18 12:22	General View	Load JPG	<input checked="" type="checkbox"/>
3	05/09/18 12:22	General View	Load JPG	<input checked="" type="checkbox"/>
4	05/09/18 12:22	General View	Load JPG	<input checked="" type="checkbox"/>
5	05/09/18 12:22	General View	Load JPG	<input checked="" type="checkbox"/>
6	05/09/18 12:22	General View	Load JPG	<input checked="" type="checkbox"/>
7	05/09/18 12:22	General View	Load JPG	<input checked="" type="checkbox"/>
8	05/09/18 12:22	General View	Load JPG	<input checked="" type="checkbox"/>
9	05/09/18 12:22	General View	Load JPG	<input checked="" type="checkbox"/>
10	05/09/18 12:22	General View	Load JPG	<input checked="" type="checkbox"/>
11	05/09/18 12:22	General View	Load JPG	<input checked="" type="checkbox"/>
12	05/09/18 12:22	General View	Load JPG	<input checked="" type="checkbox"/>
13	05/09/18 12:22	General View	Load JPG	<input checked="" type="checkbox"/>
14	05/09/18 12:22	General View	Load JPG	<input checked="" type="checkbox"/>
15	05/09/18 12:22	General View	Load JPG	<input checked="" type="checkbox"/>
16	05/09/18 12:22	General View	Load JPG	<input checked="" type="checkbox"/>
17	05/09/18 12:22	General View	Load JPG	<input checked="" type="checkbox"/>
18	11/09/18 11:56	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
19	11/09/18 11:56	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
20	11/09/18 11:56	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
21	11/09/18 11:56	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
22	11/09/18 11:56	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
23	11/09/18 11:56	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
24	11/09/18 11:56	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
25	11/09/18 11:56	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
26	11/09/18 11:56	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
27	11/09/18 11:56	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
28	11/09/18 11:56	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
29	11/09/18 11:56	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
30	11/09/18 11:56	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
31	11/09/18 11:57	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
32	11/09/18 11:57	Photo After Spray	 Load JPG	✓
33	11/09/18 11:57	Photo After Spray	 Load JPG	✓
34	11/09/18 11:57	Photo After Spray	 Load JPG	✓
35	11/09/18 11:57	Photo After Spray	 Load JPG	✓
36	11/09/18 11:57	Photo After Spray	 Load JPG	✓
37	11/09/18 11:57	Photo After Spray	 Load JPG	✓
38	11/09/18 11:57	Photo After Spray	 Load JPG	✓
39	11/09/18 11:57	Photo After Spray	 Load JPG	✓
40	11/09/18 11:57	Photo After Spray	 Load JPG	✓
41	11/09/18 11:57	Photo After Spray	 Load JPG	✓
42	11/09/18 11:57	Photo After Spray	 Load JPG	✓
43	11/09/18 11:57	Photo After Spray	 Load JPG	✓
44	11/09/18 11:57	Photo After Spray	 Load JPG	✓
45	11/09/18 11:57	Photo After Spray	 Load JPG	✓
46	11/09/18 11:57	Photo After Spray	 Load JPG	✓
47	11/09/18 11:57	Photo After Spray	 Load JPG	✓
48	11/09/18 11:57	Photo After Spray	 Load JPG	✓
49	11/09/18 11:57	Photo After Spray	 Load JPG	✓

## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18016068/ACBS2

Date: 26/09/2018

## REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	09999994784
Claimant Vehicle No :	SLR6692B	Insured Vehicle No :	SLP8756Z
Date of Loss:	21/08/2018	Nature of Claim:	TP
		Claim No:	7919773867SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLR6692B	Engine No:	2AZH830961
Make & Model:	TOYOTA ESTIMA, 2.4 (A)	Chassis No:	ACR507111529
Reg. Date:	14/09/2012 (Man. Year: 2012)	Odometer:	87123 km
Colour:	Grey		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

## CONDITION OF TYRES

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment:	03/09/2018	Team Autopro Pte Ltd (Kaki Bukit)
Date Inspected:	04/09/2018 Inspected At:	No.8 Kaki Bukit Avenue 4, #06-21 Premier@ Kaki Bukit (Gate 2)
Estimated Period of Repair:	5.0 days	Singapore 415875

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	0.00 F	*-F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*-F
3	1		*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*-F
4	1		*REAR BUMPER SPONGE LH	Cut	0.00 F	*-F
5	1		*REVERSE SENSOR	Damaged	0.00 F	*-F
6	1		*REAR END PANEL	Repair	0.00 F	*-F
7	1		*REAR END PANEL TOP GARNISH	Cut	0.00 F	*-F
8	1		*TAILGATE	Dented	0.00 F	*-F
9	1		*TAILGATE EMBLEM	Necessary	0.00 F	*-F
10	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*-F
11	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*-F
12	1		*STICKER	Necessary	0.00 F	*-F
F=Franchise part.				<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >