

REF: C83 / ASM17024635 / R1v0-1

Special Instructions:

WS: ~~\$~~ 1500.00

Third Parties:

Claimant:

Surveyor: PAR Automotive

Workshop: N-51 Automotive

ASSIGNMENT (Office)

From (Person): Heng Xinyi of Seah Ong Date/Time: 30/08/2018
Estimated Cost: Bill

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SKZ 2009X Insured: YK 5518R

at Workshop m/s N-51 Automotive Tel: 6843 0151

of 81k 2 Kuki Bulsat Ave 2 #01-17

Policy No: _____ Claim No: 18-04959 PD-0

Sum Insured: _____ Excess: _____

Make of Veh:	D.O.A.	22.12.2017
--------------	--------	------------

(Client's Record)

H.O.D. Enforcement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 11/11 Confirmed with Final Fig , days (Red \$ / %; Original 8 days)

Date/Time: 17/9/18 Submit Final Fig LS \$3000, 5 days (Red \$ 3500 / 54 %; Original days)

[illegible]

Para(1) : Parts found not replaced	(To highlight <i>R or UB, LR, Etc</i>)
------------------------------------	---

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)
--

Para(3) : Nett Value

Market Value : _____	Inspected/ Evaluated by: _____	Fee Charged:	Date:
Salvage Value : _____		Basic & Add	150
Nett Value : _____		Transport	_____
		Photos	_____
		Others	_____
		Total	150

1) Date/Time <u>17/9-1998</u> File Pass to _____	2) Date/Time _____ File Return to _____
3) Date/Time _____ File Pass to _____	4) Date/Time _____ File Return to _____
5) Date/Time _____ File Pass to _____	6) Date/Time _____ File Return to _____

Nivitha (LKK Auto)

From: Xin Yi <xinyi@seahong.com.sg>
Sent: Thursday, 30 August 2018 11:48 AM
To: 'Catherine Chong (LKK Auto)'
Cc: Chee Kiong; 'samson'; 'amanda'
Subject: SKZ 2009X [Our file ref: 18.24959 PD-O]
Attachments: TP LOD.pdf

Dear Catherine,

CLAIMANT : **ONG HUI HUA**
VEHICLE NUMBER : **SKZ 2009X**
ALLEGED ACCIDENT DATE : **22 DECEMBER 2017**
AXA VEHICLE NUMBER : **YK 5508R**

We act for AXA Insurance Pte Ltd for the above matter.

We understand that you were engaged to survey the claimant's vehicle.

The claimant has issued their LOD and their surveyor's report is attached. A copy is enclosed.

Please let us hear from you on the following: -

- a. If you have conducted post-repair inspection already, please let us have your survey report urgently.
- b. If you have not conducted post-repair inspection, please let us arrange for inspection with the claimant's solicitor and let us have your survey report in due course.

May we hear from you on the above soonest.

Thanks & Best Regards

Heng Xinyi

(Secretary to Mr Tan Chee Kiong)

Seah Ong & Partners LLP

36 Robinson Road

#12-03 City House

Singapore 068877

Tel: 6536 5369

Fax: 6536 5811

This message is intended for the recipient named above. It may contain confidential or privileged information. If you are not the intended recipient, please notify the sender immediately by replying to this message and then delete it from your system. Do not read, copy, use or circulate this communication. Thank you.

Disclaimer: Internet communications are not secure. While every reasonable effort has been made to ensure that this communication has not been tampered with, Seah Ong & Partners LLP cannot be responsible for alterations made to the contents of this message without its express consent. If you wish to receive a hard copy of this message for comparison or should you require any other form of confirmation of the contents of this message, please contact the sender. Opinions, conclusions and other information in this message that do not relate to the official business of the company shall be understood as neither given nor endorsed by Seah Ong & Partners LLP.

12/03/2007

ASS. REC. BY:

REF:

CS3/AXA 70211635/R11621

Special Instruction:

Surveyor:

Grant claim

ASSIGNMENT (Office)

From (Person):

Vale On

of

AXA

Date/Time:

26/12/2017 11:39am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SKZ 2009X

Insured:

YK 5508R

at Workshop m/s

N-51 Automotive

Tel:

68112 0051

of

2 Kaki Bukit Ave 2 #01-17

Policy No:

Claim No:

S7MD0615

Sum Insured:

Excess:

Make of Veh:

D.O.A.

23/12/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time:

28.12.2017

Person Contacted:

Hui Xin

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SKZ 2009X - X
	YK 5508R - X
	Dismantle Part: 29.12.2017
	After repair: 03.01.2018
200118 1:21pm	Email to Vale On they Grant claim

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

3019508306
60105655

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALI D/O MUNIANDY
SEGA PARAM
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
TAY HAO RAN
JANICE HAN JIA LIN
TAN YINGXIAN EELWYN

Unique Entity Number: 200721148H

✓Head Office:
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413
Branch:
490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490
Branch:
133 New Bridge Road
#10-03 Chinatown Point
Singapore 059413

HEAD OFFICE:
TEL : (65) 65342811 (Hunting)
FAX : (65) 65356802 (General)

E-MAIL: annatan@visionlawllc.com

BRANCH
TEL : (65) 63580703
TEL : (65) 65330868

BRANCH
TEL : (65) 65342811 (Hunting)
TEL : (65) 65330869

WHEN REPLYING PLEASE QUOTE OUR REFERENCE - Please reply to HEAD OFFICE for this

Our Ref : AKN-atv-Ins-T140-107384-18
Your Ref : YK 5508 R

Date: 24 August 2018

AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way
#27-01 AXA Tower
Singapore 068811
Attn: Motor Claims Department

BUILDFORMS CONSTRUCTION PTE LTD
432 Tagore Industrial Avenue
Sindo Industrial Estate
Singapore 787811

URGENT

WITHOUT PREJUDICE
BY HAND



CERTIFICATE OF POSTING
[For your information only]

Dear Sir,

CLAIMANT : ONG HUI HUA
ACCIDENT INVOLVING SKZ 2009 X & YK 5508 R ON 22-DEC-2017 ALONG HOUGANG AVENUE 3 TOWARDS EUNOS LINK AT ABOUT 0920HOURS

We are instructed by the above named to claim damages against you/your insured in connection with a road traffic accident on **22-DEC-2017 ALONG HOUGANG AVENUE 3 TOWARDS EUNOS LINK AT ABOUT 0920HOURS** involving our client's vehicle registration number **SKZ 2009 X** and vehicle registration number **YK 5508 R** driven by you/your insured at the material time.

We are instructed that the accident was caused by you/your insured's negligent driving and /or management of your your insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

01.	Cost of Repair	\$6,955.00
02.	Rental fees	\$1,080.00
03.	Survey report fees	\$ 716.00
04.	GIA & LTA search / report fees	\$ 43.98
05.	Cost Contribution (at this stage)	\$1,605.00
06.	Disbursements (at this stage)	\$ 50.00
TOTAL		\$10,449.98



.../2 to be continued next page

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

VISION LAW LLC

Advocates & Solicitors

Page 2

Our Ref : AKN-atv-Ins-T140-107384-18

Your Ref : YK 5508 R

Date: 24 August 2018

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Department

BUILDFORMS CONSTRUCTION PTE LTD

432 Tagore Industrial Avenue

Sindo Industrial Estate

Singapore 787811

We enclose a copy of each of the following documents for your consideration:-

- (a) GIA report lodged by driver of SKZ 2009 X;
 - (b) LTANet Search;
 - (c) Certificate of Insurance;
 - (d) Registration Card;
 - (e) Rental agreement, rental invoice & rental receipt;
 - (f) Final Repair Bill;
 - (g) Surveyor's report & invoice; and
 - (h) 80 coloured photographs depicting the damages to motor vehicle SKZ 2009 X.
- (P.S:- Original photographs will be sent to insurance co. only)

The demand herein is in respect of our client's claim for damages pertaining to his motor vehicle and any settlement following or subsequent to this demand shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer. Our client's claim herein is quantified based on supporting documents in our file. Until a settlement is reached, all negotiations are conducted on the basis that the damages quantified herein are subject to revision if so instructed by our client.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully



(HEAD OFFICE)

Enc.

cc: client: Ong Hui Hua

As per your instruction we have submitted your claim as set out above to the third party insurance company. Please do notify us if there is any discrepancy, if any, particularly, the number of days claimed for rental charges and/or loss of use as soon as possible. Thank you.

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0357-18-TCA

02 July 2018

Ong Hui Hua
Blk 712 Tampines St 71 #11-150
Singapore 520712

INVOICE No. 0357-18-TCA

Vehicle No. SKZ2009X

<u>S/NO</u>	<u>SERVICES RENDERED</u>	<u>Amount due</u>
1	Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).	\$716.00
Total amount payable		<u>\$716.00</u>

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy



Report No: 0357-18-TCA

02 July 2018

ACCIDENT VEHICLE SURVEY REPORT

Ong Hui Hua
Blk 712 Tampines St 71 #11-150
Singapore 520712

VEHICLE INFORMATION:

Vehicle Reg No.:	SKZ2009X	Odometer:	29785km
Make & Model:	Hyundai Elantra 1.6AT	Colour:	Silver
Chassis number:	KMHDH41CMGU656804	Date of accident:	22/12/2017
Year of Regn.:	13/01/2016	Date inspected:	28/12/2017
Repairer at:	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	Date inspected (After Repair):	04/01/2018

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	6mm/Hankook	6mm/Hankook	195/65R15
Rear:	6mm/Hankook	6mm/Hankook	195/65R15

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
REAR BOOTLID	1	buckled	1,188.00	1,188.00
REAR BOOTLID 'ELANTRA' EMBLEM	1	necessary	49.00	49.00
REAR BOOTLID 'GLS' EMBLEM	1	necessary	26.00	26.00
REAR BOOTLID 'LOGO' EMBLEM	1	necessary	26.00	26.00
REAR BOOTLID HINGES L/R	2	repair	278.00	0.00
REAR BOOTLID INNER UPHOLSTERY TRIM	1	reuse	85.00	0.00 <i>an</i>
REAR BOOTLID MECHANISM LOCK	1	bent	158.00	158.00
REAR BOOTLID NUMBER PLATE LAMP L/R	2	fractured	58.00	58.00
REAR BOOTLID OUTER LOCK HANDLE SWITCH COVER	1	reuse	28.00	0.00
REAR BOOTLID REFLECTOR LAMP BACK RUBBER GASKET L/R	2	necessary	478.00	478.00 <i>Xan</i>
REAR BOOTLID REFLECTOR LAMP CLIPS L/R	8	necessary	52.00	52.00 <i>Xan</i>
REAR BOOTLID REFLECTOR LAMP L/R	2	fractured	598.00	598.00 <i>Xsue</i>
REAR BOOTLID REVERSE CAMERA COVER	1	reuse	58.00	0.00 <i>an</i>
REAR BOOTLID RUBBER GUIDE STOPPER	4	deformed	32.00	32.00
REAR BOOTLID WEATHERSTRIP	1	deformed	79.00	79.00
REAR BUMPER	1	squashed	459.00	459.00
REAR BUMPER INNER SIDE SHIELD L/R	2	reuse	112.00	0.00 <i>an</i>
REAR BUMPER LOWER DIFFUSER	1	deformed	250.00	250.00
REAR BUMPER REFLECTOR L/R	2	fractured	70.00	70.00 <i>Xsue</i>
REAR BUMPER REINFORCEMENT	1	bent	303.00	303.00
REAR BUMPER REINFORCEMENT BRACKET L/R	2	bent	82.00	82.00 <i>Xsue</i>
REAR BUMPER REINFORCEMENT LOWER BRACKET	3	bent	75.00	75.00 <i>Xsue</i>
REAR BUMPER REINFORCEMENT TOP BRACKET L/R	2	bent	50.00	50.00 <i>Xsue</i>
REAR BUMPER SIDE RETAINER L/R	2	necessary	52.00	52.00
REAR END PANEL	1	buckled	385.00	385.00 <i>repair</i>
REAR END PANEL INNER TOP GARNISH	1	fractured	59.00	59.00
REAR END PANEL INNER TOP GARNISH CLIPS	4	necessary	26.00	26.00
REAR END PANEL LOCK STRIKER	1	bent	19.00	19.00 <i>Xsue</i>
REAR EXHAUST RUBBER MOUNTING	2	reuse	56.00	0.00 <i>an</i>
REAR EXHAUST SILENCER BOX	1	reuse	793.00	0.00 <i>an</i>
REAR FENDER INNER UPHOLSTERY TRIM L/R	2	reuse	344.00	0.00 <i>an</i>
REAR TAILLAMP CLIPS L/R	8	necessary	52.00	52.00 <i>Xan</i>
REAR TAILLAMP INNER PANEL L/R	2	repair	344.00	0.00
REAR TAILLAMP L/R	2	fractured	724.00	724.00 <i>Xsue</i>
UPHOLSTERY BOARD	1	reuse	220.00	0.00
Subtotal before discount			S\$ 7,668.00	S\$ 5,350.00 <i>2765</i>
Percentage discount 20% and 20%			S\$ 1,533.60	S\$ 1,070.00 <i>20%</i>
Sub-total 1			S\$ 6,134.40	S\$ 4,280.00 <i>2212</i>

REAR BOOTLID INNER UPHOLSTERY TRIM CLIPS - SET	1	necessary	30.00	30.00
REAR BOOTLID NUMBER PLATE	1	reuse	25.00	0.00
REAR BOOTLID NUMBER PLATE HOLDER	1	reuse	50.00	0.00
REAR BUMPER CLIPS - SET	1	necessary	50.00	50.00
REAR BUMPER INNER SIDE SHIELD CLIPS - SET	1	necessary	30.00	30.00
REAR BUMPER REVERSE SENSOR - SET	1	shorted	350.00	350.00
REAR FENDER INNER UPHOLSTERY TRIM CLIPS L/R - SET	2	necessary	60.00	60.00
SPARE TYRE PANEL INSULATOR MAT	1	necessary	350.00	350.00

Subtotal before discount S\$ 945.00 S\$ 870.00

Sub-total 2 S\$ 945.00 S\$ 870.00

Parts-total S\$ 7,079.40 S\$ 5,150.00

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

120.00 60.00

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

140.00 60.00

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

1,500.00 1,200.00

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

160.00 0.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

1,500.00 1,100.00

To apply anti-rust chemical on repaired and replaced panel.

120.00 60.00

Labour Total S\$ 3,540.00 S\$ 2,480.00

Parts & Labour Total S\$ 10,619.40 S\$ 7,630.00

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : S\$ 6,500.00 and the recommended number of working days for the repairs is within 8 day(s).

B J Loi (I Eng., MIM, AIRTE)
Automotive Appraiser

2212
310
1230
3752
202
3001.60
43-3,000
5 days

Tax Invoice/Receipt

Receipt No. : ITNET-00000-171222-001612

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - YK5508R				
As at 22 Dec 2017/09:20:00				
Insurance Co: AXA INSURANCE PTE LTD				
1	Insurance Enquiry - YK5508R Enquiry Fee 20171222160212742702	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
Paid By				
	xxxxxxxxxxxx2392	Credit Card: Visa/MasterCard		7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

TWINCAR RENTAL

Business Registration Number : 53092815M

Blk 2 Kaki Bukit Avenue 2 #01-17 Kaki Bukit Autohub, Singapore 417921

Tel: 68420051 Fax : 67410510 email: sales@n51.com.sg

Invoice To :

ONG HUI HUA
BLK 712 TAMPINES ST 71
#11-150
SINGAPORE 520712

INVOICE

Invoice No. 13-2075

Date 4/1/2018

		Hirer's Car No.	VHA No.	Terms
		SKZ2009X	71541	CASH
No. of Day	Description	Per Day	Amount (S\$)	
9	Car Rental from the period of 26/12/2017 to 04/01/2018. Vehicle no. SLP4051A Singapore Dollars One Thousand and Eighty Only	120.00	1,080.00	
		Total	\$1,080.00	

TWINCAR RENTAL



Authorised Signature



TWINCAR RENTAL

Kaki Bukit Autohub @ 2 Kaki Bukit Ave. 2 #01-18
Singapore 417921 Tel: 6744 0510 / 6842 0051

2009 VHA No: 71541
2009 (7C)

ROC NO. 53092815M

VEHICLE RENTAL AGREEMENT

HIRER'S PARTICULAR

Name: (as in I/C) ONG HUI HUA
NRIC/PASSPORT No: S 76/09/26
Address (Res): BLK 7D TAMPINES ST 71
#16-150 S(5207D)
Name & Address of Employer: _____

Occupation: _____ Driving Exp: _____
Driving Licence No: _____ D/L Type: Local / International
Pass Date: _____ Date of Birth: 12/04/1978
Tel: (O) _____ (F) 878 5511 HP 9632 2583


ADDITIONAL DRIVER'S PARTICULARS

Name: (as in I/C) ONG Kim CHIONG
NRIC/PASSPORT No: S 04/7928A
Address (Res): BLK 251 HOUKANG AVE 3
#13-372 S(530251)
Driving Licence No: S04A78A D/L Type: Local / International
Pass Date: 05/08/1992 Date of Birth: 10/07/1951
Occupation: _____ Driving Exp: _____

VEHICLE CHECKLIST

INDICATE:
D - DENTS
S - SCRATCHES

A - ACCIDENTS



ACCESSORIES CHECK

☐ Ashtray ☐ Cig Lighter ☐ S/Tyre
☐ STD Tools ☐ Jack ☐ Hub Caps
☐ Radio / Cass ☐ CD ☐ Cartridges

Vehicle No: SF4051A Replace Veh No: _____
Mileage Out: _____ Mileage Out: _____
Make & Model: Toyota Aygo Auto / Manual
Group: _____
OUT: Date 26/12/17 Time: 11:45am
HIRE/PERIOD EXPIRY
NON-WAIVER EXCESS: 500

CHARGES

Daily	@ \$ 120	per day 9	1080	00
Weekly	@ \$	per week		
Monthly	@ \$	per month		
Hours	@ \$	per hour		
Others	@ \$			
CDW	@ \$	per day/month		
PAI	@ \$	per day/month		
Delivery Service				
SUB-TOTAL \$				

PETROL LEVEL

Out	E	1/4	1/2	3/4	F	
In	E	1/4	1/2	3/4	F	

EXTENSION

Collection Service		
Misc.		
TOTAL CHARGE \$		

Rented out by: _____

Hirer's Signature 


Addition Driver's Signature 

I have read and agree to the terms & condition on both sides of this agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given TWINCAR RENTAL in connection with this Agreement is true.

* IMPORTANT

- ONLY PERSONS ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER, AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN, AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY, AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY TWINCAR RENTAL.

RETURN OF VEHICLE - THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER / DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO TWINCAR RENTAL AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	SIGNATURE OF HIRER/DRIVER
04/01/2018	11:00HRS				

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 0912E

Vehicle Details

Vehicle No.: SKZ2009X
Vehicle to be Exported: No
Intended De-registration Date: 22 Dec 2017
Vehicle Make: HYUNDAI
Vehicle Model: ELANTRA 1.6 AT ABS D/AB 2WD 4DR
Primary Colour: Silver
Manufacturing Year: 2015
Engine No.: G4FGFU069492
Chassis No.: KMHDH41CMGU656804
Maximum Power Output: 97.0 kW (130 bhp)
Open Market Value: \$12,773.00
Original Registration Date: 13 Jan 2016
First Registration Date: 13 Jan 2016
Transfer Count: 0
Actual ARF Paid: \$12,773.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 12 Jan 2026
PARF Rebate Amount: \$9,579.00

Intended COE Rebate Details

COE Expiry Date: 12 Jan 2026
COE Category: A - Car up to 1600cc & 97kW (130bhp)





Certificate of Insurance

**MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1967 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)**

Cert No./Policy No. : D17MTPV01000696
1. Registration No. : SKZ2009X
2. Insured Name : ONG HUI HUA
3. Commencement Date : 13 JANUARY 2017 00:00
4. Expiry Date : 12 JANUARY 2018 23:59
5. Coverage : Market value at time of loss - Comprehensive - ExcelDrive PRESTIGE
6. Excess : \$500 - Section I
(Waived up to S\$1,000 Standard Excess each claim at ExcelDrive Workshops for first two claims per policy year)
7. Voluntary Excess : N/A

8. Persons or Classes of Persons entitled to drive*

a) The Insured,

The Insured may also drive a motor car other than those belonging to or hired (under a hire purchase agreement or otherwise) to him or his employer or his partner.

b) Any other person who is driving on the Insured's order or with his permission.

c) In the event of the death of the insured

i) any member of the Insured's family, or a paid driver who has been driving the car during the life of the insured and permission to drive had not been withdrawn prior to the death of the insured; and

ii) any other person who has been given permission to drive the vehicle prior to the death and such permission had not been withdrawn by the insured.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

9. Limitations as to use*

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover

Use for hire or reward, racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.

10. ExcelDrive Workshops & Accident Reporting

It is a condition precedent to liability that the Policyholder shall, together with the Motor Vehicle, call at the Company's Accident Reporting Center and report the accident within 24 hours of the accident or by the next working day thereof.

It is compulsory to have the accident repairs to the insured vehicle carried out at ExcelDrive Workshops, or at the manufacturer's or distributor's appointed workshop otherwise claim is not payable.

In an emergency and for directions to the Company's Accident Reporting Centers, please contact our Emergency Hotline (65) 6226 3323


Visit www.sompo.com.sg for list of ExcelDrive Workshops and Accident Reporting Centers.

11. Loss of Use

As provided in policy wordings

WE HEREBY CERTIFY that the policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1967 (Malaysia) and (2) the Policy terms, conditions and exclusions of the Private Car Policy ref MTP.26

Sompo Insurance Singapore Pte. Ltd.



Date/Time of Issue: 27 DECEMBER 2016 11:05

*Limitation is not to be interpreted by analogy to the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and section 95 of the Road Transport Act, 1967 (Malaysia), and not to be included under these headings

IMPORTANT NOTICE

- Insureds are hereby warned that under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap 189), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.
- Insureds are further warned that on the sale of a motor vehicle or if for any reason the insurance is terminated during its currency, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to that effect must be made. Failure to comply with this regulation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap 189). The Policy will cease to be valid once a motor vehicle has been sold to another person. It is not transferable to a new owner of the vehicle.

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 203714616M

ONG HUI HUA

BLK 712 TAMPINES ST 71 #11-150

SINGAPORE 520712

Contact : 96322583, 97517217 84285511

TAX INVOICE

Date : 17/07/2018

Date in : 26/12/2017

Vehicle Num. : SKZ2009X

Make/Model : HYUNDAI ELANTRA 1.6 AT ABS D/AB 2WD 4DR-2015

Chassis/Eng# : KMHDH41CMGU656804/G4FGFU069492

Accident Date : 22/12/2017

Claim No : CLM13962

Reference : DEC-19/2017

Policy No. : D17MTPV01000696 (12/01/2018)

LUMPSUM REPAIR BILL

AS PER SURVEYOR REPORT

EF : 0357-18-TCA DATED 02/07/2018

BY PAR AUTOMOTIVE CONSULTANCY

Amount S\$

6,500.00

E. & O.E. Sub S\$: 6,500.00

Add GST (7 %) S\$: 455.00

Total Amount S\$: 6,955.00



for TWINCAR AUTOMOTIVE PTE LTD

MSME17168323 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 22/12/2017 16:46
 SUBMITTED BY: Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 22/12/2017 16:46
 Date Of Accident 22/12/2017 09:20
 Exact Location Of Accident HOUGANG AVE 3 TWDS EUNOS LINK BEFORE JUNCTION OF B
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKZ2009X
Insured/Policyholder
 Name Of Registered Owner ONG HUI HUA
 NRIC No S7610912E
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-96322583
 Alternative Phone No OFFICE-96322583

Vehicle Particulars

Manufacturer HYUNDAI
 Model ELANTRA

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company SOMPO INSURANCE SINGAPORE PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number D17MTPV01000696
 Cover Note Number

Driver

Name of Driver ONG KIM CHIONG
 NRIC No S0417978A
 Date Of Birth 10/07/1951
 Occupation INDOOR
 Date Of Driving Pass 05/08/1972
 Driving Experience 45 YEARS AND 4 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-84285511
 Fax Number
 Contact Number
 Email Address NOEMAIL

Address BLK 251 HOUGANG AVE 3 #13-372
 Postcode 530251
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured PARENT
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: PASSENGER
 GENDER: MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS DRIVIN ALONG HOUGANG AVE 3 TWD EUNOS LINK ON THE CENTER LANE OF A 3 LANES ROAD. SOMEWHERE BEFORE THE JUNCTION OF BARTLEY ROAD EAST, I SLOWED DOWN THE SPEED OF MY VEHICLE SLIGHTLY AS I WANTED TO MOVE TO THE RIGHT LAN. HOWEVER, BEFORE I COULD MOVE ON AND MY VEHICLE WAS STILL IN MIDDLE LANE, VEHICLE B CAME FROM THE REAR AND COLLIDED DIRECTLY ONTO THE REAR PORTION OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YK5508R
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



A - SKZ 2009 X
B - YK 5508 R

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Highway Ave 3 towards Ems Lane on the center line, of a 3-lane road. Somewhere before the junction of Ems Rd East, I slowed down the speed of my vehicle slightly as to I started to move to the right lane. However before I could move on and my vehicle was still in middle of my lane (center line), veh (B) came from the rear and collided directly into the rear portion of my vehicle.

A - SKZ 2009 X
B - YK 5508 R

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

TAWNOT

Enquire Vehicle & Owner Information (Vehicle No. YK5508R As At 22 Dec 2017 / 09:20:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: T140-107384-18

Current Owner Details

Owner ID Type: Company
Owner ID: 200701140E
Owner Name: BUILDFORMS CONSTRUCTION (PTE) LTD
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 432
Registered Street Name: TAGORE INDUSTRIAL AVENUE
Registered Unit No.: -
Registered Building Name: SINDO INDUSTRIAL ESTATE
Registered Postal Code: 787811

Current Vehicle Details

Vehicle No.: YK5508R
Make Description/Model: NISSAN / YU41H4
Insurance Company Name: AXA INSURANCE PTE LTD



Thank you


Ng Ching Boon Eric has successfully logged out.

Your last login date and time was 21 Aug 2018, 19:23:19.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No. 	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(S\$)	Log Date/Time
1	Vehicle	YK5508R	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	21 Aug 2018 / 19:23:46



Your Ref: 18.24959 PD-O

Date: 25th Sep 2018

Our Ref: CS3/ASM17024635/R1vbe2-1

M/s AXA Insurance Pte Ltd
C/O: Seah Ong & Partners LLP
36 Robinson Road
#12-03 City House
Singapore 068877
(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKZ 2009X
INSURED VEHICLE: YK 5508R
ACCIDENT DATE: 22/12/2017

We thank you for your instruction on 30/08/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKZ 2009X from M/s Par Automotive Consultancy.
- b) Singapore Accident Statement of Vehicles SKZ 2009X.
- c) Final Repair Bill of SKZ 2009X from M/s Twincar Automotive Pte Ltd.
- d) Colour damaged vehicle photographs of SKZ 2009X.

Pre-Repair Inspection Date : 28/12/2017 at M/s N-51 Automotive Pl, 2 Kaki Bukit Ave 2
#01-17 Kaki Bukit Autohub, Singapore 417921.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -
 - Registration Number : SKZ 2009X
 - Make & Model : Hyundai Elantra 1.6 AT ABS D/AB 2WD 4DR
 - Year of Registration : 2016
 - Chassis Number : KMHDH41CMGU656804
 - Engine Capacity : 1591 cc
2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607196-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 2009X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOTLID	BUCKLED	1,188.00	1,188.00
1	REAR BOOTLID 'ELANTRA' EMBLEM	NECESSARY	49.00	49.00
1	REAR BOOTLID 'GLS' EMBLEM	NECESSARY	26.00	26.00
1	REAR BOOTLID 'LOGO' EMBLEM	NECESSARY	26.00	26.00
2	REAR BOOTLID HINGES L/R	TO REPAIR SEE LABOUR	278.00	-
1	REAR BOOTLID INNER UPHOLSTERY TRIM	NOT NECESSARY	85.00	-
1	REAR BOOTLID MECHANISM LOCK	BENT	158.00	158.00
2	REAR BOOTLID NUMBER PLATE LAMP L/R	FRACTURED	58.00	58.00
1	REAR BOOTLID OUTER LOCK HANDLE SWITCH COVER	REUSE	28.00	-
2	REAR BOOTLID REFLECTOR LAMP BACK RUBBER GASKET L/R	NOT NECESSARY	478.00	-
8	REAR BOOTLID REFLECTOR LAMP CLIPS L/R	NOT NECESSARY	52.00	-
2	REAR BOOTLID REFLECTOR LAMP L/R	SERVICEABLE	598.00	-
1	REAR BOOTLID REVERSE CAMERA COVER	NOT NECESSARY	58.00	-
4	REAR BOOTLID RUBBER GUIDE STOPPER	DEFORMED	32.00	32.00
1	REAR BOOTLID WEATHERSTRIP	DEFORMED	79.00	79.00
1	REAR BUMPER	SQUASHED	459.00	459.00
2	REAR BUMPER INNER SIDE SHIELD L/R	NOT NECESSARY	112.00	-
1	REAR BUMPER LOWER DIFFUSER	DEFORMED	250.00	250.00
2	REAR BUMPER REFLECTOR L/R	SERVICEABLE	70.00	-
1	REAR BUMPER REINFORCEMENT	BENT	303.00	303.00
2	REAR BUMPER REINFORCEMENT BRACKET L/R	SERVICEABLE	82.00	-
3	REAR BUMPER REINFORCEMENT LOWER BRACKET	SERVICEABLE	75.00	-
2	REAR BUMPER REINFORCEMENT TOP BRACKET L/R	SERVICEABLE	50.00	-
2	REAR BUMPER SIDE RETAINER L/R	NECESSARY	52.00	52.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	385.00	-
1	REAR END PANEL INNER TOP GARNISH	FRACTURED	59.00	59.00
4	REAR END PANEL INNER TOP GARNISH CLIPS	NECESSARY	26.00	26.00
1	REAR END PANEL LOCK STRIKER	SERVICEABLE	19.00	-
2	REAR EXHAUST RUBBER MOUNTING	NOT NECESSARY	56.00	-
1	REAR EXHAUST SILENCER BOX	NOT NECESSARY	793.00	-
2	REAR FENDER INNER UPHOLSTERY TRIM L/R	NOT NECESSARY	344.00	-
8	REAR TAILLAMP CLIPS L/R	NOT NECESSARY	52.00	-

Report Ref No. CS3/ASM17024635/R1vbe2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR TAILLAMP INNER PANEL L/R	TO REPAIR SEE LABOUR	344.00	-
2	REAR TAILLAMP L/R	SERVICEABLE	724.00	-
1	UPHOLSTERY BOARD	REUSE	220.00	-
	LESS 20% DISCOUNT		-1,533.60	-553.00
			6,134.40	2,212.00
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BOOTLID INNER UPHOLSTERY TRIM CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR BOOTLID NUMBER PLATE (SN)	NOT NECESSARY	25.00	-
1	REAR BOOTLID NUMBER PLATE HOLDER (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	SET REAR BUMPER INNER SIDE SHIELD CLIPS (SN)	NECESSARY	30.00	30.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	350.00	200.00
2	SET REAR FENDER INNER UPHOLSTERY TRIM CLIPS L/R (SN)	NOT NECESSARY	60.00	-
1	SPARE TYRE PANEL INSULATOR MAT (SN)	NOT NECESSARY	350.00	-
			945.00	310.00
	<u>LABOUR</u>			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR.		120.00	30.00
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET (TO FR)		140.00	60.00
	TO RE-SPRAY PAINTING ON THE REAR BOOTLID, REAR END PANEL, REAR FENDER (L/R), SPARE TYRE PANEL AND REAR BUMPER.		1,500.00	600.00
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.	NOT NECESSARY	160.00	-
	TO PROVIDE LABOUR, WORKMANSHIP, TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR BOOTLID HINGES L/R, REAR END PANEL AND REAR TAILLAMP INNER PANEL L/R.		1,500.00	500.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	40.00
			3,540.00	1,230.00

Report Ref No. CS3/ASM17024635/R1vbe2-1



GRAND TOTAL		10,619.40	3,752.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,000.00

Report Ref No. CS3/ASM17024635/R1vbe2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.