




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS3/EGI18002118/Gvbe2-1		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 13-09-2018		
Code : EGI				
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	XD 1484A	Veh. Inspected	GY 9708T
	Policy No.		Coverage (\$)	0.00
	Claim No.	DSMCV1800239	Excess (\$)	0.00
	Assign From	YEE PEI LI	Assign Date	30/08/2018
2. Vehicle Particulars & Condition				
	Make & Model	ISUZU NHR69E	c.c	3059
	Engine No.	HIDDEN	Year of Reg.	2005
	Chassis No.	JAANHR69E57100292	Colour	WHITE
	Odometer	363409	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	GITI	5 mm
	L/H Front Tyre	195 R15	GITI	5 mm
	R/H Rear Tyre	165 R13	CHAO YANG	5 mm
	L/H Rear Tyre	165 R13	CHAO YANG	5 mm
4. Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information				
	Accident Date	30/01/2018	Inspection Date	11/09/2018
	Survey held at	ACE AUTOLUTION PTE LTD 13 KAKI BUKIT ROAD 4 #03-29 BARTLEY BIZ CENTRE SINGAPORE 417807		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	