



Our Ref :

T 0918 / SHA7316T /WT(st)

Your Ref:

Date

12-Sep-18

CDGE Taxi Claims Dept

59 Loyang Drive 4th Flr

Singapore 508969

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701

> Mainline +65 6383 6280 Facsimilie +65 6280 9755

> > www.cdge.com.sg

Company Registration No: 199506048W

Workshops

Braddell

205 Braddell Road Singapore 579701

Loyang

59 Loyang Drive Singapore 508969

Sin Ming 383 Sin Ming Drive Singapore 575717

Pandan 45 Pandan Road Singapore 609286

320 Ubi Road 3 Singapore 408649

Senoko 24 Senoko Loop Singapore 758156

Sungei Kadut 7 Sungei Kadut Way Singapore 728791

Yishun iun Industrial Park A Singapore 768732

CHINA TAIPING INSURANCE CO LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Attn: Motor Claims Department

WITHOUT PREJUDICE

Dear Sir

ACCIDENT INVOLVING OUR TAXI SHA7316T YOUR INSURED PC 4720Z
AND OTHER ON 03.09.18

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No:

SHA7316T which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving <u>PC 4720Z</u> we are submitting these claims for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	Ψ	2,300.30
2	2 days Loss of Rental @ \$ 109.14 per day	\$	218 28 ishu
3	Survey Report Fees (Surveyed by M/s LKK)	\$	-
4	LTA Search Fees	\$	7.49
5	GIA / Police Report Fees	\$	-
6	Towing / Medical / Transporation Fees	\$	-
O	Sub Total	: \$	2,526.27

HIRER'S CLAIM

We enclose herewith the following documents to support the claims: -

a) Original repair bill and photocopies of photographs :

PC 4720Z

b) LTA search slip/s of :

c) GIA / Police report/s of : SHA7316T

d) Letter of authority from owner / hirer / operator

() Traffic Compound () Towing/Medical bill/receipts () Certificate of Insurance

(X) Photograph/s of Accident Scen (x) Downtime/Mileage record

(x) Rental Rate letter

6

pcs.

2 300 50

0

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully 'William 'Ian

Deputy Manager

CDGE Claims Department

Tel: 6214 8737 Fax: 6214 1843 Email: williamtan@cdge.com.sg

This is a computer generated letter. No signature is required.

A member of









LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING SONATA SHA7316T , PC4720Z

ON 03-Sep-18 07:10

ALONG

CHANGI SOUTH AVE 3 X CHANGI BUSINESS PARK VISTA

I / We

LIM BOON TECK

(Hirer) NRIC No.: **\$1711602I**

and/or

(Relief) NRIC No .:

Taxi Number

SHA7316T

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
- 2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of

"ComfortDelGro Engineering Pte Ltd".

Date

03-Sep-2018

Name of Hirer

LIM BOON TECK

Hirer NRIC

S1711602I

Signature :

Address

121 PAYA LEBAR WAY #02-2867

381121

Contact No.

98007874



A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286

24 Senoko Loop Singapore 758156 7 Sungei Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 768732

COMPANY REG. NO.: 199506048W

Page: 1

8010012

CHINA TAIPING INSURANCE CO (S)PTE LTD SPRINGLEAF TOWER

3 ANSON ROAD #16-00 SINGAPORE 079909

CONTACT NO: 62222366

VEHCLE NO SHA7316T

NO/DATE 91394299 06.09.2018

MAKE HYUNDAI JOB NO. 305207572

MODEL SONATA ODOMETER READING

DATE OF REG 30.06.2011

CHASSIS CODE KMHET41VMBA813551

JOB TYPE

Description: 3P 03.09.2018

Invoice for Lump Sum Repair

Total Lump Sum Repair Amt 7.000 % Add GST @

2,150.00

Total Invoice amount

2,300.50

: CHEWBEELENG 06.09.2018 15:42:43

Issued by : CHEWBEELENG 06.
Repair Type : CLSO/57/57
Payment Type/Term : /Credit 30 days

ComfortDelGro Engineering Pte Ltd A member of COMFORTDELGRO

Head Office: 205 Braddell Road Singapore 579701

AMOUNT BANK/CHQ No. ACCOUNT No. INVOICE No.

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

Our Ref: CT18090029

Date: 06 September 2018



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON

03/09/2018 @ 07:10 hrs

ALONG

CHANGI SOUTH AVE 3 X CHANGI BUSINESS PARK

VISTA

INVOLVING

PC4720Z

We refer to the above-mentioned accident and wish to inform that Comfort Transportation Pte Ltd is the registered owner of the taxi bearing vehicle registration number SHA7316T (the "Taxi"). The Taxi was hired to LIM BOON TECK IC NO S1711602I a registered hirer-operator of Comfort Transportation Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$109.14 per day (inclusive of GST).

Please be advised that the Taxi was insured with MS First Capital Insurance Ltd on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

18 fee faire Mileage Heading Coyang 0720 — Lim Kwok Eng 18 fee fair of the fai		SHA73167		MILEAGE	HOURS OPERATED (TIME	D (TIME)	DATE	NAME
Repair 2 Loyang 0720 — 1630	DATE	NAME OF DRIVER	MILEAGE READING	(KM)	FROM	TO		
Refair.	03/9/18	Azcident 2		Coyang	0720 -	1	Lim Kwok Eng	
	04/9/18	Espan		7)	530		

Insurance Particulars Enquiry By Agents Detail

 $https://vrl.lta.gov.sg/lta/vrl/action/insPartDetailByAA?FUNCTION_...$

Enquire Vehicle Insurer

Vehicle No. Incident Date/Time Search Status Insurance Company Code Insurance Company Name

PC4720Z 03 Sep 2018 / 07:10:00 Successful

C01

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Previous

OK



