

INS CASE OWNER:		vsk		CC 4 ASM		6113, K 1127		LKK		IDAC	
Surveyor:		KENNETH		DOE		ASSIGNMENT		4/9/18		Date / Time:	
Pro-assign / CCU / FTE		SKX 8558 Z		Claim No.		SSMOUJY / 61416		Registered in Meriten:			
Insured Vehicle No.:		SKX 8558 Z		Policy No.:		UPM 11998476		Make / Model:		TAYOTA	
Name of Insured:		TED LEE HIAN		Place of Accident:		PUNJAB DR INFT OAS		Terraces			
Insured Tel No.:		HP: 9675877		D.O.A.:		21/8/18		Nature of Accident:			
Excess Sec II :SS		YES / NO		If NO, Driver Name / Age:		Driver Tel No.:		VIA YES / NO			
Is driver the owner?		YES / NO		OIGIA REPORT YES / NO		TP GIA REPORT YES / NO		Insured Liability:		Final ? Yes / No	
Unknown		SKX 8458 Z		5097K							
INSRS:		INSRS:		INSRS:		INSRS:		INSRS:			
WSP:		WSP:		WSP:		WSP:		WSP:			
Tel:		Tel:		Tel:		Tel:		Tel:			
Liability:		Liability:		Liability:		Liability:		Liability:			
RMKS:		RMKS:		RMKS:		RMKS:		RMKS:			
Date/Time:		6/7/18		VIC		21/8/18		17/1/19			
STAGE		DATE / PIC									
Non-Reporting 1st											
Non-Reporting 2nd											
Non-Reporting 3rd											
Notification 1st (if non-pickup)											
Call Of											
After call 1st to OL											
Documentation Check List:		Handler		Typist							
Notification 1st (if non-pickup)											
After call 1st to OL											
Authorisation To Act											
Release Voucher											
Final Repair Bill											
Car Rental Invoice											
Towing Invoice											
LTA / GIA											
Medical Bill											
PIR											
Mandate/Reject Instruction											
LOD											
Payment Breakdown Form											
Post-Repair Photos											
Others:											
PRELIMINARY ADVICE		Date/Time:		21/8/18		Sent By:		VIC			
FINALIZATION		Date/Time:		Confirm with:		Confirm by:					
Repair Cost:		SS		(days) Reduction:		%		Email		Call	
FINAL SETTLEMENT		Date/Time:		Confirm with:		Email		Call			
Final Liability:		%		(Agreed / Assessed) BOLA S/N No.:		100		If NO or B 28, Ass. Lia:		0%	
Repair Cost		SS 3156.50									
Loss of Rental (LOR):		SS 273.95		3 days x 90.95							
Loss of Use (LOU):		SS -		(5 x days)							
Loss of Income (LOI):		SS -		(5 x days)							
LOR only		LOU only		LOR + LOU		LOR + LOU		[Tick only one]			
GIA/LTA Search:		SS -									
Medical		SS -									
Disbursement:		SS -		(e.g. Tow/ Independent)							
Legal Cost		SS -									
Total:		SS 3429.35		Global Sum SS:							
FINAL PAYMENT		Date/Time:		Confirm with:		Email		Call			
Payee 1:		SS 3429.35		Name 1:		Cheng Hoe Motor Pte Ltd					
Payee 2: (Strike if N.A.)		SS		Name 2:							
Payee 3: (Strike if N.A.)		SS		Name 3:							

ASS. REC. BY:

REF:

AAA /

h

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

816k

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4-9 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STR 5093k

Yr Regn:

06, 09

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 3

c.c

1598

Colour:

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

121720

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JN 8BL 10 ZIA 0104065

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

3.18/18

D.O.I.

12/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

18 File pass to Catherine

315 11/18 8 29501 email

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18016113/hb3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 04-09-2018



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKX 8558Z	Veh. Inspected	SJR 5093K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	04/09/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	31/08/2018	Inspection Date
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SJR 5093 K
 TP/AXA

M/S : AXA INSURANCE (S) PTE LTD
 8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288
 ATTN: Motor Claim Department

FAX: 68804739

Estimate No: ES1891048/YISHUN
 Date: 12 Sep 2018
 Policy No: MT103789
 Veh Reg No: SJR5093K
 Make/Model: MAZDA MAZDA3 1.6L SDN

WS Ref: TP/AXA/YS
 Claim Type: Third Party
 Accident Date: 31/08/2018
 TP Veh Reg No: SKX8558Z

Chassis No: JM6BL10Z1A0104065
 Engine No: Z6794430
 Reg. Date: 26/06/2009

Not Notified
1/1 Sep 8 2950
Recovery After Paint 4 days

Estimate Repair Cost to Vehicle No :SJRS5093K

PAGE:1/1

Description	U/Price	Quantity	List Price SS	Amount SS
List Price				
1 REAR BUMPER	1,049.00	1 PC	1,049.00	✓
2 REAR BUMPER REINFORCEMENT	529.00	1 PC	529.00	✓
3 REAR BUMPER REFLECTORS	59.20	2 PCS	118.40	✓
4 REAR BUMPER CLIPS	4.50	4 PCS	18.00	✓
5 REAR BOOT	1,161.00	1 PC	1,161.00	✓
6 REAR BOOT LOGO	70.90	1 PC	70.90	✓
7 REAR BOOT EMBLEM (MAZDA)	38.70	1 PC	38.70	✓
8 REAR BOOT EMBLEM (3)	27.40	1 PC	27.40	✓
9 REAR BOOT INNER LOCK	177.00	1 PC	177.00	✓
10 REAR CENTRE PANEL	409.00	1 PC	409.00	✓
11 REAR CENTRE PANEL INNER TOP GARNISH	193.30	1 PC	193.30	✓
			3,791.70	
		Less 20%	758.34	3,033.36
Special Net				
12 REAR BUMPER LOWER SKIRT	480.00	1 PC	480.00	✓
13 REAR NUMBER PLATE	35.00	1 PC	35.00	✓
14 REVERSE SENSOR	200.00	1 SET	200.00	✓
			715.00	715.00
Labour				
15 REMOVE & REFIX REAR BUM PER ASSY, TAILLAMPS, REAR BOOT & ATTACHMENT, TO CUT, WELD & RENEW REAR PANEL & REALIGN THE SAME	700.00	1 LA	700.00	600
16 PUTTY & RESPRAY ON REAR PANEL, REAR BUMPER, REINFORCEMENT, BOOT	800.00	1 LA	800.00	650
17 RUSTPROOFING	30.00	1 LA	30.00	✓
			1,530.00	1,530.00
			Total	S\$ 5,278.36
			Add GST @ 7%	369.49
			Total Amount Payable	S\$ 5,647.85

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2643J
Vehicle Details	
Vehicle No.:	SJR5093K
Vehicle to be Exported:	No
Intended De-registration Date:	01 Sep 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 1.6L SDN
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	Z6794430
Chassis No.:	JM6BL10Z1A0104065
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$20,080.00
Original Registration Date:	26 Jun 2009
First Registration Date:	26 Jun 2009
Transfer Count:	0
Actual ARF Paid:	\$20,080.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Jun 2019
PARF Rebate Amount:	\$10,040.00
Intended COE Rebate Details	
COE Expiry Date:	25 Jun 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$12,899.00
COE Rebate Amount:	\$1,053.00
Total Rebate Amount:	\$11,093.00

The information contained herein is correct as at 01 Sep 2018

OK

◀ Service Request Details

Claim

S8M00U1J

Reference

None 

Loss Date

31 August 2018

Request Date

4 September 2018

Due Date

11 September 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

04092018 @ 1.33pm
Effected veh not in.

Actions

Next Step

Agree to perform service

Vehicle Information

Incident Vehicle Registration #

SJR5093K

Make

TPVD MAZDA

Model

MAZDA3 1.6L SDN

Service Address

...

Primary Contact/Insured

TEO CHEE HIAN

BLK 638C PUNGGOL DRIVE, #07-457, 823638, Singapore

96358227

DYLAN.TEO@GMAIL.COM

Claim Handler

OH Vale

6568804897

vale.oh@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)

[New Message](#)



Re:TP MANDATE IA-S8M00U1J


Type

🔍 Question

Message

Hi Pls proceed , tks-VO

Reply



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

Date:

15 JUL 2019

AXA Insurance (S) Pte Ltd
C/O LKK Auto Consultant

Attn : THE MOTOR CLAIMS DEPT

Dear Sir / Madam

**ACCIDENT INVOLVING VEHICLE NO. SJR5093K & SKX8558Z ON 31/08/2018
PUNGGOL DRIVE.**

We are authorized by SJR5093K for their above matter.

Record reveals that you are the insurer of SKX8558Z. We therefore wish to seek compensation from you as below:-

1. Cost of Repairs	S\$ 3156.50
2. Loss of Use (S\$ 90.95 /- x 3 days)	S\$ 272.85
3. Hire of Vehicle	S\$ 0.00
4. LTA Search Fee/GIA Reports	S\$ 0.00
TOTAL	S\$ 3429.35

Please let us have your reply soonest possible.

Thank you.

Yours faithfully



From: Vivian Lau (LKKAUTO)
Sent: Friday, 13 September, 2019 9:01 AM
To: dylan.teo@gmail.com
Cc: Admin A
Subject: ACCIDENT INVOLVING SKX 8558Z & SJR 5093K ALONG PUNGGOL DRIVE ON 31/08/2018

Dear Sir,

OUR REF : CC4/ASM18016113/Kwb3
YOUR REF : SKX 8558Z

ACCIDENT INVOLVING SKX 8558Z & SJR 5093K ALONG PUNGGOL DRIVE ON 31/08/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a third party claim(s) from CHENG HOE MOTOR PTE LTD acting on behalf of the owner of SJR 5093K against your motor insurance policy.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

As Insurers, they shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to AXA and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following to Vivianlau@lkkauto.com within 7 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Copy of the letter of authorization
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to us immediately. You may email it to cst@axa.com.sg or deliver it by hand to AXA Customer Care Centre.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), we shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact as at 6841 8625 or Vivianlau@lkkauto.com. Please quote our claim reference when you contact us that we can assist you more effectively.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

AUTHORIZATION TO ACT

(FOR PROPERTY DAMAGE CLAIM ONLY)

I, Chen Xiaofeng ("the third party claimant")
of Blk 676B Punggol Drive #09-712 S 822676 (address),
owner of SJR5093K (vehicle no.) hereby authorize

CHENG HOE MOTOR PTE LTD

("The workshop") to act for me with respect to my claim for
repair costs and/or rental and/or loss of use ("claim") for my
Vehicle No. SJR5093K that was damaged pursuant to the
accident which occurred on 31/8/2018 (date) along Punggol
Drive (location)


involving Vehicle No/s SKX8558Z

("The accident").


I further authorize the workshop to settle my above mentioned
claim in a manner that they deem fit and the workshop is further
authorized to receive payment further to settlement of my claim
with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach
on my behalf is on a without prejudice and without admission of
liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 31 day of August (month) 20 18 (year)



Signed by "the third party claimant"



Signed by "the workshop"



This Discharge Voucher applies strictly for Claimant's claim for property damages only does not constitute a full discharge for any other claims or further claims whatsoever present or future that may manifest arising directly or indirectly from this accident.

This settlement terms herein is without an admission of liability on the part of the claimant and the settlement terms should not be used as evidence in any related suits or claims arising from this accident.

AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SKX 8558Z (Insd veh)	Model: <u>Mercedes</u>
	SJR 5093 (RP veh)	
Date of Accident/ Time:	31/08/2018	

Repair Estimate	: \$	5,647.85
Final Repair Cost	: \$	3,156.50
Loss of Use	: \$	days at \$ per day
Rental (if any)	: \$	272.85 03 days at \$90.95 per day
LTA / GIA Search Fee	: \$	
Others:	: \$	
	: \$	
Final Settlement Sum	: \$	3,429.35
Payee Name: CHENG HOE MOTOR PTE LTD		
Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)		
A)	For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: <u>28</u>
	BOLA Liability: <u>100</u> (%)	Assessed Liability (*): <u>0</u> (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply		
Remarks:		

NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are not received within 7 days of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

Signature of workshop representative / Workshop stamp
Name of Representative: PYU LIAH HUA
Date: 12/9/19

Signature of Witness / Workshop stamp (if applicable)
Name of Witness: Edwin Bie Ma - Ahnman
Date: 12/9/19

Signature of AXA's surveyor / representative:
Name of AXA's surveyor / representative:
Date:

Cheng Hoe Motor Pte Ltd

Bldg 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

TAX INVOICE

M/S : AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP/AXA/YS

Claim Type: Third Party

Accident Date: 31/08/2018

TP Veh Reg No: SKX8558Z

NO: CL8190522
Date: 07 Jun 2019
Policy No: MT103789
Veh Reg No: SJR5093K
Make/Model: MAZDA MAZDA3 1.6L
SDN
Job No: JC1599808

Description

To Supply all replaced parts, all necessary and agreed labour & miscellaneous charges.

(As recommended by your appointed surveyor)

Quantity | List Price

1 PC SS 2,950.00

PAGE:1

Amount

SS

SS 2,950.00

Total

SS 2,950.00

Add GST @ 7%

206.50

Total Amount payable

SS 3,156.50

For Cheng Hoe Motor Pte Ltd



E. & O. E.

AUTHORISED SIGNATURE

38 WOODLANDS IND PARK E1
#05-05, SINGAPORE 757700
TEL : 64595278

GST Reg No. : 53068927L

DATE : 15-Sep-18

E & O.E.

PERFECT DRIVING & SERVICE



38 WOODLANDS IND PARK E1
#05-05 SINGAPORE 757700
(ROC/GST NO. 53068927L)

OPERATING HOURS :
MONDAY TO SATURDAY
(9AM TO 6PM)

Hirer's Name Chen X7ao FENG				Date of Birth		Passport/ Nric No. S8072643J		Nationality	
Address Blk 676 B, Rungat Ave, #09-712				Occupation		Driving License No.		Date Obtained/Expiry	
				Postal Code 822676		Contact No. 81251870		Mobile Phone No.	
Joint Hirer's/Guarantor's Name KANG KAI				Date of Birth 24/12/79		Passport/ Nric No. S7975531A		Nationality SGP	
Address As above				Occupation		Driving License No.		Date Obtained/Expiry 25/8/2006	
				Postal Code		Contact No. 98525522		Mobile Phone No.	
VEHICLE NO. SGY8528U				MODEL 7070A AL703		*Estimated Date For actual return see CHECK IN			
FROM				RETURN					
CHECK OUT		Date 12/9/18	Time 10 am	Mileage KM		E % % % F			
CHECK IN		Date 15/9/18	Time 11.20 am	Mileage KM		Remarks			

- 1) This vehicle is restricted to SINGAPORE use only.
- 2) Only Persons above 26 years of age with more than 2 years driving experience, authorised, licensed and signing this agreement may drive the vehicle.
- 3) The hirer shall be liable to pay the first S\$2000 insurance policy excess for damage to vehicle plus loss of earnings while damaged vehicle is under repairs.
- 4) Third party Liability is the first \$2000.00 in any accident involving Third Party Claims
- 5) Hirer is responsible for all parking fines & traffic summon.
- 6) Vehicle should be returned at the same time as collection except on Saturday where return time is before 12pm
- Hourly extension is charged at 1/5 of the daily rate.
- 8) As preventive maintenance, please check water & engine oil daily.
- 9) For the comfort of other users, please refrain from smoking, eating or carrying of pets in the car. A cleaning charge S\$100 will be imposed for smoky or dirty vehicle.
- 10) Please check that you have not left any of your personal belongings in the vehicle. Our company and staff will not be responsible for any loss of belongings
- 11) The vehicle is NOT covered by a motor insurance policy covering personal accident insurance for the hirer, his passengers or authorised driver
- 12) No replacement of vehicle in any accident

	UNIT		RATE (\$\$)	TOTAL (\$\$)
RATE		@		
DISCOUNT				
GST @ 5%				
TOTAL				
EXTENSION				

CHANGED OVER FROM VEH.	DATE
------------------------	------

1/We declare that all information given on this form is true and accurate.

Hirer's Signature _____

Joint Hirer's/Guarantor's Signature _____

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18016113/Kwb3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:VALE OH

Date : 20-09-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKX 8558Z	Veh. Inspected	SJR 5093K
Policy No.	VPA/P1998436	Coverage (\$)	0.00
Claim No.	S8M00U1J	Excess (\$)	0.00
Assign From		Assign Date	04/09/2018

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3 (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JM6BL10Z1A0104065	Colour	METALLIC PEARL WHITE
Odometer	121720	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm
L/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	31/08/2018	Inspection Date	12/09/2018
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 5093K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (CONSISTENT)	BUCKLED	1,049.00	1,049.00
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	529.00	529.00
2	REAR BUMPER REFLECTORS @\$59.20 (CONSISTENT)	O/S BROKEN / N/S CRACKED	118.40	118.40
4	REAR BUMPER CLIPS @\$4.50 (CONSISTENT)	NECESSARY	18.00	18.00
1	REAR BOOT (CONSISTENT)	BENT	1,161.00	1,161.00
1	REAR BOOT LOGO (CONSISTENT)	NECESSARY	70.90	70.90
1	REAR BOOT EMBLEM (MAZDA) (CONSISTENT)	NECESSARY	38.70	38.70
1	REAR BOOT EMBLEM (3) (CONSISTENT)	NECESSARY	27.40	27.40
1	REAR BOOT INNER LOCK (CONSISTENT)	TO REPAIR SEE LABOUR	177.00	-
1	REAR CENTRE PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	409.00	-
1	REAR CENTRE PANEL INNER TOP GARNISH (CONSISTENT)	SERVICEABLE	193.30	-
	LESS 20% DISCOUNT		-758.34	-602.48
			3,033.36	2,409.92
SPECIAL NETT ITEMS				
1	REAR BUMPER LOWER SKIRT (SN) (CONSISTENT)	SERVICEABLE	480.00	-
1	REAR NUMBER PLATE (SN) (CONSISTENT)	SCRATCHED	35.00	35.00
1	SET REVERSE SENSOR (SN) (CONSISTENT)	SERVICEABLE	200.00	-
			715.00	35.00
LABOUR				
	REMOVE & REFIX REAR BUMPER ASSY, TAILLAMP, REAR BOOT & ATTACHMENT, TO CUT, WELD & RENEW REAR PANEL & REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR BOOT INNER LOCK AND REAR CENTRE PANEL.		700.00	600.00
	PUTTY & RESPRAY ON REAR PANEL, REAR BUMPER, REINFORCEMENT, BOOT.		800.00	650.00
	RUSTPROOFING.		30.00	30.00
			1,530.00	1,280.00
GRAND TOTAL			5,278.36	3,724.92

Report Ref No. CC4/ASM18016113/Kwb3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,950.00
---	--	--	----------

Report Ref No. CC4/ASM18016113/Kwb3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.

Service Request Details

Claim	58M00U1J
Reference	CC4/ASM1801613/Hwb3q2
Loss Date	31 August 2018
Report Date	31 Aug 2018 4:10:00 PM
Request Date	4 March 2019
Due Date	
Vendor Name	LK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step

Wait for Approve Invoice

Add Invoice

Vehicle Information	
Incident Vehicle Registration #	SJRS093K
Make	TPVD MAZDA
Model	MAZDA3 1.6L SDN
Service Address	
...	
Primary Contact/Insured	
TEO CHEE HIAN	
BLK 638C PUNGGOL DRIVE, #07-457, 823638,	
Singapore	
96358227	
DYLAN.TEO@GMAIL.COM	

Claim Handler
OH Vale 656804897 vale.oh@axa.com.sg

Additional Instructions












- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes











Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKInvoice1144.pdf	Invoice	Surveyor/ Assessor expense	LK AUTO CONSULTANTS PTE LTD (TP)	20 September 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 September 2019
 LKKInspection (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 September 2019
 LKKAdjustment1a (7).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 September 2019
 LKK PHOTO-3.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 September 2019
 PAYMENT BREAKDOWN, EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	20 September 2019
 AUTHORIZATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	20 September 2019
 WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	20 September 2019
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	20 September 2019
 TP MANDATE IA-SUB 5093K.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 July 2019
 MARKED ESTIMATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 July 2019
 LKK Inspection Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 July 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 After Repair.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 July 2019
 LKK INSPECTION PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	24 September 2018
 TP AXA IMMEDIATE ADVICE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	24 September 2018
 TP ESTIMATE- MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	17 September 2018
 SX0558Z INSD GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	4 September 2018
 SUR5092K TP GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	4 September 2018
 SH03163C GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	4 September 2018
 TP PRI FROM WORKSHOP.msig	Letters and Correspondence	Workshop	DHAKAL Raghav	4 September 2018
 P1998436_NB_00001_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	OH Vale	3 September 2018
 P1998436_CI_00001_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	OH Vale	3 September 2018