

SS: REC. BY:

REF:

CS / msh 18016137 / Kvbez

Special Instruction:

Survivor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Monica Chung

of

msh

Date/Time:

04092018 358pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKC 2888X

Insured:

SKF 3018T

at Workshop m/s

Cheng Hoe Motor.

Tel:

6481 2001

of

Blk 10 Amk Ind Park 2A #01-04

Policy No:

B27328621SVF

Claim No:

569209

Sum Insured:

Excess:

Make of Veh:

D.O.A.

31082018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

04092018 432pm

Person Contacted:

Dorlyn

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKC 2888X - X

SKF 3018T - X

5/9/18

Send preli revised via merimen

ASS. REC. BY:

REF: *MSG /*

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKC 288X

Yr Regn:

06, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Toy Wish

c.c

1794

Colour:

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

152253

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JT0ER12W503000089

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modl:

NI / S/Rim / STD A/Rim or

Tyre Size:

F:

185/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Continental

Front

R/Bal.

5

mm

Rear

R/Bal.

4

mm

L/Bal.

5

mm

L/Bal.

4

mm

D.O.A.

3/18/18

D.O.I.

4/9/18

Survey held at

Des. of Damages: Frt / *Rear* / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*5/9 File pass to Catherine**16/10 11:24 835501 Customer Effects (Red 206.80, 39%)*

RECEIVED 16 OCT 2018

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

16/10 - typist

Report Format:

Lump Sum / I.B.I: (\$

*merimen**3550*

Days Of Repair:

6

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

150

Transportation:

S + RS. SI

Pintos

Others

TOTAL

160

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Sep 2018		04 Sep 2018 15:58 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS <div style="float: right;">[Created by insurer]</div>									
Insured:	Ed. Zublin Ag, Singapore Branch, Co. Reg. No.: S97FC5352C								
Main Claimant:	ROYSTON WEE CHYE TIAN, ID: S7234241								
Vehicle Reg. No.:	SKC2888X	Date of Loss:	31/08/2018 16:00 - :59 [122 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 569209	Policy/Cover Note No.:	B27328621SVP (Comprehensive) Coverage: 17/05/2018 - 16/05/2019						
Vehicle Reg. No. (Insured):	SKF3018T	Policy No. (Claimant):							
		Excess:	S\$400.00						
Repairer:	Cheng Hoe Motor Pte Ltd (AMK) 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT, 568047 Ang Mo Kio - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 05/09/2018]								
Driver/Custodian (Insured):	PETCHMANEE KORAVIG (47 / Male), NRIC: G5698759U								
Adj Asg. Remarks:	SJE AGREE LKK. LIAB 100%. PLS CONTACT Dorlyn @ 64812001								
ASSOCIATED MAIL RECEIVED <div style="float: right;"> View All Compose Case Mail </div>									
There are no mail for this case.									
ALL ASSOCIATED TASKS <div style="float: right;"> View All Search Tasks Create New Task Complete </div>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Monica Chung Pei Zhen	Date: 05 Sep 2018
<u>Preliminary Advice</u>	

Insured Vehicle No	: SKF3018T	Accident Date	: 31/08/2018
TP Vehicle No	: SKC2888X	Assignment Date	: 04/09/2018
Make	: TOYOTA WISH	Est. Duration of Repair	: 6.00
Date of Inspection	: 04/09/2018		
Inspection At	: CHENG HOE MOTOR PTE LTD (AMK) 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,811.80
Revised Amount	:S\$	4,109.66
Check Items (Estimated)	:S\$	1,228.22
Total	:S\$	5,337.88
Lump Sum Repair	:S\$	
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	4241J

Vehicle Details

Vehicle No.:	SKC2888X
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 AUTO
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	1ZZ3112515
Chassis No.:	JTDER12W503000089
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$18,803.00
Original Registration Date:	20 Jun 2008
First Registration Date:	20 Jun 2008
Transfer Count:	2
Actual ARF Paid:	\$18,803.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	19 Jun 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$18,953.00
COE Rebate Amount:	\$18,173.00

Total Rebate Amount: **\$18,173.00****Message**

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 03 Sep 2018

OK



TOYOTA WISH

Price Range

Depreciation

2008

Vehicle Type

Submit

Advanced Search

Used Car Comparison

--- Comparing 3 Vehicles ---

Toyota Wish 1.8A (COE till 06/2023)



Add to Shortlist

Toyota Wish 1.8A (COE till 06/2023)



Add to Shortlist

Toyota Wish 1.8A X (COE till 06/2023)



Add to Shortlist



Use search bar above to search to compare.

Clear All

Add all to Shortlist

Back to search result

CAR DETAILS

Price	\$34,800	\$34,800	\$34,800	-
Instalment	N.A.	N.A.	N.A.	-
Registration Date	13-Jun-2008	25-Jun-2008	25-Jun-2008	-
Manufactured	2008	2008	2008	-
Mileage	130,000 km	-	153,000 km	-
Transmission	Auto	Auto	Auto	-
Engine Cap	1,794 cc	1,794 cc	1,794 cc	-
Road Tax	\$972 /yr	\$972 /yr	\$972 /yr	-
Power	97.0 kW (130 bhp)	97.0 kW (130 bhp)	97.0 kW (130 bhp)	-
Curb Weight	1,310 kg	1,310 kg	1,300 kg	-
Features	Reliable, Powerful And Fuel Efficient Toyota VVT-i Engine, Dual Airbags, Foldable Side Mirrors, Foldable Rear Seats For Bigger Boot.	Powerful And Reliable 16 Valves VVT-i DOHC Engine, Smooth 4 Speed Steptronic Gearbox. Digital Climate Control Aircon. Airbags. ABS. 7 Seaters.	Powerful And Reliable 16 Valves VVT-i DOHC Engine, Smooth 4 Speed Steptronic Gearbox. Digital Climate Control Aircon. Airbags. ABS. 7 Seaters.	-
Accessories	Borneo Motor Unit. Original Sporty Grey Paintwork. Very Well Maintained Black Leather Seats, CD Player, Sports Rims.	Sports Rims. DVD Player. Reverse Sensors, Solar Film, Armrest, Leather Upholstery. Knockdown Rear Seats.	Sports Rims. Leather Upholstery, Reverse Camera, Solar Film, Knockdown Rear Seats Etc.	-
Description	Borneo Motor Unit! Wow! Check This Out! Low Mileage Done, You Got View To Appreciate It's Condition, Ideal For COE Renewal, Well Maintained By Careful Owner, Original Paintwork That Still Looks Great, Extremely Clean Interior, Leather Good Condition, Serviced Regularly Every 10k Km Without Fail, Good Size MPV To Fit A Family With Kids, Appointment To View Please.	Down Payment \$2800! Lowest Monthly \$688 Onwards. Low Interest At 3.68% Per Annum By GV Cars Financing. 100% Loan Approval. 2 Years Warranty And Servicing By GV In House Workshop. New Fully Pure Leather Seats And New \$2k Metallic Paint Color Of Your Choice! 1 To 1 Exchange Without Cash Top Up! No Gimmick! Walk In Or Call Our Hotline Now For More Information.	New Road Tax! New 5 Years COE! Fuel Efficient! Loan Available/Trade In Welcome! Call For Viewing.	-
COE	\$18,953	\$18,953	\$18,953	-
OMV	\$18,803	\$18,803	\$17,350	-
ARF	\$18,803	\$18,803	\$12,975	-
Depreciation	\$7,290 /yr	\$7,240 /yr	\$7,240 /yr	-
No. of Owners	2	2	3	-
Type of Vehicle	MPV	MPV	MPV	-
Category	COE Car	COE Car, Premium Ad Car	COE Car	-
Availability	Available	Available	Available	-
Remarks	COE expiry date 2023-06-24	COE expiry date 2023-06-24	COE expiry date 2023-06-24	-

SELLER INFORMATION

Seller	Cars Connect	GV Credit Pte Ltd	Automobile Connection	-
Address	7 Kaki Bukit Road 1 #03-05	233/235/237/239/241 Telok Kurau Road	1 Brooke Road #B1-04	-
Office Number	-	63443344	64555218	-
Contact Person	-	-	-	-

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	03/09/2018 13:32
Date Of Accident	31/08/2018 16:45
Exact Location Of Accident	AYE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKC2888X
Insured/Policyholder	
Name Of Registered Owner	ROYSTON WEE CHYE TIAN
NRIC No	S7234241J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90092222
Alternative Phone No	OTHERS-90092222
Vehicle Particulars	
Manufacturer	TOYOTA
Model	WISH-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3066551801
Cover Note Number	20/06/2018 - 19/06/2019
Driver	
Name of Driver	WEE CHENG YONG @ WEE WINSTON
NRIC No	S0268053Z
Date Of Birth	19/10/1944
Occupation	INDOOR
Date Of Driving Pass	23/06/1964
Driving Experience	54 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90092222
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	6 INDUS ROAD #11-03
Postcode	169588
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PARENT
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	AFTER RAIN
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I FOLLOW FRONT VEHICLES TO STOP. MOTOR CAR SKF3018T COULDNT STOP IN TIME AND HIT ONTO THE REAR OF MY VEHICLE. NO ONE WAS INJURED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKF3018T
Vehicle Make/Model/Colour	FORD
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KORARIG (JOE)
NRIC/Passport Number	G5698759U
Contact Number	92971791
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

VEHICLE NO.: SKC 2888X
INSURER : Ching
DATE & TIME: 31/08/2018 @ 1645

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

3 Sept. 2018

Reporting Centre Personnel's Signature
Name: Devlyn Tan
NRIC/FIN No.:

03/09/18

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle No: SKC2888X (China)

Date & Time: 31/08/2018 @ 1645 (after rain/wet)

I follow front vehicles to stop. Motor car SKF 30187 couldn't stop in time and hit onto the rear of my vehicle. No one was injured.

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 3 Sept. 2018

Reporting Centre Personnel's Signature
Name: (AWK)
NRIC/FIN No.:

IGARMC SketchPlanForm_v2 () Claim Own Policy () Claim Third Party () Reporting Only
() Claim OD/TP at other workshop ()

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO 201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/AMK

Claim Type: Third Party

Accident Date: 31/08/2018

TP Veh Reg No: SKF3018T

Estimate No: ES1891011/AMK

Date: 04 Sep 2018

Policy No: DMPCSN3066551801

Veh Reg No: SKC2888X

Make/Model: TOYOTA WISH 1.8 A

Chassis No: JTDER12W503000089

Engine No: 1ZZ3112515

Reg. Date: 20/06/2008

Estimate Repair Cost to Vehicle No :SKC2888X

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 REAR BUMPER	551.60	1 PC	551.60	—
2 REAR BUMPER SIDE RETAINER	67.80	2 PC	135.60	—
3 REAR BUMPER CLIP	3.89	5 PC	19.45	—
4 REAR BUMPER LH REINFORCEMENT BRACKET	89.77	1 PC	89.77	—
5 REAR TAILGATE	1,372.60	1 PC	1,372.60	—
6 TAILGATE INNER LOCK	490.40	1 PC	490.40	—
7 TAILGATE INNER RUBBER	372.30	1 PC	372.30	—
8 TAILGATE EMBLEM 'AERO TOURER'	35.49	1 PC	35.49	—
9 TAILGATE WINDSCREEN GLASS MOULDING	70.20	1 PC	70.20	—
10 TAILLAMP	528.73	2 PC	1,057.46	—
11 REAR END PANEL	498.60	1 PC	498.60	—
12 REAR END PANEL INNER TOP GARNISH	295.60	1 PC	295.60	—
			4,989.07	
		Less 25%	1,247.27	3,741.80
Special Net				
13 REVERSE SENSOR	200.00	1 SET	200.00	—
14 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	—
			240.00	240.00
Labour				
15 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	—
16 REMOVE & REFIX REAR BUMPER, TAILGATE & ATTACHMENTS, TAILLAMPS; TO CUT, WELD & RENEW REAR END PANEL; KNOCKING & REPAIR REAR FENDERS, REAR LUGGAGE PANEL & REALIGN THE SAME	800.00	1 LA	800.00	—
17 PUTTY & RESPRAY REAR BUMPER, TAILGATE, BOTH FENDERS, REAR END PANEL, REAR LUGGAGE PANEL & ALL AFFECTED AREAS	850.00	1 LA	850.00	—
18 RUSTPROOFING	60.00	1 LA	60.00	—
			1,830.00	1,830.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO 201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660 FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/AMK

Claim Type: Third Party

Accident Date: 31/08/2018

TP Veh Reg No: SKF3018T

Estimate No: ES1891011/AMK

Date: 04 Sep 2018

Policy No: DMPCSN3066551801

Veh Reg No: **SKC2888X**

Make/Model: TOYOTA WISH 1.8 A

Chassis No: JTDER12W503000089

Engine No: 1ZZ3112515

Reg. Date: 20/06/2008

Estimate Repair Cost to Vehicle No :SKC2888X

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
			Total	S\$ 5,811.80
			Add GST @ 7%	406.83
			Total Amount Payable	S\$ 6,218.63

VEHICLE LYING AT :
NO.10 ANG MO KIO INDUSTRIAL PARK 2A
#01-04 AMK AUTOPOINT
SINGAPORE 568047
TEL : 64812001

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Sep 2018		04 Sep 2018 15:58 Edit Adj Rpt	S\$3,550.00 Edit Estimates	S\$3,550.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: Ed. Zublin Ag, Singapore Branch , Co. Reg. No.: S97FC5352C									
Main Claimant: ROYSTON WEE CHYE TIAN , ID: S7234241J									
Vehicle Reg. No.: SKC2888X		Date of Loss: 31/08/2018 16:00 - :59 [122 Months and 11 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 569209		Policy/Cover Note No.: B27328621SVP (Comprehensive) Coverage: 17/05/2018 - 16/05/2019							
Vehicle Reg. No. (Insured): SKF3018T		Policy No. (Claimant):							
		Excess: S\$400.00							
Repairer: Cheng Hoe Motor Pte Ltd (AMK) 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT, 568047 Ang Mo Kio - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 04/10/2018]									
Driver/Custodian (Insured): PETCHMANEE KORAVIG (47 / Male) , NRIC: G5698759U									
Adj Asg. Remarks: SJE AGREE LKK. LIAB 100%. PLS CONTACT Dorlyn @ 64812001									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKC2888X (569209)
[SKF3018T]
TP
ROYSTON WEE CHYE TIAN
Aug 31 2018 4:00PM
[Ed. Zublin Ag, Singapore Branch]
Cheng Hoe Motor Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/09/18 12:22	Adjuster Immediate Advice		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/09/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
2	05/09/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
3	05/09/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
4	05/09/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
5	05/09/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
6	05/09/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
7	05/09/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
8	05/09/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
9	05/09/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
10	05/09/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
11	05/09/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
12	05/09/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
13	05/09/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
14	05/09/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
15	05/09/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
16	05/09/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
17	05/09/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
18	16/10/18 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
19	16/10/18 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
20	16/10/18 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
21	16/10/18 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
22	16/10/18 14:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	04/09/18 12:31	OI ACCIDENT REPORT		Load PDF	
2	04/09/18 12:31	Third Party Accident Report		Load PDF	
3	04/09/18 12:31	SJE AGREE LKK		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18016137/KVBE2

Date: 18/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B27328621SVP

Claimant Vehicle No: SKC2888X

Insured Vehicle No: SKF3018T

Date of Loss: 31/08/2018

Nature of Claim: TP

Claim No: 569209

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKC2888X

Make & Model: TOYOTA WISH, 1.8 (A)

Engine No: 1ZZ3112515

Reg. Date: 20/06/2008 (Man. Year: 2008)

Chassis No: JTDER12W503000089

Colour: Metallic Silver

Odometer: 152253 km

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Continental 5 mm

Rear Left Side: Continental 4 mm

Front Right Side: Continental 5 mm

Rear Right Side: Continental 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,981.80	2,977.45	1,004.35	25.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,830.00	1,500.00	330.00	18.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,811.80	4,477.45	1,334.35	22.96
Approved Total (Overridden) (S\$)		3,550.00		
(S\$)	5,811.80	3,550.00	2,261.80	38.92
+ GST 7.00/7.00% (S\$)	406.83	248.50	158.33	38.92
Nett Amount (S\$)	6,218.63	3,798.50	2,420.13	38.92

INSPECTION

Date of Assignment: 04/09/2018

Date Inspected: 04/09/2018 Inspected At:

Cheng Hoe Motor Pte Ltd (AMK)
10 ANG MO KIO IND PARK 2A, #01-04
ANG MO KIO AUTOPOINT
Singapore 568047

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Oct 2018)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKC2888X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	551.60 FL	*551.60 FL
2	1		*REAR BUMPER SIDE RETAINER	N/S Distorted	135.60 FL	*67.80 FL
3	5		*REAR BUMPER CLIP	Necessary	19.45 FL	*19.45 FL
4	1		*REAR BUMPER LH REINFORCEMENT BRACKET	Repair	89.77 FL	*- FL
5	1		*REAR TAILGATE	Bent	1,372.60 FL	*1,372.60 FL
6	1		*TAILGATE INNER LOCK	Dented	490.40 FL	*490.40 FL
7	1		*TAILGATE INNER RUBBER (\$372.30) (50%)	Cut	279.22 FS	*186.15 FS
8	1		*TAILGATE EMBLEM AERO TOURER	Necessary	35.49 FL	*35.49 FL
9	1		*TAILGATE WINDSCREEN GLASS MOULDING	Necessary	70.20 FL	*70.20 FL
10	2		*TAILLAMP	Serviceable	1,057.46 FL	*- FL
11	1		*REAR END PANEL	Bent	498.60 FL	*498.60 FL
12	1		*REAR END PANEL INNER TOP GARNISH	Dented	295.60 FL	*295.60 FL
13	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
14	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,135.99	3,827.89
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,154.19	850.44
Total Parts (\$\$)	3,981.80	2,977.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX REAR BUMPER, TAILGATE & ATTACHMENTS, TAILLAMPS; TO CUT, WELD & RENEW REAR END PANEL; KNOCKING & REPAIR REAR FENDERS, REAR LUGGAGE PANEL & REALIGN THE SAME	New	800.00	600.00
3	PUTTY & RESPRAY REAR BUMPER, TAILGATE, BOTH FENDERS, REAR END PANEL, REAR LUGGAGE PANEL & ALL AFFECTED AREAS	New	850.00	720.00
4	RUSTPROOFING	New	60.00	60.00
Gross Labour Cost (S\$)			1,830.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >