

ASS. REC. BY:

REF: CS/CT18016140/T1tda⁷² Special Instruction:Surveyor/
menmenTaufik
Elaine Cheong

ASSIGNMENT (Office)

of CT1

Date/Time: 30/8/18 @ 1:42pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJS 9090L

Insured:

GZ 52154

at Workshop m/s

Borneo Motor

Tel:

9742 7757

of

2 Pandan Crescent

Policy No:

DMCVSN 1416431804

Claim No:

SNM18P04214C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/08/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

30/8/18 @ 4:30pm

Person Contacted:

Joe

Vehicle IN / OUT

OUT

Date/Time

Action/Instruction (✓) Estimate

30/8/18-

Nobody answer at all

31/8/18-

Nobody answer at all also.

4/9/18 -

called again he said VNF.

SJS 9090L - CS/EG17004909/T1tbe 2

DOA: 8/3/17

GZ52154-X

Tamper

REP

CT1

30.01.2018

From _____ Date _____
 Estimated Cost _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No _____
 at Workshop m/s _____
 of _____
 Insured _____
 Policy No _____
 Claims No _____
 Sum Insured _____ Excess _____
 (Client's Record)
 Make of Veh _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Joe.

Veh No: 8559090L Vt Regn: 2011, July
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota m/s
 Colour: Blue
 Sp. Reading: 96141
 Eng/No: MRO 53 REE104119830
 C/No: _____
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/65R15
 R: _____

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 6/9/18e 1230
 Survey held at: Govind Pandey
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Part my Part \$3835.42 (Red: 1728.50: 31%)

RECEIVED 12 OCT 2018

Order/Time File Pass to:

to P110 Typist
 Date/Time File Return to:

☐ Prel. Report
☒ Final Report

Days Of Repair: 4

Resurvey No. of Trip: -

Survey Fee:
 Transportation

Add Fee: ☐ Site Insp. \$
☐ Interview \$
☐ Daily Insp \$
☐ Material \$

Report Format:

Lump Sum / L.B. \$

TP
 383542

220




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CS/CTI18016140/T1td3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 04-09-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GZ 5215U	Veh. Inspected	SJS 9090L	
Policy No.	DMCVSN1416431804	Coverage (\$)	0.00	
Claim No.	SNM18D04214C02	Excess (\$)	0.00	
Assign From	MERIMEN (ELAINE CHEONG)	Assign Date	04/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/08/2018	Inspection Date	06/09/2018	
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Aug 2018		30 Aug 2018 13:42 Assign				New Assignment Cancel Case

Main		Reference		Claim Details		Documents		Show All	
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ELIGIBLE TEAMS PTE LTD, Co. Reg. No.: 200306303D								
Main Claimant:	NAH KOK LEONG, ID: S7721963C								
Vehicle Reg. No.:	SJS9090L			Date of Loss:	28/08/2018 21:00 - :59				
Claim Type:	TP / SNM18D04214C02			Policy/Cover Note No.:	DMCVSN1416431804 (TP, Fire & Theft)				
Vehicle Reg. No. (Insured):	GZ5215U			Policy No. (Claimant):	CN003059				
				Excess:	S\$0.00				
Repairer:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 10/09/2018]								
Driver/Custodian (Insured):	ONG CHEE TAT(WANG JIDA) (38 / Female), NRIC: S7936454A, Tel: +6590253524								
Adj Asg. Remarks:	EST \$5953.39, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAuto)

From: Joe Tan SMTC <Joe.Tan@borneomotors.com.sg>
Sent: Friday, 12 October 2018 1:04 PM
To: Denise Tay (LKKAuto)
Subject: Re: SJS9090L TP CLAIM FOR FINALIZATION

Noted, with thanks

Best regards,
Joe Tan.

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: 12 October 2018 12:11
To: Joe Tan SMTC; SUR
Subject: RE: SJS9090L TP CLAIM FOR FINALIZATION

Dear Joe,

Confirm final figure at \$3835.42, 4days

Please submit all documents to China Taiping

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Friday, 21 September 2018 4:18 PM
To: Joe Tan SMTC <Joe.Tan@borneomotors.com.sg>; SUR <sur@lkkauto.com>
Subject: FW: SJS9090L TP CLAIM FOR FINALIZATION

Dear Denise,

FYNA-CS/CTI18016140/T1td3

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/08/2018 10:52
Date Of Accident	28/08/2018 21:00
Exact Location Of Accident	ATTAP VALLEY RD TURNING LEFT TO ADMIRALTY RD WEST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS9090L
Insured/Policyholder	
Name Of Registered Owner	NAH KOK LEONG
NRIC No	S7721963C
Email Address	NAHKL77@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90909950
Alternative Phone No	OFFICE-92722268

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	CN003059
Cover Note Number	

Driver

Name of Driver	CHONG MON TING
NRIC No	S7585737C
Date Of Birth	17/10/1975
Occupation	INDOOR
Date Of Driving Pass	29/04/2006
Driving Experience	12 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-92722268
Fax Number	
Contact Number	
Email Address	NAHKL77@GMAIL.COM

Address	BLK 75B REDHILL ROAD #27-70
Postcode	152075
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : NAH KOK LEONG GENDER: : MALE
Passenger 2	NAME: : NAH PEI EN, ALOYSIUS GENDER: : MALE
Passenger 3	NAME: : NAH JENG YUEN, ALAYNIE GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GZ5215U
Vehicle Make/Model/Colour	CABSTAR / SILVER
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ONG CHEE TAT(WANG JIDA)
NRIC/Passport Number	S7936454A
Contact Number	90253524

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

TYPE OF CLAIM: ☐ OD ☐ OD/UL ☒ DS

MCA: JOE TAN

MOTOR ACCIDENT REPORT

Date Of Report: 29/08/18 Time: 08:00 Date Of Accident: 28/08/18 Time: 21:00
 Exact Location Of Accident: Atap Valley Rd turning left to Admiralty Road West
 Country/State of Loss: Singapore ☒ / Wilayah Persekutuan ☐ / Selangor Darul Ehsan ☐ / Negeri Sembilan ☐ / Melaka ☐ / Pahang ☐ /

OWN VEHICLE DETAILS (INSURED/POLICY HOLDER)

Vehicle Registration Number: SJ59090L Co. Reg. No(for Co. Vehicle)/NRIC/PP/FIN No: S7721963C
 Name Of Registered Owner: NAH FOK LEONG
 Mobile Number: 90909950 Alternative No: Email Address: nahkl77@gmail.com

Vehicle Particulars

Manufacturer: Toyota ☒ Lexus ☐ Suzuki ☐ Hino ☐ Model: AG715
 Exact Purpose for which vehicle was being used at time of accident: Normal Usage ☒ Other ☐ (please specify):
 Are you claiming under your own insurance policy for repair to your vehicle? Yes ☐ Reporting Only ☐ Third Party ☒
 Vehicle Category: Private Car ☒ Commercial Vehicle ☐ Others ☐

Insurance Company

Name of Insurance Company: AXA
 Type Of Coverage: Comprehensive ☒ Third Party ☐ Third Party Fire and/or Theft ☐
 Fleet Policy: Yes ☐ No ☒ Policy / Cover Note No: P1633971

DRIVER DETAILS AT POINT OF ACCIDENT

Name of Driver: CHONG NON TWE NRIC/ Passport / FIN No: S7585787C
 Date Of Birth: 17/10/75 Occupation: Indoor ☒ Outdoor ☐
 Date Of Driving Pass: 29/04/06 Gender: Male ☐ Female ☒
 Mobile Number: 92722268 / 90909950 Fax No: Alternative No:
 Address: Blk 75B, Redhill Rd. # 27-70 Postal Code: 152075
 Email Address: nahkl77@gmail.com
 Was driver an employee of the Insured's Company? Yes ☐ No ☒ State relationship of the driver with the insured: Wife
 Vehicle Registration Number of Driver's Own Vehicle (if applicable):
 Insurance Company of Driver's Own Vehicle (if applicable):

GENERAL INFORMATION OF THE ACCIDENT

Type Of Accident: Rear Collision
 Number of Passengers in the above vehicle (Including Driver): 4 / If more than 2 Pax Please fill ANNEX B

PASSENGER 1

Name: NAH FOK LEONG Gender: Male ☒ Female ☐
 Weather Conditions: Clear ☒ Raining ☐ Others ☐ (If others, please state condition):
 Road Surface: Wet ☐ Dry ☒ Others ☐ (If others, please state condition):
 Was any body injured in the Accident? No ☒ Yes ☐
 Was any injured conveyed to hospital by ambulance? No ☒ Yes ☐
 Was any foreign vehicle involved in this accident? No ☒ Yes ☐ Vehicle No: Vehicle type:
 Number of vehicles involved in the accident: 2
 Was there any witness? No ☒ Yes ☐ If yes, please furnish witness details column below
 Witness Name: | Contact No.: | Email:
 Was there any other vehicle or property damaged? No ☒ Yes ☐
 Was there any video captured by Car Camera? No ☐ Yes ☒ Are accident scene photos available for attachment? No ☐ Yes ☒
 Was the accident reported to the police? No ☒ Yes ☐ (If yes, please state which Police Station):
 Was notice of intended Prosecution given? No ☒ Yes ☐ (If yes, please state against whom):
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. No ☒ Yes ☐

DETAILS OF OTHER VEHICLE PROPERTY 1 (Please fill Annex A if more vehicles involved)

Vehicle Registration Number: GZ 5215U Vehicle Make/Model/Colour: Cabstar / Silver
 Details Of Properties Damage in Accident:
 Vehicle Category: Lorry
 Name of Driver: ONG CHEE TAT (Wang Jida)
 NRIC/Passport/FIN Number: S7936454A Contact Number: 90253524 Postal Code:
 Address:
 Insurance Company Name:
 Nature Of Damage: No. Of Passenger (Including Driver):

PASSENGER 2

Name: *Wah Pei En, Aloysius*Gender: Male ☒ Female ☐

PASSENGER 3

Name: *HAN Jeng Yuen, Alayne*Gender: Male ☐ Female ☒

PASSENGER 4

Name:

Gender: Male ☐ Female ☐

PASSENGER 5

Name:

Gender: Male ☐ Female ☐

PASSENGER 6

Name:

Gender: Male ☐ Female ☐

PASSENGER 7

Name:

Gender: Male ☐ Female ☐

PASSENGER 8

Name:

Gender: Male ☐ Female ☐

PASSENGER 9

Name:

Gender: Male ☐ Female ☐

PASSENGER 10

Name:

Gender: Male ☐ Female ☐

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:


(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")


- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

 29/08/18
08:00am
Policyholder's Signature / Date & Time

 29/8/18
08:00am
Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan




Describe Circumstances of the Accident

My Car SJS9090L was travelling along Hap Valley Road. At stop line, stopped to await clearance for left turn to Admiralty Road West. During waiting, was suddenly hit onto rear bumper by lorry GZ 5215 U.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

 29/08/18
08.06am

Driver's Signature (If driver is not the policyholder) / Date & Time

 29/08/18
08.50am

Witnessed by Reporting Centre Personnel



AXA INSURANCE PTE LTD

8 Shenton Way, #24-01
AXA Tower, Singapore 068811
Customer Service Centre #B1-01
Tel: 6338 7288 Fax: 6338 2522
Website: www.axa.com.sg
GST Registration Number: 199903512M



Original

Agent Code: 04069

Policy No.(If any): P1633971

Renewal

SmartDrive Quote Ref:

MOTOR COVER NOTE

No. CN003059

- The Motor Vehicle (Third Party Risks and Compensation) Act (Cap 189) - Republic of Singapore; or
- The Road Transport Act 1987 of Malaysia; or
- The Agreement between the Minister of Finance (Singapore) and the Motor Insurers' Bureau of Singapore dated 22 February 1975; or
- The Agreement between the Minister for Transport (Malaysia) and the Motor Insurers' Bureau of West Malaysia dated 30 March 1992;
- And any subsequent revisions to the above Acts and Agreements

The Insured mentioned in the Schedule, having proposed for insurance in respect of the Motor Vehicle described in the Schedule, is hereby HELD COVERED under the terms of the Company's usual form of Motor Policy applicable thereto for the period mentioned in the Schedule unless the cover be terminated by the Company by notice in writing in which case the insurance will thereupon cease and a proportionate part of the annual premium otherwise payable for such insurance will be charged for the time the Company has been on risk.

SCHEDULE

THE COMPANY	AXA INSURANCE PTE LTD
INSURED	NAH KOK LEONG
MAKE AND DESCRIPTION OF VEHICLE	TOYOTA COROLLA ALTIS 1.6 AUTO
VEHICLE REGISTRATION NO.	SJS9090L
YEAR OF MANUFACTURE	2011
ENGINE NO.	1ZR106422
CHASSIS NO.	MR053REE304119830
ENGINE CAPACITY/TONNAGE	1598 CC
COVER TYPE	COMPREHENSIVE
HIRE PURCHASE	DBS BANK LTD
VALUE (S\$)	AS PER MARKET VALUE
PERIOD OF INSURANCE	FROM: 15/07/2018 TO: 14/07/2019
EXCESS (S\$)	\$300
AXA PREMIUM WORKSHOP?	NO

(WE HEREBY CERTIFY THAT POLICY TO WHICH THIS CERTIFICATE RELATES IS ISSUED IN ACCORDANCE WITH THE PROVISIONS OF THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) ACT (CHAPTER 189) AND PART IV OF THE ROAD TRANSPORT ACT 1987 (MALAYSIA).

AXA INSURANCE PTE LTD

Issued by META AGENCY PTE LTD on 28/06/2018 3:55 pm

Authorised Signature

- Note:** This Cover Note is only valid for 60 days from the date of issue unless replaced by the Certificate of Insurance issued by the Company.
- Premium for time on risk will be charged subject to minimum of S\$53.50 (inclusive of GST), if the policy is cancelled after the inception date.
 - An administrative fee of S\$26.75 (Inclusive of GST) will be charged :
 - Cover note issued and cancelled before inception.
 - Retaining the old registration number for a new vehicle insuring with AXA.

PREMIUM WARRANTY

For Individual Customers:
Please note that the premium in full should be paid before inception date shown above in order for the insurance cover to be valid.
For Non-Individual Customers:
Please note that where the period of cover is for more than 60 days, the premium in full should be paid within 60 days on inception / renewal / endorsement. For all other cases, the premium in full should be paid before inception.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7585737C



Name

CHONG MON TING

張夢婷

Race

CHINESE

Date of birth

17-10-1975

Sex

F

S7585737C

Country/Place of birth

MALAYSIA



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S7585737C

Name

CHONG MON TING

Birth Date 17 Oct 1975

Issue Date 29 Apr 2006



001416178H

5759221



NRIC No. S7585737C



Date of issue

22-06-2017

Address

APT BLK 75B REDHILL ROAD
#27-70
SINGAPORE 152075

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars=<3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg 29 Apr 2006



Licence No. S7585737C

NP 428A

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7721963C



Name

NAH KOK LEONG
(LAN GUOLIANG)

蓝 国 良

Race

CHINESE

Date of birth

12-08-1977

Sex

M

Country of birth

SINGAPORE

S7721963C



4086938

NRIC No. S7721963C



Date of issue

18-08-2007

Address

APT BLK 75B REDHILL ROAD
#27-70
SINGAPORE 152075

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-133050
Date of Request: 29/08/2018

Your Ref No: Online Purchase

Borneo Motors (S) Pte Ltd
33 Leng Kee Road
Singapore 159096

Dear Sir/Madam,

Enquiry Date: 29/08/2018
Enquiry By: Angela Tan Hong Choo
TP Vehicle No.: GZ5215U
Accident Date: 28/08/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GZ5215U	China Taiping Insurance (Singapore) Pte. Ltd.	02/06/2018-01/06/2019	6389 6111

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-133050
Date of Request: 29/08/2018

Your Ref No: Online Purchase

Borneo Motors (S) Pte Ltd
33 Leng Kee Road
Singapore 159096

Dear Sir/Madam,

Enquiry Date 29/08/2018
Enquiry By Angela Tan Hong Choo
TP Vehicle No. GZ5215U
Accident Date 28/08/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyotasingapore.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

TP CLAIM

ESTIMATE

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Nah Kok Leong (Lan Guoliang) 75B Redhill Road #27-70 Singapore 152075 Mobile: 90909950
	Document No 0	
	Document Date 29/08/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
11	GEPEKT	S1	ZRE141R	15/07/2011	SJS9090L	0	34689 84/TP/SJS9090L
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REE104119830	1ZRX106422	60	Joe Tan Joo Seng	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP CLAIM ACC DATE:28/08/18 TOW/DRIVE IN: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				100.00
2	B	BP-LAB TO CHECK WIRING AND LIGHT FUNCTIONING AND CARRY OUT WATER LEAK TEST.				104.72
3	B	BP-ECU TO RESET ECU AND REPROGRAMME				154.00
4	B	BP-LAB TO DRILL HOLE AND RE-INSTALL REAR SENSOR				154.00
5	B	BP-LAB TO REMOVE ALL NECESSARY DAMAGED PARTS, REPLACE AND REPAIR REAR BUMPER, END PANEL AND AFFECTED REAR PORTION OF CAR.	616			1232 1848.00
6	B	BP-RES TO SPRAY PAINT ON DAMAGED AFFECTED REAR PORTION OF CAR.	504			1012 1518.00
7	1	S52159-02710 COVER, RR BUMPER	1.00	546.10		546.10
8	2	S52155-02120 R/R SIDE BPR SUPPORT,	1.00	71.70		71.70
9	3	S52157-02050 R/R SIDE BPR RETAINER,	1.00	34.10		34.10
10	4	S52562-02120 RETAINER, RR BUMPER,	1.00	79.40		79.40

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3766985

TO SECURITY GUARD

3766985

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES:DATE 29/08/2018
TIME 11:51

VEHICLE NO SJS9090L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyotasingsapore.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Nah Kok Leong (Lan Guoliang) 75B Redhill Road #27-70 Singapore 152075 Mobile: 90909950
	Document No	
	Document Date	
	0	
	29/08/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
11	GEPEKT S1	ZRE141R	15/07/2011	SJS9090L	0	34689	84/TP/SJS9090L
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REE104119830	1ZRX106422	60	Joe Tan Joo Seng	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	5	S52563-02100 RETAINER, RR BUMPER,	1.00	79.40		✓ 79.40
12	6	S52156-02110 L/R SIDE BPR SUPPORT,	1.00	71.70		✓ 71.70
13	7	S52158-02040 L/R SIDE BPR RETAINER,	1.00	34.00		✓ 34.00
14	8	S52615-02110 REAR BUMPER ABSORBER,	1.00	127.20		✓ 127.20
15	9	S52015-02090 REAR BUMPER ARM ARM,	2.00	90.00		✓ 180.00
16	0	S52161-OK040 PIECE, RR BUMPER	10.00	4.00		✓ 40.00
17	1	S81910-02230 R/R BPR REFLECTOR ASSY,	1.00	38.50		✓ 38.50
18	2	S81920-02070 L/R BPR REFLECTOR ASSY,	1.00	38.50		✓ 38.50
19	3	S81580-02330 R/REAR BOOT LID LAMP, (FL) ✓	1.00	172.30		✓ 172.30
20	4	S81590-02330 L/REAR BOOT LID LAMP, (FL)	1.00	172.30		✓ 172.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and approved by Insurance Company

Borneo Motors is the only authorised Toyota dealer in Singapore. Your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Acknowledged by Repairer Customer's Signature:	Change Summary	Total	5,563.92
	Please acknowledge receipt of vehicle	Parts	GST 7.00%	389.47
	Date:	Labour	Less	0.00
		Materials		
		Lubrication/Fluid		
		Others		
			Amount Due	5,953.39

PLEASE TEAR ALONG PERFORATED LINE

3766986

3766986

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 29/08/2018
TIME 11:51

VEHICLE NO SJS9090L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

FOR
FINALIZATION
TP CLAIM
ESTIMATE

Borneo Motors (Singapore) Pte Lt

Online Service Booking :
www.toyotasingsapore.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail		Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	Mr Nah Kok Leong (Lan Guoliang) 75B Redhill Road #27-70 Singapore 152075 Mobile: 90909950
		Document No 0	
		Document Date 15/09/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
11	GEPEKT S1	ZRE141R	15/07/2011	SJS9090L	90037	34689	84/TP/SJS9090L
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REE104119830	1ZR106422	60	Joe Tan Joo Seng	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP CLAIM TOW/DRIVE IN:DRIVE DATE-IN:12/09/18 NO OF REPAIR DAYS:04 DAYS BY:LKK-TAUFIKH ACC DATE:28/08/18 DATE SURVEY:06/09/18 AUTHORISED ON:03/09/18				50.00
2	B	BP-LAB TO CHECK WIRING AND LIGHT FUNCTIONING AND CARRY OUT WATER LEAK TEST.				104.72
3	B	BP-ECU TO RESET ECU AND REPROGRAMME				154.00
4	B	BP-LAB TO DRILL HOLE AND RE-INSTALL REAR SENSOR				154.00
5	B	BP-LAB TO REMOVE ALL NECESSARY DAMAGED PARTS, REPLACE AND REPAIR REAR BUMPER, END PANEL AND AFFECTED REAR PORTION OF CAR.				1232.00
6	B	BP-RES TO SPRAY PAINT ON DAMAGED AFFECTED REAR PORTION OF CAR.				1012.00
7	1	S52159-02710 COVER, RR BUMPER	1.00	546.10		546.10
8	2	S52155-02120 SUPPORT, RR BUMPER RH	1.00	71.70		71.70
9	3	S52157-02050 SUPPORT, RR BUMPER RH	1.00	34.10		34.10
10	4	T52562-12120 RETAINER, BUMPER RH	1.00	79.40		79.40

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

3774761

PLEASE TEAR ALONG PERFORATED LINE

3774761

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 15/09/2018
TIME 08:39

VEHICLE NO SJS9090L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingapore.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No S1000003 / ICCI1	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	Document No 0	Mr Nah Kok Leong (Lan Guoliang) 75B Redhill Road #27-70 Singapore 152075 Mobile: 90909950
	Document Date 15/09/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
11	GEPEKT S1	ZRE141R	15/07/2011	SJS9090L	90037	34689	84/TP/SJS9090L
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REE104119830	12RX106422	60	Joe Tan Joo Seng	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	5	S52563-02100 RETAINER, RR BUMPER	1.00	79.40		79.40
12	6	S52156-02110 SUPPORT, RR BUMPER LH	1.00	71.70		71.70
13	7	S52158-02040 SUPPORT, RR BUMPER LH	1.00	34.00		34.00
14	8	S52161-0K040 PIECE, RR BUMPER	10.00	4.00		40.00
15	9	S81580-02330 LAMP ASSY, RR RH	1.00	172.30		172.30

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	3,835.42
	Please acknowledge receipt of vehicle	Parts 1,128.70	GST 7.00%	268.48
		Labour 2,706.72	Less	0.00
		Materials 0.00		
		Lubrication/Fluid 0.00		
		Others 0.00	Amount Due	4,103.90

PLEASE TEAR ALONG PERFORATED LINE

3774762

3774762

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SJS9090L

CUSTOMER

DATE 15/09/2018
TIME 08:39

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Vehicle Diagnostic Report

1ZRFE

SJS9090L

Borneo Motors

Printed By: Default User(1)

9/15/2018 11:32:28 AM

Health Check Results All Systems(1 of 1)

Enhanced

Engine and ECT		No	P1604		X			302Q6100
								A0C01000
EMPS		No	U0100		X			-
Air Conditioner		No	B1421	X				-
		No	B1479		X			-
Cruise Control								-
ABS/VSC/TRC								-
Combination Meter								-
Main Body								-
D-Door Motor								-
Theft Deterrent								-
Immobiliser								-

Vehicle Diagnostic Report

1ZRFE

SJS9090L

Borneo Motors

Printed By: Default User(1)

9/15/2018 11:33:38 AM

Health Check Results All Systems(1 of 1)

Enhanced

[REDACTED]		[REDACTED]				[REDACTED]	
Air Conditioner	No	B1421	X				-
Engine and ECT							302Q6100 A0C01000
Cruise Control							-
ABS/VSC/TRC							-
EMPS							-
Combination Meter							-
Main Body							-
D-Door Motor							-
Theft Deterrent							-
Immobiliser							-

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118016140/T1TD3N2
Date: 15/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1416431804
Claimant Vehicle No :	SJS9090L	Insured Vehicle No :	GZ5215U
Date of Loss:	28/08/2018	Nature of Claim:	TP
		Claim No:	SNM18D04214C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJS9090L	Engine No:	1ZRX106422
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053REE104119830
Reg. Date:	15/07/2011 (Man. Year: 2011)	Odometer:	96141 km
Colour:	Blue		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,785.20	1,178.70	606.50	33.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,778.72	2,656.72	1,122.00	29.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,563.92	3,835.42	1,728.50	31.07
+ GST 7.00/7.00% (S\$)	389.47	268.48	120.99	31.07
Nett Amount (S\$)	5,953.39	4,103.90	1,849.49	31.07

INSPECTION

Date of Assignment:	30/08/2018	
Date Inspected:	06/09/2018	Inspected At:
		Borneo Motors (S) Pte Ltd (Pandan)
		2 Pandan Crescent
		Singapore 128462

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Oct 2018)
 Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SJS9090L)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*COVER,RR BUMPER	Deformed	546.10 FS	*546.10 FS
3	1		*R/R SIDE BPR SUPPORT	Necessary	71.70 FS	*71.70 FS
4	1		*R/R SIDE BPR RETAINER	Necessary	34.10 FS	*34.10 FS
5	1		*RETAINER,RR BUMPER	Necessary	79.40 FS	*79.40 FS
6	1		*RETAINER,RR BUMPER	Necessary	79.40 FS	*79.40 FS
7	1		*L/R SIDE BPR SUPPORT	Necessary	71.70 FS	*71.70 FS
8	1		*L/R SIDE BPR RETAINER	Necessary	34.00 FS	*34.00 FS
9	1		*REAR BUMPER ABSORBER	Not Necessary	127.20 FS	*- FS
10	2		*REAR BUMPER ARM ARM	Not Necessary	180.00 FS	*- FS
11	10		*PIECE,RR BUMPER	Necessary	40.00 FS	*40.00 FS
12	1		*R/R BPR REFLECTOR ASSY	Not Necessary	38.50 FS	*- FS
13	1		*L/R BPR REFLECTOR ASSY	Not Necessary	38.50 FS	*- FS
14	1		*R/REAR BOOT LID LAMP,(FL)	Cracked	172.30 FS	*172.30 FS
15	1		*L/REAR BOOT LID LAMP,(FL)	Not Necessary	172.30 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					1,785.20	1,178.70

Report was unsubmitted during this print-out.

Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND LIGHT FUNCTIONING AND CARRY OUT WATER LEAK TEST	New	104.72	104.72
2	TO RESET ECU AND REPROGRAMME	New	154.00	154.00
3	TO DRILL HOLE AND RE-INSTALL REAR SENSOR	New	154.00	154.00
4	TO REMOVE ALL NECESSARY DAMAGED PARTS,REPLACE AND REPAIR REAR BUMPER,END PANEL AND AFFECTED REAR PORTION OF CAR	New	1,848.00	1,232.00
5	TO SPRAY PAINT ON DAMAGED AFFECTED REAR PORTION OF CAR	New	1,518.00	1,012.00
Gross Labour Cost (\$\$)			3,778.72	2,656.72

Report was unsubmitted during this print-out.

< END OF ESTIMATES >