

23/03/2001

ASS. REC. BY:

REF:

CS3/AIG18016143/Gcd302

Special Instruction:

Surveyor:  
meihmen

Guo Qiang

ASSIGNMENT (Office)

From (Person):

chin lee Ying

of

AIG

Date/Time:

3/9/18 @ 5:34pm

Estimated Cost:

Bill to:

OD ~~TP~~ WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKT 5197Y

Insured:

SKU 738P

at Workshop m/s

SAT MOTORS

Tel:

98599677

of

24 De fu lane 12

Policy No:

2100420193

Claim No:

440732773186

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/08/2018

CA / REV / REP. / REV 24 HRS

1up

19.09.2018 @ after 3pm

H.O.D. Endorsement:

21.09.18 @ after 2pm

Date/Time:

11:01am @ 4/9/18

Person Contacted:

jessie

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SKT 5197Y - CC4/LPC/18016128/ea3

DOA: 24/8/18

SKU 738P - CCA/LPC/18016128/ea3

DOA: 24/8/18

Dismantle: 20/9/2018

PRS  
Simulator

REF: ALH

# ASSIGNMENT

From: Date: 19092018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKT 5197Y

at Workshop m/s SAT Motor

of 24 Defu Lane 12

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SKT5K7Y Yr Regn: 12 Jun 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis C.C. 1598

Colour: silver A/C: Insured / Std / NI / NA

Sp. Reading: 74710 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MK053REH104532116

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S / Rim / STD / A / Rim or

Tyre Size: F: 205/55 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

~~\$1500 - \$1000~~

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

1) Date/Time, File Return to?

2)

Report Format : DAR.

Lump Sum / I.B.I. (\$)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

180

20

200



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18016143/Gcd3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 04-09-2018



Code : AIG

## 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SKU 738P	Veh. Inspected	SKT 5197Y
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	04/09/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	24/08/2018	Inspection Date	19/09/2018
Survey held at	SAT MOTORS 24 DEFU LANE 12 SINGAPORE 539131		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

- PRE-REPAIR INSPECTION OF SKT 7519Y - ACCIDENT INVOLVING OUR INSURED VEHICLE SKU738P AND SKT7519Y ON 24/08/2018 (Our Ref: SM.PRI-SAT.SKT)

From: Chin, Lee-Ying  
To: assignments@lkkauto.com, admin-a@lkkauto.com  
Cc: Fong, Andy-SY  
Sent: Monday, 3 September, 2018 5:34:13 PM  
Attachments:  [AIG-PRI-SAT.MOTORS.PDF](#)

---

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

# K. KRISHNA & PARTNERS

Advocates & Solicitors  
Commissioner for Oaths/Notary Public  
(UEN No. 53131210X)  
GST Registration No. M90371530C  
101 Cecil Street #24-03/04 Tong Eng Building, Singapore 069533  
Tel : 6323 3038 Fax : 6323 2120 (not for service of Court documents)  
E-mail : [kkrishna@singnet.com.sg](mailto:kkrishna@singnet.com.sg)

---

Krishnamoorthi  
LLB (Hons) (London)  
Barrister-at-Law (Gray's Inn)  
B.Sc (Hons) (Est. Man) (S'pore)

S. Manohar  
LLB (Hons) (S'pore)

Vengadesh s/o Kumaravelu  
LLB (Hons)

Our Ref : SM.PRI-SAT- SKT 7519Y(fs)

3<sup>rd</sup> September 2018

**AIG ASIA PACIFIC INSURANCE PTE LTD**

**Attention: Motor Claims Department**

**IMMEDIATE ATTENTION**  
**FAX ONLY**  
**PRE-REPAIR INSPECTION**

Email : [MohdFitri.Hassim@aig.com](mailto:MohdFitri.Hassim@aig.com)  
[Imran.ishak@aig.com](mailto:Imran.ishak@aig.com)

Dear Sirs

**PRE-REPAIR INSPECTION OF VEHICLE SKT 7519Y**  
**ACCIDENT ON 24.08.2018 INVOLVING SKT 7519Y AND SKU 738P ALONG**  
**SEMPAWANG ROAD**

We act for Mr Ang Kian Li David, the owner of motor vehicle no. **SKT 7519Y** which was involved in the above captioned accident

We are instructed that the accident was caused by the negligence of the rider of motor vehicle no. **SKU 738P**. Our search shows that you are the insurers of motor vehicle no. **SKU 738P**

We are requested to inform you that our client's vehicle is available for pre-repair inspection at the following address :-

**M/S SAT MOTORS**  
24 Defu Lane 12  
Singapore 539131

**K. KRISHNA & PARTNERS**  
Advocates & Solicitors

---

3<sup>rd</sup> September 2018

**AIG ASIA PACIFIC INSURANCE PTE LTD**

---

Please note that our client wishes to appoint their own surveyor to carry out the pre-repair inspection.

Please contact **Ms Jessie Ong of M/s SAT Motors** at his mobile no. **98599677** within **forty-eight (48) hours** from receipt of this fax to arrange for the inspection.

Yours faithfully

A handwritten signature in black ink, appearing to be 'K. Krishna', written over a horizontal line.

cc. workshop - (by fax no. 67491141)

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2415Z
Vehicle Details	
Vehicle No.:	SKT5197Y
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA COROLLA ALTIS 1.6L CVT
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1ZRX506042
Chassis No.:	MR053REH104532116
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,589.00
Original Registration Date:	12 Jun 2015
First Registration Date:	12 Jun 2015
Transfer Count:	1
Actual ARF Paid:	\$14,589.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Jun 2025
PARF Rebate Amount:	\$10,941.00
Intended COE Rebate Details	
COE Expiry Date:	11 Jun 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$67,749.00
COE Rebate Amount:	\$45,573.00
<b>Total Rebate Amount:</b>	<b>\$56,514.00</b>

The information contained herein is correct as at 20 Sep 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	25/08/2018 12:36
Date Of Accident	24/08/2018 13:05
Exact Location Of Accident	ALONG SEMBAWANG ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT5197Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ANG KIAN LI DAVID
NRIC No	S7202415Z
Email Address	DAVID1811972@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-91804348
Alternative Phone No	OTHERS-91804348

### Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z17VP05016216
Cover Note Number	22/01/2017 TO 11/12/2018

### Driver

Name of Driver	ANG KIAN LI DAVID
NRIC No	S7202415Z
Date Of Birth	18/01/1972
Occupation	INDOOR
Date Of Driving Pass	01/03/1996
Driving Experience	22 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91804348
Fax Number	
Contact Number	OTHERS-91804348
EMail Address	DAVID1811972@YAHOO.COM.SG

Address	APT BLK 985B BUANGKOK CRESCENT #07-16 (S) 532985
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER WITH ATTACH.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKU738P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	ANG KIAN LI, DAVID / S7202415Z
Approximate Age	
Injuries Sustain	W P SIM FAMILY CLINIC & SURGERY - 3 DAYS OF MC
Injured person in which vehicle?	SKT5197Y
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

## Accident Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 25/8/2018

C 1135am

Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature


Name:

NRIC/FIN No.:

# Accident Sketch Plan Pg. 1

## SKETCH PLAN

Along  
Sembawang  
Road.



A: SKT5197Y.

B: SKU738P.

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

<p>ON 24/08/18, AT 1305 HOURS, I WAS DRIVING MY VEHICLE, SKT5197Y, ALONG SEMBawang ROAD TOWARDS CHAM PANG. I WAS ON THE MIDDLE LANE, AND WHEN THE TRAFFIC LIGHT TURNS GREEN, I BEGAN TO MAKE MY WAY FORWARD.</p>
<p>SUDDENLY, VEHICLE SKU738P, CAME FROM THE LEFT AND KNOCK ONTO THE FRONT LEFT OF MY VEHICLE. WE CAME DOWN AND NOTICE DAMAGE ON MY FRONT LEFT. WE EXCHANGED PARTICULARS AND PROCEED TO MY WORKSHOP FOR ACCIDENT CLAIM REPAIRING.</p>
<p>AFTER THE INCIDENT, I FELT PAIN ON MY NECK AND I WILL BE CONSULTING MY DOCTOR.</p>
<p>Insurance Co. <u>Lompac</u></p>
<p>Vehicle No. <u>SKT5197Y</u> Date of Accident <u>24.8.2018</u></p>
<p><input type="checkbox"/> Reporting Only</p>
<p><input type="checkbox"/> Own Damage Claim</p>
<p><input checked="" type="checkbox"/> Third Party Claim</p>
<p><input checked="" type="checkbox"/> Other Workshop</p>

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 25/8/2018

1135am

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



# MOTOR CAR (Frt)

## Front Portion

Vehicle No: **SKT 51974**

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	SCR	R	
1005	992341	Frt Bumper Clips			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender	SCR	✓	R
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield	TN	✓	
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

No of Items: **2**

Accessories:

TGum

Wm

24/9/18

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Aug 2018 <a href="#">Edit Reg</a>		03 Sep 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>LAM CHOOI PENG</b> , ID: S2558900I									
Main Claimant: -									
Vehicle Reg. No.: <b>SKT5197T</b>		Date of Loss: 24/08/2018 00:00 - :59 [38 Months and 12 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 4407327731SG</b>		Policy/Cover Note No.: 2100420193 (Comprehensive)							
Vehicle Reg. No. (Insured): <b>SKU738P</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Sat Motors (HQ)</b> 24 Defu Lane 12, 539131 Defu Lane - Tel:									
Handling Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Tan, Bennie-WZ</b> - 6419 1718] Bennie-WZ.Tan@aig.com									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 13/09/2018]									
Claimant's Solicitor: <b>K. Krishna &amp; Partners</b> - Tel: 63233038									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (05/09/2018): Request To Upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;">View All Search Tasks Create New Task Complete</span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SKT5197T (4407327731SG)**  
**[SKU738P]**

TP

-  
**Aug 24 2018 12:00AM**  
**[LAM CHOOI PENG]**  
**Sat Motors**

<a href="#">Upload Documents</a>		<a href="#">Upload Photos</a>	<a href="#">Compose New Letter</a>	<a href="#">Upload Video</a>	<a href="#">Upload Audio</a>	<b>View</b> <a href="#">View in Browser</a> <input type="checkbox"/>	
<b>Assessment Reports</b>						1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)				Thumbnail	Print
1	05/09/18 11:50	<b>Accident Statement</b> <small>From: SC - Reg. No: SKU738P, Claimant: LAM CHOOI PENG</small>				Load HTM	
<b>Photos/Images</b>						3 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	20/09/18 11:30	General View				Load JPG	<input checked="" type="checkbox"/>
2	20/09/18 11:30	General View				Load JPG	<input checked="" type="checkbox"/>
3	20/09/18 11:30	General View				Load JPG	<input checked="" type="checkbox"/>
4	20/09/18 11:30	General View				Load JPG	<input checked="" type="checkbox"/>
5	20/09/18 11:30	General View				Load JPG	<input checked="" type="checkbox"/>
6	20/09/18 11:30	General View				Load JPG	<input checked="" type="checkbox"/>
7	20/09/18 11:30	General View				Load JPG	<input checked="" type="checkbox"/>
8	20/09/18 11:30	General View				Load JPG	<input checked="" type="checkbox"/>
9	20/09/18 11:30	General View				Load JPG	<input checked="" type="checkbox"/>
10	20/09/18 11:30	General View				Load JPG	<input checked="" type="checkbox"/>
11	20/09/18 11:30	General View				Load JPG	<input checked="" type="checkbox"/>
12	20/09/18 11:30	General View				Load JPG	<input checked="" type="checkbox"/>
13	20/09/18 11:30	General View				Load JPG	<input checked="" type="checkbox"/>
14	20/09/18 11:30	General View				Load JPG	<input checked="" type="checkbox"/>
15	20/09/18 11:30	General View				Load JPG	<input checked="" type="checkbox"/>
16	24/09/18 18:26	Photographs of Damaged Parts				Load JPG	<input checked="" type="checkbox"/>
17	24/09/18 18:26	Photographs of Damaged Parts				Load JPG	<input checked="" type="checkbox"/>
18	24/09/18 18:26	Photographs of Damaged Parts				Load JPG	<input checked="" type="checkbox"/>
19	24/09/18 18:26	Photographs of Damaged Parts				Load JPG	<input checked="" type="checkbox"/>
20	24/09/18 18:26	Photographs of Damaged Parts				Load JPG	<input checked="" type="checkbox"/>
21	24/09/18 18:26	Photographs of Damaged Parts				Load JPG	<input checked="" type="checkbox"/>
22	24/09/18 18:26	Photographs of Damaged Parts				Load JPG	<input checked="" type="checkbox"/>
23	24/09/18 18:26	Photographs of Damaged Parts				Load JPG	<input checked="" type="checkbox"/>
24	24/09/18 18:26	Photographs of Damaged Parts				Load JPG	<input checked="" type="checkbox"/>
25	24/09/18 18:26	Photographs of Damaged Parts				Load JPG	<input checked="" type="checkbox"/>
26	24/09/18 18:26	Photographs of Damaged Parts				Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>		<a href="#">Reset</a> <a href="#">Save</a> <a href="#">Print</a>
There are no document checklists configured.		

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18016143/GCD3E2

Date: 27/09/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100420193  
 Claimant Vehicle No: SKT5197T Insured Vehicle No: SKU738P  
 Date of Loss: 24/08/2018 Nature of Claim: TP Claim No: 4407327731SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SKT5197T  
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 L CVT (A) Engine No: 1ZR506042  
 Reg. Date: 12/06/2015 (Man. Year: 2015) Chassis No: MR053REH104532116  
 Colour: Silver Odometer: 74710 km  
 Engine Capacity: 1598 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm  
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 03/09/2018  
 Date Inspected: 19/09/2018 Inspected At: Sat Motors (HQ)  
 24 Defu Lane 12  
 Singapore 539131  
 Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Repair	0.00 F	*- F
2	1		*FRT LH FENDER	Repair	0.00 F	*- F
3	1		*FRT LH FENDER INNER SHIELD	Torn	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >