

ASS. REC. BY:

REF: CS3/AIG18016154/Gods

Special Instruction:

Surveyor
K. Lim

GO

ASSIGNMENT (Office)

From (Person):

chin lee ying

of

AG

Date/Time:

3/9/18 @ 2018 @ 5:27pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLF 529T

Insured:

SLV 7392T

at Workshop m/s:

Neo Automotive

Tel:

9109 5745

of

53 Ubi Ave 1 # 05-44

Policy No:

180009065.

Claim No:

5094845246SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

31/08/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

10:44am @ 4/1/18

Person Contacted:

Mr. Neo

Vehicle

IN/OUT

Date/Time

Action/Instruction (x) Estimate

SLF 529T - NA/INC/18015984/24

DOA: 3/18/18

SLV 7392T - NA/INC/18015984/24

DOA: 3/8/18

After repair: 10/9/2018

DAR1

08/11/13 wof
ASS. REC. HY:

PRS
Xnl

REF: AIG

ASSIGNMENT

From: Date: 11/9/16

Estimated Cost:

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLF 529T
at Workshop m/s: Neo Automotive
of 53 Ubi Ave 1 #05-44

Insured:

Policy No:

Claims No:


Sum Insured: Excess:

(Client's Record)

Make of Veh: Mr. Neo @ 9109 5745

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lump Sum: 20% 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{lump}

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLF529T Yr Regit: 11 Aug 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make: Mazda 2 c.c. 1496

Colour: silver A/C: Insured / Std / NI / NA

Sp. Reading: 109868 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MM6DL 2SAA 6W213355

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 185/65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or NEUTON

Front

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. D.O.I. 04-05-18

Survey held at w/s 5:50pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$1000 + \$2000

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: 3

1)

: Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: : Site Insp (\$)

Transportation:

: Interview (\$)

S + RS, SI

: Tech. Invs (\$)

Photos

: Weekend (\$)

Others

Report Format: DAR

Lump Sum / I.B.I: (\$)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18016154/Gcd3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 04-09-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLV 7392T	Veh. Inspected	SLF 529T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	04/09/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	31/08/2018	Inspection Date	04/09/2018
Survey held at	NEO AUTOMOTIVE- 53 UBI AVE 1 #05-44		
Repairer	-		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
 B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
 THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
 C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLV7392P AND SLF529T ON 31/08/2018

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: Monday, 3 September, 2018 5:27:55 PM
Attachments:  tmpBBF2.tif

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

From: pinky@legaloptions.biz [mailto:pinky@legaloptions.biz]
Sent: Monday, September 03, 2018 3:27 PM
To: Chan, Yoke Shi; lyna@legaloptions.biz
Cc: Tan, Lily (AIG); Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Azlan, Syazairdina
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLV7392P AND SLF529T ON 31/08/2018

Dear Sirs,

Our client rejected your list of surveyor.

We provide you herewith our client's list of surveyor: -

- 1) Ho Joo Loong, Danny
- 2) How Andrew
- 3) Chang Fuh Keong, Dave
- 4) Lee Kok Weng
- 5) Seah Kwang Boon

The said surveyor may contact Mr Neo at 9109 5745, M/s Neo Automotive at 53 Ubi Avenue 1 #05-44, Paya Ubi Industrial Park, Singapore 408934.

*If we do not hear from you within 2 days of this email, our clients shall deem that you have agree that the surveyor appointed by our clients shall be our single joint expert for this matter.

Warmest Regards,

Pinky
M/s Legal Options LLC

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/09/2018 11:40
Date Of Accident	31/08/2018 22:15
Exact Location Of Accident	JUNC WOODLANDS AVE 3 & WOODLANDS AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF529T
Insured/Policyholder	
Name Of Registered Owner	FORTE AUTO LEASING PTE LTD
Co Reg No	201631486C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91449265
Alternative Phone No	OFFICE-91449265

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA2 SEDAN 1.5L SP.6EAT
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5097558305
Cover Note Number	

Driver

Name of Driver	CHEN JUNJIE
NRIC No	S8835794I
Date Of Birth	26/09/1988
Occupation	OUTDOOR
Date Of Driving Pass	02/06/2011
Driving Experience	7 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98896025
Fax Number	
Contact Number	OFFICE-98896025
EMail Address	NOEMAIL

Address	BLK 840 YISHUN STREET 81 #09-376
Postcode	760840
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5

Passenger 1	NAME: : -
	GENDER: : MALE
Passenger 2	NAME: : -
	GENDER: : FEMALE
Passenger 3	NAME: : -
	GENDER: : FEMALE
Passenger 4	NAME: : -
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	YISHUN SOUTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 32 YISHUN ST 81 , POSTCODE: 768456 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8522999 - FAX NO: 68522239
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20180901/2048.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLV7392P
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR
Name of Driver MANE S/O SINIVASAN THUKARAM
NRIC/Passport Number S7007890B
Contact Number 94572858

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver) 2

Passenger 1
NAME: :
GENDER: :

DETAILS OF INJURED PERSON 1

Name CHEN JUNJIE
Approximate Age
Injuries Sustain RIGHT NECK & SHOULDER
Injured person in which vehicle? SLF529T
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN

Woolhouse Ave 3



A: SLF 5297

B: SLV 7392P

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report - 4/2018 0901/2018

[The rest of the form is empty with a diagonal line drawn through it.]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1486C
Vehicle Details	
Vehicle No.:	SLF529T
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Sep 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA2 SEDAN 1.5L SP.6EAT
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	P520367441
Chassis No.:	MM6DL2SAAGW213355
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$15,224.00
Original Registration Date:	11 Aug 2016
First Registration Date:	11 Aug 2016
Transfer Count:	2
Actual ARF Paid:	\$10,224.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Aug 2026
PARF Rebate Amount:	\$7,668.00
Intended COE Rebate Details	
COE Expiry Date:	10 Aug 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,000.00
COE Rebate Amount:	\$42,043.00
Total Rebate Amount:	\$49,711.00

The information contained herein is correct as at 04 Sep 2018

OK

MOTORCAR (Rear)

Rear Portion

Vehicle No: **SLF 529T**

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower	SCR	✓	
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish	DL	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	?		
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	?		
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

No of Items: 5 Assessor: _____

TTC in Min
12/9/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Sep 2018 Edit Reg		03 Sep 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	MANE S/O SINIVASAN THUKARAM , ID: S7007890B, Tel: +6594572858		
Main Claimant:	-		
Vehicle Reg. No.:	SLF529T	Date of Loss:	31/08/2018 00:00 - :59 [24 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 5094845246SG	Policy/Cover Note No.:	180009065 (Comprehensive)
Vehicle Reg. No. (Insured):	SLV7392P	Policy No. (Claimant):	
		Excess:	
Repairer:	- Not Applicable - (-)		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 13/09/2018]		
Claimant's Solicitor:	LEGAL OPTIONS LLC - Tel: 64388039		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG_SG (14/09/2018): **Request To Upload TP GIA Report**
- AIG_SG (05/09/2018): **No Policy Found**

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLF529T (5094845246SG)
[SLV7392P]**

TP

**Aug 31 2018 12:00AM
[MANE S/O SINIVASAN THUKARAM]**

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼	
Assessment Reports			1 per page ▼ <input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	14/09/18 15:42	Accident Statement From:SC - Reg. No: SLV7392P, Claimant: MANE S/O SINIVASAN THUKARAM	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page ▼ <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
2	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
3	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
4	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
5	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
6	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
7	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
8	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
9	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
10	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
11	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
12	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
13	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
14	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
15	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
16	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
17	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
18	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
19	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
20	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
21	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
22	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
23	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
24	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
25	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
26	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
27	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
28	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
29	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
30	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
31	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>
32	04/09/18 19:27	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
33	04/09/18 19:27	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
34	04/09/18 19:27	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
35	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
36	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
37	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
38	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
39	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
40	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
41	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
42	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
43	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
44	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
45	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
46	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
47	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
48	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
49	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
50	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
51	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
52	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
53	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
54	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
55	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
56	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
57	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
58	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
59	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
60	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
61	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
62	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
63	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
64	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
65	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
66	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
67	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
68	24/09/18 14:51	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18016154/GCD3S2
Date: 25/09/2018

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	180009065
Claimant Vehicle No :	SLF529T	Insured Vehicle No :	SLV7392P
Date of Loss:	31/08/2018	Nature of Claim:	TP
		Claim No:	5094845246SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF529T	Engine No:	P520367441
Make & Model:	MAZDA 2, 1.5 SEDAN L SP.6EAT (A)	Chassis No:	MM6DL2SAAGW213355
Reg. Date:	11/08/2016 (Man. Year: 2016)	Odometer:	109868 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	Neuton 6 mm	Rear Left Side:	Neuton 6 mm
Front Right Side:	Neuton 6 mm	Rear Right Side:	Neuton 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	03/09/2018	Inspected At:	NEO AUTOMOTIVE 53 UBI AVE 1 #05-44
Date Inspected:	04/09/2018		
Estimated Period of Repair:	3.0 days		

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Dented	0.00 F	*- F	
2	1		*REAR BUMPER LOWER	Scratched	0.00 F	*- F	
3	1		*REAR END PANEL TOP GARNISH	Dislodged	0.00 F	*- F	
4	1		*REAR LH TAILLAMP	*Check	0.00 F	*- F	
5	1		*REAR RH TAILLAMP	*Check	0.00 F	*- F	
					Total Parts (S\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >