

ASS. REC. BY:

REP CS3/AIG18016166/Ucd3<sup>sz</sup> Special Instruction

Survivor's

ASSIGNMENT (Office)

From (Person)

Chin Lee Ving

of AIG

Date/Time 4/1/18 @ 2:23pm

Estimated Cost

Bill to

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJU 2059P

Insured:

SFM 9891X

at Workshop m/s

JD Motorsports

Tel:

92373644

of

25 Keki Bkt Rd 4 #06-38

Policy No:

2100325036

Claim No:

019510367696

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

31/08/2018

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

5:50pm @ 4/1/18

Person Contacted:

Pennie

Vehicle IN/OUT

OUT

Date/Time

Action/Instruction ( X ) Estimate

SJU 2059P-X

SFM 9891X-CC7/AIG/2003500/Apu.g.2

D.O.A.: 19/2/2012

5/9/18-

VNI

12/9/18-

called wksp veh in (ystrdy).

Dismantle: 13/9/2018

After repair: 17/9/2018

(08/11/13) wef

REF:

Am/

ASS. REC. BY: Marcus

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJU 20597

at Workshop m/s JD mlogul.

of 06-38

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IPAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 11A8323

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SJU 20597 Yr Regn: 11 / 09

Type: Car / M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA1

Make: Hyundai Avante c.c. 1591

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 14227 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KMH0U413M-A4898869

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 155/65R15  
R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. \_\_\_\_\_ D.O.I. 12/9/18

Survey held at \_\_\_\_\_

Des. of Damages: Rear / Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>ask for BIA No further.</u>

Date/Time, File Pass to?  : Preli. Report  
 : Final Report

1) Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:	
Transportation:	
Photos	
Others	
TOTAL	

Add Fee:  : Site Insp (\$ \_\_\_\_\_ )  
 : Interview (\$ \_\_\_\_\_ )  
 : Tech. Invs (\$ \_\_\_\_\_ )  
 : Weekend (\$ \_\_\_\_\_ )

Report Format : DAR.  
Lump Sum / I.B.I: (\$ \_\_\_\_\_ )



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS3/AIG18016166/Ucd3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 04-09-2018	
		Code : AIG	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SFM 9891X	Veh. Inspected	SJU 2059P
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	04/09/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	31/08/2018	Inspection Date	12/09/2018
Survey held at	JD MOTORSPORTS PTE LTD 25 KAKI BUKIT ROAD 4 #06-38 SYNERGY @ KB SINGAPORE 417800		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...**

From: Chin, Lee-Ying  
To: assignments, Admin A  
Cc: Fan, Winnie-LW, Fong, Andy-SY  
Sent: 4/9/2018 2:23:05 PM  
Attachments:  tmp95C4 (3).tif

---

Hi LKK,

Kindly assist to survey.

Thanks.

Regards,  
Lee Ying

---

**From:** natalie\_ng@rssolomon.com [mailto:natalie\_ng@rssolomon.com]

**Sent:** Tuesday, September 04, 2018 12:39 PM

**To:** Chan, Yoke Shi

**Cc:** Tan, Lily (AIG); Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Azlan, Syazairdina

**Subject:** RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SFM9891X AND SJU2059P ON 31/08/2018

Dear Ms Chan,

We refer to your email of even date.

We regret to inform that our client will be engaging her own Surveyors.

In this respect, please contact Mr. Ronnie Tay from JD Motorsports Pte Ltd at mobile no. 92373644 for a pre-repair survey of our client's vehicle located at 25 Kaki Bukit Road 4 #06-38 Synergy @ KB Singapore 417800.

Thank you and Best Regards,

Natalie Ng

For and On behalf of

R. S. Solomon LLC

Advocates & Solicitors

300 Beach Road

#12-03/04 The Concourse

Singapore 199555

---

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	03/09/2018 12:53
Date Of Accident	31/08/2018 18:30
Exact Location Of Accident	ALONG PIE TOWARDS TUAS
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJU2059P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN CHOON HONG
NRIC No	S7625191F
Email Address	WEI_845@OUTLOOK.COM
Mobile Phone No	(LOCAL) +65-98192195
Alternative Phone No	OFFICE-98192195
<b>Vehicle Particulars</b>	
Manufacturer	HYUNDAI
Model	AVANTE 1.6 AT ABS D/AB 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00016373/07
Cover Note Number	30/11/2017-29/11/2018
<b>Driver</b>	
Name of Driver	TAN CHOON HONG
NRIC No	S7625191F
Date Of Birth	24/08/1976
Occupation	INDOOR
Date Of Driving Pass	17/08/1998
Driving Experience	20 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98192195
Fax Number	
Contact Number	OFFICE-98192195
Email Address	WEI_845@OUTLOOK.COM

Address	BLK 126A KIM TIAN ROAD #12-507
Postcode	161126
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

**General Information of the Accident**

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

**Details of Police Action**

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

REFER TO ATTACHMENT

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	SFM9891X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	WONG LEE CHING
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purposes of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Person's Signature  
Name:  
NRIC/IN ID:

SKETCH PLAN

Van A -> SJM 2059 P  
Van B -> SJM 9091X



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


I was driving along RJE towards Tross before Papa letter exit, there was a jam during the time, as the front vehicle slowed down and stopped. I followed to slow down and stopped. Suddenly, I felt a huge impact from the rear. I alighted from my vehicle and realise veh B had hit onto the rear of my vehicle.


You had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a fourteen (14) days clause whereby the claim must be made within the stipulated time frame from the day of occurrence.


Report No. 0-1
417 10
11 2 170
11 2 170 (14) 2014 11 2014 20

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

  
Reporting Person's Signature  
Name  
NR/01/01

## &gt; Back to OneMotoring

## Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SJU2059P		
Vehicle Type :	P10 - Passenger Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	HYUNDAI		
Vehicle Model :	AVANTE 1.6 AT ABS D/AB 2WD 4DR		
Chassis No. :	KMHDU41BMAU898869		
Propellant :	Petrol		
Engine No. :	G4FC9U751044		
Engine Capacity :	1591 cc		
Maximum Power Output :	89.7 kW ( 120 bhp )		
Maximum Laden Weight :	1760 kg		
Unladen Weight :	1264 kg		
Year Of Manufacture :	2009		
Original Registration Date :	24 Nov 2009		
Lifespan Expiry Date :	-		
COE Category :	A - Car (1600cc & below)		
Quota Premium :	\$17,189.00		
COE Expiry Date :	23 Nov 2019		
Road Tax Expiry Date :	23 Nov 2018		
PARF Eligibility Expiry Date :	23 Nov 2019		
Inspection Due Date :	23 Nov 2018		
Intended Transfer Date :	13 Sep 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 23 Nov 2018. You may renew the road tax from 24 Aug 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 23 Nov 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
<b>Amount Payable (From 24 Nov 2018 to 23 May 2019)</b>			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
<b>Sub Total :</b>			<b>25.00</b>
Nett Road Tax Amount (After Offsetting Over Payment) :	369.00	-	369.00
<b>Total Amount Payable :</b>			<b>394.00</b>
<b>Amount Payable (From 24 Nov 2018 to 23 Nov 2019)</b>			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	5191F
<b>Vehicle Details</b>	
Vehicle No.:	SJU2059P
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Sep 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	AVANTE 1.6 AT ABS D/AB 2WD 4DR
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	G4FC9U751044
Chassis No.:	KMHDU41BMAU898869
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,400.00
Original Registration Date:	24 Nov 2009
First Registration Date:	24 Nov 2009
Transfer Count:	0
Actual ARF Paid:	\$11,400.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Nov 2019
PARF Rebate Amount:	\$6,270.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	23 Nov 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$17,189.00
COE Rebate Amount:	\$2,053.00
<b>Total Rebate Amount:</b>	<b>\$8,323.00</b>

The information contained herein is correct as at 13 Sep 2018

OK

**Post an Advertisement**  
 Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Jan 2012 Audi Q7 3.0A TFSI Quattro S-Line @ \$99,800



In House Finance And Low  
 Down Payment From \$10,800  
 Available! Facelift Model!  
 Speedo Motoring StarAd



[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Browse by Category ▼

« Back ( 1 2 ) Next »

Sort b

40 vehicles

Hyundai Avante

Advanc

Make Model Price Depreciation Reg Date Eng Cap Mil

**Search Selection** Hyundai Avante Any Any 2009 Any



**Hyundai Avante 1.6M** \$8,800 \$5,860 /yr 26-May-2009 1,591 cc 12  
 Cheapest In Town, Well Kept, Min Parf \$4736 Lose Only \$400 Plus Per Month, Body Value About \$600, Call For Viewing /  
 Needed Till Scrap, Tires Still Quite New, Cold Aircon, Cheap I...

Posted: 14-Sep-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai



**Hyundai Avante 1.6M (New 5-yr COE)** \$27,300 \$5,460 /yr 14-Apr-2009 1,591 cc  
 Original Condition, Low Mileage, Used As A Second Car And In Excellent Condition, No Repair, New Brakes / Clutch / Tyr  
 Regularly Serviced And Always Parked Under Shelter.

Posted: 13-Sep-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai



**Hyundai Avante 1.6A S** \$11,800 \$7,120 /yr 29-Jul-2009 1,591 cc  
 2 Owners, Efizzig Motor Traders. Roxy Square Carmart Level 5. New Paintwork. Full Reconditioned Engine, Transmission  
 Replaced And Repaired. We Provide In House Loans And Other F...

Posted: 13-Sep-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai



**Hyundai Avante 1.6A S** \$14,800 \$8,060 /yr 29-Oct-2009 1,591 cc

Car Search

Posted: 13-Sep-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai

[Car Buying](#) [Car Selling](#) [Car Ownership](#)  
[Car Aftermarket](#) [On The Move](#) [Lifestyle](#)

Compare: Hyundai Avante 1.6A S (New) \$25,988 \$5,190 /yr 19-Jan-2009 1,591 cc 91

5/14/2019

Rear bumper D.D/De  
Rear bumper side holders x2 nec  
Rear bumper reinforcement bracket  
Rear bumper reinforcement bracket x2 Twisted  
1set Rear bumper clips nec  
1set Rear bumper reverse sensor Damaged  
Rear end panel Repair

4/7.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Sep 2018 <a href="#">Edit Reg</a>		04 Sep 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	<b>KUAH YI PIN</b> , ID: S7346204E		
Main Claimant:	<b>TAN CHOON HONG</b> , ID: S7625191F		
Vehicle Reg. No.:	<b>SJU2059P</b>	Date of Loss:	31/08/2018 00:00 - :59 [105 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / 0195103676SG</b>	Policy/Cover Note No.:	2100325036 (Comprehensive)
Vehicle Reg. No. (Insured):	<b>SFM9891X</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>Jd Motorsports Pte Ltd (HQ)</b> 25 KAKI BUKIT ROAD 4, #06-38 SYNERGY@KB, 417800 Kaki Bukit - Tel:		
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Foo, Chit Yan</b> ] Chityan.Foo@aig.com		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... <b>[Final Rpt due 13/09/2018]</b>		
Claimant's Solicitor:	<b>R.S. SOLOMON LLC</b> - Tel: 68177498		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG\_SG (05/09/2018): **Request To Upload TP GIA Report**

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SJU2059P (0195103676SG)**  
**[SFM9891X]**  
**TP**  
**TAN CHOON HONG**  
**Aug 31 2018 12:00AM**  
**[KUAH YI PIN]**  
**Jd Motorsports Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a> <a href="#">Upload Video</a> <a href="#">Upload Audio</a>			View	View In Browser ▾	
<b>Assessment Reports</b>			1 per page ▾	<input checked="" type="checkbox"/>	
No	Finalized On	ATIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	05/09/18 10:03	<b>Accident Statement</b> <small>From:SC - Reg. No: SFM9891X, Claimant: KUAH YI PIN</small>		Load HTM	
<b>Photos/Images</b>			3 per page ▾	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/09/18 12:11	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
2	13/09/18 12:11	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
3	13/09/18 12:11	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
4	13/09/18 12:11	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
5	13/09/18 12:11	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
6	13/09/18 12:11	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
7	13/09/18 12:11	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
8	13/09/18 12:11	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
9	13/09/18 12:11	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
10	13/09/18 12:11	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
11	13/09/18 12:11	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
12	13/09/18 12:11	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
13	13/09/18 12:11	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
14	13/09/18 12:11	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
15	13/09/18 12:11	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
16	13/09/18 12:11	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
17	13/09/18 12:11	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
18	13/09/18 12:11	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
19	13/09/18 12:11	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
20	13/09/18 12:11	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
21	13/09/18 12:11	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
22	13/09/18 12:11	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
23	13/09/18 12:11	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
24	13/09/18 12:11	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
25	13/09/18 12:11	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
26	01/10/18 10:06	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>
27	01/10/18 10:06	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>
28	01/10/18 10:06	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>
29	01/10/18 10:06	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>
30	01/10/18 10:06	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>
31	01/10/18 10:06	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
32	01/10/18 10:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	01/10/18 10:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	01/10/18 10:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	01/10/18 10:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
37	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
38	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
39	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
40	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
41	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
42	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
43	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
44	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
45	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
46	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
47	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
48	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
50	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	01/10/18 10:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

**DOCUMENTS CHECKLIST**

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG18016166/UCD3S2  
**Date:** 02/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100325036  
**Claimant Vehicle No :** SJU2059P **Insured Vehicle No :** SFM9891X  
 Date of Loss: 31/08/2018 Nature of Claim: TP Claim No: 0195103676SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJU2059P**  
 Make & Model: HYUNDAI AVANTE, 1.6 (A) Engine No: G4FC9U751044  
 Reg. Date: 24/11/2009 (Man. Year: 2009) Chassis No: KMHDU41BMAU898869  
 Colour: Black Odometer: 142127 km  
 Engine Capacity: 1591 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65R15 Rear Tyre Size: 185/65R15  
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment: 04/09/2018  
 Date Inspected: 12/09/2018 Inspected At: Jd Motorsports Pte Ltd (HQ)  
 25 KAKI BUKIT ROAD 4, #06-38 SYNERGY@KB  
 Singapore 417800  
 Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA

**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	0.00 F	*- F
2	2		*REAR BUMPER SIDE HOLDERS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER REINFORCEMENT	Cracked	0.00 F	*- F
4	2		*REAR BUMPER REINFORCEMENT BRACKET	Twisted	0.00 F	*- F
5	1		*SET REAR BUMPER CLIPS	Necessary	0.00 F	*- F
6	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	0.00 F	*- F
7	1		*REAR END PANEL	Repair	0.00 F	*- F
<b>Total Parts (\$\$)</b>					<b>0.00</b>	<b>0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >