

Date In: 4/19/18 17:51	Job description	Date & Time Completed	Done by
Ref No: NAI1MC18016167164 ^C	SAS e-filing		
Veh No: SLM 8568R	E-mail (within 8hrs, AIC 2hrs)		
D.O.A: 4/19/18 15:20	i-Motor Claim Form	MT/10# 169-001	5/19/18 09:16
OD: <input checked="" type="checkbox"/> Reporting Only	i-Motor W/O (Within: OD 2hrs, TP 4hrs)		
TP Insurer:	i-Photo Uploaded		
	Assessment/Survey Report		
	Ass't Report by Fax / Hand to Owner/Wksp		

Preferred Wksp / INC Assign Wksp / QW: ()	Tel: ()	Fax: ()
TP Particulars:	Veh No: SJP 80400	INC () / Non-INC ()
Owner / Driver: ()	Tel: ()	
Policy No: ()	Period: ()	Cover Type: ()
Confirmed by: ()	Date: ()	Time: ()
Insured/Driver Liability: () %	[Note-Est. Status (WO): N: 0-20%; P: 21-79%. F: 80-100%]	
Year of Registration: ()	Warranty: YES () / NO ()	
Excess: (\$)	Loading: \$1,000 () / \$2,000 ()	

General Remarks:-

() Walk-In Customer : Customer's information strictly Confidential & Strictly NO refer of repairer.

() Total Loss Case : to e-mail Insurer URGENTLY.

Drive-In () / Towed-In () ; Invoice: YES () / NO () ; Towing Co: ()

Remarks:- (INC hotline: 6788 6616)	Date & Time Completed	Done by
1) Apply for Transport Allowance () / Courtesy Car ()		
2) QC Check / Post Repair Inspection ()		
3) Upload Resurvey Photo [Repair Cost > \$3000] ()		

Injury: _____

Date/Time	Actions

Claimant's Particulars :- Driver/Owner: Contact No: Damaged Portion: QC Checked by (Engr-In-Charge): Auditors' Comments :- Cat. 1: Cat. 2/3:	Invoice Preparation Checklist		Amt (\$) In Bill	Amt (\$) Add Bill
	1) AR : Accident Reporting (\$30);		30.00	
	2) DA : Damage Assessment (\$100); INC (\$80)		80.00	
	3) TP : Towing Fee \$40/\$45			
	4) FT : Follow-Through Survey \$120			
	5) FT : Follow-Through Survey (Resurvey) \$30			
	6) TR : Re-inspection \$75			
	7) N1 : Idac DA + SMRT Survey \$160			
	8) NTUC Additional Services -			
	*N5: Courtesy Car / Tpt Allowance \$5 *N6: Repair Co-ordination \$10 *N7: Post Repair Inspection \$25 *N8: DV / Collect Excess Coordination \$5 *N11: TP (Non INC) against INC \$20 *N12: Idac Mobile \$0		10.00	
Invoice dated _____ Fee Charged _____ Invoice dated _____ Fee Charged _____				

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/09/2018 17:51
Date Of Accident	04/09/2018 15:20
Exact Location Of Accident	LOR 14 GEYLANG BESIDE GUILLEMARD RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM8568R
Insured/Policyholder	
Name Of Registered Owner	KEN LEO CHUN HOU (LIAO JUNHAO)
NRIC No	S7930358E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93867371
Alternative Phone No	OFFICE-93867371

Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE
Exact Purpose for which vehicle was being used at time of accident	PARKED
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5090076104-01
Cover Note Number	-

Driver

Name of Driver	KEN LEO CHUN HOU (LIAO JUNHAO)
NRIC No	S7930358E
Date Of Birth	28/09/1979
Occupation	OUTDOOR
Date Of Driving Pass	02/01/2001
Driving Experience	17 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93867371
Fax Number	
Contact Number	OFFICE-93867371
EMail Address	NOEMAIL

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SJL8552P

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MMA118114850 Vehicle Registration No: SLM 8568R.
 Name (as shown in NRIC) : Ken Leo Chun Hou (Chiao Junhao) NRIC/FIN/Passport No : 57930358E
 (*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
 Address : _____ Singapore()
 Contact (Tel) : _____ Mobile No. : 93867371
 Email Address : _____
 Date of Accident : 4/9/18 Time of Accident : 15:20
 Place of Accident : Lor 14 Geylang Beside Guillemard Rd.
 Insurance Company : MTC

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Amend Revert from third party to own Damage
claims.



 Policyholder / Driver's Signature
 Date: 11/09/2018



 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:
 Date: 11/9/18.



**SINGAPORE
POLICE FORCE**



T/20180904/2118

2 of 3

Police Station Of Origin:
Geylang N.P.C
132 Paya Lebar Road SINGAPORE 409014
Tel No: 1800-8486999

Report No. T/20180904/2118

CONTINUATION OF REPORT

Brief Details.

On the above mentioned date and place, at about 2pm, I had parked my vehicle at the said location. After that, I left for work. At 3.30pm, I went back to my vehicle and discovered that there severe dents on the left side of my vehicle. I then made a further checks and discovered that there was another car which was also damaged. I then called the Police who came down to assist. My vehicle suffered severe dents and scratches on the left side. My left side skirting had also fell off due to the incident. My steering control was also badly damaged. I was not injured in the incident. I wished to state I have a in-car camera in my vehicle. I had passes the memory card to the Traffic Office.

The other affected vehicle is SJL8552P. The car then hit onto my car and the other affected car is SJP8040D, Mazda/Red



**SINGAPORE
POLICE FORCE**



T/20180904/2118

Police Station Of Origin:
Geylang N.P.C
132 Paya Lebar Road SINGAPORE 409014
Tel No: 1800-8486999

3 of 3


Report No. T/20180904/2118

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: G / Staff Sgt MUHAMMAD FARHAN BIN MOHD NOOR	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 04/09/2018 17:36
Officer In Charge Of Case: TP / HRT / Sr Staff Sgt ESTHER CHONG Contact No.: 65476368	Classification Of Case:
Authentication Stamp NP168	

REPUBLIC OF SINGAPORE
 IDENTITY CARD NO. S7930358E



Name
 KEN LEO CHUN HOU
 (LIAO JUNHAO)
 廖俊豪

Race
 CHINESE

Date of birth 28-09-1979 Sex M

Country of birth
 SINGAPORE




REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number S7930358E

Name
 KEN LEO CHUN HOU
 (LIAO JUNHAO)

Birth Date 28 Sep 1979
 Issue Date 27 Apr 2004




001205421D

3521460




NRIC No. S7930358E

Date of issue
 27-04-2004


Address
 APT BLK 343 WOODLANDS AVENUE 1
 #03-619
 SINGAPORE 730343

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	PASS DATE
Class 2B	Motorcycles not exceeding 200 cc	17 Mar 1999
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	02 Jan 2001

NP 429A

License No: S7930358E



Hello, NAC_PAYA_UBI_800601

Change Language

Change Password

Log Out

My Desktop

Notice of Loss

Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="04/09/2018 17:50"/>
Vehicle No. (For Motor)	<input type="text" value="SLM8568R"/>	Certificate Number	<input type="text"/>

Search

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5090076104-01		KEN LEO CHUN HOU (LIAO JUNHAO)	S7930358E	GPC	drive CLASSIC	SLM8568R	SLM8568R	13/04/2018	12/04/2019

Continue

Claim Handling

Accident MT/1010169

Policy No.	5090076104-01	Vehicle No.	SLM8568R	GST Registration No.	
Certificate No.					
Policyholder Name	KEN LEO CHUN HOU (LIAO JUNHAO)	Cover Type	drive CLASSIC	Policyholder NRIC	S7930
Product Code	PRIVATE CAR INSURANCE	Contact No.(Office)		Loading	0
Contact No.(Mobile)	93867371	Special Remark		Contact No.(Home)	
Email Address		TCA	<input checked="" type="radio"/> No <input type="radio"/> Yes	eCode	No
KFK	<input type="radio"/> No <input checked="" type="radio"/> Yes	NCD Entitlement(%)	50	eCode Reason	
NCD Protection	Yes			Private Hire	No

▼ Accident Details

Report Date	05/09/2018 09:09	Accident Report Within 24 hrs	Yes	Accident Type	Damag
Date of Accident	04/09/2018	Time of Accident hh:mm	15:20	Country of Accident	Singap
Reporting Centre		Orange Force		ICM No.	
Accident Location	LOR 14 GEYLANG BESIDE GUILLEMARD RD				

▼ Excess

Own damage Excess	600.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	600.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		

▼ Benefits

▼ GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

▼ Policyholder Mailing Address

Address 1	BLK 343 #03-619	Address 2	WOODLANDS AVENUE 1	Address 3	SINGA
Address 4		Address Type	Singapore address	Post Code	73034
Unit No.		Related Policy Number	5090076104-01		

▼ OI Driver Info

Driver Name	KEN LEO CHUN HOU	Driver Type	Main Driver	Driver DOB	28/09/
Unnamed driver Name		Driver NRIC	S7930358E	Driving Experience	17
Register Date of Driver License	02/01/2001	Driver Age	38	Contact No.(Home)	
Contact No.(Mobile)	93867371	Contact No.(Office)		Address 3	SINGA
Address 1	BLK 343 #03-619	Address 2	WOODLANDS AVENUE 1	Post Code	73034
Address 4		Address Type	Singapore address		
Unit No.					
Does he own a Singapore Registered car?	<input checked="" type="radio"/> Yes <input type="radio"/> No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	<input type="radio"/> Yes <input checked="" type="radio"/> No
-------------------------------------	------	-------------	---

Modification History

Claim 001 **New**

Claim Type *	OD-MX	Insured Name	KEN LEO CHUN HOU (LIAO JUN
Contact No.(Mobile)	93867371	Contact No.(Home)	NIL
Email Address	LIAO79SG@YAHOO.COM	OI Vehicle Number	SLM8568R
Claim Description	SLM8568R / SJP8040D ON 4 Sept 2018		
Preferred Workshop	0	Insured Liability	Not at Fault
Contract No. Finalisation	Yes	Preferred Repair Option	Preferred Workshop, Name unknown
Date Registered		GIA report	Received
Report Taken By		Claim Close Date	05/09/2018 09:13
			LIEW SHAN HUI

Print AK letter

Save Submit

Attachment

Accident No.	MT/1010169	Claim No.	001
--------------	------------	-----------	-----

Last Doc. Received

Yes No

Upload Date

05/09/2018 09:16

Path *

- Choose File: No file chosen

Message Read

Clear	Category *	Confidential	Urgency *
Clear	Please Select	NO	Normal
Clear	Please Select	NO	Normal
Clear	Please Select	NO	Normal
Clear	Please Select	NO	Normal
Clear	Please Select	NO	Normal
Clear	Please Select	NO	Normal

Attachment List

Attachment	Uploaded By/Date	Category	Urgency	Description
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 05 Sep 2018 09:16	NRIC/ Driving License	Normal	NRIC/ Driving License 2018-9-5
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 05 Sep 2018 09:16	SAS	Normal	SAS 2018-9-5
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 05 Sep 2018 09:16	Photos	Normal	Photos 2018-9-5
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 05 Sep 2018 09:16	Photos	Normal	Photos 2018-9-5
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 05 Sep 2018 09:16	Photos	Normal	Photos 2018-9-5
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 05 Sep 2018 09:13	Photos	Normal	Photos 2018-9-5
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 05 Sep 2018 09:13	Photos	Normal	Photos 2018-9-5
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 05 Sep 2018 09:13	Photos	Normal	Photos 2018-9-5
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 05 Sep 2018 09:13	Photos	Normal	Photos 2018-9-5
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 05 Sep 2018 09:13	Photos	Normal	Photos 2018-9-5
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 05 Sep 2018 09:13	Photos	Normal	Photos 2018-9-5

Video List

Uploaded By/Date	Folder Date	File Name	Source
		<input type="button" value="Display in New Window"/> <input type="button" value="Scan and uploading"/>	

ASSIGNMENT (D50)

By 2) Nature of Accident:

- 1) Vehicle hit Vehicle:
 - a) Pedestrian ()
 - b) Animal ()
 - c) Bicycle ()
- 2) Vehicle hit Road Side Object:
 - a) Govt Property ()
 - b) Road Work Object ()
 - c) Private Property ()
- 3) Vehicle drop into drain ()
- 4) Damage thro to Act of God:
 - a) Fallen Object ()
 - b) Flood ()
 - c) Other ()
- 5) Parked & Found Damaged:
 - a) Vandalism ()
 - b) Hit by Moving Object ()
- 6) Theft Case:
 - a) Stolen ()
 - b) Damage found when recovered ()
- 7) Fire:
 - a) Whilst driving ()
 - b) Parked ()
- 8) Accident date more than 24hrs ()

Remarks for internal information

Remarks to appear in Works Order & Assessment report

- 1) Potential Total Loss ()
- 2) LRS Light on ()
- 3) ABS Light on ()

By Assessor- 1) Vehicle Information

Vehicle: **SLM 856FR** on 13 Apr 2017
 Year: **2007** / Motorcycle / Bus / Van / Heavy / Taxi / Private Motor / Car / Truck / Trailer or
 Make & Model: **Honda Shuttle 15GV** no. **1496**
 Colour: **Silver** Transmission type: **Auto** / Manual
 Engine: **42683**
 Chassis: **GK 8100 4109**
 Gen. Cond: **Good** / Fair / Poor / Burnt or
 Steering: **Good** / Jammed / Leaked / Burnt or
 Brakes: **In order** / Jammed / Leaked / Burnt or
 Mod: **NH** / SRim / STD A/Rim or
 Tyre Size: F: **205/50 R16**
 R: **—————**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal	7 mm	R/Bal	7 mm
L/Bal	7 mm	L/Bal	7 mm

Parallel Import: Yes / No
 Towed In: Yes / No
 Repair Type: LS / L.B.I.
 Towing Required: Yes / No
 No of Repair Days: **8**
 Vehicle in H/c: Yes / No
 D.O.I: **12/9/2017**
 Time: **9.25am**

By Assessor- 2) Comments

- 1) Damages not due to recent accident.
- 2) Damages do not seem hit onto:
 - a) Vehicle () b) Motorcycle () c) Bicycle () d) Pedestrian ()
 - e) Animal () f) Govt Object () g) Road Work Object ()
 - h) Private Property () i) Drain () j) Road Edge/Grass/Verge ()
- 3) Vehicle does not seem damaged as a result of:
 - a) Fallen Object () b) Flood () c) Vandalism () d) Fire ()
 - e) Moving Object () f) Stolen () g) Stolen & Recovered ()

Time Started	Time Completed
09:50	
10:00	
Total Time Spent on this job: 1 Day	

Condition (CON)

- (01) Best (2) Dented (3) Distorted (4) Cracked (5) Cur (6) Scuffed
- (7) Deformed (8) Stuffed (9) Sunk (10) Broken (11) Necessary (12) Missing
- (13) Torn (14) Unconfirmed (15) Not Working

ACTION (AC)

- (1) Replace (2) Repair (3) Check (4)
- (5) For Consensus (6) For

Aug 2005

MOTOR CAR (LH)

1073

Left Portion

Vehicle No: **SLM 8568 R**

NAC	INC	Item	CON	AC	Qty
1255	995326	Frt LH Door	BUC	/	
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge Lower	BT	/	
1258	995142	Frt LH Door Wing Mirror			
1259	995102	Frt LH Door Garnish			
1260	991593	Frt LH Door Glass Outer Moulding			
1261	991588	Frt LH Door Glass Inner Moulding			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator	?	/	
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1267	991607	Frt LH Door Inner Handle			
1268	991625	Frt LH Door Lock w/Key			
1269	991624	Frt LH Door Lock	?	/	
1270	991562	Frt LH Door Central Lock			
1271	991675	Frt LH Door Switch			
1272	991617	Frt LH Door Inner Trim Board			
1273	991568	Frt LH Door Checker	?	/	
1274	991575	Frt LH Door Sticker	NEC	/	
1275	991688	Frt LH Door Wire Harness			
1276	991683	Frt LH Door Window Glass Pillar			
1277	991640	Frt LH Door Outer Pillar			
1278	991613	Frt LH Door Inner Pillar			
1279	991646	Frt LH Door Pillar Inner Garnish			
1280	990554	Centre Pillar LH	DDR	/	
1281	990542	Centre Inner Pillar LH			
1282	990517	Centre Pillar Upper Garnish LH			
1283	990564	Centre Pillar Lower Garnish LH			
1284	991670	Frt LH Door Step Garnish			
1285	994052	Rocker Panel LH	DDR	/	
1286	994049	Rocker Panel Inner Panel LH			
1287	994046	Rocker Panel Garnish LH			
1288	994055	Rocker Panel Outer Side Skirt LH	?	/	
1004	991300	Frt Bumper	?	/	
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1029	995153	Frt LH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1096	995070	Frt LH Fender	DDR	/	
1098	995147	Frt LH Fender Inner shield	?	/	
1099	995148	Frt LH Fender Protector			
		Frt LH Wheel Rim	BR	/	
		" " " " Tyre	?	/	8076

NAC	INC	Item	CON	AC	Qty
1289	995156	Rear LH Door	BUC	/	
1290	993282	Rear LH Door Protector			
1291	995194	Rear LH Door Hinge			
1292	993228	Rear LH Door Garnish			
1293	993278	Rear LH Door Glass Outer Moulding			
1294	993231	Rear LH Door Glass Inner Moulding			
1295	995190	Rear LH Door Glass			
1296	993238	Rear LH Door Glass Regulator	?	/	
1297	995192	Rear LH Door Glass Regulator Motor			
1298	993294	Rear LH Door Rubber	DD	/	
1299	993275	Rear LH Door Outer Handle			
1300	993250	Rear LH Door Inner Handle			
1301	993261	Rear LH Door Lock			
1302	993256	Rear LH Door Inner Trim Board			
1303	993218	Rear LH Door Checker			
1304	993230	Rear LH Door Glass Channel			
1305	993242	Rear LH Door Glass Triangle Garnish			
1306	993285	Rear LH Door 1/4 Glass			
1307	993288	Rear LH Door 1/4 Glass Rubber			
1308	993287	Rear LH Door 1/4 Glass Pillar			
1309	993305	Rear LH Door Step Garnish			
1310	993309	Rear LH Door Sticker	NEC	/	
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1163	993851	Rear LH Taillamp			
1218	993436	Rear LH Fender	SCR R	/	
1219	993449	Rear LH Fender Inner shield	?	/	
1136	990247	Sticker			

No of Items: _____ Assessor: _____

Condition (CON)

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
 (07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
 (12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTOR CAR (UC)

ACTION (AC)

(1) Replace (✓) (2) Repair (X) (3) Check (?)
 (4) Not Consistent (NC)

AUG 2005
 2 of 2

Vehicle No: SLM 8568 R

Undercarriage

NAC	INC	Item	CON	AC	Qty
1372	995163	Frnt LH Shock Absorber		?	
1373	991944	Frnt LH Shock Absorber Mounting		?	
1374	990632	Frnt LH Coil Spring			
1375	995198	Frnt LH Knuckle Arm	DIS	✓	
1376	995199	Frnt LH Knuckle Arm Bearing	NEC	✓	
1377	995178	Frnt LH Lower Arm	BT	✓	
1378	995169	Frnt LH Upper Arm			
1379	995183	Frnt LH Tie Rod	BT	✓	
1380	995143	Frnt LH Drive Shaft		?	
1381	990661	Frnt LH Control Arm			
1382	992062	Frnt LH Trailing Arm			
1383	991848	Frnt LH Leaf Spring			
1384	991293	Frnt LH Brake Disc Rotor			
1385	991281	Frnt LH Brake Caliper			
1386	991292	Frnt LH Brake Pipe			
1387	991287	Frnt LH Brake Hose			
1388	991295	Frnt LH Brake Sensor Wire			
1389	991989	Frnt Stay Bar Bracket			
1390	994455	Steering Rack & Pinion		??	
1391	994435	Steering Cross Member		?	
1392	994519	Frnt Sub Frame			
1393	992003	Frnt Sub Frame Mounting			
1394	991217	Frnt Anti Roll Bar			
1395	991219	Frnt Anti Roll Bar Linkage LH	BT	✓	
1396	990887	Engine Block			
1397	990890	Engine Block Gasket			
1398	990972	Engine Oil Sump			
1399	990960	Engine Oil			
1400	992224	Gear Box Assy			
1401	992229	Gear Box Gasket			
1402	992241	Gear Box Oil Sump			
1403	992257	Gear Oil			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1404	991134	Floor Panel			
1405	993719	Rear LH Shock Absorber			
1406	993723	Rear LH Shock Absorber Mounting			
1407	993170	Rear LH Coil Spring			
1408	993550	Rear LH Knuckle Arm			
1409	993551	Rear LH Knuckle Arm Bearing			
1410	993597	Rear LH Lower Arm			
1411	993884	Rear LH Upper Arm			
1412	995161	Rear LH Drive Shaft			
1413	995216	Rear LH Control Arm			
1414	993881	Rear LH Trailing Arm			
1415	993573	Rear LH Leaf Spring			
1416	992941	Rear LH Brake Disc Rotor			
1417	992937	Rear LH Brake Caliper Assy			
1418	990434	Rear LH Brake Pipe			
1419	992946	Rear LH Brake Hose			
1420	993819	Rear Sub Frame			
1421	993820	Rear Sub Frame Mounting			
1422	992813	Rear Anti Roll Bar			
1423	990168	Rear Anti Roll Bar Linkage			
1424	990202	Axle Beam			
1425	990170	Rear Axle Panhard Rod			
1426	990810	Differential Assy			
1427	992706	Propeller Shaft			

NAC	INC	Item	CON	AC	Qty
1428	991935	Frnt RH Shock Absorber			
1429	991944	Frnt RH Shock Absorber Mounting			
1430	990632	Frnt RH Coil Spring			
1431	991844	Frnt RH Knuckle Arm			
1432	991845	Frnt RH Knuckle Arm Bearing			
1433	991851	Frnt RH Lower Arm			
1434	992064	Frnt RH Upper Arm			
1435	992040	Frnt RH Tie Rod			
1436	991692	Frnt RH Drive Shaft			
1437	990661	Frnt RH Control Arm			
1438	992062	Frnt RH Trailing Arm			
1439	991848	Frnt RH Leaf Spring			
1440	991293	Frnt RH Brake Disc Rotor			
1441	991281	Frnt RH Brake Caliper			
1442	991292	Frnt RH Brake Pipe			
1443	991287	Frnt RH Brake Hose			
1444	991295	Frnt RH Brake Sensor Wire			
1445	993720	Rear RH Shock Absorber			
1446	993723	Rear RH Shock Absorber Mounting			
1447	993173	Rear RH Coil Spring			
1448	993550	Rear RH Knuckle Arm			
1449	993551	Rear RH Knuckle Arm Bearing			
1450	993601	Rear RH Lower Arm			
1451	993885	Rear RH Upper Arm			
1452	993322	Rear RH Drive Shaft			
1453	993178	Rear RH Control Arm			
1454	995117	Rear RH Trailing Arm			
1455	995110	Rear RH Leaf Spring			
1456	992942	Rear RH Brake Disc Rotor			
1457	992938	Rear RH Brake Caliper Assy			
1458	990434	Rear RH Brake Pipe			
1459	992947	Rear RH Brake Hose			

No of Items: _____ Assessor: _____

Claim Handling

[Task Transfer](#) [Exit](#)

▼ **Accident MT/1010169**

[LOS](#) [SAL](#) [SUB](#)

Policy No.	5090076104-01	Vehicle No.	SLM8568R	GST Registration No.	
Certificate No.					
Policyholder Name	KEN LEO CHUN HOU (LIAO JUNHAO)	Policyholder NRIC	S7930358E		
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	93867371	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	No ▼
KFK	<input checked="" type="radio"/> No <input type="radio"/> Yes	TCA	<input type="radio"/> No <input type="radio"/> Yes	eCode Reason	
NCD Protection	Yes	NCD Entitlement(%)	50	Private Hire	No

▼ **Accident Details**

Report Date	05/09/2018 09:09	Accident Report Within 24 hrs	Yes	Accident Type	Damaged whilst parked
Date of Accident	04/09/2018	Time of Accident hh:mm	15:20	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	Yes	ICM No.	3641606
Accident Location	LOR 14 GEYLANG BESIDE GUILLEMARD RD				

▼ **Excess**

Own damage Excess	600.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess	0.00	Outside Singapore OD Excess			600.00
Third Party Excess	0.00	Outside Singapore TP Excess			0.00

▼ **Benefits**

▼ **GST Registered Information**

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

▼ **Policyholder Mailing Address**

Address 1	BLK 343 #03-619	Address 2	WOODLANDS AVENUE 1	Address 3	SINGAPORE 730343
Address 4		Address Type	Singapore address	Post Code	730343
Unit No.		Related Policy Number	5090076104-01		

▼ **OI Driver Info**

Driver Name	KEN LEO CHUN HOU	Driver Type	Main Driver		
Unnamed driver Name		Driver NRIC	S7930358E	Driver DOB	28/09/1979
Register Date of Driver License	02/01/2001	Driver Age	38	Driving Experience	17
Contact No.(Mobile)	93867371	Contact No.(Office)		Contact No.(Home)	
Address 1	BLK 343 #03-619	Address 2	WOODLANDS AVENUE 1	Address 3	SINGAPORE 730343
Address 4		Address Type	Singapore address	Post Code	730343
Unit No.					
Does he own a Singapore Registered car?	<input type="radio"/> Yes <input checked="" type="radio"/> No	Driver Vehicle No.		Driver Insurer Company	

▼ **Declaration**

Breathalyser or Blood Test Reading?	0 mg	Any injury?	<input type="radio"/> Yes <input checked="" type="radio"/> No
Modification History	10/09/2018 16:15 s990621 Modify Orange Force(N-->Y) 10/09/2018 16:15 s990621 Modify ICM No(-->3641606)		

▼ **Investigation**

Claim 001 OD-MD

▼ **Claim Case Officer Ng Hak Joo**

[LOS](#) [SAL](#) [SUB](#)

Claim Type	OD-MD	Insured Name	KEN LEO CHUN HOU (LIAO JUNH)	Insured NRIC	S7930358E
Contact No.(Mobile)	93867371	Contact No. (Home)	NIL	Contact No. (Office)	
Email Address	LIAO79SG@YAHOO.COM	OI Vehicle Number	SLM8568R	TP Vehicle Number	SJP8040D
Claim Description	SLM8568R / SJP8040D ON 4 Sept 2018			Name of Preferred Workshop	0
Preferred Workshop Contact Finalisation	<input type="radio"/> No <input checked="" type="radio"/> Yes	Preferred Repair Option	Preferred Workshop Name unknown	Insured ability report	Not at all received
Date Registered	05/09/2018 09:17	Claim Close Date		Date Received	12/09/2018 12:12
Report Taken By	LIEW SHAN HUI	Workshop Repairer		Total Loss but Repaired	
<input checked="" type="checkbox"/> Print AK letter				OD Excess Collected by Workshop	
Modification History	11/09/2018 13:17 s069588 Modify Claim Type(OD-MX-->OD-MD)				

▼ **Special Claim Creation Approval**

Approval	Reason
Remarks	

[damage assessment](#) [Activity Handling](#) [Attachment](#)

Vehicle Info

Vehicle Make	HONDA	Vehicle Model	SHUTTLE	Engine Capacity	
Date of Registration	13/04/2017	Classis No.	GK61004109		
Towing Required *	<input checked="" type="radio"/> Yes <input type="radio"/> No	Vehicle in IDAC *	<input checked="" type="radio"/> Yes <input type="radio"/> No	Parallel Import *	<input checked="" type="radio"/> Yes <input type="radio"/> No
Type of Tender *	Own Damage	Assessor Name *	SIMON	Survey Current Status	
IDAC/Workshop Name	NATIONAL ASSESSMENT CENTR	IDAC/Workshop Location	51 UBI AVENUE 1 #01-25 PAYA		
Windscreen Parts & Labour Cost		Total Loss *	<input type="radio"/> Yes <input checked="" type="radio"/> No		
Market Value(\$)		Scrape Value(\$)		Economical Repair Value(\$)	
Remark	REMARK:NO OF REPAIR DAYS:8 DAYS.1X FRT LH DOOR LOCK - UNCONFIRM.1X CENTRE PILLAR LH - REPAIR.1X ROCKER PANEL OUTER SIDE SKIRT LH - UNCONFIRM.1X FRT LH WHEEL RIM - REPLACE.1X FRT LH TIE ROD - REPLACE.1X FRT LH ANTI ROLL BAR LINKAGE - REPLACE.1X FRT LH DOOR STICKER - REPLACE.1X REAR LH DOOR STICKER - REPLACE.				

Remark for Supplementary

Damage Listing

Find a Part	No.	Part No.	Description	Qty *	Repair Code *	
root						
Not Applicable	1	23300201	DOOR (FRONT LEFT)	1	Replace	X
ABS	2	23303001	DOOR HINGE (BOTTOM) (FRONT LEFT)	1	Replace	X
ABSORBER	3	23302401	DOOR GLASS REGULATOR (FRONT LEFT)	1	Unconfirm	X
ACCELERATOR	4	23301601	DOOR CHECKER (FRONT LEFT)	1	Unconfirm	X
ACTUATOR	5	35500701	ROCKER PANEL (LEFT)	1	Repair	X
ADVERTISEMENT STICKER	6	16000101	BUMPER (FRONT)	1	Unconfirm	X
AIR BAG	7	25400102	FENDER (FRONT LEFT)	1	Repair	X
AIR BLOWER	8	25400901	FENDER INNER SHIELD (FRONT LEFT)	1	Unconfirm	X
AIR BOX	9	43600101	TYRE (FRONT LEFT)	1	Unconfirm	X
AIR CHAMBER BOX	10	23300203	DOOR (REAR LEFT)	1	Replace	X
AIR CLEANER	11	23302403	DOOR GLASS REGULATOR (REAR LEFT)	1	Unconfirm	X
AIR COMPRESSOR	12	23306103	DOOR RUBBER (REAR LEFT)	1	Replace	X
AIR CON	13	25400105	FENDER (REAR LEFT)	1	Repair	X
AIR CON (VAN)	14	25400903	FENDER INNER SHIELD (REAR LEFT)	1	Unconfirm	X
AIR COOLER	15	36600101	SHOCK ABSORBER (FRONT LEFT)	1	Unconfirm	X
AIR DISTRIBUTOR	16	36600601	SHOCK ABSORBER MOUNTING (FRONT LEFT)	1	Unconfirm	X
AIR FILTER	17	30000101	KNUCKLE ARM (FRONT LEFT)	1	Replace	X
AIR FLOW	18	30000201	KNUCKLE ARM BEARING (FRONT LEFT)	1	Replace	X
AIR GRILLE	19	30500101	LOWER ARM (FRONT LEFT)	1	Replace	X
AIR HORN	20	23600101	DRIVE SHAFT (FRONT LEFT)	1	Unconfirm	X
AIR INTAKE	21	401028	STEERING RACK & PINION	1	Unconfirm	X
AIR RESONATOR BOX	22	401021	STEERING CROSS MEMBER	1	Unconfirm	X
AIR THROTTLE BODY AND SENSOR						
ALARM						
ALTERNATOR						
ALUMINIUM PANEL - SIDE						
AMPLIFIER						
ANTENNA						
ANTI ROLL						
APRON						

Save Submit



NATIONAL ASSESSMENT CENTRE SERVICES
(LKK GROUP)

51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,
Singapore 408933, TEL: 6841 0055 FAX: 6841 6315



Vehicle Movement Form

Vehicle Check-In

Vehicle No: SLM8568R Date In: _____ Time In: _____ with Keys: Yes / No

For Office use

Attended by: _____

Workshop Collection of Vehicle

Workshop: Hock Wah

Collection Date: 13.09.2018 Time: _____ with Keys: Yes / No

Tow Truck No: YP7951D Tow Man: Rabien Tan NRIC: S8106925/E

Signature: _____

For office use

Attended by: ROSLINDA

Approved by: _____

Workshop Return of Vehicle

Workshop: _____

Returned Date: _____ Time: _____ with Key: Yes / No

* Tow In / Drive In

Tow Man / Workshop Representative: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Owner Collection of Vehicle

Collection Date: _____ Time: _____ with Key: Yes / No

Owner: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Approved by: _____

LKK Paya Ubi

From: Ng Hak Joo <hakjoo.ng@income.com.sg>
Sent: Thursday, 13 September 2018 11:05 AM
To: Hock Wah Motor Pte Ltd
Cc: LKK Paya Ubi
Subject: MT/1010169-001, VEHICLE NUMBER: SLM8568R
Attachments: UIL CLAIM FORM.doc

Dear Hock Wah

Please tow this vehicle from Idac and contact owner Mr Ken Leo at 93867371 when the vehicle arrived at your premises to revert on the LH Rim, excess \$642.

Please also assist the owner to complete the attached UIL Form and email to our Recovery Team at: motor@income.com.sg

We have also high lite to the owner that how long and how much our Recovery Team can recover, we unable to commit, therefore, you may advise him to email to motor@income.com.sg for any Recovery query.

Our Ref: MT/CA/OD/051/1010169-001/NHJ
13 Sep 2018
HOCK WAH MOTOR WORKSHOP PTE LTD
BLK 3011 BEDOK NORTH AVE 4 #01-2008/10/12
BEDOK INDUSTRIAL PARK E
SINGAPORE 489977

Dear Sir

CLAIM NUMBER: MT/1010169-001
REPAIR OF VEHICLE NUMBER: SLM8568R

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as follows:

Award Date: 13 Sep 2018
Make: HONDA
Model: SHUTTLE
Estimated Repair Days: 7
Location: NATIONAL ASSESSMENT CENTRE SERVICES
Address: 51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933
Benefits Applicable: N/A
Excess Applicable: 600.00

Please note that supplementary items will not be allowed.

If you have any queries, please contact Ng Hak Joo at 64307890 or email us at motor@income.com.sg.

Yours sincerely
Low Choo Mee
Senior Manager
Motor Insurance
Thank You

Ng Hak Joo, Iata-Uftaa-ltc
Executive
Motor Insurance

T +65 64307890

www.income.com.sg

 income
mode different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at Income.com.sg/careers

In with you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.