

ASS. REC. BY:

REP

es/MSG/180016206/ Urd342

Special Instruction:

Surveyor  
Mehmen

Marcus

ASSIGNMENT (Office)

From (Person):

Elaine Ngu

of

MSG

Date/Time

5/9/18 @ 9:35am

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBM 1884S

Insured:

SLC 8290T

at Workshop m/s

Ban Hock Hin

Tel:

62816520

of

No. 6 Defu Lane 4

Policy No:

80457041QMX

Claim No:

569275

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/08/2018

CA / REV / REP. / REV 24 HRS

1up

6/9/2018

H.O.D. Endorsement:

Date/Time: 11:32am @

Person Contacted:

Raymond

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

Wsp request marcus to survey, so arrange on 6/9/18.

FBM1884S-X

SLC8290T-X

10/9/18

Sent preli than Mehmen n

(08/11/88) welf

REF: MS16

ASS REC BY:

## ASSIGNMENT

From:

Date: 6/9/18

Estimated Cost:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBM1884S

at Workshop m/s

Ban Hock Hin

of

No. 6 Defu Lane 4

Insured:

Policy No

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

ID/C Accident Rpt:

Consistent? : Yes or No

GVA / PR Seek:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

131

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

lup

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

FBM1884S

Yr Regn:

8/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha F2N150

c.c

149

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

13250

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ME1R616126200248

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

100-80-17

R:

140/60 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MRF

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

30/8/18

D.O.I.

6/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time

Action / Instruction

5/10/18 confirmed fine by \$724 with Raymond.

Red: \$871.94, 55%.

RECEIVED 05 NOV 2018

Signature: [Signature]

5/11/2018

Date/Time, File Pass to?



: Prel. Report

1) typist



: Final Report

Date/Time, File Return to?

2)

Report Format :

TP

Lump Sum / I.B.I. (\$) 794.00

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

Survey Fee:

150

Transportation:

S + RS, SI

Photos

Others

10

TOTAL

160

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18016206/Urd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 05-09-2018



Code : MSG

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	SLC 8290T	Veh. Inspected	FBM 1884S
Policy No.	80457041QMX	Coverage (\$)	0.00
Claim No.	569275	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	05/09/2018

**2. Vehicle Particulars & Condition**

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

**4. Description of Damages**

--

**5. General Information**

Accident Date	30/08/2018	Inspection Date	06/09/2018
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
----------------------------------------------------------------------------------------------------------------------------------------

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Sep 2018		05 Sep 2018 09:35 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ONG PANG YONG, ID: S8413534H		
Main Claimant:	CERTIS CISCO AUXILIARY POLICE FORCE PTE LTD, Co. Reg. No.: 200900882K		
Vehicle Reg. No.:	FBM1884S	Date of Loss:	30/08/2018 00:00 - :59 [12 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 569275	Policy/Cover Note No.:	80457041QMX Coverage: 26/05/2018 - 25/05/2019
Vehicle Reg. No. (Insured):	SLC8290T	Policy No. (Claimant):	
		Excess:	
Repairer:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4, 539410 Defu Lane - Tel: 62816520		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 06/09/2018]		
Adj Asg. Remarks:	ON WP, Bike is in, Non Reporting, Liability unclear, Contact Person: Raymond / 6281 6520 x 220		

### ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 10 Sep 2018

**Preliminary Advice**

Insured Vehicle No	: SLC8290T	Accident Date	: 30/08/2018
TP Vehicle No	: FBM1884S	Assignment Date	: 05/09/2018
Make	: YAMAHA FZN150	Est. Duration of Repair	: 3.00
Date of Inspection	: 06/09/2018		
Inspection At	: BAN HOCK HIN CO. PTE LTD (HQ) NO. 6 DEFU LANE 4 SINGAPORE 539410		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,342.00
Revised Amount	:S\$	45.00
Check Items (Estimated)	:S\$	330.00
Total	:S\$	375.00

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	FBM1884S		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	YAMAHA		
Vehicle Model :	FZN150		
Chassis No. :	ME1RG1612G2002485		
Propellant :	Petrol		
Engine No. :	G3E3E0048287		
Engine Capacity :	149 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	330 kg		
Unladen Weight :	122 kg		
Year Of Manufacture :	2016		
Original Registration Date :	14 Aug 2017		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
Quota Premium :	\$5,851.00		
COE Expiry Date :	13 Aug 2027		
Road Tax Expiry Date :	13 Feb 2019		
Inspection Due Date :	13 Aug 2020		
Intended Transfer Date :	05 Sep 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK      Print

**GREAT AMERICAN INSURANCE COMPANY**

UEN: T15FC0029B GST REG. NO.: M90370081T  
3 TEMASEK AVENUE, #16-01 CENTENNIAL TOWER  
SINGAPORE 039190  
TEL: +65 6804 6000  
FAX: +65 6235 2616

**MOTOR COVER NOTE: MT20180243**

The Insured mentioned in this Cover Note, having proposed for insurance in respect of the Motor Vehicle described, is hereby HELD COVERED under the terms of the Insurer's usual form of Motor Policy applicable thereto for the period mentioned unless the cover is terminated by the Insurer by notice in writing in which case the insurance will thereupon cease and a proportionate part of the annual premium payable for such insurance will be charged for the time the Company has been on risk.

The Insurer	: GREAT AMERICAN INSURANCE COMPANY
The Insured	: CERTIS CISCO AUXILIARY POLICE FORCE PTE LTD
Insured NRIC/Passport No/ ROC	: 200900882K
Policy Coverage	: COMPREHENSIVE
Make And Description Of Vehicle	: YAMAHA FZN150 MOTORCYCLE
Vehicle Registration No.	: FBM1884S
Year Of Manufacture	: 2017
Engine No.	: G3E3E0048287
Chassis No.	: ME1RG1612G2002485
Engine Capacity/ Tonnage/ Seater	: 125 cc
Hire Purchase	: NIL
Value (\$\$)	: AS PER MARKET VALUE
Period of Insurance	: FROM: 01/04/2018 TO: 31/03/2019
Excess (\$\$)	: Section I : \$750 Section II : Nil Windscreen Excess : Nil
Great American Authorized Workshop	: CHIN MENG MOTORS + AUTHORISED WORKSHOP

I/WE HEREBY CERTIFY THAT POLICY TO WHICH THIS CERTIFICATE RELATES IS ISSUED IN ACCORDANCE WITH THE PROVISIONS OF THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) ACT (CHAPTER 189) AND PART IV OF THE ROAD TRANSPORT ACT 1987 (MALAYSIA)

For and on behalf of Great American Insurance Company

Great American Insurance Company  
Authorized Signatory

Date of Issue : 29/03/2018  
Intermediary : JARDINE LLOYD THOMPSON PTE LTD  
Cover Note Validity : 30 days from the Date of Issuance

MTR/COVERNOTE/V02/18

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	31/08/2018 11:48
Date Of Accident	30/08/2018 07:50
Exact Location Of Accident	AIRLINE ROAD ICA TRAFFIC LIGHT JUNCTION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	FBM1884S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CERTIS CISCO AUXILIARY POLICE FORCE PTE LTD
Co Reg No	200900882K
Email Address	JEREMYC_QUEK@CERTISSECURITY.COM
Mobile Phone No	
Alternative Phone No	OFFICE-68428579
<b>Vehicle Particulars</b>	
Manufacturer	YAMAHA
Model	FZN150-149CC
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
<b>Insurance Company</b>	
Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	MT20180243
Cover Note Number	
<b>Driver</b>	
Name of Driver	PRETHAB RAO APPANA
Passport No/FIN	G8106168N
Date Of Birth	28/04/1988
Occupation	OUTDOOR
Date Of Driving Pass	07/10/2010
Driving Experience	7 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	+65-82479401
Fax Number	
Contact Number	
Email Address	ROAL_BECKHAM@YAHOO.COM



Address	20 JALAN AFIFI
Postcode	409179
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ACCIDENT STATEMENT ATTACHED.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLC8290T
Vehicle Make/Model/Colour	HONDA / VEZEL / WHITE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ONG PANG YONG
NRIC/Passport Number	S8413534H
Contact Number	9816977Z
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Chen Shua Chun  
Logistics & Transport Supervisor  
Aviation Security  
Civils CTRC

51 AUG 2018

Police Officer's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)


Date & Time: 30/08/2018 2200

Reporting Centre Personnel's Signature  
Name: Tan Chae Loo  
NRIC/FIN No.: 9771533R



# Accident Sketch Plan

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I stopped at zebra crossing at T-junction between  
 alp8 avenue and airline road going to cachi farm.  
 As I stopped to give way to vehicle from  
 I lap 33186 Prothab Rax, stopped at zebra  
 crossing at T-junction between alp8 avenue  
 and airline going to cachi farm. As I stopped  
 to give way to vehicle from airline road,  
 my motorcycle was hit from behind by  
 xul white honda car plate number 8LC 8290 T  
 and cause my rear plate bend inwards. That's all.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.



Chen Shao Chun  
 Legation & Transport Supervisor  
 Amalgam Security  
 Corp. (P) Ltd.

Policyholder's Signature 31 AUG 2018  
 Date 2018

Driver's Signature  
 (if driver is not the policyholder)  
 Date & Time: 30/08/2018 2200

Reporting Centre Personnel's Signature  
 Name: Chen Shao Chun  
 NRIC/FIN No.: 6771525R



SPAR/SP SketchPlanForm\_V2

# Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE  
6 Raffles Quay #18-00 Singapore 048580  
Tel (65) 6224 0010 Fax (65) 6224 0030  
Operating Hours : Monday to Friday, 09:00 - 17:00  
UEN: S665500206 / GST Reg. No.: M400017735

**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

## ADDENDUM

### (A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MBAN18112897-01 Vehicle Registration No: F8M 18845  
Name (as shown in NRIC) : Cecil Cicio Auxiliary Police Force No Let NRIC/FIN/Passport No : 200900882K  
(\*Vehicle Driver / Vehicle Owner) (\*) Please delete as appropriate  
Address : 20 Jalan Afiq Singapore (409179)  
Contact (Tel) : 6842 8579 Mobile No. : \_\_\_\_\_  
Email Address : JeremyYC\_Quack@certisecurity.com  
Date of Accident : 30/08/2018 Time of Accident : 07:50  
Place of Accident : Airline Road 2CA Traffic Light Junction  
Insurance Company : Great American Insurance Company

### (B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Change Screenshot Plan due to wrongly attached

---

---

---

---

---

---

---

---

---

---

Policyholder / Driver's Signature  
Date:

Reporting Centre Personnel's Signature  
Name: Tan Chou Wei  
NRIC/FIN No.: G7715235R  
Date: 31/08/2018



# Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE  
6 Raffles Quay #18-00 Singapore 048580  
Tel (65) 6224 0010 Fax (65) 6224 0030  
Operating Hours : Monday to Friday, 09:00 - 17:00  
UEN: S66500206 / GST Reg. No.: M400017735

**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

## ADDENDUM

### (A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MBAN18112897-01 Vehicle Registration No: F8M 1884S  
Name(as shown in NRIC) : Cerfic Cico Auxiliary Police force Pte Ltd NRIC/FIN/Passport No : 200900882K  
(\*Vehicle Driver / Vehicle Owner) (\*) Please delete as appropriate  
Address : 20 Jalan Afi Singapore(409179)  
Contact (Tel) : 6842 8579 Mobile No. : \_\_\_\_\_  
Email Address : JeremyYC\_Quen@certificsecurity.com  
Date of Accident : 30/08/2018 Time of Accident : 07:50  
Place of Accident : Airline Road 2CA Traffic Light Junction  
Insurance Company: Great American Insurance Company

### (B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Change Screenshot Plan due to wrongly attached

---

---

---

---

---

---

---

---

---

---

Policyholder / Driver's Signature  
Date:

Reporting Centre Personnel's Signature  
Name: Tan Chuan Lian  
NRIC/FIN No.: G7715235R  
Date: 31/08/2018



> **Back to OneMotoring****Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 0882K

**Vehicle Details**

Vehicle No.: FBM1884S

Vehicle to be Exported: No

Intended Deregistration Date: 06 Sep 2018

Vehicle Make: YAMAHA

Vehicle Model: FZN150

Primary Colour: White

Manufacturing Year: 2016

Engine No.: G3E3E0048287

Chassis No.: ME1RG1612G2002485

Maximum Power Output: -

Open Market Value: \$2,502.00

Original Registration Date: 14 Aug 2017

First Registration Date: 14 Aug 2017

Transfer Count: 0

Actual ARF Paid: \$376.00

**Intended PARF Rebate Details**

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

**Intended COE Rebate Details**

COE Expiry Date: 13 Aug 2027

COE Category: D - Motorcycle

COE Period(Years): 10

QP Paid: \$5,851.00

COE Rebate Amount: \$5,228.00

**Total Rebate Amount: \$5,228.00**

The information contained herein is correct as at 06 Sep 2018

OK



**BAN HOCK HIN**  
Co., Pte Ltd

Co.Reg.No: 197000288K  
MOTORCYCLE ACCESSORIES | SERVICE CENTRE  
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL  
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

## QUOTATION

Customer :

MSIG INSURANCE (S) PTE LTD  
4 SHENTON WAY  
#21-01 SGX CENTRE 2  
SINGAPORE 068807

NO. : 32961

DATE : 04/09/2018  
CLAIM NO. : 11180  
POLICY NO. :  
FROM : RAYMOND

*Not Authorised  
6/9/18  
marcus Hah  
The photo after repair  
3 dy.*

VEHICLE NO. : FBM1884S  
MAKE/MODEL : YAM / FZN150

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BOX SIDE (GIVI) E22N (BLACK) P/N: 49418	REPLACE	1.00	\$255.00	255.00 <i>good</i> X
2	COVER TANK CENTRE	REPLACE	1.00	\$62.00	62.00 <i>alc scan</i> X
3	CRASHBAR FRONT ASSY	REPLACE	1.00	\$266.00	266.00 <i>scan alc</i> X
4	INNER TUBE COMP P/N: 52255	REPLACE	2.00	\$168.00	336.00 <i>17</i> X
5	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING PARTS QUOTED.	<i>4</i> Supply/Install	1.00	\$250.00	250.00 <i>220</i>
6	MUDGUARD REAR P/N: 53970	REPLACE	1.00	\$55.00	55.00 <i>good</i> ?
7	OIL FORK (FUCHS) MR-10 P/N: 27651	REPLACE	1.00	\$12.00	12.00 <i>17</i> X
8	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951	<i>4</i> REPLACE	1.00	\$15.00	15.00 <i>scan</i> <i>105</i>
9	SEAL OIL (40X53X8) FORK P/N: 27176	REPLACE	2.00	\$18.00	36.00 <i>17</i> X
10	STICKER (CERTIS CISCO) SIDE BOX (LH/RH) P/N: 55649	<i>4</i> REPLACE	1.00	\$20.00	20.00 <i>u</i> ?
11	TRANSPORT CHARGES P/N: 07169 - FOR COLLECTION OF ACCIDENT BIKE.		1.00	\$35.00	35.00 ✓

SUB TOTAL  
GST @ 7 %

\$1,342.00  
\$93.94



1901



S/N	Description	Action	Qty	Unit Price	Amount
GRAND TOTAL					\$1,435.94

1595.94

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of  
**BAN HOCK HIN CO PTE LTD**

Acknowledge &amp; Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-310  
 10h  
 279  
 S.N 190  
 16h 255  
 724







**BAN HOCK HIN**  
Co., Pte Ltd

Co. Reg. No: 197000288K  
MOTORCYCLE ACCESSORIES | SERVICE CENTRE  
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL  
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

## QUOTATION

Customer :

MSIG INSURANCE (S) PTE LTD  
4 SHENTON WAY  
#21-01 SGX CENTRE 2  
SINGAPORE 068807

NO. : 33207

Supplementary 1 To QTN: 32961

DATE : 02/11/2018

CLAIM NO. : 11180

POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FBM1884S  
MAKE/MODEL : YAM / FZN150

S/N	Description	Action	Qty	Unit Price	Amount
1	STICKER (CERTIS CISCO) REFLECTIVE BOXES P/N: 55650	Replace <i>ADD</i>	1.00	\$160.00	160.00
SUB TOTAL					\$160.00
GST @ 7 %					\$11.20
GRAND TOTAL					<b>\$171.20</b>

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of  
**BAN HOCK HIN CO PTE LTD**



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.



CERT NO.: 2002-1-0383  
ISO 9001: 2015

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg  
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759



**BAN HOCK HIN**  
Co., Pte Ltd

Co. Reg. No: 197000288K  
MOTORCYCLE ACCESSORIES | SERVICE CENTRE  
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL  
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

## QUOTATION

Customer :

NO. : 32961

- Rev. 2

MSIG INSURANCE (S) PTE LTD  
4 SHENTON WAY  
#21-01 SGX CENTRE 2  
SINGAPORE 068807

DATE : 04/09/2018  
CLAIM NO. : 11180  
POLICY NO. :  
FROM : RAYMOND

VEHICLE NO. : FBM1884S  
MAKE/MODEL : YAM / FZN150

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BOX SIDE (GIVI) E22N (BLACK) P/N: 49418	REPLACE	1.00	\$255.00 Disc %: 10.00	229.50
2	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING PARTS QUOTED.	Supply/Install	1.00	\$220.00	220.00
3	MUDGUARD REAR P/N: 53970	REPLACE	1.00	\$55.00 Disc %: 10.00	49.50
4	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951	REPLACE	1.00	\$10.00	10.00
5	STICKER (CERTIS CISCO) SIDE BOX (LH/RH) P/N: 55649	REPLACE	1.00	\$20.00	20.00
6	TRANSPORT CHARGES P/N: 07169 - FOR COLLECTION OF ACCIDENT BIKE.	Supply/Install	1.00	\$35.00	35.00
7	STICKER (CERTIS CISCO) REFLECTIVE BOXES P/N: 55650	Replace	1.00	\$160.00	160.00

SUB TOTAL

\$724.00

GST @ 7 %

\$50.68

GRAND TOTAL

**\$774.68**

**50% deposit required before ordering of parts.**

Validity: 30 days

For & on Behalf of  
**BAN HOCK HIN CO PTE LTD**

Acknowledge & Accepted By



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg  
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0363  
ISO 9001: 2015

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
------------	--------------------	---------------	------------	-------------------	---------------

**RAYMOND**

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.



### ...CLAIM SUBFOLDER...(Pending for Survey Report)




































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Sep 2018		05 Sep 2018 09:35 <a href="#">Edit Adj Rpt</a>	<b>S\$724.00</b> <a href="#">Edit Estimates</a>	<b>S\$724.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>ONG PANG YONG</b> , ID: S8413534H									
Main Claimant: <b>CERTIS CISCO AUXILIARY POLICE FORCE PTE LTD</b> , Co. Reg. No.: 200900882K									
Vehicle Reg. No.: <b>FBM1884S</b>		Date of Loss: 30/08/2018 00:00 - :59 [12 Months and 16 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 569275</b>		Policy/Cover Note No.: 80457041QMX Coverage: 26/05/2018 - 25/05/2019							
Vehicle Reg. No. (Insured): <b>SLC8290T</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Ban Hock Hin Co. Pte Ltd (HQ)</b> No. 6 Defu Lane 4, 539410 Defu Lane - Tel: 62816520									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Elaine Ngu Siau Mei</b> - 6594 2540]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 05/10/2018]									
Adj Asg. Remarks: ON WP. Bike is in. Non Reporting. Liability unclear. Contact Person: Raymond / 6281 6520 x 220									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*FBM1884S (569275)**  
**[SLC8290T]**  
**TP**  
**CERTIS CISCO AUXILIARY POLICE FORCE PTE LTD**  
**Aug 30 2018 12:00AM**  
**[ONG PANG YONG]**  
**Ban Hock Hin Co. Pte Ltd**

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/09/18 09:44	Adjuster Immediate Advice	 Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/09/18 17:48	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
2	06/09/18 17:48	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
3	06/09/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
4	06/09/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
5	06/09/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
6	06/09/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
7	06/09/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
8	06/09/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
9	06/09/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
10	06/09/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
11	06/09/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
12	06/09/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
13	06/09/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
14	06/09/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
15	06/09/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
16	06/09/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
17	06/09/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
18	06/09/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
19	06/09/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
20	06/09/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
21	06/09/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
22	06/09/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
23	06/09/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
24	06/09/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
25	06/09/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
26	06/09/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
27	06/09/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
28	06/09/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
29	06/09/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
30	05/11/18 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	05/11/18 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	05/11/18 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	05/11/18 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	05/11/18 08:57	Reinspection Photo	 Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	05/11/18 08:57	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	05/11/18 08:57	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	05/11/18 08:57	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	05/11/18 08:57	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	05/11/18 08:57	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	05/11/18 08:57	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	05/11/18 08:57	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	05/11/18 08:57	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	05/11/18 08:57	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/09/18 16:23	Estimate	Load PDF	
2	04/09/18 16:24	Email - PRI	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/11/18 08:54	Supplementary	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18016206/URD3E2

Date: 07/11/2018

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: 80457041QMX
Claimant Vehicle No : FBM1884S	Insured Vehicle No : SLC8290T
Date of Loss: 30/08/2018	Nature of Claim: TP Claim No: 569275

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBM1884S	Engine No: G3E3E0048287
Make & Model: YAMAHA FZN150, 149cc	Chassis No: ME1RG1612G2002485
Reg. Date: 14/08/2017 (Man. Year: 2016)	Odometer: 13050 km
Colour: White	
Engine Capacity: 149 cc	
Market Value/New Car Price: N/A	
Sum Insured (\$\$): Market Value/New Car Price	

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	100-80-17	Rear Tyre Size:	140/60 R17
Front Left Side:	MRF 8 mm	Rear Left Side:	MRF 8 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,217.00	469.00	748.00	61.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	285.00	255.00	30.00	10.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>1,502.00</b>	<b>724.00</b>	<b>778.00</b>	<b>51.80</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>105.14</b>	<b>50.68</b>	<b>54.46</b>	<b>51.80</b>
<b>Nett Amount (\$\$)</b>	<b>1,607.14</b>	<b>774.68</b>	<b>832.46</b>	<b>51.80</b>

### INSPECTION

Date of Assignment:	05/09/2018	
Date Inspected:	06/09/2018	Inspected At: Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4 Singapore 539410
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 07 Nov 2018)	
<b>Parts:</b>	N/A	YAMAHA FZN150 149cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBM1884S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOX SIDE (GIVI) E22N (BLACK)	Grazed	255.00 F	*255.00 FL
2	1		*COVER TANK CENTRE (SCRATCHED)	Not Consistent With The Impact	62.00 F	*- FL
3	1		*CRASHBAR FRONT ASSY (SCRATCHED)	Not Consistent With The Impact	266.00 F	*- FL
4	2		*INNER TUBE COMP	Not Necessary	336.00 F	*- FL
5	1		*MUDGUARD REAR	Grazed	55.00 F	*55.00 FL
6	1		*OIL FORK (FUCHS) MR-10	Not Necessary	12.00 F	*- FL
7	1		*PLATE NUMBER REAR (6.5 INCH X 9 INCH)	Bent	15.00 FS	*10.00 FS
8	1		*SEAL OIL (40X53X8) FORK	Not Necessary	36.00 F	*- FL
9	1		*STICKER (CERTIS CISCO) SIDE BOX (LH/RH)	Necessary	20.00 FS	*20.00 FS
10	1		*STICKER (CERTIS CISCO) REFLECTIVE BOXES	Necessary	160.00 FS	*160.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>1,217.00</b>	<b>500.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	<b>0.00</b>	<b>31.00</b>
<b>Total Parts (\$\$)</b>	<b>1,217.00</b>	<b>469.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR-FOR DISMANTLING AND ASSEMBLING PARTS	New	250.00	220.00
2	TRANSPORT CHARGES-FOR COLLECTION OF ACCIDENT BIKE	New	35.00	35.00
Gross Labour Cost (\$\$)			285.00	255.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >