

ASS. REC. BY:

REF: CS3/AIG18016231/R/cd3⁸²

Special Instructions:

Surveyor
menmen

Rasu

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

5/9/18 12:31 pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE 5670 H

Insured:

SLM 5283G

at Workshop no/s

Glocke Werke

Tel:

8112 6485

of

1 Kaki Bkt Ave 6 # 01-08

Policy No:

2100507642

Claim No:

44164216773G

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

03/09/2018

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

12:43 pm 5/9/18

Person Contacted:

Annabelle

Vehicle

IN / OUT

Date/Time	Action/Instruction (X) Estimate
	GBE 5670 H -
	SLM 5283G - X
	Demantle: 6/9/2018
	After repair: 10/9/2018



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS3/AIG18016231/R1cd3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 05-09-2018		
		Code : AIG		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SLM 5283G	Veh. Inspected	GBE 5670H	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	CHIN LEE YING	Assign Date	05/09/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	03/09/2018	Inspection Date	05/09/2018	
Survey held at	GLOCKEWERKE- 1 KAKI BUKIT AVE 6 # 01-08			
Repairer	-			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 5/9/2018 12:31:54 PM
Attachments:  GIA Report - GBE5670H.PDF  PRS Letter to AIG 04092018.pdf
 2nd PRS Letter to AIG 04092018.pdf

Hi LKK,

Kindly assist to survey, vehicle in workshop, please contact Annabelle to arrange.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

From: pri@satwantlaw.com [mailto:pri@satwantlaw.com]
Sent: Tuesday, September 04, 2018 1:44 PM
To: Chan, Yoke Shi
Cc: pri@satwantlaw.com
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLM5283G AND GBE5670H ON 03/09/2018

Without Prejudice

Dear Yoke Shi,

We have instructions to reject your surveyor and propose to engage Constant Appraiser Services.

Kindly see attached our letter and workshop details as below:-

Workshop name: GLOCKEWERKE

Address: Blk 1 Kaki Bukit Avenue 6, #01-08, Autobay @ Kaki Bukit Singapore 417883

Contact Person: Annabelle (HP:8112 6485)

Kindly liaise with the workshop directly for the PRS on an urgent basis. Thank you.

Regards,

Spencer

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Sarwant Singh
Priam Singh
Khong Zi-Wei

SATWANT ASSOCIATES

ADVANCED SOLUTIONS & REPRESENTATION FOR CLAIMS & LITIGATION

CONVEYANCING OFFICE:
450 Lorong 6 Toa Payoh
#02-03 Harsing Centre
Singapore 319394
Tel: 6221 6114
Fax: 6266 6925
www.satwantlaw.com.sg
(Fax not for service
of documents)

An Official Member of The Lawyer Network, an international network of law firms

(Please quote our Ref. when replying)

Your Ref : To be advised
Our Ref: PD/DL/1801594 (sp) – Toa Payoh Office
(pri@satwantlaw.com)

04 September 2018

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#07-16 AIG Building
Singapore 079120

BY EMAIL ONLY


Attention: Motor Claims Department

Dear Sir/Mdm,

**ACCIDENT INVOLVING GBE5670H & SLM5283G ALONG UPPER JURONG ROAD
TURNING RIGHT TO BENOI ROAD ON 03/09/2018 @ 07:50**

1. We are instructed by Hohin Industrial Tradings Pte Ltd to notify you of a road accident on 03 September 2018 at about 07:50 along Upper Jurong Road turning right to Benoi Road involving our client's vehicle registration number GBE5670H and vehicle registration number SLM5283G driven by your insured at the material time. A copy of the Singapore accident statement filed is enclosed.
2. As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully,



SATWANT & ASSOCIATES

enc

MAIN OFFICE:
3 Jalan Bingka
Singapore 588896
Tel: 6299 9470 Fax: 6299 5541

CONVEYANCING BRANCH OFFICE:
450 Lorong 6 Toa Payoh #02-03 Harsing Centre
Singapore 319394
Tel: 6221 6114 Fax: 6266 6925

This document is intended for the addressee(s) only and may contain confidential information and/or may be subject to legal privilege. If you have received this in error, please contact us immediately and destroy the original message.

Satwant Singh
Pritam Singh
Khong Zi-Wei



CONVEYANCING OFFICE:
450 Lorong 6 Toa Payoh
#02-03 Harsing Centre
Singapore 319394
Tel: 6221 6114
Fax: 6266 6925
www.satwantlaw.com.sg
(Fax not for service
of documents)

An Official Member of The Lawyer Network, an international network of law firms

(Please quote our Ref. when replying)

Your Ref: To be advised
Our Ref: PD/DL/1801594 (sp) – Toa Payoh Office
(pri@satwantlaw.com)

04 September 2018

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#07-16 AIG Building
Singapore 079120

BY EMAIL ONLY

Attention: Motor Claims Department

Dear Sir/Mdm,

**ACCIDENT INVOLVING GBE5670H & SLM5283G ALONG UPPER JURONG ROAD
TURNING RIGHT TO BENOI ROAD ON 03/09/2018 @ 07:50**

We refer to your email dated 04 September 2018 confirming your intention to conduct a pre-repair survey on our client's vehicle GBE5670H.

Please be informed that said vehicle can be inspected at:

Workshop name: GLOCKEWERKE

Address: Blk 1 Kaki Bukit Avenue 6, #01-08, Autobay @ Kaki Bukit Singapore 417883

Contact Person: Annabelle (HP:8112 6485)

In the event you fail to conduct the pre-repair survey within the next 2 working days, excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,

SATWANT & ASSOCIATES

cc client

For Surveyor: To initial after Completion

1st Inspection
Appointed surveyor
(Name & Signature)

Date & Time

2nd Inspection
Appointed surveyor
(Name & Signature)

Date & Time

3rd Inspection
Appointed surveyor
(Name & Signature)

Date & Time

NB: Any Settlement of offer is on the express condition that no settlement is in respect of our client's claim for property related damaged only and shall not preclude our client from claiming injury-related damages arising from this accident.
This document is intended for the addressee(s) only and may contain confidential information and/or may be subject to legal privilege. If you have received this in error, please contact us immediately and destroy the original message.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/09/2018 16:00
Date Of Accident	03/09/2018 07:50
Exact Location Of Accident	UPPER JURONG RD TURNING RIGHT TO BENOI RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE5670H
Insured/Policyholder	
Name Of Registered Owner	HOHIN INDUSTRIAL TRADINGS PTE LTD
Co Reg No	199400246D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-68484566

Vehicle Particulars

Manufacturer	FIAT
Model	DOBLO MAXI
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P1708819
Cover Note Number	

Driver

Name of Driver	ONG JUN LI
NRIC No	S8506215H
Date Of Birth	07/02/1985
Occupation	INDOOR
Date Of Driving Pass	29/03/2006
Driving Experience	12 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94570291
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 678B PUNGGOL DRIVE #04-832
 Postcode 822678
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

MY VEHICLE WAS STATIONARY. SUDDENLY, I FELT AN IMPACT FROM BEHIND. FOUND OUT THAT VEHICLE B HAD REAR ENDED MY VEHICLE.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLM5283G
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)


SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My vehicle was stationary. Suddenly i felt an impact from behind. Found out that vehicle B had rear ended my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NAIC/FIN No.:


LETTER OF UNDERTAKING

I/We, PTG LTD
HOTHING INDUSTRIAL TRADING, the owner of vehicle no. 8938 567017

My/Our Insurance is under M/s AXA Insurance Singapore Pte Ltd, I/we shall decide whether to claim under my/our Policy or against the Third Party and if the former shall submit such a claim to M/s AXA Insurance Singapore Pte Ltd with all relevant facts and documents within 14(fourteen) days of occurrence or discovery of damage.

My/Our Third Party claim is handle by my/our preferred workshop, _____

Signed and Acknowledge by:


Nric no. and signature of policyholder

.....
Company Stamp

03/09/2018
.....
Date

Driving License

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8506215H



name

ONG JUN LI

王 俊 力


CHINESE

Date of birth

07-02-1945
COMMUNIST, FORMERLY
SINGAPORE

三三


H3-PR615-



5543076



內政部警政司 38508215H



23-12-2015

Address

APT' BLK 8788 PUNGOOL DRIVE
204-832
SINGAPORE 622678



> **Back to OneMotoring**

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	GBE5670H		
Vehicle Type :	A50 - Goods (Closed) Van/Van Panel (Delivery)		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	FIAT		
Vehicle Model :	DOBLO CARGO MAXI 1.6 MTJ AMT GLAZE		
Chassis No. :	ZFA26300006B57886		
Propellant :	Diesel		
Engine No. :	263A50007511371		
Engine Capacity :	1598 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	2465 kg		
Unladen Weight :	1500 kg		
Year Of Manufacture :	2015		
Original Registration Date :	13 Jan 2016		
Lifespan Expiry Date :	12 Jan 2036		
COE Category :	C - Goods Vehicle & Bus		
Quota Premium :	\$42,036.00		
COE Expiry Date :	12 Jan 2026		
Road Tax Expiry Date :	12 Jan 2019		
Inspection Due Date :	12 Jan 2019		
Intended Transfer Date :	06 Sep 2018		
CO2 Emission :	141.00 (g/km)		
CEV/VES Rebate Utilised Amount :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00
Message			
This vehicle has a road tax Over Payment of \$142.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.			

You may print this page for reference.

OK

Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0246D
Vehicle Details	
Vehicle No.:	GBE5670H
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Sep 2018
Vehicle Make:	FIAT
Vehicle Model:	DOBLO CARGO MAXI 1.6 MTJ AMT GLAZE
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	263A50007511371
Chassis No.:	ZFA26300006B57886
Maximum Power Output:	-
Open Market Value:	\$19,685.00
Original Registration Date:	13 Jan 2016
First Registration Date:	13 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$985.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 Jan 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$42,036.00
COE Rebate Amount:	\$30,894.00
Total Rebate Amount:	\$30,894.00

The information contained herein is correct as at 06 Sep 2018

OK

Condition (1) (2) (3) (4) (5) (6) (7) (8) (9) (10) (11) (12) (13) (14) (15) (16) (17) (18) (19) (20) (21) (22) (23) (24) (25) (26) (27) (28) (29) (30) (31) (32) (33) (34) (35) (36) (37) (38) (39) (40) (41) (42) (43) (44) (45) (46) (47) (48) (49) (50) (51) (52) (53) (54) (55) (56) (57) (58) (59) (60) (61) (62) (63) (64) (65) (66) (67) (68) (69) (70) (71) (72) (73) (74) (75) (76) (77) (78) (79) (80) (81) (82) (83) (84) (85) (86) (87) (88) (89) (90) (91) (92) (93) (94) (95) (96) (97) (98) (99) (100) (101) (102) (103) (104) (105) (106) (107) (108) (109) (110) (111) (112) (113) (114) (115) (116) (117) (118) (119) (120) (121) (122) (123) (124) (125) (126) (127) (128) (129) (130) (131) (132) (133) (134) (135) (136) (137) (138) (139) (140) (141) (142) (143) (144) (145) (146) (147) (148) (149) (150) (151) (152) (153) (154) (155) (156) (157) (158) (159) (160) (161) (162) (163) (164) (165) (166) (167) (168) (169) (170) (171) (172) (173) (174) (175) (176) (177) (178) (179) (180) (181) (182) (183) (184) (185) (186) (187) (188) (189) (190) (191) (192) (193) (194) (195) (196) (197) (198) (199) (200) (201) (202) (203) (204) (205) (206) (207) (208) (209) (210) (211) (212) (213) (214) (215) (216) (217) (218) (219) (220) (221) (222) (223) (224) (225) (226) (227) (228) (229) (230) (231) (232) (233) (234) (235) (236) (237) (238) (239) (240) (241) (242) (243) (244) (245) (246) (247) (248) (249) (250) (251) (252) (253) (254) (255) (256) (257) (258) (259) (260) (261) (262) (263) (264) (265) (266) (267) (268) (269) (270) (271) (272) (273) (274) (275) (276) (277) (278) (279) (280) (281) (282) (283) (284) (285) (286) (287) (288) (289) (290) (291) (292) (293) (294) (295) (296) (297) (298) (299) (300) (301) (302) (303) (304) (305) (306) (307) (308) (309) (310) (311) (312) (313) (314) (315) (316) (317) (318) (319) (320) (321) (322) (323) (324) (325) (326) (327) (328) (329) (330) (331) (332) (333) (334) (335) (336) (337) (338) (339) (340) (341) (342) (343) (344) (345) (346) (347) (348) (349) (350) (351) (352) (353) (354) (355) (356) (357) (358) (359) (360) (361) (362) (363) (364) (365) (366) (367) (368) (369) (370) (371) (372) (373) (374) (375) (376) (377) (378) (379) (380) (381) (382) (383) (384) (385) (386) (387) (388) (389) (390) (391) (392) (393) (394) (395) (396) (397) (398) (399) (400) (401) (402) (403) (404) (405) (406) (407) (408) (409) (410) (411) (412) (413) (414) (415) (416) (417) (418) (419) (420) (421) (422) (423) (424) (425) (426) (427) (428) (429) (430) (431) (432) (433) (434) (435) (436) (437) (438) (439) (440) (441) (442) (443) (444) (445) (446) (447) (448) (449) (450) (451) (452) (453) (454) (455) (456) (457) (458) (459) (460) (461) (462) (463) (464) (465) (466) (467) (468) (469) (470) (471) (472) (473) (474) (475) (476) (477) (478) (479) (480) (481) (482) (483) (484) (485) (486) (487) (488) (489) (490) (491) (492) (493) (494) (495) (496) (497) (498) (499) (500) (501) (502) (503) (504) (505) (506) (507) (508) (509) (510) (511) (512) (513) (514) (515) (516) (517) (518) (519) (520) (521) (522) (523) (524) (525) (526) (527) (528) (529) (530) (531) (532) (533) (534) (535) (536) (537) (538) (539) (540) (541) (542) (543) (544) (545) (546) (547) (548) (549) (550) (551) (552) (553) (554) (555) (556) (557) (558) (559) (560) (561) (562) (563) (564) (565) (566) (567) (568) (569) (570) (571) (572) (573) (574) (575) (576) (577) (578) (579) (580) (581) (582) (583) (584) (585) (586) (587) (588) (589) (590) (591) (592) (593) (594) (595) (596) (597) (598) (599) (600) (601) (602) (603) (604) (605) (606) (607) (608) (609) (610) (611) (612) (613) (614) (615) (616) (617) (618) (619) (620) (621) (622) (623) (624) (625) (626) (627) (628) (629) (630) (631) (632) (633) (634) (635) (636) (637) (638) (639) (640) (641) (642) (643) (644) (645) (646) (647) (648) (649) (650) (651) (652) (653) (654) (655) (656) (657) (658) (659) (660) (661) (662) (663) (664) (665) (666) (667) (668) (669) (670) (671) (672) (673) (674) (675) (676) (677) (678) (679) (680) (681) (682) (683) (684) (685) (686) (687) (688) (689) (690) (691) (692) (693) (694) (695) (696) (697) (698) (699) (700) (701) (702) (703) (704) (705) (706) (707) (708) (709) (710) (711) (712) (713) (714) (715) (716) (717) (718) (719) (720) (721) (722) (723) (724) (725) (726) (727) (728) (729) (730) (731) (732) (733) (734) (735) (736) (737) (738) (739) (740) (741) (742) (743) (744) (745) (746) (747) (748) (749) (750) (751) (752) (753) (754) (755) (756) (757) (758) (759) (760) (761) (762) (763) (764) (765) (766) (767) (768) (769) (770) (771) (772) (773) (774) (775) (776) (777) (778) (779) (780) (781) (782) (783) (784) (785) (786) (787) (788) (789) (790) (791) (792) (793) (794) (795) (796) (797) (798) (799) (800) (801) (802) (803) (804) (805) (806) (807) (808) (809) (810) (811) (812) (813) (814) (815) (816) (817) (818) (819) (820) (821) (822) (823) (824) (825) (826) (827) (828) (829) (830) (831) (832) (833) (834) (835) (836) (837) (838) (839) (840) (841) (842) (843) (844) (845) (846) (847) (848) (849) (850) (851) (852) (853) (854) (855) (856) (857) (858) (859) (860) (861) (862) (863) (864) (865) (866) (867) (868) (869) (870) (871) (872) (873) (874) (875) (876) (877) (878) (879) (880) (881) (882) (883) (884) (885) (886) (887) (888) (889) (890) (891) (892) (893) (894) (895) (896) (897) (898) (899) (900) (901) (902) (903) (904) (905) (906) (907) (908) (909) (910) (911) (912) (913) (914) (915) (916) (917) (918) (919) (920) (921) (922) (923) (924) (925) (926) (927) (928) (929) (930) (931) (932) (933) (934) (935) (936) (937) (938) (939) (940) (941) (942) (943) (944) (945) (946) (947) (948) (949) (950) (951) (952) (953) (954) (955) (956) (957) (958) (959) (960) (961) (962) (963) (964) (965) (966) (967) (968) (969) (970) (971) (972) (973) (974) (975) (976) (977) (978) (979) (980) (981) (982) (983) (984) (985) (986) (987) (988) (989) (990) (991) (992) (993) (994) (995) (996) (997) (998) (999) (1000)

VAN / LORRY (Rear)

ACTION (AO)
(1) Replace (✓) (2) Repair (X) (3) Check (✓)
(4) Not Compliant (NC)

Aug 2015

Vehicle No: GBE 5670 H

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
2044	993628	Rear Number Plate Bracket			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper		CUT ✓	
1142	993108	Rear Bumper Upper Reflector		CRA ✓	
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side Clips		NEC ✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer RH		CR ✓	1
1149	993045	Rear Bumper Reinforcement		BT ✓	
2045	993081	Rear Bumper Step Panel			
2046	993079	Rear Bumper Step Garnish		NEC ✓	
2047	993186	Rear Crash Bar			
1158	994023	Reverse Sensor		CUT ✓	1
1159	993327	Rear End Panel			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp		CRA ✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1289	995156	Rear LH Door			
1350	993201	Rear RH Door		DD ✓	
2048	991328	Rear Door Emblem		NEC ✓	3
2049	993274	Rear Door Outer Handle			
2050	993228	Rear Door Garnish			
2051	993294	Rear Door Rubber			
1291	995194	Rear LH Door Hinge			
1352	995307	Rear RH Door Hinge			
1301	993261	Rear LH Door Lock			
1362	993261	Rear RH Door Lock			
2052	993232	Rear Door Glass			
2053	993955	Rear Door Glass Sealant			
1248	994729	Third Brake Light			
1181	994543	Tailgate			
2054	993700	Rear Rubber Stopper			
2055	993701	Rear Rubber Stopper Bracket			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1185	994545	Tailgate Garnish			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
2056	994597	Tailgate Extension Mirror			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			
2057	993992	Rear Wiper Arm			
2058	993995	Rear Wiper Blade			
2059	993997	Rear Wiper Motor			
2060	993484	Rear Floor Panel			
1204	995065	Spare Tyre			
2061	993785	Spare Tyre Bracket			
1212	993364	Rear Exhaust Pipe			
1214	993361	Rear Exhaust Mounting			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			

NAC	INC	Item	CON	AC	Qty
2062	993748	Rear Sidegate			
2063	994225	Rear Sidegate Lock			
2064	993749	Rear Sidegate Hinge			
2065	994226	Sidegate Lower Panel			
2066	994227	Sidegate Railing			
2067	994208	Side Cover Hook			
2068	991965	Side Step Panel			
2069	994496	Side Step Panel Stopper			
2070	992857	Rear Body Panel			
2071	992866	Rear Body Panel Inner			
2072	995329	Sliding Door LH			
2073	995328	Sliding Door RH			
2074	994295	Sliding Door Handle			
2075	994300	Sliding Door Lock			
2076	994313	Sliding Door Rubber			
2077	994291	Sliding Door Bottom Roller			
2078	994317	Sliding Door Top Roller			
2079	994306	Sliding Door Rail			
2080	994315	Sliding Door Stepboard			
2081	994316	Sliding Door Stepboard Garnish			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1136	990247	Sticker (6 PAX)		NEC ✓	1
1		Rear RH door glass sealant		NEC ✓	

24/9/2018

No of Items: 9 Assessor:

21/9/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Sep 2018 Edit Reg		05 Sep 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	SONG YONGFENG, ID: S7979181D		
Main Claimant:	-		
Vehicle Reg. No.:	GBE5670H	Date of Loss:	03/09/2018 00:00 - :59 [31 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 4916421677SG	Policy/Cover Note No.:	2100507642 (Comprehensive)
Vehicle Reg. No. (Insured):	SLM5283G	Policy No. (Claimant):	
		Excess:	
Repairer:	- Not Applicable - (-)		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 14/09/2018]		
Claimant's Solicitor:	SATWANT & ASSOCIATES - Tel: 62216114		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (06/09/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***GBE5670H (4916421677SG)**
[SLM5283G]

TP

Sep 3 2018 12:00AM
[SONG YONGFENG]

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View
[View in Browser](#)



Assessment Reports



























1 per page
 ☒

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	06/09/18 10:50	Accident Statement From:OD - Reg. No: SLM5283G, Claimant: SONG YONGFENG	 Load HTM	<input checked="" type="checkbox"/>

Photos/Images

3 per page
 ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
2	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
3	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
4	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
5	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
6	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
7	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
8	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
9	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
10	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
11	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
12	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
13	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
14	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
15	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
16	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
17	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
18	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
19	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
20	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
21	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
22	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
23	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
24	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
25	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
26	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
27	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
28	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
29	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
30	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
31	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
32	06/09/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
33	11/09/18 12:01	Photographs of Damaged Parts	 Load JPG	✓
34	11/09/18 12:01	Photographs of Damaged Parts	 Load JPG	✓
35	11/09/18 12:01	Photographs of Damaged Parts	 Load JPG	✓
36	11/09/18 12:01	Photographs of Damaged Parts	 Load JPG	✓
37	11/09/18 12:01	Photographs of Damaged Parts	 Load JPG	✓
38	11/09/18 12:01	Photographs of Damaged Parts	 Load JPG	✓
39	11/09/18 12:01	Photographs of Damaged Parts	 Load JPG	✓
40	11/09/18 12:01	Photographs of Damaged Parts	 Load JPG	✓
41	11/09/18 12:01	Photographs of Damaged Parts	 Load JPG	✓
42	11/09/18 12:01	Photographs of Damaged Parts	 Load JPG	✓
43	11/09/18 12:01	Photographs of Damaged Parts	 Load JPG	✓
44	11/09/18 12:01	Photographs of Damaged Parts	 Load JPG	✓
45	11/09/18 12:01	Photographs of Damaged Parts	 Load JPG	✓
46	11/09/18 12:01	Photographs of Damaged Parts	 Load JPG	✓
47	11/09/18 12:01	Photographs of Damaged Parts	 Load JPG	✓
48	11/09/18 12:01	Photo After Spray	 Load JPG	✓
49	11/09/18 12:01	Photo After Spray	 Load JPG	✓
50	11/09/18 12:01	Photo After Spray	 Load JPG	✓
51	11/09/18 12:01	Photo After Spray	 Load JPG	✓
52	11/09/18 12:01	Photo After Spray	 Load JPG	✓
53	11/09/18 12:01	Photo After Spray	 Load JPG	✓
54	11/09/18 12:01	Photo After Spray	 Load JPG	✓
55	11/09/18 12:01	Photo After Spray	 Load JPG	✓
56	11/09/18 12:01	Photo After Spray	 Load JPG	✓
57	11/09/18 12:01	Photo After Spray	 Load JPG	✓
58	11/09/18 12:01	Photo After Spray	 Load JPG	✓

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18016231/R1CD3S2
Date: 25/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100507642
Claimant Vehicle No: GBE5670H Insured Vehicle No: SLM5283G
Date of Loss: 03/09/2018 Nature of Claim: TP Claim No: 4916421677SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBE5670H
Make & Model: FIAT DOBLO CARGO MAXI, 1.6 D MTJ AMT GLAZE (M) Engine No: 263A50007511371
Reg. Date: 13/01/2016 (Man. Year: 2015) Chassis No: ZFA26300006B57886
Colour: Blue Odometer: 112580 km
Engine Capacity: 1598 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60R16 Rear Tyre Size: 195/60R16
Front Left Side: Continental 5 mm Rear Left Side: Continental 5 mm
Front Right Side: Continental 5 mm Rear Right Side: Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 05/09/2018
Date Inspected: 05/09/2018 Inspected At: GLOCKEWERKE
1 KAKI BUKIT AVE 6 # 01-08
Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	0.00 F	*- F
2	1		*REAR BUMPER REFLECTOR RH	Cracked	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*REAR BUMPER SIDE RETAINER RH	Cracked	0.00 F	*- F
5	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
6	1		*REAR BUMPER STEP GARNISH	Necessary	0.00 F	*- F
7	1		*REVERSE SENSOR	Cut	0.00 F	*- F
8	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
9	1		*REAR RH DOOR	Dented	0.00 F	*- F
10	3		*REAR DOOR EMBLEM	Necessary	0.00 F	*- F
11	1		*STICKER (6PAX)	Necessary	0.00 F	*- F
12	1		*REAR RH DOOR GLASS SEALANT	Necessary	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
-------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >