

22/03/2002

ASS. REC. BY:

REF: CS31 LCR 18016237 / Bcd3

Special Instruction:

Surveyor: Mr. Jim

ASSIGNMENT (Office)

From (Person):

Chin Bee Ying

of

LCR

Date/Time

19/11/04 @ 4.04pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBB 4335Z

Insured:

SLJ 1289H

at Workshop m/s

Motor Intel

Tel:

8838 3318

of

13 Kelci Bkt Rd 4 # 01-20

Policy No:

0999994809

Claim No:

55291057198G

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

5/9/2018

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

9:30am @ 5/9/18

Person Contacted:

Wilson

Vehicle  IN  OUT

Date/Time

Action/Instruction ( x ) Estimate

GBB 4335Z - X

SLJ 1289H - X

Dismantle: 6/9/2018

After repair: 11/9/2018





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/LCR18016237/Bcd3

78 SHENTON WAY #08-16  
CHARTIS BUILDINGS SINGAPORE 079120

Date : 05-09-2018



Code : LCR

## 1. Policy Particulars :- (THIRD PARTY CLAIM)

|              |               |                |            |
|--------------|---------------|----------------|------------|
| Insured Veh. | SLJ 1289H     | Veh. Inspected | GBB 4335Z  |
| Policy No.   |               | Coverage (\$)  | 0.00       |
| Claim No.    |               | Excess (\$)    | 0.00       |
| Assign From  | CHIN LEE YING | Assign Date    | 05/09/2018 |

## 2. Vehicle Particulars & Condition

|              |        |              |   |
|--------------|--------|--------------|---|
| Make & Model |        | c.c          | 0 |
| Engine No.   | HIDDEN | Year of Reg. |   |
| Chassis No.  |        | Colour       |   |
| Odometer     | -      | Steering     |   |
| Brakes       |        | Modification |   |
| General      |        |              |   |

## 3. Conditions of Tyres

|                | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre |      |      | mm      |
| L/H Front Tyre |      |      | mm      |
| R/H Rear Tyre  |      |      | mm      |
| L/H Rear Tyre  |      |      | mm      |

## 4. Description of Damages

|  |
|--|
|  |
|--|

## 5. General Information

|                |   |                 |            |
|----------------|---|-----------------|------------|
| Accident Date  | 03/09/2018  | Inspection Date | 05/09/2018 |
| Survey held at | MOTOR INTEL AUTOMO PTE LTD<br>13 KAKI BUKIT ROAD 4 @ BARTLEY BIZ CENTRE #01-20 SINGAPORE 147807 |                 |            |

## 5a. Remarks

|   |
|---|
| <p>A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br/>         B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.<br/>         THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.<br/>         C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.</p> |
|---|

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...**

From: Chin, Lee-Ying  
To: assignments, Admin A  
Cc: Fan, Winnie-LW, Fong, Andy-SY  
Sent: 4/9/2018 4:04:15 PM  
Attachments:  20180904142850492.pdf

---

Hi LKK,

Kindly assist to survey.

Thanks.

Regards,  
Lee Ying

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**CHIA S ARUL LLC**  
ADVOCATES & SOLICITORS  
UEN 201330709H

ARULCHELVAN S

Our Ref : GBB 4335Z (wk)

Your Ref : To be advised

4 September 2018

**AIG Asia Pacific Insurance Pte Ltd**

**BY EMAIL ONLY**

Dear Sirs,

**RE: PROPERTY DAMAGE CLAIM**  
**CLAIMANT : DING FENG CAPITAL PTE LTD**  
**ACCIDENT INVOLVING GBB 4335Z & SLJ 1289H ALONG BUANGKOK**  
**GREEN ROAD ON 3 SEPTEMBER 2018**  
**PRE-REPAIR SURVEY NOTICE**

1. We act for Ding Feng Capital Pte Ltd, the owner of motor vehicle no. GBB 4335Z which was involved in the aforesaid accident.
2. We hereby in compliance with the Pre-Action Protocol for Non-Injury Motor Accident Claims, Appendix C of the State Courts Practice Directions Amendment No. 1 of 2016 ("the NIMA Protocol") give you **NOTICE** that we are claiming against your insured motor vehicle no. SLJ 1289H for damages, costs and disbursements as a result of your insured driver's negligence.
3. Please let us know if you wish to conduct a pre-repair survey on our client's motor vehicle at:

|                |  |
|----------------|--|
| Workshop       | Motor Intel Automo Pte. Ltd.                                       |
| Address        | 13 Kaki Bukit Road 4 #01-20 Bartley Biz Centre<br>Singapore 417807 |
| Contact Person | Mr. Wilson (8838 3318)   |

4. Pursuant to paragraph 2.3 of the NIMA Protocol, in the event we do not receive your response within next two (2) working days (excluding any Saturday, Sunday or public holiday), our client will instruct the workshop to commence appraisal and repairs to the damaged motor vehicle without further reference to you.
5. Please advise the appointed surveyor to endorse on page 2 of this letter after the completion of each inspection.

Yours faithfully,

**MR ARULCHELVAN S**  
cc: Client (By Email)

---

151 CHIN SWEE ROAD • #03-09  
MANHATTAN HOUSE • SINGAPORE 169876  
TEL : (65) 6733 4647 • FAX : (65) 6733 8183 (not for Service of Court documents)  
EMAIL : info@chiaarul.com

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars     |                         |
|-------------------------------|-------------------------|
| Owner ID Type:                | Company                 |
| Owner ID:                     | 3082Z                   |
| Vehicle Details               |                         |
| Vehicle No.:                  | GBB4335Z                |
| Vehicle to be Exported:       | No                      |
| Intended Deregistration Date: | 05 Sep 2018             |
| Vehicle Make:                 | NISSAN                  |
| Vehicle Model:                | CABSTAR                 |
| Primary Colour:               | Silver                  |
| Manufacturing Year:           | 2003                    |
| Engine No.:                   | QD32177763              |
| Chassis No.:                  | JN15F4F23Z0850333       |
| Maximum Power Output:         | -                       |
| Open Market Value:            | \$20,020.00             |
| Original Registration Date:   | 04 Apr 2003             |
| First Registration Date:      | 04 Apr 2003             |
| Transfer Count:               | 3                       |
| Actual ARF Paid:              | \$1,001.00              |
| Intended PARF Rebate Details  |                         |
| PARF Eligibility:             | No                      |
| PARF Eligibility Expiry Date: | -                       |
| PARF Rebate Amount:           | \$0.00                  |
| Intended COE Rebate Details   |                         |
| COE Expiry Date:              | 31 Mar 2019             |
| COE Category:                 | C - Goods Vehicle & Bus |
| COE Period(Years):            | 10                      |
| PQP Paid:                     | \$3,733.00              |
| COE Rebate Amount:            | \$212.00                |
| <b>Total Rebate Amount:</b>   | <b>\$212.00</b>         |

The information contained herein is correct as at 05 Sep 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |   |
|----------------------------|---|
| Date Of Report             | 04/09/2018 12:16                            |
| Date Of Accident           | 03/09/2018 13:00                            |
| Exact Location Of Accident | BUANGKOK GREEN RD SLIP RD TO HOUGANG AVE 04 |
| Country/State of Loss      | SINGAPORE                                   |

### DETAILS OF OWN VEHICLE

|                             |                             |
|-----------------------------|-----------------------------|
| Vehicle Registration Number | GBB4335Z                    |
| <b>Insured/Policyholder</b> |                             |
| Name Of Registered Owner    | DING FENG CAPITAL PTE. LTD. |
| Co Reg No                   | 201223082Z                  |
| Email Address               | NOEMAIL                     |
| Mobile Phone No             |                             |
| Alternative Phone No        | OFFICE-90000000             |

### Vehicle Particulars

|  |                       |
|--|-----------------------|
| Manufacturer   | NISSAN                |
| Model  | CABSTAR-3.0 D F24 (M) |
| Exact Purpose for which vehicle was being used at time of accident           | COMMERCIAL USE        |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO                    |
| If No, Please state action to be taken                                       | THIRD PARTY           |
| Vehicle Category   | COMMERCIAL VEHICLE    |

### Insurance Company

|                           |  |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage          | THIRD PARTY FIRE AND/OR THEFT          |
| Fleet Policy              | NO                                     |
| Policy Number             | 5091127164-01                          |
| Cover Note Number         |  |

### Driver

|                      |                        |
|----------------------|------------------------|
| Name of Driver       | ONG AIK SENG           |
| NRIC No              | S1574604A              |
| Date Of Birth        | 04/07/1963             |
| Occupation           | OUTDOOR                |
| Date Of Driving Pass | 15/09/1983             |
| Driving Experience   | 34 YEARS AND 11 MONTHS |
| Gender               | MALE                   |
| Mobile Number        | (LOCAL) +65-82355160   |
| Fax Number           |                        |
| Contact Number       |                        |
| EMail Address        | NOEMAIL                |

Address BLK 120B EDGEFALE PLAINS #03-293  
 Postcode 822120  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 3  
 Passenger 1 NAME: : -  
 GENDER: : MALE  
 Passenger 2 NAME: : -  
 GENDER: : MALE

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

REFER TO BELOW STATEMENT/SKETCH PLAN


**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SLJ1289H  
 Vehicle Make/Model/Colour HONDA VEZEL  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver  
 NRIC/Passport Number S7663193Z  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Buangkok Green Rd towards Hougang Ave 4. Somewhere on the single lane slip road to Hougang Ave 4, I slowed down and stopped to give way to traffic along the main road when I suddenly felt an impact from the rear portion of my vehicle. After the accident, I alighted to see that Vehicle B had collided into the rear portion of my vehicle. Hence I was involved in an accident of 2 vehicles.

Veh A GBB 4335 Z  
Veh B SLJ 1289 H

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature: *ONG*  
Date & Time: \_\_\_\_\_



Driver's Signature: *ONG*  
Date & Time: \_\_\_\_\_

03 SEP 2018

IDAC KAKI BUKIT (VAC)  
23 KAKI BUKIT AVE 4  
Singapore 415933  
Name: \_\_\_\_\_  
Tel: 67416697  
NRIC/FIN No.: \_\_\_\_\_  
Fax: 67492305  
Email: vackb@singnet.com.sg

Condition (1) OK

(01) Bent (2) Dented (3) Distorted (4) Melted (5) Cracked (6) Scratched  
 (07) Deformed (08) Stiffened (09) Bent (10) Broken (11) Necessary  
 (12) Missing (13) Torn (14) Unconfirmed (15) Not Working

**VAN / LORRY (Rear)**

ACTION (AC)

(1) Replace (✓) (2) Repair (X) (3) Check (P)  
 (4) Not Consistent (NC)

Aug 2015

Vehicle No: **GBB 4335Z**

**Rear Portion**

| NAC  | INC    | Item                        | CON | AC | Qty |
|------|--------|-----------------------------|-----|----|-----|
| 1137 | 993626 | Rear Number Plate           | BR  | ✓  |     |
| 1138 | 993627 | Rear Number Plate Base      |     |    |     |
| 2044 | 993628 | Rear Number Plate Bracket   | BT  | ✓  |     |
| 1140 | 993632 | Rear Number Plate Lamp      |     |    |     |
| 1141 | 992958 | Rear Bumper                 |     |    |     |
| 1142 | 993108 | Rear Bumper Upper           |     |    |     |
| 1143 | 993017 | Rear Bumper Lower           |     |    |     |
| 1144 | 993054 | Rear Bumper Side            |     |    |     |
| 1147 | 992976 | Rear Bumper Bracket         |     |    |     |
| 1148 | 993068 | Rear Bumper Side Retainer   |     |    |     |
| 1149 | 993045 | Rear Bumper Reinforcement   |     |    |     |
| 2045 | 993081 | Rear Bumper Step Panel      |     |    |     |
| 2046 | 993079 | Rear Bumper Step Garnish    |     |    |     |
| 2047 | 993186 | Rear Crash Bar              |     |    |     |
| 1158 | 994023 | Reverse Sensor              |     |    |     |
| 1159 | 993327 | Rear End Panel              |     |    |     |
| 1163 | 993851 | Rear LH Taillamp            | BR  | ✓  |     |
| 1164 | 993853 | Rear LH Taillamp Garnish    |     |    |     |
| 1165 | 993859 | Rear LH Taillamp Panel      | BT  | ✓  |     |
| 1166 | 995116 | Rear RH Taillamp            | SCR | ✓  |     |
| 1167 | 993853 | Rear RH Taillamp Garnish    |     |    |     |
| 1168 | 993859 | Rear RH Taillamp Panel      | BT  | ✓  |     |
| 1169 | 993554 | Rear Apron Panel            |     |    |     |
| 1289 | 995156 | Rear LH Door                |     |    |     |
| 1350 | 993201 | Rear RH Door                |     |    |     |
| 2048 | 991328 | Rear Door Emblem            |     |    |     |
| 2049 | 993274 | Rear Door Outer Handle      |     |    |     |
| 2050 | 993228 | Rear Door Garnish           |     |    |     |
| 2051 | 993294 | Rear Door Rubber            |     |    |     |
| 1291 | 995194 | Rear LH Door Hinge          |     |    |     |
| 1352 | 995307 | Rear RH Door Hinge          |     |    |     |
| 1301 | 993261 | Rear LH Door Lock           |     |    |     |
| 1362 | 993261 | Rear RH Door Lock           |     |    |     |
| 2052 | 993232 | Rear Door Glass             |     |    |     |
| 2053 | 993955 | Rear Door Glass Sealant     |     |    |     |
| 1248 | 994729 | Third Brake Light           |     |    |     |
| 1181 | 994543 | Tailgate                    |     |    |     |
| 2054 | 993700 | Rear Rubber Stopper         |     |    |     |
| 2055 | 993701 | Rear Rubber Stopper Bracket |     |    |     |
| 1182 | 991328 | Tailgate Emblem             |     |    |     |
| 1183 | 994643 | Tailgate Outer Handle       |     |    |     |
| 1185 | 994545 | Tailgate Garnish            |     |    |     |
| 1193 | 994602 | Tailgate Glass              |     |    |     |
| 1194 | 994606 | Tailgate Glass Rubber       |     |    |     |
| 1195 | 994604 | Tailgate Glass Moulding     |     |    |     |
| 1196 | 994607 | Tailgate Glass Sealant      |     |    |     |
| 2056 | 994597 | Tailgate Extension Mirror   |     |    |     |
| 1197 | 994629 | Tailgate Lock               | DIS | ✓  | 2   |
| 1198 | 994651 | Tailgate Rubber             |     |    |     |
| 1199 | 994611 | Tailgate Hinge              |     |    |     |
| 1200 | 994594 | Tailgate Damper             |     |    |     |
| 1201 | 994613 | Tailgate Inner Board        |     |    |     |
| 2057 | 993992 | Rear Wiper Arm              |     |    |     |
| 2058 | 993995 | Rear Wiper Blade            |     |    |     |
| 2059 | 993997 | Rear Wiper Motor            |     |    |     |
| 2060 | 993484 | Rear Floor Panel            |     |    |     |
| 1204 | 995065 | Spare Tyre                  |     |    |     |
| 2061 | 993785 | Spare Tyre Bracket          |     |    |     |
| 1212 | 993364 | Rear Exhaust Pipe           | BT  | ✓  |     |
| 1214 | 993361 | Rear Exhaust Mounting       | DIS | ✓  |     |
| 1216 | 995223 | Rear LH Chassis Member      |     |    |     |
| 1217 | 993165 | Rear RH Chassis Member      |     |    |     |

| NAC  | INC    | Item                           | CON | AC | Qty |
|------|--------|--------------------------------|-----|----|-----|
| 2062 | 993748 | Rear Sidegate                  | DD  | ✓  |     |
| 2063 | 994225 | Rear Sidegate Lock             |     |    |     |
| 2064 | 993749 | Rear Sidegate Hinge            |     |    |     |
| 2065 | 994226 | Sidegate Lower Panel           |     |    |     |
| 2066 | 994227 | Sidegate Railing               |     |    |     |
| 2067 | 994208 | Side Cover Hook                |     |    |     |
| 2068 | 991965 | Side Step Panel                |     |    |     |
| 2069 | 994496 | Side Step Panel Stopper        |     |    |     |
| 2070 | 992857 | Rear Body Panel                |     |    |     |
| 2071 | 992866 | Rear Body Panel Inner          |     |    |     |
| 2072 | 995329 | Sliding Door LH                |     |    |     |
| 2073 | 995328 | Sliding Door RH                |     |    |     |
| 2074 | 994295 | Sliding Door Handle            |     |    |     |
| 2075 | 994300 | Sliding Door Lock              |     |    |     |
| 2076 | 994313 | Sliding Door Rubber            |     |    |     |
| 2077 | 994291 | Sliding Door Bottom Roller     |     |    |     |
| 2078 | 994317 | Sliding Door Top Roller        |     |    |     |
| 2079 | 994306 | Sliding Door Rail              |     |    |     |
| 2080 | 994315 | Sliding Door Stepboard         |     |    |     |
| 2081 | 994316 | Sliding Door Stepboard Garnish |     |    |     |
| 1224 | 993621 | Rear LH Mudflap                |     |    |     |
| 1225 | 993933 | Rear LH Wheel Rim              |     |    |     |
| 1226 | 994025 | Rear LH Rim Cover              |     |    |     |
| 1227 | 995065 | Rear LH Tyre                   |     |    |     |
| 1234 | 993622 | Rear RH Mudflap                |     |    |     |
| 1235 | 993934 | Rear RH Wheel Rim              | SCR | ✓  |     |
| 1236 | 994025 | Rear RH Rim Cover              |     |    |     |
| 1237 | 995065 | Rear RH Tyre                   |     |    |     |
| 1252 | 992179 | Fuel Tank                      |     |    |     |
| 1253 | 992184 | Fuel Tank Bracket              |     |    |     |
| 1136 | 990247 | Sticker                        | NEC | ✓  |     |

No of Items: 10

Assessor: TGLIM

TGLIM *[Signature]*  
 21/9/18

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

PRI

| CLAIM SUBFOLDER TRACKING |   |               |  |  |  |             |   |
|--------------------------|---|---------------|--|--|--|-------------|---|
| Case                     | Notified                                | Est Submitted | Adj Assigned   | Adj Rpt  | Adj Submitted                              | Ins Auth'ed | Status  |
| Main                     | 04 Sep 2018<br><a href="#">Edit Reg</a> |               | 04 Sep 2018<br>00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$0.00</b><br><a href="#">Edit Estimates</a> | <b>S\$0.00</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

|             |                  |                      |                  |                          |
|-------------|------------------|----------------------|------------------|--------------------------|
| <b>Main</b> | <b>Reference</b> | <b>Claim Details</b> | <b>Documents</b> | <a href="#">Show All</a> |
|-------------|------------------|----------------------|------------------|--------------------------|

**CLAIM SUBFOLDER DETAILS** [\[Created by adjuster\]](#)

|                             |   |                        |  |
|-----------------------------|---|------------------------|--|
| Insured:                    | <b>LCRF PTE LTD</b> , Co. Reg. No.: 201624597K  |                        |  |
| Main Claimant:              | -   |                        |  |
| Vehicle Reg. No.:           | <b>GBB4335Z</b>   | Date of Loss:          | 03/09/2018 00:00 - :59<br><b>[184 Months and 30 Days From LTA Reg Date (Man Yr)]</b> |
| Claim Type:                 | <b>TP / 5529105719SG</b>  | Policy/Cover Note No.: | 0999994809 (Comprehensive)   |
| Vehicle Reg. No. (Insured): | <b>SLJ1289H</b>   | Policy No. (Claimant): |  |
|                             |   | Excess:                |  |
| Repairer:                   | <b>Motor Intel Automo Pte Ltd (HQ)</b> Bartley Biz Centre,13 Kakai Bukit Road 4,#01-20, 417807 Kaki Bukit - Tel:                        |                        |  |
| Handling Insurer:           | <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Boyogan, Joane</b> ] Joane.Boyogan@aig.com |                        |  |
| Adjuster:                   | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Lim Teow Guan</b> ] ... <b>[Final Rpt due 14/09/2018]</b>  |                        |  |
| Claimant's Solicitor:       | <b>CHIA S ARUL &amp; LLC</b> - Tel: 67334647  |                        |  |

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

- AIG\_SG (06/09/2018): **Request To Upload TP GIA Report**

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

### Claim Documents

**\*GBB4335Z (5529105719SG)**  
**[SLJ1289H]**  
**TP**

**Sep 3 2018 12:00AM**  
**[LCRF PTE LTD]**  
**Motor Intel Automo Pte Ltd**

| <a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>   <a href="#">Upload Video</a>   <a href="#">Upload Audio</a> |                 |  | <b>View</b> <a href="#">View in Browser</a> |                                     |
|---|-----------------|--|---|-------------------------------------|
| <b>Assessment Reports</b>   |                 |  | 1 per page                                  | <input checked="" type="checkbox"/> |
| No  | Finalized On    | AIG Asia Pacific Insurance Pte. Ltd. (SG)  | Thumbnail                                   | Print                               |
| 1   | 06/09/18 10:05  | <b>Accident Statement</b><br>From:SC - Reg. No: SLJ1289H, Claimant: LCRF PTE LTD | Load HTM                                    |                                     |
| <b>Photos/Images</b>  |                 |  | 3 per page                                  | <input checked="" type="checkbox"/> |
| No  | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)  | Thumbnail                                   | Print                               |
| 1   | 05/09/18 18:20  | <b>General View</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 2   | 05/09/18 18:20  | <b>General View</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 3   | 05/09/18 18:20  | <b>General View</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 4   | 05/09/18 18:20  | <b>General View</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 5   | 05/09/18 18:20  | <b>General View</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 6   | 05/09/18 18:20  | <b>General View</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 7   | 05/09/18 18:20  | <b>General View</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 8   | 05/09/18 18:20  | <b>General View</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 9   | 05/09/18 18:20  | <b>General View</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 10  | 05/09/18 18:20  | <b>General View</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 11  | 05/09/18 18:20  | <b>General View</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 12  | 05/09/18 18:20  | <b>General View</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 13  | 05/09/18 18:20  | <b>General View</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 14  | 05/09/18 18:20  | <b>General View</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 15  | 05/09/18 18:20  | <b>General View</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 16  | 05/09/18 18:20  | <b>General View</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 17  | 05/09/18 18:20  | <b>General View</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 18  | 05/09/18 18:20  | <b>General View</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 19  | 05/09/18 18:20  | <b>General View</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 20  | 05/09/18 18:20  | <b>General View</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 21  | 05/09/18 18:20  | <b>General View</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 22  | 05/09/18 18:20  | <b>General View</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 23  | 05/09/18 18:20  | <b>General View</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 24  | 05/09/18 18:20  | <b>General View</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 25  | 05/09/18 18:20  | <b>General View</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 26  | 05/09/18 18:20  | <b>General View</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 27  | 05/09/18 18:20  | <b>General View</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 28  | 05/09/18 18:20  | <b>General View</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 29  | 05/09/18 18:20  | <b>General View</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 30  | 11/09/18 10:18  | <b>Photographs of Damaged Parts</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 31  | 11/09/18 10:18  | <b>Photographs of Damaged Parts</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 32  | 11/09/18 10:18  | <b>Photographs of Damaged Parts</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |
| 33  | 11/09/18 10:18  | <b>Photographs of Damaged Parts</b>  | Load JPG                                    | <input checked="" type="checkbox"/> |

| Assessment Reports |                |   | 1 per page   | <input checked="" type="checkbox"/> |
|--------------------|----------------|---|--|-------------------------------------|
| No                 | Finalized On   | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail  | Print                               |
| 34                 | 11/09/18 10:18 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 35                 | 11/09/18 10:18 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 36                 | 11/09/18 10:18 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 37                 | 11/09/18 10:18 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 38                 | 11/09/18 10:18 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 39                 | 11/09/18 10:18 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 40                 | 11/09/18 10:18 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 41                 | 11/09/18 10:18 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 42                 | 11/09/18 10:18 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 43                 | 24/09/18 15:03 | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 44                 | 24/09/18 15:03 | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 45                 | 24/09/18 15:03 | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 46                 | 24/09/18 15:03 | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 47                 | 24/09/18 15:03 | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 48                 | 24/09/18 15:03 | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 49                 | 24/09/18 15:03 | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 50                 | 24/09/18 15:03 | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 51                 | 24/09/18 15:03 | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 52                 | 24/09/18 15:03 | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 53                 | 24/09/18 15:03 | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 54                 | 24/09/18 15:03 | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 55                 | 24/09/18 15:03 | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 56                 | 24/09/18 15:03 | Photo After Spray                         |  Load JPG  | <input checked="" type="checkbox"/> |
| 57                 | 24/09/18 15:03 | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 58                 | 24/09/18 15:03 | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |

### Documents Checklist

| DOCUMENTS CHECKLIST  | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured.   |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b><br><div style="border: 1px solid black; height: 40px; width: 100%;"></div>        |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer<br><small>Note: Remarks are private unless you show it to other parties.</small> |       |      |       |

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/LCR18016237/BCD3E2

**Date:** 25/09/2018

#### REFERENCE

|  |                                      |                        |
|--|--------------------------------------|------------------------|
| Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. | Policy No: 0999994809                |                        |
| <b>Claimant Vehicle No :</b> GBB4335Z                  | <b>Insured Vehicle No :</b> SLJ1289H |                        |
| Date of Loss: 03/09/2018                               | Nature of Claim: TP                  | Claim No: 5529105719SG |

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>GBB4335Z</b>                   |             |                   |
| Make & Model:               | NISSAN CABSTAR, 3.0 D F24 (M)     | Engine No:  | QD32177763        |
| Reg. Date:                  | 04/04/2003 (Man. Year: 2003)      | Chassis No: | JN1SF4F23Z0850333 |
| Colour:                     | Silver                            | Odometer:   | 406875 km         |
| Engine Capacity:            | 3153 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

#### CONDITION OF TYRES

|                   |          |                  |              |
|-------------------|----------|------------------|--------------|
| Front Tyre Size:  | 195 R15C | Rear Tyre Size:  | 155 R12C     |
| Front Left Side:  | CST 6 mm | Rear Left Side:  | Firenza 6 mm |
| Front Right Side: | CST 6 mm | Rear Right Side: | Firenza 6 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS           | Repairer's  | Adjuster's  | Difference  | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts                    | 0.00        | 0.00        | 0.00        |        |
| Miscellaneous Items      | 0.00        | 0.00        | 0.00        |        |
| Labour                   | 0.00        | 0.00        | 0.00        |        |
| Paintwork Labour         | 0.00        | 0.00        | 0.00        |        |
| Towing                   | 0.00        | 0.00        | 0.00        |        |
| <b>Nett Amount (S\$)</b> | <b>0.00</b> | <b>0.00</b> | <b>0.00</b> |        |

#### INSPECTION

|                             |                          |   |
|-----------------------------|--------------------------|---|
| Date of Assignment:         | 04/09/2018               |   |
| Date Inspected:             | 05/09/2018 Inspected At: | Motor Intel Automo Pte Ltd (HQ)<br>Bartley Biz Centre, 13 Kakai Bukit Road<br>4, #01-20<br>Singapore 417807 |
| Estimated Period of Repair: | 3.0 days                 |   |

**Adjuster:** Lim Teow Guan

**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                | Condition | Repairer's                | Amount      |             |
|-----|-----|----------|----------------------------|-----------|---------------------------|-------------|-------------|
| 1   | 1   |          | *REAR NUMBER PLATE         | Broken    | 0.00 F                    | *- F        |             |
| 2   | 1   |          | *REAR NUMBER PLATE BRACKET | Bent      | 0.00 F                    | *- F        |             |
| 3   | 1   |          | *REAR LH TAILLAMP          | Broken    | 0.00 F                    | *- F        |             |
| 4   | 1   |          | *REAR LH TAILLAMP PANEL    | Bent      | 0.00 F                    | *- F        |             |
| 5   | 1   |          | *REAR RH TAILLAMP          | Scratched | 0.00 F                    | *- F        |             |
| 6   | 1   |          | *REAR RH TAILLAMP PANEL    | Bent      | 0.00 F                    | *- F        |             |
| 7   | 2   |          | *TAILGATE LOCK             | Distorted | 0.00 F                    | *- F        |             |
| 8   | 1   |          | *REAR EXHAUST PIPE         | Bent      | 0.00 F                    | *- F        |             |
| 9   | 1   |          | *REAR EXHAUST MOUNTING     | Distorted | 0.00 F                    | *- F        |             |
| 10  | 1   |          | *REAR RH WHEEL RIM         | Scratched | 0.00 F                    | *- F        |             |
| 11  | 1   |          | *STICKER                   | Necessary | 0.00 F                    | *- F        |             |
|     |     |          |                            |           | <b>Total Parts (\$\$)</b> | <b>0.00</b> | <b>0.00</b> |

F=Franchise part.

|   |
|---|
| Report was unsubmitted during this print-out. |
|---|

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

|   |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >