

22/03/2002

ASS. REC. BY:

REF:

CS3 / msl118016240 / T10002

Special Instruction:

Surveyor

Munim

Taufik

ASSIGNMENT (Office)

From (Person):

Monica Chung

of

MS16

Date/Time:

05092018 4:45pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

STS 5553 S

Insured:

SJF 8278M

at Workshop m/s

Car Laboratories

Tel:

8777 7227

of

1 Bukit Batuk Crescent # 04-56

Policy No:

AS021519342mx

Claim No:

568595

Sum Insured:

Excess:

Make of Veh:

D.O.A.

21082018

(Client's Record)

CA / REV / REP. / REV 24 HRS WP

06092018 @ morning

H.O.D. Endorsement:

Date/Time:

05092018 5:05pm

Person Contacted:

Zen

Vehicle

IN OUT

Date/Time	Action/Instruction (✓) Estimate
	STS 5553 S - X
	SJF 8278M - CS / ALH / 2009521 / Rqm
	Diemante: 7/9/18

OCA: 250412

Tanpin

REF:

MSH

ASIA NAIL

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m's

of

Insured.

Policy No.

Claims No.

Sum Insured

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

PRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No.

SF555538

Yr Regn:

2015 Jan

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

1496

Colour

white

A/C

Insured / Std / NI / NA

Sp. Reading

82797

T/Radio

Insured / Std / NI / NA

Eng/No:

RU11013.778

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60K16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Viking

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

6/9/18 @ 1330

Survey held at

Car Lab

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt o/s

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

Estimated repair range \$4,500 - \$5,300.

17/9/2018

Date/Time: File Pass to?

☐

: Preli. Report

To:

☐

: Final Report

Date/Time: File Return to?

To:

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Insp (\$)

☐

Mapland (\$)

Survey Fee

Transportation

Food & Bev

Other

Total

Grand Total

Remarks

120

10

130

Report Format:

PRE

Lump Sum / LB to (\$)




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG18016240/T1cb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 05-09-2018	
		Code : MSG	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>			
Insured Veh.	SJF 8278M	Veh. Inspected	SFS 5553S
Policy No.	A80451934QMX	Coverage (\$)	0.00
Claim No.	568595	Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	05/09/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	21/08/2018	Inspection Date	06/09/2018
Survey held at	CAR LABORATORIES PTE LTD NO. 1 BUKIT BATOK CRESCENT #04-56 WCEGA PLAZA SINGAPORE 658064		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

### ...CLAIM SUBFOLDER...(New Assignment)

#### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Aug 2018		05 Sep 2018 16:09 Assign				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	ARUNACHALAM SUBRAMANIAN, ID: S8166797G			[Created by insurer]					
Main Claimant:	NG CHONG TIK, ID: S7878036C								
Vehicle Reg. No.:	SFS5553S	Date of Loss:	21/08/2018 08:00 - :59 [42 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 568595	Policy/Cover Note No.:	A80451934QMX (Comprehensive) Coverage: 20/12/2017 - 22/03/2019						
Vehicle Reg. No. (Insured):	SJF8278M	Policy No. (Claimant):							
Repairer:	Car Laboratories Pte Ltd (HQ) 1 BUKIT BATOK CRESCENT, #04-56 WCEGA PLAZA, 658064 Bukit Batok - Tel: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 06/09/2018]								
Driver/Custodian (Insured):	ARUNACHALAM SUBRAMANIAN (37 / Male), NRIC: S8166797G								
Adj Asg. Remarks:	on WP. SJE DISAGREE. PLS APPOINT LKK. LIAB 100% Contact Person : Mr Zen @ 8777 7227 / 6570 0330								
<b>ASSOCIATED MAIL RECEIVED</b>									
There are no mail for this case.									
<a href="#">View All</a> <a href="#">Compose Case Mail</a>									
<b>ALL ASSOCIATED TASKS</b>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	8036C
<b>Vehicle Details</b>	
Vehicle No.:	SFS5553S
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Sep 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X A
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	L15B3513792
Chassis No.:	RU11013778
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$18,464.00
Original Registration Date:	22 Jan 2015
First Registration Date:	22 Jan 2015
Transfer Count:	1
Actual ARF Paid:	\$8,464.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jan 2025
PARF Rebate Amount:	\$6,348.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	21 Jan 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$66,010.00
COE Rebate Amount:	\$42,054.00
<b>Total Rebate Amount:</b>	<b>\$48,402.00</b>

The information contained herein is correct as at 07 Sep 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	05/09/2018 10:46
Date Of Accident	21/08/2018 07:55
Exact Location Of Accident	ALONG ROAD 1 WOODLANDS DRIVE 16 OPEN C/P BLK 543
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFS5553S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NG CHONG TIK
NRIC No	S7878036C
Email Address	HEBITAN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91558366
Alternative Phone No	OFFICE-91558366

### Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A28993385QMY
Cover Note Number	

### Driver

Name of Driver	IVY TAN LEE MOOI
NRIC No	S7778660J
Date Of Birth	04/12/1977
Occupation	INDOOR
Date Of Driving Pass	26/11/2005
Driving Experience	12 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91558366
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	97 JALAN SENDUDOK #02-66 THE NAUTICAL
Postcode	S769474
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	SEMBAWANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	<b>ROAD:</b> 4 SEMBAWANG CRESCENT , <b>POSTCODE:</b> 757633 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> 1800-5549999 - <b>FAX NO:</b> 68522499
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT T/20180821/2021 AND SKETCH PLAN (ATTENDED BY IFAM)

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WILL PROVIDE LATER
Was there any audio recorded?	NO

#### Details of Witness 1

Name	MR CHEH
Phone Number	96651769
Email Address	

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJF8278M
Vehicle Make/Model/Colour	TOYOTA CAMRY
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ARUNACHALAM SUBRAMANIAM
NRIC/Passport Number	S8166797G

Contact Number	82332565
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



## Sketch Plan Pg. 1

### SKETCH PLAN


#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


IDAC SIN MING (VAC)  
385 Sin Ming Drive  
Singapore 575718  
Tel: 6455 5358 (ARC)  
Fax: 6452 8621

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN





DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 21/8/2018 about 07.55hrs, Ivy parked vehicle SF55535
at open car park at Blk 543 Woodlands Drive 16
everything was intact.
On 21/8/2018 about 0910hrs, Ivy returned to vehicle
and discovered there is a big dent and scratch on the
front right of the vehicle. Mr. Choh (contact - 9665 1769)
approached Ivy and informed that he saw earlier
the vehicle parked beside my vehicle → drove out and hit
my vehicles. There is a lorry parking in front which
cause obstruction that is why turning angle become
small. The driver did not stop and check after the
incident and drove away.
Mr. Choh the witness managed to take take down the
car number / model / make of the car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

**IDAC SIN MING (PAC)**  
385 Sin Ming Drive  
- Singapore 57571  
Tel: 6455 5358 (A/C)  
Fax: 6452 8621  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



MSIG

MSIG Insurance (Singapore) Pte. Ltd.  
 4 Robinson Way, # 21-01, Robinson 2, Singapore 469007  
 Tel: +65 6592 7888 Fax: +65 6592 7800  
 Co Reg No: 100472100 GST Reg No: 206417210

DUPLICATE COPY  
 FOR FINANCE COMPANY

## MOTOR MAX PLUS

## RENEWAL CERTIFICATE

Policy Number	Period of Insurance	Place of Issue
A 28993185 OMV	22/07/2018 to 21/07/2019	SINGAPORE
Name and Address of Insured		Date of Issue
Ng Cheng Tih 87 Jalan Senduduk 602-66 The Nautical Singapore 769474		19/07/2018
		Account Number
		1363030
Premium	GST	Total Due
SGD771.32	SGD53.99	SGD825.31

RISK NUMBER 1

MOTORMAX PLUS

## OCCUPATION

Sales

## FINANCIAL INTEREST

DBS Bank Ltd  
 as Hire Purchase Owners

SCOPE OF COVER Comprehensive

## INTEREST INSURED

REGISTRATION NO. SFS55538  
 MAKE/MODEL Honda Vezel 1.5X A  
 ENGINE NUMBER D15B3513792  
 CHASSIS NUMBER RU11013778  
 YEAR OF MFG 2014  
 CAPACITY 1496 C.C.  
 SEATING CAPACITY 5 (INCL. DRIVER)  
 WINDSCREEN UNLIMITED

SUM INSURED MARKET VALUE  
 INCL. COE/PARF YES  
 OFF-PEAK CAR NO  
 NO CLAIM DISCOUNT 50.00% (or F/D)  
 GOOD DRIVER'S  
 DISCOUNT SGD40.60  
 NCD PROTECTOR COVERED  
 EXCESS SGD500  
 ANNUAL PREMIUM SGD771.32

ACCESSORIES Aircon, radio/cassette/compact disc player, in-vehicle unit,  
 rust-proofing and other accessories that are factory fitted.

## AUTHORISED DRIVERS

Ng Cheng Tih



**SINGAPORE  
POLICE FORCE**



T/20180821/2021

1 of 3

Report No. T/20180821/2021

Police Station Of Origin:  
Sembawang N.P.C  
4 Sembawang Crescent SINGAPORE  
757633  
Tel No 1800-5549999

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 21/08/2018 10:50	Video Report No.:	Station Diary No.: 24
--	-------------------	--------------------------

**Informant's Particulars**

Name of Informant: IVY TAN LEE MOOI		Address: 97 JALAN SENDUDOK #02-66 THE NAUTICAL SINGAPORE 769474	
ID Type / ID No. NRIC NO / S7778660J		Contact No.: Home/Office: Mobile: 91558386	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Female	Age: 40	Date of Birth: 04/12/1977	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: SELF EMPLOYED		Driving Licence Information: Class: 2B,3 Date of Expiry:	

**General Information of the Accident**

Type of Accident: Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 21/08/2018 07:55	Type of Location:
Location: Along Road 1 WOODLANDS DRIVE 16 Open Carpark at Blk 543, Woodlands Drive 16			
Weather:	Road Surface:	Road Speed Limit:	
Traffic Flow:	Traffic Control:	Traffic Volume:	
Type of Collision:			Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
3FS5553S	Car				Slightly Damaged	0
6JF8276	Car	SEMPAWANG NPC			Slightly Damaged	0
(Not Accurate)		4 Sembawang Crescent Singapore 757633 Tel: 1800-5549999 Fax: 86422499				

**Details of Person Involved**

Any Pedestrian Involved: No  
No. of Pedestrians Injured: Nil

Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Sembawang N.P.C  
4 Sembawang Crescent SINGAPORE  
757633  
Tel No: 1800-5549999



T/20180821/2021

2 of 3

Report No. T/20180821/2021

**CONTINUATION OF REPORT**

<b>Driver</b>				
Name	IVY TAN LEE MOOI		ID No.	S7778660J
Related Vehicle	SF85553S (Car)		Contact No.	91558366
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	

**Brief Details.**

On 21.08.2018, at about 0755hrs, I parked my vehicle SF85553S at open carpark at Blk 543 Woodlands Drive 16, everything was intact.

On 21.08.2018, at about 0910hrs, I returned to my vehicle and I discovered there is a big dent and scratch on the front right of my vehicle. One Mr Cheh contact 96651769 approached me and informed that earlier he saw the vehicle parked beside my car drove out and hit my vehicle. Mr Cheh also informed there is a lorry parked vertically in front of my car, causing some obstruction. As such the turning angle for the said vehicle become very narrow. Mr Cheh did not manage to take down the exact vehicle number, but he informed it is Camry, believed to be black colour. He informed that the driver is a Indian subject, and he did not stop after hitting my vehicle.





**SINGAPORE  
POLICE FORCE**



T20180821/2021

Police Station Of Origin:  
Sembawang N.P.O  
4 Sembawang Crescent SINGAPORE  
757633  
Tel No: 1800-5548999

3 of 3

Report No: T20180821/2021

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Staff Sgt WANG LIZHE

Signature Of Informant:

*[Handwritten Signature]*

Signature Of Interpreter:

Not applicable

Date/Time:

21/08/2018 10:50

Officer In Charge Of Case:

TP / HRT /

SI KALESWARI PALANI

Contact No: 65476902

Classification Of Case:

Section

Authentication Stamp

NP-13

### ...CLAIM SUBFOLDER...(Pending for Survey Report)



































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Aug 2018		05 Sep 2018 16:09 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>ARUNACHALAM SUBRAMANIAN</b> , ID: S8166797G									
Main Claimant: <b>NG CHONG TIK</b> , ID: S7878036C									
Vehicle Reg. No.: <b>SFS5553S</b>		Date of Loss: 21/08/2018 08:00 - :59 [42 Months and 30 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 568595</b>		Policy/Cover Note No.: A80451934QMX (Comprehensive) Coverage: 20/12/2017 - 22/03/2019							
Vehicle Reg. No. (Insured): <b>SJF8278M</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Car Laboratories Pte Ltd (HQ)</b> 1 BUKIT BATOK CRESCENT, #04-56 WCEGA PLAZA, 658064 Bukit Batok - Tel:									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Monica Chung Pei Zhen</b> - 6594 2552]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Imm.Advice due 06/09/2018]									
Driver/Custodian (Insured): ARUNACHALAM SUBRAMANIAN (37 / Male), NRIC: S8166797G									
Adj Asg. Remarks: on WP, SJE DISAGREE, PLS APPOINT LKK. LIAB 100% Contact Person : Mr Zen @ 8777 7227 / 6570 0330									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SFS5553S (568595)**  
**[SJF8278M]**  
**TP**  
**NG CHONG TIK**  
**Aug 21 2018 8:00AM**  
**[ARUNACHALAM SUBRAMANIAN]**  
**Car Laboratories Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/09/18 15:32	<b>Accident Statement</b> <small>From:SC - Reg. No: SJF8278M, Claimant: ARUNACHALAM SUBRAMANIAN</small>	 <a href="#">Load HTM</a>	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/09/18 13:46	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
2	07/09/18 13:46	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
3	07/09/18 13:46	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
4	07/09/18 13:46	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
5	07/09/18 13:46	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
6	07/09/18 13:46	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
7	07/09/18 13:46	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
8	07/09/18 13:46	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
9	07/09/18 13:46	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
10	07/09/18 13:46	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
11	07/09/18 13:46	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
12	07/09/18 13:46	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
13	07/09/18 13:46	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
14	07/09/18 13:46	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
15	07/09/18 13:46	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
16	07/09/18 13:46	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
17	07/09/18 13:46	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
18	17/09/18 18:54	Photographs of Damaged Parts	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
19	17/09/18 18:54	Photographs of Damaged Parts	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
20	17/09/18 18:54	Photographs of Damaged Parts	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
21	17/09/18 18:54	Photographs of Damaged Parts	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
22	17/09/18 18:54	Photographs of Damaged Parts	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
23	17/09/18 18:54	Photographs of Damaged Parts	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
24	17/09/18 18:54	Photographs of Damaged Parts	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
25	17/09/18 18:54	Photographs of Damaged Parts	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
26	17/09/18 18:54	Photographs of Damaged Parts	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
27	17/09/18 18:54	Photographs of Damaged Parts	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
28	17/09/18 18:54	Photographs of Damaged Parts	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
29	17/09/18 18:54	Photographs of Damaged Parts	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
30	17/09/18 18:54	Photographs of Damaged Parts	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
31	17/09/18 18:54	Photographs of Damaged Parts	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
32	17/09/18 18:54	Photographs of Damaged Parts	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
33	17/09/18 18:54	Photographs of Damaged Parts	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	17/09/18 18:54	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
35	17/09/18 18:54	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/09/18 15:33	PRI	Load PDF	
2	04/09/18 16:41	SJE DISAGREE APPOINT LKK	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18016240/T1CBE2

Date: 18/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A80451934QMX

Claimant Vehicle  
No : SFS5553S

Insured Vehicle No : SJF8278M

Date of Loss: 21/08/2018

Nature of Claim: TP

Claim No: 568595

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFS5553S

Make &amp; Model: HONDA VEZEL, 1.5 (A)

Engine No: L15B3513792

Reg. Date: 22/01/2015 (Man. Year: 2014)

Chassis No: RU11013778

Colour: White

Odometer: 82794 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Viking 6 mm

Rear Left Side: Viking 6 mm

Front Right Side: Viking 6 mm

Rear Right Side: Viking 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment: 05/09/2018

Date Inspected: 06/09/2018 Inspected At:

Car Laboratories Pte Ltd (HQ)  
1 BUKIT BATOK CRESCENT, #04-56  
WCEGA PLAZA  
Singapore 658064

Estimated Period of Repair: 0.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,500.00 -\$5,300.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 18 Sep 2018)
<b>Parts:</b>	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SFS5553S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >