

22/03/2002

ASS. REC. BY:

REF: CS3

AIG/18016243/R1cd3ed

Special Instruction:

Surveyor:

Rasul

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

5/9/18 12.10pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR 1584M

Insured:

SLH 6628R

at Workshop m/s

Leng Wang Motor

Tel:

9817 2032

of

Blk 3007 Ubi Rd 1 #01-414

Policy No:

2100487228.

Claim No:

9794645491SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

3/9/2018

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

12.42pm @ 5/9/18

Person Contacted:

Alice

Vehicle IN OUT

Date/Time

Action/Instruction (X) Estimate

SLR 1584M - X

SLH 6628R - X

Diamond K: 6/9/2018

After repair: 11/9/2018.

09/11/18
Surveyor

Rose


REF:

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SLR 1584M
at Workshop m/s LEACH WORK MOTOR
of 3007, WBI RD 1 #01-414
Insured: AIS
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: 6 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLR 1584M Yr Regn: Mar / 09
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: NISSAN SYLPHY C.C. 1498
Colour: GR6Y A/C: Insured / Std / NI / NA
Sp. Reading: 195931 T/Radio: Insured / Std / NI / NA

Eng/No: _____
C/No: 3N1BAAG1120107577

Gen. Cond: Good / Fab / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15
R: 2-

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or CONTINENTAL

Front 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 05/09/18

Survey held at LEACH WORK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6.

Resurvey No. of Trip: 2.

Survey Fee: 180

Transportation: _____

) S + RS, SI

) Photos

) Others

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format: DAR.

Lump Sum / I.B.I: (\$ _____)

200



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18016243/R1cd3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 05-09-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLH 6628R	Veh. Inspected	SLR 1584M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	05/09/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--


5. General Information

Accident Date	03/09/2018	Inspection Date	05/09/2018
Survey held at	LENG WANG MOTOR BLK 3007 UBI ROAD #01-414 SINGAPORE 408701		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
 B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
 THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
 C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 5/9/2018 12:10:25 PM
Attachments:  180905-GIA report SLR1584M(new).pdf

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

From: Yvonne [mailto:yvonne@ealc.com.sg]

Sent: Wednesday, September 05, 2018 11:46 AM

To: Chan, Yoke Shi

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Azlan, Syazairdina

Subject: PRI AIG Insured SLH6628R [EAL.2018.5905.MK.ya- SLR1584M]

Our ref : 2018.5905.MK.ya- **SLR1584M**

Your ref : **SLH6628R**

PLEASE REPLY VIA EMAIL (yvonne@ealc.com.sg)

AIG Asia Pacific Insurance Pte Ltd
No. 78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Department
2 DAYS' PRE-REPAIR NOTICE

Surveyor from M/s AIG Asia Pacific Insurance Pte Ltd

Vehicle **SLR1584M** inspected as follows by Name:

Before repair

Parts removed

After repair

Signature

Signature

Signature

Date/ Time:

Date/ Time:

Date/ Time:

Dear Sir/Madam,

NOTICE TO THIRD PARTY INSURERS FOR PRE-REPAIR NOTICE

CLAIMANT: STREET DNA

ACCIDENT INVOLVING SLR1584M & SLH6628R ON 03 SEPTEMBER 2018 ALONG BUKIT BATOK EAST AVENUE 6 AT ABOUT 0730 HOURS

We refer to the above matter wherein we are instructed to act for **STREET DNA**, the owner of vehicle no. **SLR1584M**.

There is no agreement to the surveyors proposed by parties.

Our client's vehicle **SLR1584M** is available as follows, **please call prior appointment** for the pre-repair inspection:

M/s Leng Wang Motor
Blk 3007 Ubi Road 1
#01-414 Singapore 408701
Tel: 9817 2032 (Alice)

Please arrange for the pre-repair inspection on the damaged vehicle within 2 working days from the time of notification, excluding Saturdays, Sundays and public holidays.

Regards,
Yvonne Ang

East Asia Law Corporation
No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413
Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

[> Back to OneMotoring](#)

Enquire Transfer Fee

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SLR1584M		
Vehicle Type :	N18 - Passenger (Co) Company Car (Single Rate)		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	NISSAN		
Vehicle Model :	SYLPHY 1.5 4AT		
Chassis No. :	JN1BAAG11Z0107577		
Propellant :	Petrol		
Engine No. :	HR15111986B		
Engine Capacity :	1498 cc		
Maximum Power Output :	80.0 kW (107 bhp)		
Maximum Laden Weight :	1520 kg		
Unladen Weight :	1175 kg		
Year Of Manufacture :	2009		
Original Registration Date :	13 Mar 2009		
Lifespan Expiry Date :	-		
COE Category :	E - Open Category		
Quota Premium :	\$3,200.00		
COE Expiry Date :	12 Mar 2019		
Road Tax Expiry Date :	12 Mar 2019		
PARF Eligibility Expiry Date :	12 Mar 2019		
Inspection Due Date :	12 Mar 2020		
Intended Transfer Date :	06 Sep 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

> Back to OneMotoring



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	2526K
Vehicle Details	
Vehicle No.:	SLR1584M
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Sep 2018
Vehicle Make:	NISSAN
Vehicle Model:	SYLPHY 1.5 4AT
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	HR15111986B
Chassis No.:	JN1BAAG11Z0107577
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$21,468.00
Original Registration Date:	13 Mar 2009
First Registration Date:	13 Mar 2009
Transfer Count:	1
Actual ARF Paid:	\$21,468.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Mar 2019
PARF Rebate Amount:	\$10,734.00
Intended COE Rebate Details	
COE Expiry Date:	12 Mar 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$3,200.00
COE Rebate Amount:	\$138.00
Total Rebate Amount:	\$10,872.00

The information contained herein is correct as at 06 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 03/09/2018 13:15
 Date Of Accident 03/09/2018 07:30
 Exact Location Of Accident ALONG BUKIT BATOK EAST AVE 6
 Country/State Of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLR1584M
 Insured/Policyholder
 Name Of Registered Owner STREET DNA
 Co Reg No 53372526K
 Email Address NOEMAIL
 Mobile Phone No
 Alternative Phone No OFFICE-98524833

Vehicle Particulars

Manufacturer NISSAN
 Model SYLPHY 1.5 4AT
 Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 5095467141
 Cover Note Number

Driver

Name of Driver TANG YAH HUI, ALETHEA
 NRIC No S9139635A
 Date Of Birth 27/10/1991
 Occupation INDOOR
 Date Of Driving Pass 14/10/2010
 Driving Experience 7 YEARS AND 10 MONTHS
 Gender FEMALE
 Mobile Number (LOCAL) +65-93290587
 Fax Number
 Contact Number OTHERS-91477004
 Email Address NOEMAIL

Address 23 JALAN SONGKET
 Postcode 537395
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured CHILDREN
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : CHUA KENG YONG
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO POLICE REPORT NO. T/20180903/7009.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLH6628R
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	TANG YAH HUI, ALETHEA
Approximate Age	
Injuries Sustain	03 DAYS MC
Injured person in which vehicle?	SLR1584M
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	
Address	23 JALAN SONGKET
Postcode	537395

DETAILS OF INJURED PERSON 2

Name	CHUA KENG YONG
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SLR1584M
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	



**SINGAPORE
POLICE FORCE**



T/20180903/7009

1 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20180903/7009

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/09/2018 13:50		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: TANG YAH HUI, ALETHEA			Address: 23 JALAN SONGKET SINGAPORE 537395		
ID Type / ID No.: NRIC NO / S9139635A			Contact No.: Home/Office: Mobile: 93290587		
Nationality: SINGAPORE CITIZEN			Email: alethea_surf73@hotmail.com		
Sex: Female	Age: 26	Date of Birth: 27/10/1991	Type of Informant: Driver		
Race: Chinese		Language: English		Institution / School Name:	
Occupation: UNEMPLOYED		Driving Licence Information: Class: 3A		Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 03/09/2018 07:30	Type of Location: Straight Road
Location: BUKIT BATOK EAST AVENUE 6				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume:
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLH6628R	Car					0
SLR1584M	Car	NISSAN	SYLPHY+1.5+4AT	Silver	Seriously Damaged	2

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLR1584M	NTUC Income Insurance Co-Operative Limited	5095467141	01/11/2017	31/10/2018



**SINGAPORE
POLICE FORCE**



T/20180903/7009

2 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20180903/7009

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Passenger			
Name	CHUA KENG YONG	ID No.	S9238019Z
Related Vehicle	SLR1584M (Car)	Contact No.	91123835
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	03/09/2018	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	TANG YAH HUI, ALETHEA	ID No.	S9139635A
Related Vehicle	SLR1584M (Car)	Contact No.	93290587
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3A Date of Expiry: NIL
Date Treatment	03/09/2018	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

MY VEHICLE WAS STATIONARY ON THE EXTREME RIGHT LANE OF A 3-LANES ROAD, ALONG BUKIT BATOK EAST AVE 6, DUE TO RED TRAFFIC LIGHT. VEHICLE B BEARING REGN NO. SLH6628R CAME FROM BEHIND AND HIT ONTO THE REAR PORTION OF MY STATIONARY VEHICLE. I HAVE 01 PASSENGER ON BOARD AND WE SUSTAINED INJURIES DUE TO THE IMPACT OF ACCIDENT. WE SOUGHT MEDICAL TREATMENT AND WERE GIVEN 03 DAYS MC RESPECTIVELY. THAT'S ALL.

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:




SKETCH PLAN

A= SLR1884M
B= SLH6628R

BUKIT BATOK EAST AVE 2



BUKIT BATOK EAST AVE 6



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to police report no. T1018009103/7009.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180903/7009

3 of 3

Report No. T/20180903/7009

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
SHARIFAH NOR FARIZAN BINTE SYED MOHD
SAID
Contact No.: 65476172

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
03/09/2018 13:50

Classification Of Case:

MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector	RH	RA	✓
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel	DD	✓	
1160	993339	Rear End Panel Top Garnish	DIS	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	CR	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel	DD	✓	
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	DD	✓	
1171	991328	Bootlid Emblem	NEC	✓	2
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding	LOWEN	SCR	✓
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: SLR 1584M

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender	DD	✓	
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			
1256		Rear bumper lower chrome moulding		BT	✓
1257					
1258					
1259					
1260					
1261					
1262					
1263					
1264					
1265					
1266					
1267					
1268					
1269					
1270					
1271					
1272					
1273					
1274					
1275					
1276					
1277					
1278					
1279					
1280					
1281					
1282					
1283					
1284					
1285					
1286					
1287					
1288					
1289					
1290					
1291					
1292					
1293					
1294					
1295					
1296					
1297					
1298					
1299					
1300					
1301					

No of Items: 11

Assessor: .

TGLim

21/9/18

mm

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Sep 2018 Edit Reg		05 Sep 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	SEAH ENG ENG, ID: S0359112C		
Main Claimant:	-		
Vehicle Reg. No.:	SLR1584M	Date of Loss:	03/09/2018 00:00 - :59 [113 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 9794645491SG	Policy/Cover Note No.:	2100487228 (Comprehensive)
Vehicle Reg. No. (Insured):	SLH6628R	Policy No. (Claimant):	
		Excess:	
Repairer:	Leng Wang Motor (HQ) Blk 3007 Ubi Road 1, #01-414, 408701 Ubi - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 14/09/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (07/09/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									





































Claim Documents

***SLR1584M (9794645491SG)**
[SLH6628R]

TP

-
Sep 3 2018 12:00AM
[SEAH ENG ENG]
Leng Wang Motor

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser		
Assessment Reports															1 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>	
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print		
1	07/09/18 11:30		Accident Statement From:OD - Reg. No: SLH6628R, Claimant: SEAH ENG ENG														Load HTM		
															3 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>	
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
2	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
3	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
4	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
5	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
6	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
7	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
8	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
9	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
10	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
11	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
12	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
13	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
14	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
15	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
16	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
17	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
18	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
19	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
20	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
21	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
22	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
23	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
24	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
25	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
26	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
27	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
28	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
29	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
30	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
31	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
32	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>
33	06/09/18 11:43		General View														Load JPG		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	06/09/18 11:43	General View	 Load JPG	<input checked="" type="checkbox"/>
35	06/09/18 11:43	General View	 Load JPG	<input checked="" type="checkbox"/>
36	06/09/18 11:43	General View	 Load JPG	<input checked="" type="checkbox"/>
37	06/09/18 11:43	General View	 Load JPG	<input checked="" type="checkbox"/>
38	11/09/18 12:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	11/09/18 12:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	11/09/18 12:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	11/09/18 12:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	11/09/18 12:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	11/09/18 12:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	11/09/18 12:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	11/09/18 12:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	11/09/18 12:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	11/09/18 12:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	11/09/18 12:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	11/09/18 12:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	11/09/18 12:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	11/09/18 12:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	11/09/18 12:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	11/09/18 12:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	11/09/18 12:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	24/09/18 15:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	24/09/18 15:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	24/09/18 15:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	24/09/18 15:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	24/09/18 15:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	24/09/18 15:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	24/09/18 15:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	24/09/18 15:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	24/09/18 15:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	24/09/18 15:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	24/09/18 15:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	24/09/18 15:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	24/09/18 15:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	24/09/18 15:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	24/09/18 15:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	24/09/18 15:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	24/09/18 15:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	24/09/18 15:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	24/09/18 15:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	24/09/18 15:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	24/09/18 15:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	24/09/18 15:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	24/09/18 15:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	24/09/18 15:10	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)



Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18016243/R1CD3E2

Date: 25/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100487228
 Claimant Vehicle No: SLR1584M Insured Vehicle No: SLH6628R
 Date of Loss: 03/09/2018 Nature of Claim: TP Claim No: 9794645491SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLR1584M**
 Make & Model: NISSAN SYLPHY, 1.5 4AT (A) Engine No: HR15111986B
 Reg. Date: 13/03/2009 (Man. Year: 2009) Chassis No: JN1BAAG11Z0107577
 Colour: Grey Odometer: 195931 km
 Engine Capacity: 1498 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 05/09/2018
 Date Inspected: 05/09/2018 Inspected At: Leng Wang Motor (HQ)
 Blk 3007 Ubi Road 1, #01-414
 Singapore 408701
 Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER REFLECTOR RH	Cracked	0.00 F	*- F
4	1		*REAR END PANEL	Dented	0.00 F	*- F
5	1		*REAR END PANEL TOP GARNISH	Distorted	0.00 F	*- F
6	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
7	1		*REAR RH TAILLAMP PANEL	Dented	0.00 F	*- F
8	1		*BOOTLID	Dented	0.00 F	*- F
9	2		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
10	1		*BOOTLID MOULDING LOWER	Scratched	0.00 F	*- F
11	1		*REAR LH FENDER	Dented	0.00 F	*- F
12	1		*REAR BUMPER LOWER CHROME MOULDING	Bent	0.00 F	*- F
Total Parts (\$\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >