

ASS. REC. BY:

REF: CS/CTI18016277/ Ktd3SM

Special Instruction:

Surveyor
menmen

Kenneth

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of CTI

Date/Time:

6/9/18 @ 11:06am

Estimated Cost:

Bill to:

TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLM 9471 D

Insured:

at Workshop m/s:

Cheng Hoe Motor

Tel:

6481 2001

of

Blk 1019 #01-374/382 Yishun Ind. Park A

Policy No:

DMPCSN 3048801700

Claim No:

SNM18D04269C01

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

02/09/2018

CA /

REV

REP. / REV 24 HRS

Insp: Cheng Hoe (AMK)

H.O.D. Endorsement:

Date/Time:

11:45am @ 6/9/18

Person Contacted:

Dorylyn

Vehicle

IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLM 9471D-X
7/9-	Revert via menmen total loss with poli advise.
	Market value x 16,000-
	LTA: 10,201
	NV: 5799.

ASS. REC. BY:

REF: CT21

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: _____

at Workshop m/s Cheng Hoe

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 816k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLM 94710 Yr Regn: 03, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: Chevrolet Cruze c.c. 1598

Colour: W. Black A/C: Insured / Std / NI / NA

Sp. Reading: 148551 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: K21JA 6961AK 608011

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 219/18

Survey held at _____

Rear


R/Bal. 8 mm

L/Bal. 8 mm

D.O.I. 6/9/18

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame & Body Structure affected due to collision.



Date / Time Action / Instruction
7/19 File pass to Catherine

Submit extensive total loss

RECEIVED 10 SEP 2018

Date/Time, File Pass to?

1) 10/9/18 Typist

Date/Time, File Return to?

2) _____

: Prell. Report

: Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: 220

Transportation: _____

S + RS: \$ _____

Photos _____

Others _____

TOTAL

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

Report Format: OD-TV

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18016277/Ktd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 06-09-2018	
		Code : CTI	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SLM 9471D
Policy No.	DMPCSN3048801700	Coverage (\$)	0.00
Claim No.	SNM18D04269C01	Excess (\$)	0.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	06/09/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	02/09/2018	Inspection Date	06/09/2018
Survey held at	10 ANG MO KIO IND PARK 2A #01-04		
Repairer	CHENG HOE MOTOR PL		
5a. Remarks			
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Sep 2018 Sendback Est	05 Sep 2018 16:32 S\$150.00	06 Sep 2018 11:06 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	MADHAN S/O ELAVALAHAN, ID: S9431880G, Tel: +6591015165, Email: maddytourch@hotmail.com		
Vehicle Reg. No.:	SLM9471D	Date of Loss:	02/09/2018 07:00 - :59 [101 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM18D04269C01	Policy/Cover Note No.:	DMPCSN3048801700 (Comprehensive)
		Excess:	S\$0.00
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/09/2018]		
Driver/Custodian:	MADHAN S/O ELAVALAHAN (23 / Male), NRIC: S9431880G, Tel: +6591015165		
Adj Asg. Remarks:	SURVEY REVERT		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)
[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 07 Sep 2018

Preliminary Advice

Vehicle No	: SLM9471D	Accident Date	: 02/09/2018
Make	: CHEVROLET CRUZE	Policy No.	: DMPCSN3048801700
Assignment Date	: 06/09/2018	Excess	: S\$0.00
Date of Inspection	: 06/09/2018	Est. Duration of Repair	: 0.00
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident. the undercarriage and body structure affected due to collision.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	16,000.00
COE / PARF Rebate	:S\$	10,201.00
Salvage Value	:S\$	
Margin for Repair	:S\$	5,799.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/09/2018 10:59
Date Of Accident	02/09/2018 07:30
Exact Location Of Accident	OUTSIDE 93/95 OWEN RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM9471D
Insured/Policyholder	
Name Of Registered Owner	MADHAN S/O ELAVALAHAN
NRIC No	S9431880G
Email Address	MADDYTOURCH@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-91015165
Alternative Phone No	OTHERS-91015165

Vehicle Particulars

Manufacturer	CHEVROLET
Model	CRUZE-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3048801700
Cover Note Number	15/06/2018 - 30/09/2018

Driver

Name of Driver	MADHAN S/O ELAVALAHAN
NRIC No	S9431880G
Date Of Birth	05/09/1994
Occupation	INDOOR
Date Of Driving Pass	27/11/2013
Driving Experience	4 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91015165
Fax Number	
Contact Number	OTHERS-91015165
Email Address	MADDYTOURCH@HOTMAIL.COM

SKETCH PLAN

VEHICLE NO.: SLM194711
INSURER : China
DATE & TIME: 02/09/18 @ 0730

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

 03/09/18 10:57am
Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: Dorlyn (AMK) 03/09/18
NRIC/FIN No.:

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 1880G

Vehicle Details

Vehicle No.: SLM9471D

Vehicle to be Exported: No

Intended Deregistration Date: 03 Sep 2018

Vehicle Make: CHEVROLET

Vehicle Model: CRUZE 1.6L AUTO ABS D/AB 2WD 4DR

Primary Colour: Black

Manufacturing Year: 2009

Engine No.: F16D35374321

Chassis No.: KL1JA6961AK608011

Maximum Power Output: 80.0 kW (107 bhp)

Open Market Value: \$12,601.00

Original Registration Date: 31 Mar 2010

First Registration Date: 31 Mar 2010

Transfer Count: 1

Actual ARF Paid: \$12,601.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 30 Mar 2020

PARF Rebate Amount: \$6,930.00

Intended COE Rebate Details

COE Expiry Date: 30 Mar 2020

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$20,802.00

COE Rebate Amount: \$3,271.00

Total Rebate Amount: \$10,201.00

The information contained herein is correct as at 03 Sep 2018

OK

- Cannot invest CPF SA anymore ?
- What Did You Makan Today PT 5
- Where is your favorite wanton noodle?

Chevrolet Cruze Price Range Depreciation 2010 Vehicle Type Submit

Advanced Search

Used Car Comparison

--- Comparing 2 Vehicles ---

Chevrolet Cruze 1.6A

Chevrolet Cruze 1.6A



Clear All

Add all to Shortlist

Back to search result

Add to Shortlist


Add to Shortlist

Use search bar above to select another car to compare.

Use search bar above to select another car to compare.

CAR DETAILS

Price	\$17,800	\$16,300
Instalment	\$723	\$662
Registration Date	19-Mar-2010	19-Mar-2010
Manufactured	2009	2010
Mileage	150,300 km	95,246 km
Transmission	Auto	Auto
Engine Cap	1,598 cc	1,598 cc
Road Tax	\$742 /yr	\$742 /yr
Power	80.0 kW (107 bhp)	80.0 kW (107 bhp)
Curb Weight	1,388 kg	1,388 kg
Features	1.6L 4 Cylinders Inline Eco Tec II DOHC Engine, 6 Speed Automatic Transmission, SRS Airbags, ABS, Knockdown Rear Seats, Steering Wheel Audio Controls.	Powerful And Reliable Eco Tec II DOHC 16V Engine Running On 6-Speed Automatic Transmission, ABS, ESP, 2 Airbags, Immobilizer, 4 Disc Brakes.
Accessories	Factory Fitted Audio System, Leather Seats, Sports Rims, Solar Films, Reverse Sensors, Auto Rain Sensors.	Leather Seats, Sports Rims, Factory Fitted Audio System With GPS Steering Control, Digital Climatic Aircon, Fog Lamps.
Description	Reliable And Great Fuel Efficient 1.6L Sedan, Candy Red Wrap With Luxury Black Leather, Straight Chassis/Undamaged Structure, Road Tax Till 09/2018. View And Test To Believe The Superb Conditions Rather Than Words, Welcome STA/VICOM Evaluation, Loan And Trade In Available. Call Us Now To View The Car Before It's Sold!	Reliable And Great Fuel Efficient 1.6L Sedan, Genuine Low Mileage. Regularly Serviced And Well Maintained By Non Smoker Owner. Popular Family Sedan Because Of Its Sturdy Continental Built Offering Safety And Peace Of Mind. Welcome To View And Test The Spacious Continental Ride And Great Condition.
COE	\$20,802	\$20,802
OMV	\$12,601	\$12,674
ARF	\$12,601	\$12,674
Depreciation	\$7,470 /yr	\$6,470 /yr
No. of Owners	3	2
Type of Vehicle	Sedan	Sedan
Category	PARF Car	PARF Car
Availability	Available	Available
SELLER INFORMATION		
Seller	Jetsprint Auto Enterprises	Thrive Auto
Address	335 Upper Paya Lebar Road	61 Ubi Avenue 2 #03-07
Office Number	63484711	64750078
Contact Person	Mr Ho / Mr Chua	Alvin / Carven
Contact Number	87788448 / 96714711	97274730 / 84985097



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761
 Tel : 67556142 Fax : 67557719
 Email: chmotor@singnet.com.sg

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/CHINA
Policy No:	DMPCSN3048801700	Date of Loss:	02/09/2018
Vehicle Reg. No.:	SLM9471D	Driveable?	
Driver Age/Info:	23 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	MADHAN S/O ELAVALAHAN	Contact No:	+6591015165
Driver:	MADHAN S/O ELAVALAHAN		
Make/Model:	CHEVROLET CRUZE, 1.6 (A)	Vehicle Reg. Date:	31/03/2010
Vehicle Colour:	BLACK	Chassis No:	KL1JA6961AK608011
Engine No:	F16D35374321		
Odometer:	0 KM		
Paint Type:			<i>Not Authored</i>
Total Loss?	YES		<i>7/01/18</i>
Est. Duration of Repair (day)	0		

Description of Accident/Loss REFER TO STATEMENT

Remarks: VEHICLE TOW INTO ANG MO KIO WORKSHOP SINCE 02/09/2018 MORNING.

VEHICLE SUSTAIN SEVERE DAMAGE AND OUR ESTIMATED REPAIR COST IS @ \$12K.

Present Location: CHENG HOE MOTOR PTE LTD (AMK)

COST OF CLAIMS	Amount
Parts	0.00
Miscellaneous Items	0.00
Labour	150.00
Paintwork Labour	0.00
Towing	0.00
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company 	
Acknowledged by Repairer	
Signature:	Gross Total (S\$) 150.00
Date:	+ GST 7.00% (S\$) 10.50
	Nett Amount (S\$) 160.50

This claim is handled by: **DORLYN LI YAZHU**

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Sep 2018)
 Parts: 143 CHEVROLET CRUZE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: **Cheng Hoe Motor Pte Ltd/SLM9471D/05/09/2018 16:32**
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

There are no new parts selected.

Cheng Hoe Motor Pte Ltd/SLM9471D/05/09/2018 16:32. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Towing (crane up & tow by king dolly) - bill attach	New	150.00
Gross Labour Cost (S\$)			150.00

Cheng Hoe Motor Pte Ltd/SLM9471D/05/09/2018 16:32. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

張建福 (機件) 拖車服務
TEO KIAN HOCK (CHEE CHEN) TOWING SERVICES

Mailing Address: 40 Cactus Road, Singapore 809597

Tel: 6858 4067 Fax: 6854 0407

廿四小時服務 24 HOURS SERVICE

Reg. No. 413736/00L

CASH SALE / WORK ORDER

No. 1578

Date: 22/09/2018

寶號

Messrs: 濟河

車號

Vehicle No: SLM9471D

車型

Model No:

由

From: Awam Bel

到

To: 12-12

時間 (日/夜)

Time (day/night):

其他

Others: Acc King Dolly 吊車

CASH \$: 150

CHEQUE:

經手人

Authorised by: [Signature]

收貨人

Received by:

注意: 本公司對所托之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Sep 2018 Sendback Est	05 Sep 2018 16:32 S\$150.00	06 Sep 2018 11:06 Edit Adj Rpt	S\$150.00 Edit Estimates	S\$150.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	MADHAN S/O ELAVALAHAN , ID: S9431880G, Tel: +6591015165, Email: maddyturch@hotmail.com								
Vehicle Reg. No.:	SLM9471D	Date of Loss:	02/09/2018 07:00 - :59 [101 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM18D04269C01	Policy/Cover Note No.:	DMPCSN3048801700 (Comprehensive)						
		Excess:	S\$0.00						
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 17/09/2018]								
Driver/Custodian:	MADHAN S/O ELAVALAHAN (23 / Male), NRIC: S9431880G, Tel: +6591015165								
Adj Asg. Remarks:	SURVEY REVERT								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• CHINA_TAIPING (10/09/2018): Alert - Adj Mandate Approved (S\$0.00) - SLM9471D - Claim Handler: Chong Boon Sen									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLM9471D (SNM18D04269C01)
OD
Sep 2 2018 7:00AM
[MADHAN S/O ELAVALAHAN]
Cheng Hoe Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser ▼		
Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>	
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
1	03/09/18 18:14	Accident Statement	1	Load HTM	
2	05/09/18 16:32	Repairer Estimates	2	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/09/18 13:32	Adjuster Immediate Advice	1	Load HTM	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>	
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
1	03/09/18 17:30	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
2	03/09/18 17:30	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
3	03/09/18 17:30	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
4	03/09/18 17:30	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
5	03/09/18 17:30	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
6	03/09/18 17:30	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
7	03/09/18 17:30	SCENE PHOTO [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
8	03/09/18 17:30	SCENE PHOTO [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
9	03/09/18 17:30	SCENE PHOTO [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
10	03/09/18 17:30	SCENE PHOTO [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/09/18 13:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	07/09/18 13:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	07/09/18 13:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	07/09/18 13:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	07/09/18 13:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	07/09/18 13:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	07/09/18 13:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	07/09/18 13:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	07/09/18 13:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	07/09/18 13:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	07/09/18 13:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	07/09/18 13:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	07/09/18 13:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	07/09/18 13:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	07/09/18 13:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	07/09/18 13:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	07/09/18 13:32	General View	1	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
18	07/09/18 13:32	General View	Load JPG	<input checked="" type="checkbox"/>
19	07/09/18 13:32	General View	Load JPG	<input checked="" type="checkbox"/>
20	07/09/18 13:32	General View	Load JPG	<input checked="" type="checkbox"/>
21	07/09/18 13:32	General View	Load JPG	<input checked="" type="checkbox"/>
22	07/09/18 13:32	General View	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	03/09/18 17:29	Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	03/09/18 17:29	Sketch Plan #2 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	03/09/18 17:29	Sketch Plan #3 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	05/09/18 16:30	IC & DL	Load JPG	<input checked="" type="checkbox"/>
5	05/09/18 16:30	TOWING BILL	Load JPG	<input checked="" type="checkbox"/>

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/09/18 09:22	LTA REBATE	Load PDF	

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	03/09/18 18:14	Accident Statement	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	03/09/18 17:30	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	03/09/18 17:30	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	03/09/18 17:30	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	03/09/18 17:30	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	03/09/18 17:30	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	03/09/18 17:30	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	03/09/18 17:30	SCENE PHOTO	Load JPG	<input checked="" type="checkbox"/>
8	03/09/18 17:30	SCENE PHOTO	Load JPG	<input checked="" type="checkbox"/>
9	03/09/18 17:30	SCENE PHOTO	Load JPG	<input checked="" type="checkbox"/>
10	03/09/18 17:30	SCENE PHOTO	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	03/09/18 17:29	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	03/09/18 17:29	Sketch Plan #2	Load JPG	<input checked="" type="checkbox"/>
3	03/09/18 17:29	Sketch Plan #3	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Repairer Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTChina Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909**Our File No:** CS/CTI18016277/KTD3S2**Date:** 11/09/2018REFERENCE

Insured/Claimant:	MADHAN S/O ELAVALAHAN	Policy No:	DMPCSN3048801700
Date of Loss:	02/09/2018	Nature of Claim:	OD
			Claim No: SNM18D04269C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM9471D	Engine No:	F16D35374321
Make & Model:	CHEVROLET CRUZE, 1.6 (A)	Chassis No:	KL1JA6961AK608011
Reg. Date:	31/03/2010 (Man. Year: 2009)	Odometer:	148551 km
Colour:	Metallic Black		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$16,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	150.00	150.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	150.00	150.00	0.00	0.00
+ GST 7.00/7.00% (S\$)	10.50	10.50	0.00	0.00
Nett Amount (S\$)	160.50	160.50	0.00	0.00

INSPECTION

Date of Assignment:	06/09/2018		Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	06/09/2018	Inspected At:	Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	0.0 days		

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

TOTAL LOSS ASPECT

Market Value :	\$16,000.00
OMV :	\$12,601.00
PARF Rebate (1) :	\$6,930.00
Quota Premium Paid :	\$20,802.00
COE Rebate (2) :	\$3,271.00
Total Rebate (1) + (2) = :	\$10,201.00

The total amount incurred will be Market Value \$16,000.00 minus Total Rebate \$10,201.00 = \$5,799.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Sep 2018)

Parts: 143 CHEVROLET CRUZE 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLM9471D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Towing (crane up & tow by king dolly) - bill attach	New	150.00	150.00
			Gross Labour Cost (\$\$)	150.00
				150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >