

INS. CASE OWNER: CC 6 /AIG1801 6290, u. ebnh LKK IDAC

Surveyor: UPS Assignment DOI: 11/11/18 Date / Time: 6/11/18 Registered in Merimen: 6/11/18

Pre-assign / CCU / FTE



Insured Vehicle No.: SU 18692 Claim No.: 6384222256
 Name of Insured: MOHAMED SARAHADIN AIN MOHAMED MOHIOU Policy No.: 700500665-01
 Insured Tel No.: HP: 9786796 Make / Model: MYSAN
 Excess Sec II :SS D.O.A: 11/11/18 HADAMUWAH Place of Accident: 94 HADAMUWAH MEETPOINT
 Is driver the owner? (YES / NO) Nature of Accident:
 If NO, Driver Name / Age: Driver Tel No.: 9786796 (V/L: YES / NO) OI GIA REPORT: YES / NO TP GIA REPORT: YES / NO
 Insured Liability: % Final ? Yes / No

SU 18692



INSRS: Jin WSP: Auto. Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date/Time: 11/11/18
 11.9.18 @ 1.41pm

5007096-X 50018692-X
 CALLED ON CONFIRMED ACCIDENT. ON REAR END OF TP, INFORM TP
 ROWN. ADVISED TO SEND AND ADVISE ABOUT PICO ISSUE.
 BRW WSP LIABILITY CLEAR

RECEIVED 04 DEC 2018

STAGE	DATE / PIC
Non-Reporting Itr (1st):	
Non-Reporting Itr (2nd):	
Non-Reporting Itr (Final):	
Notification Itr (if non-pickup):	
Call OI:	6/11/18 10.10
After call Itr to OI:	
Documentation Check List: Handler Typist	
Notification Itr (if non-pickup):	<input type="checkbox"/>
After call Itr to OI:	<input checked="" type="checkbox"/>
Authorisation To Act:	<input checked="" type="checkbox"/>
Release Voucher:	<input checked="" type="checkbox"/>
Final Repair Bill:	<input checked="" type="checkbox"/>
Car Rental Invoice:	<input type="checkbox"/>
Towing Invoice:	<input type="checkbox"/>
LTA / GIA:	<input type="checkbox"/>
Medical Bill:	<input type="checkbox"/>
PIR:	<input type="checkbox"/>
Mandate/Reject Instruction:	<input type="checkbox"/>
LOD:	<input type="checkbox"/>
Payment Breakdown Form:	<input type="checkbox"/>
Post-Repair Photos:	<input type="checkbox"/>
Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: - Sent By: -	
FINALIZATION Date/Time: 11.9.18 Confirm with: JOM Confirm by: QCS	
Repair Cost: 1/1 SS 800 (2 days) Reduction: 4/1 5	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT Date/Time: 29.11.18 Confirm with: JOM Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>	
Final Liability: 1/1 (Agreed / Assessed) BOLA S/N No.: 27	If NO or B 28, Ass. Lia:
Repair Cost: 4/1 SS 850.00 ON REAR END OF TP	
Loss of Rental (LOR): SS - (days)	
Loss of Use (LOU): SS 120.00 (500 x 3 days)	
Loss of Income (LOI): SS - (5 x days)	
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/> [Tick only one]	
GIA/LTA Search: SS -	
Medical: SS -	
Disbursement: SS - (e.g. Tow/ Independent)	
Legal Cost: SS -	
Total: SS 970.00 Global Sum SS:	
FINAL PAYMENT Date/Time: 29.11.18 Confirm with: JOM Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>	
Payee 1: SS 970.00 Name 1: JIN AUTO SERVICES PTE LTD	
Payee 2: (Strike if N.A.) SS Name 2:	
Payee 3: (Strike if N.A.) SS Name 3:	

COPY SENT

(08/11/3) waf

ASS. REC. BY: Marcus

REF:

A1w/ l

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLV 26194at Workshop m/s Tin Ato

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLV 26194 Yr Regn: 12/17Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CarMake: Hyundai Elantra c.c. 1591Colour: Red A/C: Insured / Std / NI / NASp. Reading: 12932 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHD841CMJU592300Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or nexen

Front

Rear

R/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 3/9/18 D.O.L. 12/9/18

Survey held at _____

Des. of Damages: Free / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time

Action / Instruction

2/9/18 4/5 @ 800 conf. with Jones.

(SIB: 308 A 4.7.)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG18016290/eb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 06-09-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLL 1869Z	Veh. Inspected	SLV 2619U
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	06/09/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	03/09/2018	Inspection Date
Survey held at	JIN AUTO SERVICES PTE LTD BLK 14 DEFU LANE 10 #01-412 SINGAPORE 539195	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. E) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel: 62898126 Fax: 62870590

Company Reg No: 200704370C GST Reg No: 200704370C

Your ref : SLV2619U

Date: 11.09.2018

M/S AIG ASIA PACIFIC INSURANCE PTE LTD

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR SLV2619U(HYUNDAI ELANTRA)

DATE OF ACCIDENT : 03.09.2018

TO SUPPLY :

LIST ITEMS

01)	1 PC	REAR BUMPER	DD/Deq (C/S)	\$ 459.00	=
02)	1 PC	REAR BUMPER LOWER GARNISH(BLACK)	(C/S)	\$ 250.10	=
				\$ 709.10	
			20% LESS 10%	\$ (70.91)	
				\$ 638.19	

Labour Cost

03)	SPRAY PAINT	\$ 320.00	200
04)	LABOUR CHARGE	\$ 320.00	200
05)	TRANSFER PARKING SENSOR	\$ 80.00	50
	TOTAL LABOUR COST	\$ 720.00	

TOTAL \$ 1,358.19

Not Attached
like
12/9/18
telephone After rep-
2dy.
4/5 \$800

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0047B
Vehicle Details	
Vehicle No.:	SLV2619U
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Sep 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA AD 1.6 GLS AT
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	G4FGHU830245
Chassis No.:	KMHD841CMJU592300
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$10,338.00
Original Registration Date:	27 Dec 2017
First Registration Date:	27 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$10,338.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Dec 2027
PARF Rebate Amount:	\$7,753.00
Intended COE Rebate Details	
COE Expiry Date:	26 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,200.00
COE Rebate Amount:	\$35,478.00
Total Rebate Amount:	\$43,231.00

The information contained herein is correct as at 12 Sep 2018

OK

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412
Singapore 539195
Tel:62898126 Fax :62870590
Business Registration No:200704370C

Date : 24/09/2018

Your ref : SLL1869Z

AIG ASIA PACIFIC INSURANCE PTE LTD
C/O LKK Auto Consultants Pte Ltd
51 Ubi Ave 1
#01-25 Paya Ubi Industrial Park
(S) 408933

Dear Sir/Madam

Accident involving vehicle SLV2619U & SLL1869Z ON 3/09/2018

We are instructed by the owner SLV2619U to write ,negotiate and settle claim on her behalf for the above mentioned accident. we are now seeking the total amount of claim as follow:

Repair cost	S\$856.00(with gst)
LOSS OF USE	160.00

TOTAL S\$ 1016.00

We shall appreciate if you could kindly consider our claim at your earliest convenience and kindly let us have your acknowledgement of receipt of this letter within 14days of your receipt of this letter.

Yours faithfully



Jouis Seow (Email: jouis@jinauto.com.sg)

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Monday, 8 October 2018 12:19 PM
To: 'MSMMH1@YAHOO.COM'
Subject: ACCIDENT INVOLVING SLL 1869Z AND SLV 2619U ON 03/09/2018

Our Ref: CC6/AIG18016290/Ueb3

08 OCT 2018

MOHAMED SALAHUDDIN BIN MOHAMED MOHIDIN HABIBULLAH

Dear Sir/Madam,

ACCIDENT INVOLVING SLL 1869Z AND SLV 2619U ON 03/09/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: Ashersng@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

LETTER OF AUTHORITY

To: Jin Auto Services Pte Ltd
Block 14 Defu Lane 10
#01-410/412
Singapore 539195

Dear Sir

ACCIDENT INVOLVING SLV2619U & SLL1869Z ON 3/9/18

I/We, the owner of vehicle no: SLV2619U hereby instruct and authorise you to commence repairs to the said vehicle.

I/We, hereby appoint you recover my damages sustained in the above accident.

Please recover the following:

1. Cost of repairs/Excess
2. Loss Of Use/Rental fees

You may proceed to apply to the relevant authorities for all necessary reports/documents to enable you to process my claim.. The entire amount claimed shall belong and make payable to Jin Auto Services Pte Ltd absolutely.

Yours faithfully



Henry Choo Pany Kwoc

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, JIN AUTO SERVICES PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$856.00 (Repair Cost), S\$120.00 (Loss of Use/Rental), S\$ - (Disbursement) for vehicle no. SLV 2619U that was damaged pursuant to the accident which occurred on 03/09/2018 (date) along TOWARDS JOHOR CUSTOM (DIRECTION TO SINGAPORE) (location) involving vehicle no/s SLL 1869Z.

This is pursuant to the inspection conducted on 12/09/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner HENRY CHOO PUAY KWEE ("the third party claimant") of vehicle no. SLV 2619U make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLV 2619U (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 29 (day) of NOV (month) 2018 (year)



CKS

Signed by appointed surveyor



Signed by "the workshop" (with chop)

JIN AUTO SERVICES PTE LTD

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Sep 2018 Edit Reg		12 Sep 2018 00:00 Edit Adj Rpt	\$5800.00 Edit Estimates	\$5800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	MOHAMED SALAHUDDIN BIN MOHAMED MOHIDIN HABIBULLAH , ID: S7408907J								
Main Claimant:	HENRY CHOO PUAY KWEE , ID: S7040047B								
Vehicle Reg. No.:	SLV2619U	Date of Loss:	03/09/2018 21:00 - :59 [8 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6384222923SG	Policy/Cover Note No.:	2100500665 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLL1869Z	Policy No. (Claimant):	5097561231						
		Excess:							
Repairer:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 17/09/2018]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLV2619U (6384222923SG)

[SLL1869Z]

TP







HENRY CHOO PUAY KWEE

Sep 3 2018 9:00PM

[MOHAMED SALAHUDDIN BIN MOHAMED MOHIDIN HABIBULLAH]

Jln Auto Services Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Letters/Correspondences										1 per page 1	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown						1 Edit			
Assessment Reports										1 per page 1	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail		Print	
1	07/09/18 09:30	Accident Statement <small>From: SC - Reg. No: SLL1869Z, Claimant: MOHAMED SALAHUDDIN BIN MOHAMED MOHIDIN HABIBULLAH</small>						1 Load HTML			
Photos/Images										3 per page 1	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	12/09/18 16:23	Chassis Number						1 Load JPG		1	
2	12/09/18 16:23	Odometer Reading						1 Load JPG		1	
3	12/09/18 16:23	General View						1 Load JPG		1	
4	12/09/18 16:23	General View						1 Load JPG		1	
5	12/09/18 16:23	General View						1 Load JPG		1	
6	12/09/18 16:23	General View						1 Load JPG		1	
7	12/09/18 16:23	General View						1 Load JPG		1	
8	12/09/18 16:23	General View						1 Load JPG		1	
9	12/09/18 16:23	General View						1 Load JPG		1	
10	12/09/18 16:23	General View						1 Load JPG		1	
11	12/09/18 16:23	General View						1 Load JPG		1	
12	12/09/18 16:23	General View						1 Load JPG		1	
13	12/09/18 16:23	General View						1 Load JPG		1	
14	12/09/18 16:23	General View						1 Load JPG		1	
15	12/09/18 16:23	General View						1 Load JPG		1	
16	12/09/18 16:23	General View						1 Load JPG		1	
17	12/09/18 16:23	General View						1 Load JPG		1	
18	12/09/18 16:23	General View						1 Load JPG		1	
19	12/09/18 16:23	General View						1 Load JPG		1	
20	12/09/18 16:23	General View						1 Load JPG		1	
21	12/09/18 16:23	General View						1 Load JPG		1	
22	12/09/18 16:23	General View						1 Load JPG		1	
23	12/09/18 16:23	General View						1 Load JPG		1	
24	12/09/18 16:23	General View						1 Load JPG		1	
25	12/09/18 16:23	General View						1 Load JPG		1	
26	12/09/18 16:23	General View						1 Load JPG		1	
27	12/09/18 16:23	General View						1 Load JPG		1	
Documentation										1 per page 1	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/09/18 14:43	TP GIA REPORT	 Load PDF	
2	13/09/18 17:41	TP ESTIMATE- MARKED	 Load PDF	
3	08/10/18 12:19	LETTER TO OI	 Load PDF	
4	17/12/18 08:33	WORKSHOP INVOICE	 Load PDF	
5	17/12/18 08:33	AUTHORISATION TO ACT FORM	 Load PDF	
6	17/12/18 08:33	Release Voucher	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div> Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div></div> <div> Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> </div> </div>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLL1869Z (Insd veh)	Model:	HYUNDAI ELANTRA 1.6 (A)
	SLV2619U (TP veh)		
Date of Accident:	03/09/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	1,453.26	
Final Repair Cost	:	\$	856.00	
Loss of Use	:	\$	120.00	2.00 days at \$60.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	0.00	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	976.00	

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Jin Auto Services Pte Ltd	:	\$ 976.00
2)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

17 Dec
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18016290/UEB3Q2

Date: 17/12/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100500665

Claimant Vehicle No: SLV2619U Insured Vehicle No: SLL1869Z

Date of Loss: 03/09/2018 Nature of Claim: TP Claim No: 6384222923SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLV2619U**
 Make & Model: HYUNDAI ELANTRA, 1.6 (A) Engine No: G4FGHU830245
 Reg. Date: 27/12/2017 (Man. Year: 2017) Chassis No: KMHD841CMJU592300
 Colour: Red Odometer: 12932 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Nexen 8 mm Rear Left Side: Nexen 8 mm
 Front Right Side: Nexen 8 mm Rear Right Side: Nexen 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	638.19	567.28	70.91	11.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	720.00	450.00	270.00	37.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,358.19	1,017.28	340.91	25.10
Approved Total (Overridden) (S\$)		800.00		
(S\$)	1,358.19	800.00	558.19	41.10
+ GST 7.00/7.00% (S\$)	95.07	56.00	39.07	41.10
Nett Amount (S\$)	1,453.26	856.00	597.26	41.10
+ Loss of Use (2.0 x S\$60.00/day) (S\$)		120.00		
Nett Liability (S\$)		976.00		

INSPECTION

Date of Assignment: 12/09/2018

Date Inspected: 12/09/2018 Inspected At:

Jin Auto Services Pte Ltd (Defu)
 Blk 14 Defu Lane 10, #01-410/412
 Singapore 539195

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deep Cut	459.00 FL	*459.00 FL
2	1		*REAR BUMPER LOWER GARNISH (BLACK)	Cut	250.10 FL	*250.10 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	709.10	709.10
- List Item Discount on L Items 10.00/20.00% (\$)	70.91	141.82
Total Parts (\$)	638.19	567.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINT	New	320.00	200.00
2	LABOUR CHARGE	New	320.00	200.00
3	TRANSFER PARKING SENSOR	New	80.00	50.00
Gross Labour Cost (\$\$)			720.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >