

INSURANCE

INS. CASE OWNER:

Ang Yao

CC 4/AIG1801

6218, 6pb39

LKK:

IDAC:

Surveyor:

YGA

DOI:

ASSIGNMENT

10/11/18

Date / Time:

6/11/18

Registered in Merit:

6/11/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKR 1195P

Name of Insured:

LIAM WAI HUNG MERVIN

Insured Tel No.:

HP: 9679684

Excess Sec II :SS

D.O.A.:

4/11/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

0700011754

Policy No.:

70074707-07

Make / Model:

HATCHBACK

Place of Accident:

OPHIZ RD OPP RAFFLES HOSPITAL

If NO. Driver Name / Age:

Driver Tel No.:

(V/L / YES / NO)

OI GIA REPORT YES / NO : TP GIA REPORT YES / NO

Insured Liability: % Final ? Yes / No

SGX 442AC



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Fortuna



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/Time

10/11/18

8/11/18

SGX 442AC - X

SKR 1195P - X

- OI rear ended P

2/11/18 - For pass to Shupai future

RECEIVED 05 NOV 2018

STAGE	DATE / PIC
Non-Reporting 1st (1st)	
Non-Reporting 1st (2nd)	
Non-Reporting 1st (Final)	
Notification 1st (if non-pickup)	
Call OI	
After call 1st to OI	
Documentation Check List:	Handler Typist
Notification 1st (if non-pickup)	
After call 1st to OI	
Authorisation To Act:	
Release Voucher:	
Final Repair Bill:	
Car Rental Invoice:	
Towing Invoice:	
LTA / GIA:	
Medical Bill:	
PIR:	
Mandate/Reject Instruction:	
LOD:	
Payment Breakdown Form:	
Post-Repair Photos:	
Others:	

<b>PRELIMINARY ADVICE</b> Date/Time:		Sent By:	
<b>FINALIZATION</b> Date/Time:		Confirm with:	
Repair Cost:	\$S	( days) Reduction:	%
<b>FINAL SETTLEMENT</b> Date/Time:		Confirm with:	
Final Liability:	%	(Agreed / Assessed) BOLA S/N No.	27
Repair Cost:	\$S 1456.00		
Loss of Rental (LOR):	\$S	( days)	
Loss of Use (LOU):	\$S 3w.w	(5w x 3 days)	
Loss of Income (LOI):	\$S	(5 x days)	
LOR only	<input type="checkbox"/>	LOU only	<input type="checkbox"/>
LOR + LOU	<input type="checkbox"/>	LOR + LO	<input type="checkbox"/>
[Tick only one]			
GIA/LTA Search	\$S		
Medical:	\$S		
Disbursement:	\$S	(e.g. Tow/ Independent)	
Legal Cost:	\$S		
Total:	\$S 2226.00	Global Sum \$S:	
<b>FINAL PAYMENT</b> Date/Time:		Confirm with:	
Payee 1:	\$S 2226.00	Name 1:	Fortuna Motor
Payee 2: (Strike if N.A.)	\$S	Name 2:	
Payee 3: (Strike if N.A.)	\$S	Name 3:	

COPY SENT

1) Claim status: Normal/Reject/Private Settle  
2) Report format:  
3) Survey fee: \$320 + \$20.

Yael

Alt

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop n/s Fortuna Motor  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_


(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

Bal. or Market Value: 64K  
 IDAC Accident Rpt.: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 3 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT



Veh No: 56X9929C Yr Regn: 23 Dec 2011  
 Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: BMW cc 2497  
 Colour: white A/C: Insured / Std / NI / NA  
 Sp. Reading: 114798 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: WBAFP32090C 867994  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 275/40R18  
 R: 11  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Continental  
 Front R/Bal: 6 mm Rear R/Bal: 6 mm  
 L/Bal: 6 mm L/Bal: 6 mm  
 D.O.A. D.O.I. 10-03-18  
 Survey held at w/s 9AM  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
 10/9 Estimate given later. Do direct settlement.  
 US\$ 1800 (Red \$ 2620/597).

Date/Time File Pass to?

☐ : Preli. Report  
☐ : Final Report

1)

Date/Time File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

\$ - RS \$

Phone

Other

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ )

Add Fee: ☐ Site Insp (\$ )

☐ Interview (\$ )

☐ Tech. Invs (\$ )

☐ Weekend (\$ )

Surveyor Yael REF: Alb (2021)

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop ins: Fortuna Motor  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: 9116 5700 Han  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$64K

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle IN / OUT

Veh No: 56X9929C Yr Regn: 23 Dec 2011  
 Type: M/Cycle / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 523i cc 2497

Colour: white A/C Insured / Std / Nil / NA

Sp Reading: 114798 T/Radio: Insured / Std / Nil / NA

Eng/No: \_\_\_\_\_

C/No: WBAFP32090C 867994

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Ins / Jammed / Leaked / Burnt or

Brake: Ins / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/40R18  
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal: 6 mm

R/Bal: 6 mm

L/Bal: 6 mm

L/Bal: 6 mm

D.O.A.

D.O.I. 10-03-18

Survey held at W/S

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
10/9	Estimate given later. Do direct settlement.

p.motunuiue.com

Date/Time, File Pass to?

☐ : Preli. Report

11

☐ : Final Report

Date/Time, File Return to?

21

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

1 \$ + RS \$

2 Photos

3 Other

4

TOTAL

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Insp (\$

☐ Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC4/AIG18016318/Gpb3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 06-09-2018



Code : AIG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKR 1195P	Veh. Inspected	SGX 9929C
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHAN YOKE SHI	Assign Date	06/09/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer		Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	04/09/2018	Inspection Date	10/09/2018
Survey held at	FORTUNA MOTOR 40 UPPER EAST COAST ROAD SINGAPORE 455212		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



# Shell autoserv

## JOB AUTHORISATION FORM

NAME:

ADDRESS:

CONTACT NO:

CHASSIS NO:

PAYMENT:

DATE OF REGN:

QUOTATION: YES/NO

I hereby authorize the repairer to hence notify the insurance company the following:

- To insure/alter/repair/spray painting
- To display damaged part(s) during repair
- Parts prices are subject to confirmation
- This quote is on a "without prejudice" basis
- No liability for consequential damage

VEHICLE NO:

ENGINE NO:

MAKE:

MODEL:

Serial No: A

DATE:

TIME:

MILEAGE:

FUEL TANK LEVEL:





174.7  
1050.6!  
~~1167.2~~

### MAINTENANCE SERVICE

1pc	REAR BUMPER	2,800/00	1 De	1532
1pc	LOWER COVER	380/00	1 Gt	1
1pc	CLIP	80/00	1 MC	40
1pc	REAR LOWER COVER	180/00	X NN	
RENEW	BUMPER AND ASSY	- 400/00	<del>200</del> 250	
TOUCH-UP	BUMPER	- 580/00	<del>200</del> 250	
<p>1950 1805.35 3 Days. - 5% : 1805.35 1732.08 3 Days. 2254.4 2232.08 after repair plates. 4,420/00</p>				

Kindly remove your cash & valuables from vehicle.

- 20% : 1806

Hub Caps ☐Cigarette Lighter ☐Tool Kit ☐Spare Tire ☐Jack ☐Others ☐

X - Missing

O - Dent

/ - Scratch

# - Crack

\* - Paint Fade

### I hereby:

Authorize the above repairs and any essential work and supply of materials arising therefrom. The vehicle may be driven on the road for testing purposes or others in carrying out such repairs. Any claim for any damage caused to the vehicle during the course of the road test or repair arising from any accident or otherwise is limited to the rectification free of cost. No claim for incidental or consequential losses is admissible. Any claim for faulty workmanship is limited solely to the rectification free of cost of such faulty work, no claim for loss consequential or other being admissible.

☐ Give consent to the staff of Shell Autoserv to contact me for the purpose of obtaining my approval for additional work to be done to my vehicle, inform me of the collection of my vehicle and/or remind me of the next service/repair date.

I accept the foregoing conditions which I have read

Signature of Customer/Representative

Signature of Service Advisor

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9552C
Vehicle Details	
Vehicle No.:	SGX9929C
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Sep 2018
Vehicle Make:	B.M.W.
Vehicle Model:	523I 2.5 AT ABS D/AB 2WD 4DR GAS/D
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	08157867N52B25AF
Chassis No.:	WBAFP32090C867994
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$41,598.00
Original Registration Date:	23 Dec 2011
First Registration Date:	23 Dec 2011
Transfer Count:	1
Actual ARF Paid:	\$41,598.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Dec 2021
PARF Rebate Amount:	\$27,038.00
Intended COE Rebate Details	
COE Expiry Date:	22 Dec 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$70,003.00
COE Rebate Amount:	\$22,698.00
<b>Total Rebate Amount:</b>	<b>\$49,736.00</b>

The information contained herein is correct as at 24 Sep 2018

OK



[> Back to OneMotoring](#)

## Enquire Transfer Fee

### Vehicle Details

Vehicle No.:	SGX9929C
Vehicle Type:	P10 - Passenger Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	B.M.W.
Vehicle Model:	523i 2.5 AT ABS D/AB 2WD 4DR GAS/D
Chassis No.:	WBAFP32090C867994
Propellant:	Petrol
Engine No.:	08157867N52B25AF
Engine Capacity:	2497 cc
Maximum Power Output:	150.0 kW (201 bhp)
Maximum Laden Weight:	2260 kg
Unladen Weight:	1650 kg
Year Of Manufacture:	2011
Original Registration Date:	23 Dec 2011
Lifespan Expiry Date:	-
COE Category:	B - Car (1601cc & above)
Quota Premium:	\$70,003.00
COE Expiry Date:	22 Dec 2021
Road Tax Expiry Date:	22 Dec 2018
PARF Eligibility Expiry Date:	22 Dec 2021
Inspection Due Date:	22 Dec 2018
Intended Transfer Date:	24 Oct 2018
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

The current road tax expiry is 22 Dec 2018. You may renew the road tax from 23 Sep 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 22 Dec 2018, late renewal fee(s) will be imposed. Please use [Enquire Road Tax Payable](#) to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

### Amount Payable (From 23 Dec 2018 to 22 Jun 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
<b>Sub Total:</b>			<b>25.00</b>
Nett Road Tax Amount (After Offsetting Over Payment):	898.00	-	898.00
<b>Total Amount Payable:</b>			<b>923.00</b>

### Amount Payable (From 23 Dec 2018 to 22 Dec 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
<b>Sub Total:</b>			<b>25.00</b>
Nett Road Tax Amount (After Offsetting Over Payment):	1,796.00	-	1,796.00
<b>Total Amount Payable:</b>			<b>1,821.00</b>

You may print this page for reference.

[OK](#)
[Print](#)



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG18016318/Gpb3

09 OCT 2018

**CHAN WAI HONG MELVIN**  
3 JALAN SIMPANG BEDOK  
SINGAPORE 488149

Dear Sir/Madam,

**ACCIDENT INVOLVING SKR 1195C & SGX 9929C ALONG/AT OPHIR ROAD  
OPPOSITE RAFFLES HOSPITAL ON 04/09/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SGX 9929C against your motor insurance policy.

Based on the accident report and accident scenario, liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG  
Case Handler  
DID: 6742 3197  
FAX: 6741 4108  
Email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com)

c.c. *AIG Asia Pacific Insurance Pte Ltd*  
*(Motor Claims Dept)*



**AUTHORIZATION TO ACT**  
**(AIG Asia Pacific - Express Third Party Claim)**

I, LIM HUAT SIONG (the third party claimant") of BLK 20 BEDOK SOUTH ROAD #08-35 (S)460020 (address), owner of SGX 9929C (vehicle no.) hereby authorize FORTUNA MOTOR ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no SGX 9929C that was damaged pursuant to the accident which occurred on 04/09/2018 (date) along OPHIR ROAD (location) involving vehicle no/s SKR 1195P ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 01<sup>st</sup> (day) of NOV (month) 2018 (year)



Signed by "the third party claimant"  
(with chop if applicable)

 **FORTUNA MOTORS**  
40 UPPER EAST COAST ROAD  
SINGAPORE 455212

Signed by "the workshop"  
(with chop)

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, FORTUNA MOTOR ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$1,926.00 (Repair Cost), S\$300.00 (Loss of Use/Rental), S\$ - (Disbursement) for vehicle no. SGX 9929C that was damaged pursuant to the accident which occurred on 04/09/2018 (date) along OPHIR ROAD (location) involving vehicle no/s SKR 1195P. This is pursuant to the inspection conducted on 10/09/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner LIM HUAT SIONG (the third party claimant") of vehicle no. SGX 9929C make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SGX 9929C (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 01 (day) of NOV (month) 2018 (year)



*X/GQ*

Signed by appointed surveyor

FORTUNA MOTO  
40 UPPER EAST COAST R  
SINGAPORE 455212

Signed by "the workshop" (with chop)

FORTUNA MOTORS  
40 UPPER EAST COAST ROAD  
SINGAPORE 455212



**Fortuna Motors**  
*An AA Approved Workshop*

Tax Invoice No.: 14106

CO. REG. NO. : 49-369100-J

GST. REG. NO.: M90367971E

Shell Siglap

40 Upper East Coast Road Singapore 455212  
Tel: 6468 6790 Fax: 6468 6791

Payment By:

CASH / VISA / AMEX / MASTER

[illegible]

### Terms:

- a) Payment to be made upon collection of vehicles.  
b) Any objections to the validity of the charges or jobs must be made within 7 days from the date of this invoice. Otherwise it is assumed that the invoice is accepted as correct.  
c) Estimate cost of repairs, delivery date or time are only given on the understanding that these are not binding or definite.



Some parts changed are under warranty for a period of 3 months from the date of this invoice.

Customer's Signature

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane
















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Sep 2018 <a href="#">Edit Reg</a>		06 Sep 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$1,800.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,800.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	Chan Wai Hong Melvin, ID: S7036024A								
Main Claimant:	LIM HUAT SIONG, ID: S7539552C								
Vehicle Reg. No.:	SGX9929C	Date of Loss:	04/09/2018 16:00 - :59 [80 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0244812113SG	Policy/Cover Note No.:	2100399209 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKR1195P	Policy No. (Claimant):	P1776503						
		Excess:							
Repairer:	Fortuna Motor (HQ) 40 Upper East Coast Road, 455212 East Coast Park - Tel: 6468 6790								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 17/09/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (07/09/2018): Request To Upload TP GIA Report</li> <li>AIG_SG (07/09/2018): No OI GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SGX9929C (0244812113SG)  
[SKR1195P]  
TP  
LIM HUAT SIONG  
Sep 4 2018 4:00PM  
[Chan Wai Hong Melvin]  
Fortuna Motor

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	(Draft)		Third Party Express Settlement – Payment Breakdown															Edit		
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	04/10/18 16:16		General View															Load JPG		
2	04/10/18 16:16		General View															Load JPG		
3	04/10/18 16:16		General View															Load JPG		
4	04/10/18 16:16		General View															Load JPG		
5	04/10/18 16:16		General View															Load JPG		
6	04/10/18 16:16		General View															Load JPG		
7	04/10/18 16:16		General View															Load JPG		
8	04/10/18 16:16		General View															Load JPG		
9	04/10/18 16:16		General View															Load JPG		
10	04/10/18 16:16		General View															Load JPG		
11	04/10/18 16:16		General View															Load JPG		
12	04/10/18 16:16		General View															Load JPG		
13	04/10/18 16:16		General View															Load JPG		
14	04/10/18 16:16		General View															Load JPG		
15	04/10/18 16:16		General View															Load JPG		
16	04/10/18 16:16		General View															Load JPG		
17	04/10/18 16:16		General View															Load JPG		
18	04/10/18 16:16		General View															Load JPG		
19	04/10/18 16:16		General View															Load JPG		
20	04/10/18 16:16		General View															Load JPG		
21	04/10/18 16:16		General View															Load JPG		
22	04/10/18 16:16		General View															Load JPG		
23	04/10/18 16:16		General View															Load JPG		
24	04/10/18 16:16		General View															Load JPG		
25	04/10/18 16:16		General View															Load JPG		
26	04/10/18 16:16		General View															Load JPG		
27	04/10/18 16:16		General View															Load JPG		
28	04/10/18 16:16		General View															Load JPG		
29	04/10/18 16:16		General View															Load JPG		
30	04/10/18 16:16		General View															Load JPG		
31	04/10/18 16:16		General View															Load JPG		
32	04/10/18 16:16		General View															Load JPG		
33	04/10/18 16:16		General View															Load JPG		
34	04/10/18 16:16		General View															Load JPG		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	04/10/18 16:16	General View	 Load JPG	<input checked="" type="checkbox"/>
36	04/10/18 16:16	General View	 Load JPG	<input checked="" type="checkbox"/>
37	04/10/18 16:16	General View	 Load JPG	<input checked="" type="checkbox"/>
38	04/10/18 16:16	General View	 Load JPG	<input checked="" type="checkbox"/>
39	04/10/18 16:16	General View	 Load JPG	<input checked="" type="checkbox"/>
40	04/10/18 16:16	General View	 Load JPG	<input checked="" type="checkbox"/>
41	04/10/18 16:16	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
42	04/10/18 16:16	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/09/18 16:27	EMAIL FROM AIG DD 06092018	 Load PDF	
2	19/09/18 09:54	TP GIA REPORT	 Load PDF	
3	07/11/18 08:04	WORKSHOP INVOICE	 Load PDF	
4	07/11/18 08:04	AUTHORISATION TO ACT FORM	 Load PDF	
5	07/11/18 08:04	Release Voucher	 Load PDF	
6	07/11/18 08:04	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	10/09/18 17:22	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKR1195P (Insd veh)	Model:	BMW 523i 2.5 (A)
	SGX9929C (TP veh)		
Date of Accident:	04/09/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	4,729.40
Final Repair Cost	:	\$	1,926.00
Loss of Use	:	\$	300.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	0.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	2,226.00

3.00 days at \$100.00 per day

days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_ 100 \_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_

BOLA Liability: \_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Fortuna Motor	:	\$ 2,226.00
2)		:	\$

JOANNE LEE KHANG MIN

07 Nov  
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



# LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18016318/GPB3Q2

Date: 07/11/2018

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100399209  
**Claimant Vehicle No :** SGX9929C **Insured Vehicle No :** SKR1195P  
 Date of Loss: 04/09/2018 Nature of Claim: TP Claim No: 0244812113SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGX9929C**  
 Make & Model: BMW 523i, 2.5 (A) Engine No: 08157867N52B25AF  
 Reg. Date: 23/12/2011 (Man. Year: 2011) Chassis No: WBAFP32090C867994  
 Colour: White Odometer: 114798 km  
 Engine Capacity: 2497 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 275/40 R18 Rear Tyre Size: 275/40 R18  
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm  
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,440.00	1,772.08	1,667.92	48.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	980.00	500.00	480.00	48.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,420.00</b>	<b>2,272.08</b>	<b>2,147.92</b>	<b>48.60</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,800.00</b>		
(S\$)	4,420.00	1,800.00	2,620.00	59.28
<b>+ GST 7.00/7.00% (S\$)</b>	309.40	126.00	183.40	59.28
<b>Nett Amount (S\$)</b>	<b>4,729.40</b>	<b>1,926.00</b>	<b>2,803.40</b>	<b>59.28</b>
<b>+ Loss of Use (3.0 x S\$100.00/day) (S\$)</b>		300.00		
<b>Nett Liability (S\$)</b>		<b>2,226.00</b>		

### INSPECTION

Date of Assignment: 06/09/2018  
 Date Inspected: 10/09/2018 Inspected At: Fortuna Motor (HQ)  
 40 Upper East Coast Road  
 Singapore 455212  
 Estimated Period of Repair: 3.0 days

---

**Adjuster:** XING GUO QIANG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,800.00 F	*1,650.65 FL
2	1		*LOWER COVER	Cut	380.00 F	*174.70 FL
3	1		*SET CLIP	Necessary	80.00 F	*40.00 FL
4	1		*REAR LOWER COVER	Not Necessary	180.00 F	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,440.00</b>	<b>1,865.35</b>
<b>- List Item Discount on L Items 0.00/5.00% (\$\$)</b>	<b>0.00</b>	<b>93.27</b>
<b>Total Parts (\$\$)</b>	<b>3,440.00</b>	<b>1,772.08</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW BUMPER AND ASSY	New	400.00	250.00
2	TOUCH UP BUMPER	New	580.00	250.00
Gross Labour Cost (S\$)			980.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >