

22/03/2002

ASS. REC. BY:

REF: CS/SMO18016319/Uqd307

Special Instruction:

Surveyor: Marcus  
Meinmen

ASSIGNMENT (Office)

From (Person): Gnroh Pau Jung of SMO

Date/Time: 6/9/18 @ 3:12pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / ~~TP~~ / ~~WS~~ / ~~TP~~ RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBL 3376J

Insured: FBB 5315A

at Workshop m/s Ban Hock Hin

Tel: 62816520

of No. 6 De fu Lane 4

Policy No: DI7MTM01003486

Claim No: CMTD1803737

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_

D.O.A. 24/08/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 3:30pm @ 6/9/18

Person Contacted: Raymond

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	FBL 3376J - X
	FBB 5315A - X
<u>09/9/18 @ 1:50pm</u>	<u>revised to Gnroh Pau Jung via Meinmen.</u>

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

Som/

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD  TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBL3376J

at Workshop m/s SMH

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 131 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: FBL3376J Yr Regn: 9, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha MT-03 c.c. 321

Colour: Red/Black A/C: Insured / Std / NI / NA

Sp.Reading: 56844 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MH3RH 07 K-000004839

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/60ZR17

R: 160/60ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or roadtec

Front

Rear

R/Bal. 8 mm

R/Bal. 8 mm

L/Bal. \_\_\_\_\_ mm

L/Bal. \_\_\_\_\_ mm

D.O.A. 24/8/18

D.O.I. 6/9/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S & R., N/S Body.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>6/12/18</u>	<u>8 4514.70 confirmed with Raymond. (RED B 591.30, 12%)</u>

RECEIVED 07 DEC 2018

[Signature]  
6/12/2018

Date/Time, File Pass to?

: Preli. Report

1) 07/12/18

: Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

<u>250</u>
<u>10</u>

Report Format: MER-7P

Lump Sum / I.B.I: (\$ 4514.70)

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Aug 2018		06 Sep 2018 15:12 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

Insured:	AZRI SYAZWAN BIN AHMAD, ID: S9317222A, Tel: +6582017214, Email: asyazwan18@gmail.com		[Created by insurer]
Main Claimant:	HAIRUL ALI BIN NOH, ID: S8937755B		
Vehicle Reg. No.:	FBL3376J	Date of Loss:	24/08/2018 07:00 - :59
Claim Type:	TP / CMTD1803737	Policy/Cover Note No.:	D17MTMC01003486 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	FBB5315A	Policy No. (Claimant):	
		Excess:	
Repairer:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4, 539410 Defu Lane - Tel: 62816520		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/09/2018]		
Driver/Custodian (Insured):	AZRI SYAZWAN BIN AHMAD (25 / Male), NRIC: S9317222A, Tel: +6582017214		

### ASSOCIATED MAIL RECEIVED

- SOMPO\_SG (06/09/2018): TP SURVEY

[View All](#)[Compose Case Mail](#)

### ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO18016319/Uqd3	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 06-09-2018	
		Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FBB 5315A	Veh. Inspected	FBL 3376J
Policy No.	D17MTMC01003486	Coverage (\$)	0.00
Claim No.	CMTD1803737	Excess (\$)	0.00
Assign From	MERIMEN (GNOH PAU LOONG)	Assign Date	06/09/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	24/08/2018	Inspection Date	06/09/2018
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

## Nivitha (LKK Auto)

---

**From:** Teo, Grace <grace.teo@sompo.com.sg>  
**Sent:** Thursday, 6 September 2018 3:14 PM  
**To:** Raymond; admin-d@lkkauto.com; assignments@lkkauto.com  
**Cc:** Gnoh, Pau Loong; Ye, Yong Kang Melvin  
**Subject:** CMTD1803737/GPL - SUV(LKK)/ FBL3376J, FBB5315A & SJE3628A on 24/08/2018

### Without Prejudice

Our Claim Reference: CMTD1803737/GPL  
Your Reference: FBL3376J

Hi Raymond,

We acknowledged receipt of your claim documents.

Please be informed that Gnoh Pau Loong is the handler of this case.

As agreed, we shall appoint **LKK AUTO** to conduct the survey.

-----  
Aside to **LKK AUTO**,

Please make arrangement to conduct the survey for FBL3376J on a without Prejudice Basis and without any admission of liability basis.

Please submit with your report upon completion of survey to my colleague, Mr. Pau Loong.

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG

Download now @  or 

<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** Raymond [mailto:raymond@bhh.com.sg]  
**Sent:** Thursday, September 06, 2018 2:42 PM  
**To:** Claims - Motor Survey  
**Subject:** Accident Involving FBL3376J, FBB5315A & SJE3628A on 24/08/2018

Dear Sir / Madam,

We attached the third party claim documents for your perusal.

Appreciate for you to arrange for the pre-repair survey.

Thanks

Best Regards,

Raymond

**Ban Hock Hin Co., Pte Ltd**

Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969

Visit us at <http://www.bhh.com.sg>

Facebook: <http://www.facebook.com/bhhsg>



No. 6 Defu Lane 4, Singapore 539410

[www.bhh.com.sg](http://www.bhh.com.sg)

MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS | L



**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: GNOH PAU LOONG

Date: 07 Sep 2018

**Preliminary Advice**

Insured Vehicle No	: FBB5315A	Accident Date	: 24/08/2018
TP Vehicle No	: FBL3376J	Assignment Date	: 06/09/2018
Make	: YAMAHA MT-03 ABS (MTN320-A)	Est. Duration of Repair	: 4.00
Date of Inspection	: 06/09/2018		
Inspection At	: BAN HOCK HIN CO. PTE LTD (HQ) NO. 6 DEFU LANE 4 SINGAPORE 539410		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear o/s, front portion & n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,106.00
Revised Amount	:S\$	3,841.00
Check Items (Estimated)	:S\$	167.00
Total	:S\$	4,008.00
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	7755B
<b>Vehicle Details</b>	
Vehicle No.:	FBL3376J
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Sep 2018
Vehicle Make:	YAMAHA
Vehicle Model:	MT-03 ABS (MTN320-A)
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	H402E0039467
Chassis No.:	MH3RH07K000004839
Maximum Power Output:	-
Open Market Value:	\$4,019.00
Original Registration Date:	01 Sep 2016
First Registration Date:	01 Sep 2016
Transfer Count:	1
Actual ARF Paid:	\$603.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	31 Aug 2026
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,352.00
COE Rebate Amount:	\$5,069.00
<b>Total Rebate Amount:</b>	<b>\$5,069.00</b>

The information contained herein is correct as at 07 Sep 2018

OK

[> Back to OneMotoring](#)**Enquire Transfer Fee**

<b>Vehicle Details</b>			
Vehicle No. :	FBL3376J		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	YAMAHA		
Vehicle Model :	MT-03 ABS (MTN320-A)		
Chassis No. :	MH3RH07K000004839		
Propellant :	Petrol		
Engine No. :	H402E0039467		
Engine Capacity :	321 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	328 kg		
Unladen Weight :	168 kg		
Year Of Manufacture :	2016		
Original Registration Date :	01 Sep 2016		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
Quota Premium :	\$6,352.00		
COE Expiry Date :	31 Aug 2026		
Road Tax Expiry Date :	28 Feb 2019		
Inspection Due Date :	31 Aug 2019		
Intended Transfer Date :	07 Sep 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
<b>Amount Payable</b>			
	<b>Amount Before GST (S\$)</b>	<b>GST Amount (S\$)</b>	<b>Amount After GST (S\$)</b>
Transfer Fee :	25.00	-	25.00
<b>Total Amount Payable :</b>			<b>25.00</b>

You may print this page for reference.

OK

Print

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	29/08/2018 17:45
Date Of Accident	24/08/2018 07:00
Exact Location Of Accident	BKE (KJE) NEAR MANDAI EXIT
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBL3376J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	HAIRUL ALI BIN NOH
NRIC No	S8937755B
Email Address	DAIJIROAYUL@GMAIL.COM
Mobile Phone No	(LOCAL) +65-93261060
Alternative Phone No	OFFICE-93261060

#### Vehicle Particulars

Manufacturer	YAMAHA
Model	MT-03 ABS (MTN320-A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

#### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5093906547
Cover Note Number	

#### Driver

Name of Driver	HAIRUL ALI BIN NOH
NRIC No	S8937755B
Date Of Birth	12/10/1989
Occupation	INDOOR
Date Of Driving Pass	18/02/2010
Driving Experience	8 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93261060
Fax Number	
Contact Number	OFFICE-93261060
EEmail Address	DAIJIROAYUL@GMAIL.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	TELOK BLANGAH NEIGHBOURHOOD POLICE POST
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

Refer to police report no:T/20180827/2133 On 24/08/2018 at about 0700hrs, I was riding my motorcycle bearing registration number:FBL3376J along BKE/KJE on the second lane (Near Mandai exit), I subsequently intended to change to the first lane. As such, I proceeded to check my blind spot (right side) to make sure it was clear before I overtake that I could not do so as the traffic was heavy, so I aborted the intention of changing lanes and immediately turned my head to focus on my front. However when I turned to my focus to the front, I realized that the car in front of me had slowed down, I proceeded to do an emergency brake however the said car bearing registration number SJE3628A had slowed down to a point where I did not have ample distance stop in time to prevent a collision. My motorcycle then collided with the said vehicle causing me apparently, behind me collided into my motorcycle which also caused him to crash and fall. Immediately after the crash, I got up to check my surroundings, I realized that the vehicle that I had collided with had immediately turned my focus to the motorcyclist that had collided into me to check if he was okay. The rider informed me that he was in a great deal of pain. At this point an unknown rider had stopped to assist me by moving my motorcycle so it did not block the first lane. Subsequently I sat down on the second lane as I was feeling weak, at this point an unknown driver stopped at the chevron markings to call for ambulance, me and the other rider were conveyed to Khoo Teck Puat hospital to treat our injuries.

#### Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBB5315A
Vehicle Make/Model/Colour	HONDA CB400 M
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	AZRI SYAZWAN
NRIC/Passport Number	S9317222A

Contact Number 82017214  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number SJE3628A  
Vehicle Make/Model/Colour HONDA CIVIC  
Details Of Properties MUHD HAFIZ  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number S8630541J  
Contact Number 96658647  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name HAIRUL ALI BIN NOH  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? FBB5315A  
Were seat belts worn? NO  
Was this injured conveyed to hospital by ambulance? YES  
Address  
Postcode

Sketch Plan

**SKETCH PLAN**


**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the submission of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore (GIA) may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicles involved in this accident (all insurers who have insured vehicles) involved in the accident that be collectively referred to as the "insurers", the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claim;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims including the making of correspondence, settlements, invoices, reports or returns to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/packages; and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
  - (b) all insurers who have insured vehicles involved in this accident and the insurers' lawyers/law firms, may be permitted to collect, use and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may be disclosed by any of the insurers (other than GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time      Driver's Signature (if driver is not the policyholder) / Date & Time      Witnessed by Reporting Centre Personnel

**Sketch Plan**



Sketch Plan #2



**SINGAPORE  
POLICE FORCE**



T20180627/2133

1 of 4

Police Station Of Origin:  
Telok Blangah NPP  
31 Telok Blangah Drive #01-118  
SINGAPORE 100055  
Tel No: 1800-2729999

Report No: T20180627/2133

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made 27/08/2018 17:31	Vide Report No:	Station Diary No: 34
---	-----------------	-------------------------

**Informant's Particulars**

Name of Informant HAIRUL ALI BIN NOH		Address: APT BLK 554 WOODLANDS DRIVE 53 #02-01 SINGAPORE 730554	
ID Type / ID No.: NRIC NO / S8937755B		Contact No.: Home/Office: Mobile: 93251090	
Nationality SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 28	Date of Birth: 12/10/1989	Type of Informant: Rider
Race: Malay		Language:	Institution / School Name:
Occupation: cisco officer		Driving Licence Information: Class: 2B 2A	Date of Expiry:

**General Information of the Accident**

Type of Accident:	Injury Conveyed By Ambulance:	Drink Drive:	Date/Time of Accident:	Type of Location:
	No	No	24/08/2018 07:00	Straight Road
Location: Ailing Road 1 BUKIT TIMAH EXPRESSWAY BKEK JIE Near Mandal Exit				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FB55315A	Motorcycle	HONDA	CB400 M	Silver	Slightly Damaged	0
FBL3175J	Motorcycle	YAMAHA	MT-03 ABS (MTN320-A)	Black	Slightly Damaged	0
SJE3628A	Car	HONDA	CRVIC 1.8L A	Blue	Slightly Damaged	0

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date

Sketch Plan #3



**SINGAPORE  
POLICE FORCE**



T/20180827/2133

Police Station Of Origin:  
Telok Blangah NPP  
51 Telok Blangah Drive #01-116  
SINGAPORE 100055  
Tel No. 1800-2729999

2 of 4

Report No. T/20180827/2133

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
FBL3376J	NTUC Income Insurance Co-Operative Limited	5093906547	01/09/2017	31/08/2018

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	ID No.	Related Vehicle	Contact No.
AZRI SYAZWAN	S9317222A	FBB5315A (Motorcycle)	82017214
Hospital/Clinic	Class of Driving Licence & Expiry Date		
KHOO TECK PUAT HOSPITAL	Class: NIL Date of Expiry: NIL		
Date Treatment	Date Discharge	No. of Days granted Medical Leave	Degree of Injury
24/08/2018	25/08/2018	NIL	Serious

Rider			
Name	ID No.	Related Vehicle	Contact No.
HAIRUL ALI BIN NOH	S8937755B	FBL3376J (Motorcycle)	93281060
Hospital/Clinic	Class of Driving Licence & Expiry Date		
KHOO TECK PUAT HOSPITAL	Class: 2B,2A Date of Expiry: NIL		
Date Treatment	Date Discharge	No. of Days granted Medical Leave	Degree of Injury
24/08/2018	24/08/2018	05	Slight

Driver			
Name	ID No.	Related Vehicle	Contact No.
MUHD HAFIZ	S8630541J	SJE3628A (Car)	96658647
Hospital/Clinic	Class of Driving Licence & Expiry Date		
NIL	Class: NIL Date of Expiry: NIL		
Date Treatment	Date Discharge	No. of Days granted Medical Leave	Degree of Injury
NIL	NIL	NIL	NIL



SINGAPORE  
POLICE FORCE



T/20180627/2133

Police Station Of Origin:  
Telok Blangah NPP  
51 Telok Blangah Drive #01-116  
SINGAPORE 100055  
Tel No: 1800-2729999

3 of 4

Report No: T/20180627/2133

## CONTINUATION OF REPORT

Brief Details.

On the 24/08/2018 at about 0700hrs, I was riding my motorcycle bearing registration number: FBL3376J along BKE/KJE on the second lane (Near mandai exit). I subsequently intended to change to the first lane. As such I proceeded to check my blind spot (right side) to make sure it was clear before I overtake the vehicle in front of me. When I checked my blind spot (checking took me less than 1 second), I realized that I could not do so as the traffic was heavy, so I aborted the intention of changing lanes and immediately turned my head to focus on my front. However when I turned to my focus to the front I realized that the car in front of me had slowed down. I proceeded to do an emergency brake however the said car bearing registration number SJE3628A had slowed down to a point where I did not have ample distance stop in time to prevent a collision. My motorcycle then collided with the said vehicle causing me to crash and fall, that being said, a motorcycle bearing registration number FBB5315A who was, apparently, behind me collided into my motorcycle which also caused him to crash and fall. Immediately after the crash, I got up to check my surroundings, I realized that the vehicle that I had collided with had already moved his vehicle to the side of the expressway to the chevron markings at mandai exit. I immediately turned my focus to the motorcyclist that had collided into me to check if he was okay. The rider informed me that he was in a great deal of pain. At this point an unknown rider had stopped to assist me by moving my motorcycle so it did not block the first lane. Subsequently I sat down on the second lane as I was feeling weak. At this point an unknown driver stopped at the chevron markings to call for ambulance. Me and the other rider were conveyed to Khoo Teck Puat hospital to treat our injuries.

Sketch Plan #5



SINGAPORE  
POLICE FORCE



T20180627/2133

Police Station Of Origin  
Telok Bangah NPP  
51 Telok Bangah Drive #01-116  
SINGAPORE 100055  
Tel No: 1800-2729999

4 of 4  
Report No. T20180627/2133

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: D / Sgt 1 JUNAIDI STANLEY SNOWDEN BIN MUHD ZAINAL ABIDIN NIGEL	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 27/08/2018 17:31
Officer In Charge Of Case: TP / GIT / Sgt 2 LIM HONG LEE Contact No.: 65476438	Classification Of Case:
Authentication Stamp NP-15A	SN 045
 Singapore Police Force	



**QUOTATION**

Customer :

NO. : 32969

SOMPO INSURANCE SINGAPORE PTE LTD  
50 RAFFLES PLACE  
#05-01/06 SINGAPORE LAND TOWER  
SINGAPORE 048623

*not Affected  
2nd  
Take photo. After repair  
4 days.  
6/9/18*

DATE : 05/09/2018  
CLAIM NO. : 11182  
POLICY NO. : 5093906547  
FROM : RAYMOND

MOTOR CLAIMS DEPT

VEHICLE NO. : FBL3376J  
MAKE/MODEL : /

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	AXLE WHEEL FRONT P/N: 55911	REPLACE	1.00	\$45.00	45.00 ?
2	BALANCER HANDLE SET (MOTOVATION)	REPLACE	1.00	\$98.00	98.00
3	BEARING STEERING CONE UPPER P/N: 27588	REPLACE	1.00	\$68.00	68.00 ?
4	BOLT FOOTREST FRONT P/N: 55160	REPLACE	2.00	\$7.00	14.00
5	BOX REAR (KAPPA) K-VENTURE 42L P/N: 57761	REPLACE	1.00	\$742.00	742.00
6	BRACKET METER	REPLACE	1.00	\$28.00	28.00 ?
7	BUSH 1	REPLACE	2.00	\$13.00	26.00 ?
8	CRASH BAR LOWER(RED) K2 FACTORY	REPLACE	1.00	\$672.00	672.00
9	CRASH BAR UPPER (BLACK)	REPLACE	1.00	\$392.00	392.00
10	CROWN HANDLE	REPLACE	1.00	\$132.00	132.00
11	FENDER FRONT	REPLACE	1.00	\$7.00	7.00
12	FOOTREST <i>LH</i> P/N: 56189	REPLACE	1.00	\$24.00	24.00
13	FOOTREST FRONT RH P/N: 55155	REPLACE	1.00	\$24.00	24.00



S/N	Description	Action	Qty	Unit Price	Amount
14	FORK FRONT ASSY	REPLACE	1.00	\$980.00 <i>hand/Daye</i>	980.00 <i>✓</i>
15	FRONT FLASHER LIGHT ASSY 1	REPLACE	1.00	\$82.00 <i>(11)</i>	82.00 <i>✓</i>
16	GRAPHIC 1	REPLACE	2.00	\$3.00 <i>m</i>	6.00 <i>✓</i>
17	GRIP HANDLE (PLAYLIFE)	REPLACE	1.00	\$14.00 <i>7/11</i>	14.00 <i>✓</i>
18	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING PARTS QUOTED.	Supply/Install	1.00	\$245.00 <i>2 20</i>	245.00 <i>✓</i>
19	LEVER CLUTCH P/N: 53490	REPLACE	1.00	\$26.00 <i>500</i>	26.00 <i>✓</i>
20	MIRROR LH P/N: 48240	REPLACE	1.00	\$83.00 <i>BAD</i>	83.00 <i>✓</i>
21	MIRROR RH P/N: 47686	REPLACE	1.00	\$83.00 <i>500</i>	83.00 <i>X</i>
22	MUFFLER ASSY 1	REPLACE	1.00	\$875.00 <i>10/34</i>	875.00 <i>✓</i>
23	SLIDER REAR AXLE (MOTOVATION) <i>4H</i>	REPLACE	1.00	\$84.00 <i>(11)</i>	84.00 <i>✓</i>
24	TAPE CRASH BAR (RED) P/N: 54775	REPLACE	2.00	\$12.00 <i>7/11</i>	24.00 <i>✓</i>
25	TRANSPORT CHARGES (MOTORCYCLE) CLASS 2A P/N: 45835 - FOR COLLECTION OF ACCIDENT BIKE.		1.00	\$45.00 <i>35</i>	45.00 <i>✓</i>
26	VISOR	REPLACE	1.00	\$215.00 <i>500</i>	215.00 <i>✓</i>
27	X-GRIP (RAM) UNIVERSAL (LARGE) P/N: 46451	REPLACE	1.00	\$72.00 <i>Daye</i>	72.00 <i>✓</i>

SUB TOTAL \$5,106.00  
 GST @ 7 % \$357.42  
**GRAND TOTAL \$5,463.42**

**50% deposit required before ordering of parts.**

Validity: 30 days

For & on Behalf of  
**BAN HOCK HIN CO PTE LTD**



**RAYMOND**

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Acknowledge & Accepted By

*9 - 4733*  
*10%*  
*4289.70*  
*4514.70*



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
------------	--------------------	---------------	------------	-------------------	---------------

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.





**QUOTATION**

Customer :

NO. : **32969** - Rev. 1

SOMPO INSURANCE SINGAPORE PTE LTD  
50 RAFFLES PLACE  
#05-01/06 SINGAPORE LAND TOWER  
SINGAPORE 048623

DATE : 05/09/2018  
CLAIM NO. : 11182  
POLICY NO. : 5093906547

MOTOR CLAIMS DEPT

FROM : RAYMOND

VEHICLE NO. : FBL3376J  
MAKE/MODEL : /

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	AXLE WHEEL FRONT P/N: 55911	REPLACE	1.00	\$45.00 Disc %: 10.00	40.50
2	BALANCER HANDLE SET (MOTOVATION)	REPLACE	1.00	\$98.00 Disc %: 10.00	88.20
3	BEARING STEERING CONE UPPER P/N: 27588	REPLACE	1.00	\$68.00 Disc %: 10.00	61.20
4	BOLT FOOTREST FRONT P/N: 55160	REPLACE	2.00	\$7.00 Disc %: 10.00	12.60
5	BOX REAR (KAPPA) K-VENTURE 42L P/N: 57761	REPLACE	1.00	\$742.00 Disc %: 10.00	667.80
6	BRACKET METER	REPLACE	1.00	\$28.00 Disc %: 10.00	25.20
7	BUSH 1	REPLACE	2.00	\$13.00 Disc %: 10.00	23.40
8	CRASH BAR LOWER(RED) K2 FACTORY	REPLACE	1.00	\$672.00 Disc %: 10.00	604.80
9	CRASH BAR UPPER (BLACK)	REPLACE	1.00	\$392.00 Disc %: 10.00	352.80
10	CROWN HANDLE	REPLACE	1.00	\$132.00 Disc %: 10.00	118.80
11	FENDER FRONT	REPLACE	1.00	\$7.00 Disc %: 10.00	6.30
12	FOOTREST P/N: 56189	REPLACE	1.00	\$24.00 Disc %: 10.00	21.60
13	FOOTREST FRONT RH P/N: 55155	REPLACE	1.00	\$24.00 Disc %: 10.00	21.60
14	FORK FRONT ASSY	REPLACE	1.00	\$980.00 Disc %: 10.00	882.00



S/N	Description	Action	Qty	Unit Price	Amount
15	FRONT FLASHER LIGHT ASSY 1	REPLACE	1.00	\$82.00	73.80
				Disc %: 10.00	
16	GRAPHIC 1	REPLACE	2.00	\$3.00	5.40
				Disc %: 10.00	
17	GRIP HANDLE (PLAYLIFE)	REPLACE	1.00	\$14.00	12.60
				Disc %: 10.00	
18	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING PARTS QUOTED.	Supply/Install	1.00	\$220.00	220.00
19	LEVER CLUTCH P/N: 53490	REPLACE	1.00	\$26.00	23.40
				Disc %: 10.00	
20	MIRROR LH P/N: 48240	REPLACE	1.00	\$83.00	74.70
				Disc %: 10.00	
21	MUFFLER ASSY 1	REPLACE	1.00	\$875.00	787.50
				Disc %: 10.00	
22	SLIDER REAR AXLE (MOTOVATION)	REPLACE	1.00	\$84.00	75.60
				Disc %: 10.00	
23	TAPE CRASH BAR (RED) P/N: 54775	REPLACE	2.00	\$12.00	21.60
				Disc %: 10.00	
24	TRANSPORT CHARGES (MOTORCYCLE) CLASS 2A P/N: 45835 - FOR COLLECTION OF ACCIDENT BIKE.		1.00	\$35.00	35.00
25	VISOR	REPLACE	1.00	\$215.00	193.50
				Disc %: 10.00	
26	X-GRIP (RAM) UNIVERSAL (LARGE) P/N: 46451	REPLACE	1.00	\$72.00	64.80
				Disc %: 10.00	
SUB TOTAL					\$4,514.70
GST @ 7 %					\$316.03
<b>GRAND TOTAL</b>					<b>\$4,830.73</b>

**50% deposit required before ordering of parts.**

Validity: 30 days

For & on Behalf of  
**BAN HOCK HIN CO PTE LTD**



**RAYMOND**

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.



**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Status
Main	28 Aug 2018		06 Sep 2018 15:12 <a href="#">Edit Adj Rpt</a>	<b>S\$4,514.70</b> <a href="#">Edit Estimates</a>	<b>S\$4,514.70</b> <a href="#">View Rpt</a>	<b>Pending for Survey Report</b>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>AZRI SYAZWAN BIN AHMAD</b> , ID: S9317222A, Tel: +6582017214, Email: asyazwan18@gmail.com								
Main Claimant:	<b>HAIRUL ALI BIN NOH</b> , ID: S8937755B								
Vehicle Reg. No.:	<b>FBL3376J</b>	Date of Loss:	24/08/2018 07:00 - :59 [23 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / CMTD1803737</b>	Policy/Cover Note No.:	D17MTMC01003486 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	<b>FBB5315A</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Ban Hock Hin Co. Pte Ltd (HQ)</b> No. 6 Defu Lane 4, 539410 Defu Lane - Tel: 62816520								
Handling Insurer:	<b>Sompo Insurance Singapore Pte. Ltd. (HQ)</b> - Tel: 6461 6555 ... [Handled by <b>GNOH PAU LOONG</b> - 63295217]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 17/09/2018]								
Driver/Custodian (Insured):	AZRI SYAZWAN BIN AHMAD (25 / Male), NRIC: S9317222A, Tel: +6582017214								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>SOMPO_SG (14/01/2019): <b>Alert - Adj Mandate Revoked - FBL3376J - Claim Handler: GNOH PAU LOONG</b></li> <li>SOMPO_SG (06/09/2018): <b>TP SURVEY</b></li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

### Claim Documents

**\*FBL3376J (CMTD1803737)**  
**[FBB5315A]**  
**TP**  
**HAIRUL ALI BIN NOH**  
**Aug 24 2018 7:00AM**  
**[AZRI SYAZWAN BIN AHMAD]**  
**Ban Hock Hin Co. Pte Ltd**

Upload Documents		Upload Photos		Compose New Letter		View <input type="button" value="View in Browser"/>	
<b>Video</b>						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail	Print		
1	06/09/18 15:12	<b>Video - Accident</b> From: SC - Reg. No: FBB5315A, Claimant: AZRI SYAZWAN BIN AHMAD		Load MOV			
<b>Assessment Reports</b>						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	07/09/18 13:50	<b>Adjuster Immediate Advice</b>		Load HTM			
<b>Photos/Images</b>						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	06/12/18 17:27	<b>Chassis Number</b>		Load JPG	<input checked="" type="checkbox"/>		
2	06/12/18 17:27	<b>Odometer Reading</b>		Load JPG	<input checked="" type="checkbox"/>		
3	06/12/18 17:27	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
4	06/12/18 17:27	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
5	06/12/18 17:27	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
6	06/12/18 17:27	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
7	06/12/18 17:27	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
8	06/12/18 17:27	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
9	06/12/18 17:27	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
10	06/12/18 17:27	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
11	06/12/18 17:27	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
12	06/12/18 17:27	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
13	06/12/18 17:27	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
14	06/12/18 17:27	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
15	06/12/18 17:27	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
16	06/12/18 17:27	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
17	06/12/18 17:27	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
18	06/12/18 17:27	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
19	06/12/18 17:27	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
20	06/12/18 17:27	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
21	06/12/18 17:27	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
22	06/12/18 17:27	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
23	06/12/18 17:27	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
24	06/12/18 17:27	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
25	06/12/18 17:27	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
26	06/12/18 17:27	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
27	06/12/18 17:27	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
28	06/12/18 17:27	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
29	06/12/18 17:27	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
30	06/12/18 17:27	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
31	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
32	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
33	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
34	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
35	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
36	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
37	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
38	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
39	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
40	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
41	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
42	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
43	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
44	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
45	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
46	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
47	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
48	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
49	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
50	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
51	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
52	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
53	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
54	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
55	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
56	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
57	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
58	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
59	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
60	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
61	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
62	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
63	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
64	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
65	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
66	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
67	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
68	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
69	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
70	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
71	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
72	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
73	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
74	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
75	06/12/18 17:27	General View	Load JPG	<input checked="" type="checkbox"/>
76	06/12/18 17:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
77	06/12/18 17:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
78	06/12/18 17:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
79	06/12/18 17:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
80	06/12/18 17:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
81	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	06/12/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	06/09/18 15:06	Third Party E-filed GIA report	Load PDF	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
2	07/12/18 08:46	<b>NOTED PIR AGAINST THIRD PARTY</b>	Load PDF	
3	07/12/18 13:00	<b>LETTER W ENCLS FROM BAN HOCK HIN DT 06.11.18 - FBB5315A</b>	Load PDF	

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/SMO18016319/UQD3E2  
**Date:** 15/01/2019

#### REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D17MTMC01003486  
**Claimant Vehicle No :** FBL3376J **Insured Vehicle No :** FBB5315A  
 Date of Loss: 24/08/2018 Nature of Claim: TP Claim No: CMTD1803737

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBL3376J**  
 Make & Model: YAMAHA MT-03 ABS (MTN320-A), 321cc Engine No: H402E0039467  
 Reg. Date: 01/09/2016 (Man. Year: 2016) Chassis No: MH3RH07K000004839  
 Colour: Red/Black Odometer: 56844 km  
 Engine Capacity: 321 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size: 120/60 ZR17 Rear Tyre Size: 160/60 ZR17  
 Front Left Side: ROADTEC 8 mm Rear Left Side: ROADTEC 8 mm  
 Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,816.00	4,259.70	556.30	11.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	290.00	255.00	35.00	12.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,106.00</b>	<b>4,514.70</b>	<b>591.30</b>	<b>11.58</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>357.42</b>	<b>316.03</b>	<b>41.39</b>	<b>11.58</b>
<b>Nett Amount (S\$)</b>	<b>5,463.42</b>	<b>4,830.73</b>	<b>632.69</b>	<b>11.58</b>

#### INSPECTION

Date of Assignment: 06/09/2018  
 Date Inspected: 06/09/2018 Inspected At: Ban Hock Hin Co. Pte Ltd (HQ)  
 No. 6 Defu Lane 4  
 Singapore 539410  
 Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 15 Jan 2019)	
<b>Parts:</b>	N/A	YAMAHA MT-03 ABS (MTN320-A) 321cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBL3376J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*AXLE WHEEL FRONT	Bent	45.00 F	*45.00 FL
2	1		*BALANCER HANDLE SET (MOTOVATION)	Scratched	98.00 F	*98.00 FL
3	1		*BEARING STEERING CONE UPPER	Necessary	68.00 F	*68.00 FL
4	2		*BOLT FOOTREST FRONT	Broken	14.00 F	*14.00 FL
5	1		*BOX REAR (KAPPA) K-VENTURE 42L	Cut	742.00 F	*742.00 FL
6	1		*BRACKET METER	Bent	28.00 F	*28.00 FL
7	2		*BUSH 1	Necessary	26.00 F	*26.00 FL
8	1		*CRASH BAR LOWER (RED) K2 FACTORY	Cut	672.00 F	*672.00 FL
9	1		*CRASH BAR UPPER (BLACK)	Cut	392.00 F	*392.00 FL
10	1		*CROWN HANDLE	Bent	132.00 F	*132.00 FL
11	1		*FENDER FRONT	Broken	7.00 F	*7.00 FL
12	1		*FOOTREST LH	Broken	24.00 F	*24.00 FL
13	1		*FOOTREST FRONT RH	Broken	24.00 F	*24.00 FL
14	1		*FORK FRONT ASSY	Bent / Damaged	980.00 F	*980.00 FL
15	1		*FRONT FLASHER LIGHT ASSY 1	Cut	82.00 F	*82.00 FL
16	2		*GRAPHIC 1	Necessary	6.00 F	*6.00 FL
17	1		*GRIP HANDLE (PLAYLIFE)	Torn	14.00 F	*14.00 FL
18	1		*LEVER CLUTCH	Scratched	26.00 F	*26.00 FL
19	1		*MIRROR LH	Broken	83.00 F	*83.00 FL
20	1		*MIRROR RH	Serviceable	83.00 F	*- FL
21	1		*MUFFLER ASSY 1	Dented / Bent	875.00 F	*875.00 FL
22	1		*SLIDER REAR AXLE (MOTOVATION) LH	Cut	84.00 F	*84.00 FL
23	2		*TAPE CRASH BAR (RED)	Torn	24.00 F	*24.00 FL
24	1		*VISOR	Scratched	215.00 F	*215.00 FL
25	1		*X-GRIP (RAM) UNIVERSAL (LARGE)	Damaged	72.00 F	*72.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,816.00</b>	<b>4,733.00</b>
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	473.30
<b>Total Parts (\$\$)</b>	<b>4,816.00</b>	<b>4,259.70</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR - FOR DISMANTLING AND ASSEMBLING PARTS QUOTED	New	245.00	220.00
2	TRANSPORT CHARGES (MOTORCYCLE) CLASS 2A - FOR COLLECTION OF ACCIDENT BIKE	New	45.00	35.00
Gross Labour Cost (\$\$)			<b>290.00</b>	<b>255.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >