

ASS. REC. BY:

REF

CS/MSG18016346/Grd3

n2

Special Instruction:

Surveyor

ASSIGNMENT (Office)

menmen

From (Person):

Jasmine Lok

of

MSG

Date/Time: 07/09/18 @ 9:25am

Estimated Cost:

Bill to:

OD (IP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKC 6597J

Insured:

FBK 6074R

at Workshop m/s

Seng Kiat Motor

Tel:

6748 7343

of

Blk 3022A Ubi Rd 1

Policy No:

MSD/VMT/17-987296-WTT

Claim No:

MSC/V/18-001184

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 07/08/2018

CA / REV / REP. / REV 24 HRS

wps

11/09/2018 @ 11am owner waiting

H.O.D. Endorsement:

Date/Time:

11/09/18 @ 9:44am

Person Contacted:

Mr. Yeo

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKC 6597J - CS/DAI17021971/GH32 DOA: 14/08/2017
	FBK 6074R - X
	Revert 1A thru menmen
10/10/18	Confirm with Mr Yeo L/S \$650 @ 2 days (Red. \$687.40, 51'1' -)

Page 1 of 1

Handwritten: *Handwritten*

REF: MSIG

11816

ASSIGNMENT

From:
 Date: 11/9/18
 Estimated Cost:
 OD: ☒ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV
 To inspect Vehicle No: SKC 6597J
 at Workshop m/s: Seng Kiat Motor
 of: Blk 3022A Ubi Rd 1 # 01-53
 Insured:
 Policy No:
 Claims No:
 Sum Insured:
 Excess:
 (Client's Record) 11am @ owner waiting
 Make of Veh:

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: \$31K
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 2 days Res: Yes or No
 Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. 1-24 HRS ^{up}

Date:
 Person Contacted:
 Vehicle: IN / OUT

Veh No: SKC6597J Yr Regn: 21 Sep 2011
 Type: ☒ M Car / ☐ M Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /
 Truck / Trailer or
 Make: Hyundai Elantra 1591
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 159798 T/Radio: Insured / Std / NI / NA
 Eng/No:
 C/No: KM11DH 41 CM CU 249421
 Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt
 Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or
 Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or
 Modi: Nil / ☒ S/Rim / ☐ STD A/Rim or
 Tyre Size: F: 225 / 45 N7
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front
 R/Bal. 6 mm
 L/Bal. 6 mm
 D.O.A.
 Rear
 R/Bal. 6 mm
 L/Bal. 6 mm
 D.O.I. 11-09-18
 Survey held at w/s 11AM
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
 L4 o/s
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
 11/9 Estimate Given later.

RECEIVED 11 OCT 2018

Handwritten signature and date: 10/10/2018

Date/Time, File Pass to?
 1) *Copy* ☐ : Preli. Report
☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2
 Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:
 Transportation:
) \$ + RS. SI
) Photos
) Others

Report Format: TP
 Lump Sum / T.B.I: (\$ 650)

TOTAL

150
 10

160

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 10 Oct 2018

Preliminary Advice

Insured Vehicle No	: FBK6074R	Accident Date	: 07/08/2018
TP Vehicle No	: SKC6597J	Assignment Date	: 07/09/2018
Make	: HYUNDAI ELANTRA	Est. Duration of Repair	: 2.00
Date of Inspection	: 11/09/2018		
Inspection At	: SENG KIAT MOTOR TRADING 1999 (HQ) BLK 3022A UBI ROAD 1 #01-53 SINGAPORE 408716		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,337.40
Revised Amount	:S\$	821.92
Check Items (Estimated)	:S\$	0.00
Total	:S\$	821.92

Lump Sum Repair	:S\$	650.00
-----------------	------	--------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Sep 2018		07 Sep 2018 09:25 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	PANDIDURAI SLELVAKUMAR, ID: G7961565Q		
Main Claimant:	ESTATE OF REZUAN BIN ROSDI, ID: S1681181E		
Vehicle Reg. No.:	SKC6597J	Date of Loss:	07/08/2018 00:00 - :59 [82 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/18-001184	Policy/Cover Note No.:	MSD/VMT/17-987296-WTT (Third Party Only) Coverage: 20/11/2017 - 19/11/2018
Vehicle Reg. No. (Insured):	FBK6074R	Policy No. (Claimant):	
		Excess:	
Repairer:	Seng Kiat Motor Trading 1999 (HQ) BLK 3022A UBI ROAD 1 #01-53, 408716 Eunos - Tel: 6748 7393		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 08/09/2018]		
Adj Asg. Remarks:	Third Party Pre-Repair Survey. TP selected LKK to be SJE, please arrange. Insured non-reporting Contact : Mr Yeo Cheng Kiat @ 6748 7393		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/08/2018 11:44
Date Of Accident	07/08/2018 10:20
Exact Location Of Accident	BASEMENT CARPARK BLK 438A ALEXANDRA TECHNO PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKC6597J
Insured/Policyholder	
Name Of Registered Owner	ESTATE OF REZUAN BIN ROSDI
NRIC No	S1681181E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-85981868
Alternative Phone No	OFFICE-85981868
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	ELANTRA 1.6 AT ABS D/AB 2WD 4DR

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00123466/05
Cover Note Number	21/03/2018-20/03/2019

Driver

Name of Driver	MOHAMED ISA BIN SHAMSUDDIN
NRIC No	S1712332G
Date Of Birth	10/05/1965
Occupation	INDOOR
Date Of Driving Pass	21/12/1982
Driving Experience	35 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85981868
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address ELK 104 TECK WHYE LANE
#05-454

Postcode 680104

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured RELATIVE

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBK6074R

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category MOTORCYCLE

Name of Driver RAMALINGAM MANOGARAN

NRIC/Passport Number G8285356T

Contact Number

Address


Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 07 AUG 2018 AT ABOUT 10:50am AT BASEMENT CARPARK ^{DATE DAY} 438A ALEXANDRA TECHNOPARK I WAS TRAVELLING ALONG THE LANE TOWARDS EXIT. SUDDENLY RIDER OF FBK 6074R WAS EXITING FROM A LANE ON MY RIGHT AND SPONTANEOUSLY TURNING TO HIS RIGHT. THERE WAS INDICATOR ON THE LANE A 'STOP' SIGN N ALSO AN ARROW TO TURN RIGHT ONLY (REF PATH) ON THE RIDER'S LANE. FAILING TO STOP AND TURNING LEFT BY THE RIDER RESULTING IN THE RIDER HITTING AGAINST MY VEHICLE. RESULT OF IMPACT CAUSING MY VEHICLE TO BE DAMAGED HOWEVER NO INJURIES OCCUR ON BOTH RIDER AND DRIVER.

You had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a **Fourteen (14) days clause** whereby the claim must be made within the stipulated timeframe from the day of occurrence:

	Reporting Only
	Claim OD
	Claim TP
☒	Claims OD & TP at other workshop

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature:
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1181E
Vehicle Details	
Vehicle No.:	SKC6597J
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Sep 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA 1.6 AT ABS D/AB 2WD 4DR
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	G4FGBU307180
Chassis No.:	KMHDH41CMCU249421
Maximum Power Output:	95.6 kW (128 bhp)
Open Market Value:	\$10,969.00
Original Registration Date:	21 Sep 2011
First Registration Date:	21 Sep 2011
Transfer Count:	1
Actual ARF Paid:	\$10,969.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Sep 2021
PARF Rebate Amount:	\$7,129.00
Intended COE Rebate Details	
COE Expiry Date:	20 Sep 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$50,053.00
COE Rebate Amount:	\$15,399.00
Total Rebate Amount:	\$22,528.00

The information contained herein is correct as at 13 Sep 2018

OK

成吉汽車貿易 SENG KIAT MOTOR TRADING 1999

KAMPONG UBI ROAD 1, BLK 3022A #01-53

SINGAPORE 408716 • TEL: 6748 7393

本號修理汽車，噴漆，燒焊等工程

SKC65975

KMH0H41CM CH

13-09-2018

1pc Front Bumper B474/46 / BR

1/2 Front Bumper Retainer (R) B2800 - R

1pc Front Bumper Lamp (R) B25.00 / R.

- Labor of Bumper work charge \$350.00 200

- Spray Painting Bumper work charge \$380.00 200

- wiring work Front Head Lamp, ~~lock~~ Lock work B80.00 X NN

1337.40

527

20%: 421.6

+400

821.6

20%: 650

2Days.

11/9/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18016346/GRD3N2

Date: 11/10/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/17-987296-WTT
Claimant Vehicle No :	SKC6597J	Insured Vehicle No :	FBK6074R
Date of Loss:	07/08/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-001184

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKC6597J	Engine No:	G4FGBU307180
Make & Model:	HYUNDAI ELANTRA, 1.6 D/AB 2WD 4DR (A)	Chassis No:	KMHDH41CMCU249421
Reg. Date:	21/09/2011 (Man. Year: 2011)	Odometer:	159798 km
Colour:	Silver		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	527.40	421.92	105.48	20.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	810.00	400.00	410.00	50.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,337.40	821.92	515.48	38.54
Approved Total (Overridden) (S\$)		650.00		
Nett Amount (S\$)	1,337.40	650.00	687.40	51.40

INSPECTION

Date of Assignment:	07/09/2018		
Date Inspected:	11/09/2018	Inspected At:	Seng Kiat Motor Trading 1999 (HQ) BLK 3022A UBI ROAD 1 #01-53 Singapore 408716
Estimated Period of Repair:	2.0 days		

Adjuster: XING GUO QIANG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Oct 2018)
Parts:	143	HYUNDAI ELANTRA 1.6 D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKC6597J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	474.40 F	*474.40 FL
2	2		*FRONT BUMPER RETAINER (R)	Deformed	28.00 F	*28.00 FL
3	1		*FRONT BUMPER LAMP COVER (R)	Scratched	25.00 F	*25.00 FL
				Sub Total (S\$)	527.40	527.40
				- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	105.48
				Total Parts (S\$)	527.40	421.92

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR OF BUMPER WORK CHARGES	New	350.00	200.00
2	SPRAY PAINTING BUMPER WORK CHARGES	New	380.00	200.00
3	WIRING WORK FRONT HEAD LAMP,LOCK WORKS	New	80.00	-
Gross Labour Cost (S\$)			810.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >