

ASS. REC. BY:

REF: CS3/MSG18016 348/RICd3^{SR} Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

Elaine Ngu

of

MSIA

Date/Time:

07/09/2008 13pm

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLT 5436X

Insured:

FBM 1380D

at Workshop m/s

Kok Wang Car Grooming

Tel:

9183 9633

of

No. 1 Soon Lee St. # 06-40

Policy No:

MSD/VMS/17-369619-CA

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 22/05/2018

CA / REV / REP. / REV 24 HRS

/wp

H.O.D. Endorsement:

Date/Time:

10:35am @ 7/9/18

Person Contacted:

Mr. KOK

Vehicle IN (OUT)

Date/Time

Action/Instruction (X) Estimate

SLT 5436 X - X

FBM 1380D - X

Dismantle: 12/9/2018

After repair: 13/9/2018

ASSIGNMENT

From: Date: 10/9/18

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLT 5436X

at Workshop n/s

Kok wang

of No. 1 soon lee st. # 06-40

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

After 12pm

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. 1-24 HRS (up)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLT 5436X Yr Regn: 2017 / Jan

Type: (C) M, Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz C180 c.c. 1595

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 32411 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD 205 340 2FA 94963

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 22/05/18 D.O.I. 11/09/18

Survey held at Kok wang

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Estimated repair range \$5,300 - \$6,000

17/9/2018

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: 4

1)

☐ : Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

Survey Fee:

Transportation

2)

Add Fee: ☐ Site Insp (\$)

) S + RS \$

☐ Interview (\$)

) Photos

☐ Tech Invs (\$)

) Others

☐ Weekend (\$)

TOTAL

Report Format: PRS

Lump Sum / I.B.I. (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG18016348/R1cd3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 07-09-2018		
		Code : MSG		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	FBM 1380D	Veh. Inspected	SLT 5436X	
Policy No.	MSD/MS/17-369619-CA	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	MERIMEN (ELAINE NGU)	Assign Date	07/09/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/05/2018	Inspection Date	11/09/2018	
Survey held at	KOK WANG CAR GROOMING (HQ) 1 SOON LEE STREET #06-40 PIONEER CENTRE SINGAPORE 627605			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Sep 2018 09:14		07 Sep 2018 08:13 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LIOW KIM CHONG, ID: S7068570A		
Main Claimant:	MUN WAI HO, KELVIN, ID: S8824403F		
Vehicle Reg. No.:	SLT5436X	Date of Loss:	22/05/2018 12:00 - :59 [15 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	MSD/VMS/17-369619-CA Coverage: 31/07/2017 - 30/07/2018
Vehicle Reg. No. (Insured):	FBM1380D	Policy No. (Claimant):	
		Excess:	
Repairer:	Kok Wang Car Grooming - Pioneer (HQ) No. 1 Soon Lee Street, #06-40 Pioneer Centre, 627603 Pioneer - Tel: 91839633		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 08/09/2018]		
Adj Asg. Remarks:	on WP, OI non reporting, Liability not clear, TP reject SJE- assign LKK Auto Consultants Pte Ltd, contact: Mr. Kok - 9183 9633		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MN118087318-02 / NTUC Income Insurance Co-operative Ltd - HQ
 ENTRY DATE & TIME: 24/05/2018 08:22
 SUBMITTED BY: Arch Ng

Your NCD will be affected due to late reporting
 Actual e-Filing Submission Date & Time: 04/09/2018 13:20

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 24/05/2018 08:22
 Date Of Accident 22/05/2018 12:55
 Exact Location Of Accident BLK 496 JURONG WEST ST 41 OSCP
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLT5436X
Insured/Policyholder
 Name Of Registered Owner MUN WAI HO, KELVIN (WEN WEIHAO)
 NRIC No S8824403F
 Email Address KELVINMUN@LIVE.CO.UK
 Mobile Phone No (LOCAL) +65-98634739
 Alternative Phone No OFFICE-NOPHONE
Vehicle Particulars
 Manufacturer MERCEDES-BENZ
 Model C180-1.6 (A)
 Exact Purpose for which vehicle was being used at time of accident PRIVATE
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR
Insurance Company
 Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 5095875358
 Cover Note Number
Driver
 Name of Driver MUN WAI HO, KELVIN (WEN WEIHAO)
 NRIC No S8824403F
 Date Of Birth 18/07/1988
 Occupation INDOOR
 Date Of Driving Pass 09/05/2008
 Driving Experience 10 YEARS AND 0 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-98634739
 Fax Number
 Contact Number OFFICE-NOPHONE
 Email Address KELVINMUN@LIVE.CO.UK

Address 10 TAO CHING ROAD
#18-24 LAKE LIFE
Postcode 618725
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1
NAME: : JULETTE LEE GEOK MING
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name JURONG WEST NEIGHBOURHOOD POLICE CENTRE
Police Station Address ROAD: 700 CORPORATION ROAD , POSTCODE: 649616 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: 1800-2689999 - FAX NO: 62672438
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: ADVISED OI TO SUBMIT TO MOTOR CLAIMS EMAIL
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBM1380B
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category MOTORCYCLE
Name of Driver UNKNOWN
NRIC/Passport Number
Contact Number UNKNOWN

04-09-18;20:37 ;

RECEIVED 17/09/2018 10:17
KW

3/ 18

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan


SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

5. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders


 Policyholder's Signature

 Date & Time: 23/05/2018
 13:45:46

 Driver's Signature
 (if driver is not the policyholder)
 Date & Time:


 Arbitration Centre Personnel's Signature
 Name: R. S. S. S. S.
 NRIC/IN No: 991022

Sketch Plan #2

SKETCH PLAN

A: 8LT5436X

B: FBM1380D



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Location: Blk 496 Jurong West St 41 OSCP

Weather: Clear

Road: Dry

Traffic: Moderate

Refer to Police Report
from Jurong West NPC.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 23/05/2018
23:15 HZDriver's Signature
(If driver is not the policyholder)
Date & Time:Reporting Centre Personnel's Signature
Name: RND 2W HZ
NRIC/PIN No: 991022



**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408865
Tel +65 6547 0000
Fax +65 6547 4883
www.police.gov.sg

Our Ref : TP/IP/32677/2018
Date : 26 June 2018

Mun Wai Ho, Kelvin
Blk 10 Tao Ching Road
#18-24
Singapore 618725

Dear Sir / Madam,

TRAFFIC ACCIDENT INVOLVING FBM1380D AND SLT5436X ALONG JURONG WEST STREET 41 ON 22/05/2018 AT ABOUT 1300 HRS

I refer to the above accident.

2. Please be informed that we have completed our investigations which revealed that the driver of **FBM1380D** had committed the following offences:
- (i) Failing to exchange particulars after an accident under Section 84(1) of the Road Traffic Act Chapter 276;
 - (ii) Failing to report an accident within 24 Hours under Section 84(2) of the Road Traffic Act Chapter 276.

Action has been initiated against the driver for the said offences.

3. If you have any clarification, you may contact the Investigation Officer, SSS Leslie Tan at office number: 6547 6144.
4. Thank you.

Yours faithfully,

**HEAD INVESTIGATION
TRAFFIC POLICE
SINGAPORE POLICE FORCE**

This is a computer-generated letter. No signature is required.



SINGAPORE POLICE FORCE



T/20180522/2066

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

1 of 4

Report No: T/20180522/2066

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/05/2018 13:29	Vide Report No.:	Station Diary No.: 105
--	------------------	---------------------------

Informant's Particulars

Name of Informant: MUN WAI HO, KELVIN	Address: APT BLK 10 TAO CHING ROAD #18-24 SINGAPORE 618725
ID Type / ID No.: NRIC NO / S8824403F	Contact No.: Home/Office: Mobile: 98634739
Nationality: SINGAPORE CITIZEN	Email:
Sex: Male Age: 29 Date of Birth: 18/07/1988	Type of Informant: Driver
Race: Chinese	Language: Institution / School Name:
Occupation: Business development manager	Driving Licence Information: Class: 3 Date of Expiry:

General Information of the Accident

Type of Accident: Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 22/05/2018 13:00	Type of Location: Car Park
Location: JURONG WEST STREET 41 Open space car park of B/496 Jurong West Street 41	Weather: Clear	Road Surface: Dry	Road Speed Limit:
Traffic Flow:	Traffic Control:	Traffic Volume: Light	Type of Collision: Between Moving Vehicles - Head On
		Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBM1380D	Motorcycle				No Damage	0
SLT5436X	Car	MERCEDES BENZ	C180 COUPE AMG LINE (R18 LED)	Blue	Slightly Damaged	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



**SINGAPORE
POLICE FORCE**



T/20180522/2066

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

3 of 4

Report No. T/20180522/2066

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20180522/2066

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

4 of 4

Report No. T/20180522/2066

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sgt 2 PERRY P NG WEE PHONG

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

22/05/2018 13:29

Officer In Charge Of Case:

TP / HRT /

Sr Staff Sgt TAN JEOK LENG

Contact No.: 65476144

Classification Of Case:

Authentication Stamp

NP168



SINGAPORE POLICE FORCE



T/20180522/2066

2 of 4

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

Report No. T/20180522/2066

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle	Insurance Company	Policy No.	Start Date	End Date
SLT5436X	NTUC Income Insurance Co-Operative Limited	5095875358	15/11/2017	14/11/2018

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	Unknown Rider	ID No.	NIL
Related Vehicle	FBM1380D (Motorcycle)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	MUN WAI HO, KELVIN	ID No.	S8824403F
Related Vehicle	SLT5436X (Car)	Contact No.	98634739
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 22/05/2018 at about 1255hrs, I have entered the open space car park near to B/496 Jurong West Street 41. I then saw a car park lot which near to B/496 and I intend to park. As I was reversing my vehicle to the said lot, I noticed that there was a motorcycle which ride by a male/Chinese and travelling from the left side of my vehicle. The said motorcycle was then collided onto the front left side of my vehicle. I did signalled the said rider to stop however he has leave the said car park after the incident.

I managed to take down his motorcycle number before he left. There was in car camera installed in my vehicle however I have yet to check whether any footage recorded. I am not sure whether any CCTV around the vicinity.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4403F
Vehicle Details	
Vehicle No.:	SLT5436X
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Sep 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C180 COUPE AMG LINE (R18 LED)
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	27491030912517
Chassis No.:	WDD2053402F494963
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$40,893.00
Original Registration Date:	23 Jan 2017
First Registration Date:	23 Jan 2017
Transfer Count:	1
Actual ARF Paid:	\$44,251.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Jan 2027
PARF Rebate Amount:	\$33,188.00
Intended COE Rebate Details	
COE Expiry Date:	22 Jan 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,229.00
COE Rebate Amount:	\$38,636.00
Total Rebate Amount:	\$71,824.00

The information contained herein is correct as at 13 Sep 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)**CLAIM SUBFOLDER TRACKING**

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Sep 2018		07 Sep 2018 08:13 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)**CLAIM SUBFOLDER DETAILS****[Created by insurer]**

Insured:	LIOW KIM CHONG , ID: S7068570A		
Main Claimant:	MUN WAI HO, KELVIN , ID: S8824403F		
Vehicle Reg. No.:	SLT5436X	Date of Loss:	22/05/2018 12:00 - :59 [15 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/18-001195	Policy/Cover Note No.:	MSD/VMS/17-369619-CA Coverage: 31/07/2017 - 30/07/2018
Vehicle Reg. No. (Insured):	FBM1380D	Policy No. (Claimant):	
		Excess:	
Repairer:	Kok Wang Car Grooming - Pioneer (HQ) No. 1 Soon Lee Street, #06-40 Pioneer Centre, 627603 Pioneer - Tel: 91839633		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 08/09/2018]		
Adj Asg. Remarks:	on WP. OI non reporting. Liability not clear. TP reject SJE- assign LKK Auto Consultants Pte Ltd. contact: Mr. Kok - 9183 9633		

ASSOCIATED MAIL RECEIVED[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***SLT5436X (MSC/V/18-001195)**
[FBM1380D]

TP

MUN WAI HO, KELVIN

May 22 2018 12:00PM

[LIOW KIM CHONG]

Kok Wang Car Grooming - Pioneer

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
View
[View in Browser](#)

Photos/Images

3 per page



No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/09/18 11:52	General View	Load JPG	
2	13/09/18 11:52	General View	Load JPG	
3	13/09/18 11:52	General View	Load JPG	
4	13/09/18 11:52	General View	Load JPG	
5	13/09/18 11:52	General View	Load JPG	
6	13/09/18 11:52	General View	Load JPG	
7	13/09/18 11:52	General View	Load JPG	
8	13/09/18 11:52	General View	Load JPG	
9	13/09/18 11:52	General View	Load JPG	
10	13/09/18 11:52	General View	Load JPG	
11	13/09/18 11:52	General View	Load JPG	
12	13/09/18 11:52	General View	Load JPG	
13	13/09/18 11:52	General View	Load JPG	
14	13/09/18 11:52	General View	Load JPG	
15	13/09/18 11:52	General View	Load JPG	
16	13/09/18 11:52	General View	Load JPG	
17	13/09/18 11:52	General View	Load JPG	
18	13/09/18 11:52	General View	Load JPG	
19	13/09/18 11:52	General View	Load JPG	
20	13/09/18 11:52	General View	Load JPG	
21	13/09/18 11:53	Photographs of Damaged Parts	Load JPG	
22	13/09/18 11:53	Photographs of Damaged Parts	Load JPG	
23	13/09/18 11:53	Photographs of Damaged Parts	Load JPG	
24	13/09/18 11:53	Photographs of Damaged Parts	Load JPG	
25	13/09/18 11:53	Photographs of Damaged Parts	Load JPG	
26	13/09/18 11:53	Photographs of Damaged Parts	Load JPG	
27	13/09/18 11:53	Photographs of Damaged Parts	Load JPG	
28	13/09/18 11:53	Photographs of Damaged Parts	Load JPG	
29	13/09/18 11:53	Photographs of Damaged Parts	Load JPG	
30	13/09/18 11:53	Photographs of Damaged Parts	Load JPG	
31	13/09/18 11:53	Photographs of Damaged Parts	Load JPG	
32	17/09/18 19:20	Photo After Spray	Load JPG	
33	17/09/18 19:20	Photo After Spray	Load JPG	
34	17/09/18 19:20	Photo After Spray	Load JPG	
35	17/09/18 19:20	Photo After Spray	Load JPG	

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	17/09/18 19:20	Photo After Spray	Load JPG	✓
37	17/09/18 19:20	Photo After Spray	Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/09/18 09:19	TP GIA REPORT	Load PDF	
2	06/09/18 09:19	TP PRI NOTICE	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18016348/R1CD3S2

Date: 18/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VMS/17-369619-CA
 Claimant Vehicle No: SLT5436X Insured Vehicle No: FBM1380D
 Date of Loss: 22/05/2018 Nature of Claim: TP Claim No: MSC/V/18-001195

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLT5436X**
 Make & Model: MERCEDES-BENZ C180, 1.6 COUPE AMG LINE (R18 LED SR) (A) Engine No: 27491030912517
 Reg. Date: 23/01/2017 (Man. Year: 2016) Chassis No: WDD2053402F494963
 Colour: Blue Odometer: 32411 km
 Engine Capacity: 1595 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40R18 Rear Tyre Size: 245/40R18
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 07/09/2018
 Date Inspected: 11/09/2018 Inspected At: Kok Wang Car Grooming - Pioneer (HQ)
 No. 1 Soon Lee Street, #06-40 Pioneer Centre
 Singapore 627603
 Estimated Period of Repair: 0.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,300.00 - \$6,000.00

REPAIR DETAILS

Reference	
Part Source:	MRM-SG Version: 1.0 (Last Synchronised: 18 Sep 2018)
Parts:	M1-COUPE MERCEDES-BENZ C180 1.6 COUPE AMG LINE (R18 LED SR) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT5436X)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >