

REC. BY:

REF: CS/FCI18016351/Ucd30

Special Instruction:

Surveyor:

aws

ASSIGNMENT (Office)

From (Person):

Screener

of

FCI

Date/Time:

6/9/18 @ 5.55pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLW 174T

Insured:

SHC 81691

at Workshop m/s

Autolution

Tel:

67038691 / 96450084

of

19 ubi Rd 4

Policy No:

Claim No:

D18006591 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01/09/2018

CA / REV / REP. / REV 24 HRS

(DS)

12/09/2018 @ 2pm owner waiting

H.O.D. Endorsement:

Date/Time:

7/9/18 @ 11:09am

Person Contacted:

Elmer

Vehicle IN /

OUT

Date/Time	Action/Instruction (✓) Estimate
	SLW 174T-x
	SHC 81691-CS/FCI18012134/Rlqd3 DOA: 21/6/18
12/9/18	Int pre: thu email

ASSIGNMENT

From: Date: 12/9/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLW 1747
 at Workshop no: Autolution
 of: 19 ubi Rd 4

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Elmer
 2pm @ owner waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IPAC Accident Report:

Consistent? : Yes or No

GLA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3 days Res: Yes or No

Lum Sum:

13.1 % 3 Val: Yes or No

CA / REV / REP. 1-24 HRS

(OS)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SLW 1747 Yr Reg: 1 / 18

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (FA)

Make: NISSAN Qashqai cc 1197

Colour: Brown A/C: Insured / Std / NI / NA

Sp. Reading: 12213 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: SJNFEAY1102171786

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / Std / STD A/Rim or

Tyre Size: F:

R: 215/60R17

MS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 7 mm

R/Bal: 7 mm

L/Bal: 7 mm

L/Bal: 7 mm

D.O.A: 1/9/18

D.O.I: 12/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

12/12/18 17449699
 confirmed final by \$1733.20 with Elmer (Red. 2267.44, 56%)

RECEIVED 08 DEC 2018

Date/Time: File Pass to?

: Prel. Report

II

: Final Report

Date/Time: File Return to?

III

Add Fee:

Site Insp \$

Interview \$

Tech Invs \$

Weekend \$

Days Of Repair: 3

Resurvey No. of Trip: 1

Report Format: TP

Lump Sum / (13.1) \$ 1733.20

Survey Fee:

Transportation:

... + RS ...

Phone:

Other:

TOTAL

135
 50
 50
 28

263

MOTOR SURVEY ASSIGNMENT

Date	04-09-2018	Our Ref No. D18006591MFSH
Accident Date	01-09-2018	Claim Type. Third Party
Insured Vehicle	SHC8169J	Third Party Vehicle. SLW174T
Survey Location	19 UBI ROAD 4	
Contact Person.	ELMER ALFONSO	
Contact No.	67038691/ 96450084	Fax No. 0
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	AUTOLUTION INDUSTRIAL PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006591MFSH

Our Ref: CS/FCII8016351/Urd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLW 174T

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12.09.2018 at the premises of M/s AUTOLUTION INDUSTRIAL PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,983.84</u>
Revised Estimate Amount	: S\$ <u>1,713.20</u>
"Check" Items Amount	: S\$ <u>199.12</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:
The vehicle sustained damages
at o/s rear portion.



Yours faithfully

MARCUS CHUA
Automotive Assessor

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9211F
Vehicle Details	
Vehicle No.:	SLW174T
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Sep 2018
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI 1.2 DIG-T CVT
Primary Colour:	Brown
Manufacturing Year:	2017
Engine No.:	HRA2559185A
Chassis No.:	SJNFEAJ11U2171786
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$20,143.00
Original Registration Date:	25 Jan 2018
First Registration Date:	25 Jan 2018
Transfer Count:	0
Actual ARF Paid:	\$20,201.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Jan 2028
PARF Rebate Amount:	\$15,150.00
Intended COE Rebate Details	
COE Expiry Date:	24 Jan 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,890.00
COE Rebate Amount:	\$34,549.00
Total Rebate Amount:	\$49,699.00

The information contained herein is correct as at 12 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/09/2018 11:28
Date Of Accident	01/09/2018 17:35
Exact Location Of Accident	SENGKANG EAST ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW174T
Insured/Policyholder	
Name Of Registered Owner	LEE KHIOK MENG
NRIC No	S1189211F
Email Address	KHIOKMENG.LEE@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98439774
Alternative Phone No	OTHERS-98439774

Vehicle Particulars

Manufacturer	NISSAN
Model	QASHQAI-1.2 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800007098
Cover Note Number	

Driver

Name of Driver	LEE KHIOK MENG
NRIC No	S1189211F
Date Of Birth	14/11/1956
Occupation	INDOOR
Date Of Driving Pass	10/12/1979
Driving Experience	38 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98439774
Fax Number	
Contact Number	OTHERS-98439774
EMail Address	KHIOKMENG.LEE@GMAIL.COM

Address	29 FERNVALE CLOSE #20-20
Postcode	797464
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC8169J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	SUNACHI BIN KARTO
NRIC/Passport Number	S0178573G
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time: 3/9/18
 11.40am

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.: SINGAPORE INDUSTRIAL PTE LTD
 11, CECIL ROAD 4
 SINGAPORE 408623
 TEL: 6496 7588 FAX: 6848 7483

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 1/9/18 at about 5:35pm, I was driving on Sengkang East Rd towards Buangkok Green. As I approached to stop at the traffic light junction at Anchorage St/Compassvale St, taxi (SHC 81693) turned out from the right hand turning lane and contacted the rear end of my car (SLW174T). There were many cars waiting at the red traffic junction, ~~at~~ right-hand turning lane when SHC 81693 decided to change lane without ensuring my car had cleared his car before coming out of his lane.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time: 3/9/18
 11:40 am

Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

AM
 Reporting Centre Personnel's Signature: ITU
 Name: [unclear]
 NRIC/PIN No: [unclear]
 408623
 408623
 408623

Name of Policyholder : Lee Khock Meng
 Period of Insurance : 25 Jan 2018 (to 25 Jan 2019)
 Engine No. : HRA2599185A
 Chassis No. : SJNFEALH1102171786

Vehicle No. : NEW 1117
 Policy No. : 1800010796
 Endorsement No. :
 Issued Date : 21 Jan 2018

ABOUT THE COVER			
Make/Model	NISSAN Qashqai 1.2 DIG-Turbo		
Engine Capacity/Tonnage	1,197.00 CC	Sum Insured	Market Value
Driver Restriction	: NA	Off Peak Car	: No
		First Year of Registration	2018
		Insuring with COE/PART	: Yes
Person or Classes of Persons Entitled to Drive* (a) The Policyholder (b) Any other person who is driving on the Policyholder's or on his/her premises premises We Policy will not cover the Policyholder or any other person if he/she is driving the vehicle in violation You have to pay an additional sum of \$5,000 as "Third Party Compensation Excess" ("TPC") if You are of Your Authorized Drivers covered in compensation under Group 1 or 2 within the first two (2) years' driving experience			
Age Condition	: All Age Condition		
Limitation as to use* Use only for social, domestic and pleasure purposes and for the Policyholder's business. The Policy does not cover use for hire or reward, driving tuition, driving test, racing, pre-empting, victory trial or speed racing, the carriage of goods, other than commercial vehicles, and use for business or use for any purpose in connection with Motor Vehicle.			
Loss of Use 1600cc - 1800cc * Limitations rendered operative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 188) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.			

EXCESS	
Section 1	Fire - \$0, Own Damage - \$500, Theft - \$0, Flood Cover - \$0
Section 2	Property Damage - \$0
	Windscreen - \$100
Named Driver and Excess (where applicable) Lee Khock Meng - \$600 (Own Damage)	

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)
1 TC AutoCrew: Add: No.1, South Lok Yang Road Singapore 63009 62622213 2 Automation Industrial: Add: 19 Ubi Road 4 Singapore 40823 64069666 3 TC AutoCrew: Add: 25 Leng Kee Road Singapore 15907 67038511 67038512 67038513 4 Tan Chong Motor Sales: Add: 913 Bukit Timah Road Singapore 58622 64694091 64694092 64694093 5 Tan Chong Motor Sales: Add: 17 Lorong 8 Tee Payoh Singapore 310254 63570733 63570734
For other Approved Reporting Centres/AIG Authorized Repairers, please contact our 24-hour accident emergency helpline at +65 6338 6300. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES
Hire Purchase Company/Employer's Loan: NA

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 188), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1998 (Malaysia)

0500610487

TAN CHONG CREDIT PTE LTD - CCH
 911 BUKIT TIMAH ROAD TAN CHONG MOTOR CENTRE
 SINGAPORE 58622 ANSP-MOTOR
 Underwritten by AIG Asia Pacific Insurance Pte. Ltd.



AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

What to do if you are involved in an accident:

If no one is injured in the accident:

- Take one day's holiday or take any other leave.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Record details (name, address and contact number) of witnesses and try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours of the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours of the next working day of the accident.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **5** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Tan Chong Motor Sales** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Downtown Travel Services Pte Ltd
Activation Hotline: 63345745
19 Lorong 8 Toa Payoh Singapore 319255
Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 1pm

*The Rental Car Company's Terms & Conditions apply to the individual security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc.

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

1000188493A/CU/Debit

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0520/18

DATE : 03-SEP-2018

MS FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD

#16-01 CITY HOUSE

S(068877)

TEL : 65073948

FAX :

ATTN: MOTOR CLAIM DEPT

OWNER'S NAME : MR. LEE KHIOK MENG

ADDRESS : 29 FERNVALE CLOSE

#20-20

S(797464)

TELEPHONE NO : 96439774

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM

POLICY NO : 1800057098

VEHICLE NO : SLW174T

MODEL CODE : FRLARDW11USA-A--

MODEL/YEAR : NISSAN QASHQAI 1.2 MY2017

ENGINE NO : HRA25591854

CHASSIS NO : SJNFEA11102171786

MILEAGE : 11704 KM

DATE IN : 03/09/2018

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : ELMER

ACCIDENT DATE : 01/09/2018

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

- 9645 0054

elmer@teacheng.com

Not Authorised

Mark

Marcus

12/9/18

Take photo before partly.

3 day.

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLW174T

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO REPAIR REAR END PANEL & LH REAR FENDER, RENEW REAR BUMPER	780.00	390
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME	750.00	250
3	ZZ/003	RENEW REVERSE SENSOR 4 EYE	110.00	50
TOTAL LABOUR CHARGES			1640.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLW174T

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 SUNDRIES	NRK		all	50.00 20
2 SENSOR-REVERSE 4 EYE	SENSOR		un	250.00 X
3 REAR LICENCE PLATE	RLP		11	60.00 X
4 RH REAR FENDER WHEEL HOUSE PROTECTOR	7574B-4EA2A	11		186.40 X
5 RH REAR FENDER WHEEL ARC MOLDING	9382B-4EA0A	ground		483.00 /
6 RH STAY REAR BUMPER	H5210-4EAM	11		126.00 X
7 LH STAY REAR BUMPER	H5211-4EAM	11		126.00 X
8 REINFORCEMENT REAR BUMPER	H5030-4EAM	11		619.20 X
9 ENERGY ABSORBER REAR BUMPER	B5090-HV00A	11		126.40 X
10 RH SIDE BRACKET REAR BUMPER	B5220-4EA0A	all		35.90 /
11 LH SIDE BRACKET REAR BUMPER	B5221-4EA0A	all		35.90 /
12 TOW HOOK COVER REAR BUMPER	B5071-HV00A	11		16.80 X
13 CLIP REAR BUMPER @ SGD \$ 1.20 EACH	01553-05933	all		7.20 /
14 REAR BUMPER	B5022-4EADH	Deep cut		717.00 /
SUB TOTAL		2479.80	0.00	360.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		495.96	0.00	0.00
GRAND TOTAL		1983.84	0.00	360.00
OVERALL TOTAL		2343.84		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLW174T

TOTAL LABOUR CHARGES	1640.00	
TOTAL SPARE PARTS CHARGES	2343.84	
GRAND TOTAL	3983.84	4000.64

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.



Autolution Industrial Pte Ltd

Tan Chong Motor Sales Pte Ltd's Authorized Dealer
19 Ubi Road 4
Singapore 408623
Tel: (65) 64909666 / 67038680
Fax: (65) 68467483
Business Reg. No.: 199500071W

28/11/2018

INS/IC/EA/0520/18

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
Attn : Motor Claim Manager
Claim Dept.

Dear Sir

SUPPLEMENTARY CLAIM


REGN. NO : SLW174T
CLAIM NO: INS/IC/EA/0520/18

Further to our claim INS/IC/EA/0520/18 we are submitting a supplementary claim for the below mentioned labour and part for the above mentioned case.

	PARTS NEED TO CHANGE		
1	TOW HOOK COVER REAR BUMPER <i>ae n/c</i>	\$	16.80 <i>X</i>

We trust the above supplementary claim will meet with your kind approval and we will forward to you the final repair bill together with the satisfaction note on completion repairs.

Yours faithfully
AUTOLUTION INDUSTRIAL PTE LTD


ELMER ALFONSO
Insurance Claim Dept

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

Cc: Surveyor-MARCUS



REVOLUTION INDUSTRIAL PTE. LTD.

FINALIZED : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/SA/0620/18
DATE : 03-SEP-2018

HS FIRST CAPITAL INSURANCE LIMITED
30 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 65073848
FAX :
ATTN:MOTOR CLAIM DEPT

OWNER'S NAME : MR LEE KHION HENG
ADDRESS : 29 FERNALE CLOSE
#10-20
S(797464)
TELEPHONE NO : 98430774

3 DAYS

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 1800007098
VEHICLE NO : SWL174T
MODEL CODE : FRLAR0N213USA--A--
MODEL/YEAR : NISSAN QASHQAI 1.6 MY2017
ENGINE NO : HRA255R085A
CHASSIS NO : S3RFEA111U2171786
MILEAGE : 16320 KM
DATE IN : 03/09/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER
ACCIDENT DATE : 01/09/2018

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO. SLW774T

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO RENEW REAR BUMPER	780.00	390.00
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME	750.00	250.00
3	ZZ/003	RENEW REVERSE SENSOR 4 EYE	130.00	50.00
TOTAL LABOUR CHARGES			1660.00	690.00

MATERIAL LIST FOR ACCIDENT VEHICLE (VEH NO SLK2NT)

S/N	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	SPARKIES	SPK			20.00 OK
2	SENSOR-REVERSE 4 EYE	SENSOR			250.00 X
3	REAR LICENCE PLATE	R/LP			60.00 X
4	RH REAR FENDER WHEEL HOUSE PROTECTOR	75748-4EADA	186.40		X
5	RH REAR FENDER WHEEL ARC MOLDING	93828-4EADA	480.00		OK
6	RH STAY REAR BUMPER	H5211-4EAMA	126.00		X
7	LH STAY REAR BUMPER	H5211-4EAMA	126.00		X
8	REINFORCEMENT REAR BUMPER	H5030-4EAMA	619.20		X
9	ENERGY ABSORBER REAR BUMPER	B5090-HV00A	126.40		X
10	RH SIDE BRACKET REAR BUMPER	B5220-4EADA	36.90		OK
11	LH SIDE BRACKET REAR BUMPER	B5221-4EADA	36.90		OK
12	TOW HOOK COVER REAR BUMPER	B5071-HV00K	16.80		X
13	CLIP REAR BUMPER # S20 \$ 1.20 EACH	01853-05933	7.20		OK
14	REAR BUMPER	B5022-4EADH	717.00		OK
SUB TOTAL			1279.00	0.00	20.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			266.80	0.00	0.00
GRAND TOTAL			1023.20	0.00	20.00
OVERALL TOTAL			1043.20		

LEGEND: REMARKS('OK') = APPROVED, REMARKS('X') = NOT APPROVED

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SW1741

NETT ITEM	1279.00
LESS 20.00%	(255.80)
NETT AMOUNT	1023.20
LIST ITEM	0.00
LESS 30.00%	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	20.00
LESS .00%	0.00
SPECIAL NETT AMOUNT	20.00
TOTAL LABOUR CHARGES	690.00
TOTAL SPARE PARTS CHARGES	1043.20
TOTAL CHARGES	1733.20
KO 7 & GST	121.32
GRAND TOTAL	1854.52



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18016351/Ucd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 10-12-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 8169J	Veh. Inspected	SLW 174T
Policy No.		Coverage (\$)	0.00
Claim No.	D18006591MFSH	Excess (\$)	0.00
Assign From	SERENE LER	Assign Date	06/09/2018
2. Vehicle Particulars & Condition			
Make & Model	NISSAN QASHQAI (A)	c.c	1197
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	SJNFEAJ11U2171786	Colour	BROWN
Odometer	12213	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R17	BRIDGESTONE	7 mm
L/H Front Tyre	215/60 R17	BRIDGESTONE	7 mm
R/H Rear Tyre	215/60 R17	BRIDGESTONE	7 mm
L/H Rear Tyre	215/60 R17	BRIDGESTONE	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	01/09/2018	Inspection Date	12/09/2018
Survey held at	AUTOLUTION INDUSTRIAL PTE LTD 19 UBI ROAD 4 SINGAPORE 408623		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 174T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RH REAR FENDER WHEEL HOUSE PROTECTOR (N)	NOT NECESSARY	186.40	-
1	RH REAR FENDER WHEEL ARC MOULDING (N)	GRAZED	483.00	483.00
1	RH STAY REAR BUMPER (N)	NOT NECESSARY	126.00	-
1	LH STAY REAR BUMPER (N)	NOT NECESSARY	126.00	-
1	REINFORCEMENT REAR BUMPER (N)	NOT NECESSARY	619.20	-
1	ENERGY ABSORBER REAR BUMPER (N)	NOT NECESSARY	126.40	-
1	RH SIDE BRACKET REAR BUMPER (N)	NECESSARY	35.90	35.90
1	LH SIDE BRACKET REAR BUMPER (N)	NECESSARY	35.90	35.90
1	TOW HOOK COVER REAR BUMPER (N)	NOT NECESSARY	16.80	-
6	CLIP REAR BUMPER @\$1.20 (N)	NECESSARY	7.20	7.20
1	REAR BUMPER (N)	DEEP CUT	717.00	717.00
	LESS 20% DISCOUNT		-495.96	-255.80
			1,983.84	1,023.20
SPECIAL NETT ITEMS				
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
1	SENSOR-REVERSE 4 EYE (SN)	NOT NECESSARY	250.00	-
1	REAR LICENCE PLATE (SN)	NOT NECESSARY	60.00	-
1	TOW HOOK COVER REAR BUMPER (DEFORMED)(SN)	NOT CONSISTENT WITH THE IMPACT	16.80	-
			376.80	20.00
LABOUR				
	LABOR CHARGES TO REPAIR REAR END PANEL & LH REAR FENDER,RENEW REAR BUMPER.		780.00	390.00
	CHARGES TO SPRAY PAINTING SAME.		750.00	250.00
	REFIX REVERSE SENSOR 4 EYE.		110.00	50.00
			-	-
			-	-
			1,640.00	690.00
GRAND TOTAL			4,000.64	1,733.20
RECOMMENDED COST OF REPAIRS				1,733.20

Report Ref No. CS/FC118016351/Ucd3e2



Report Ref No. CS/FCI18016351/Ucd3e2

A handwritten signature in black ink, appearing to read 'Chua'.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.