

WSP

ASSIGNMENT

DOI: 10/18

Date / Time: 6/9/18

Registered in Merimen: 7/9/18

Pre-assign / CCU / FIE



Insured Vehicle No: SLM 4453P
 Name of Insured: MADAIKKA B. ANAND WASTI
 Insured Tel No: HP: 92372952
 Excess Sec II :SS D.O.A: 5/9/2018
 Is driver the owner? YES / NO Nature of Accident:

Claim No: 120100011157
 Policy No: PMPV 2017 - 0000 4501-01
 Make / Model: 7. Rave 4
 Place of Accident: Campney St 20

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SGG 466U



INSRS:
WSP: Focus Auto
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

SGG 466U - CLAIM 1300 230 / Rqur, MA: 31/1/19
 SLM 4453P - X

STAGE	DATE / PIC
Non-Reporting ltr (1st)	
Non-Reporting ltr (2nd)	
Non-Reporting ltr (Final)	
Notification ltr (if non-pickup)	
Call OI	
After call ltr to OI	
Documentation Check List: Handler Typist	
Notification ltr (if non-pickup)	<input type="checkbox"/>
After call ltr to OI	<input type="checkbox"/>
Authorisation To Act	<input checked="" type="checkbox"/>
Release Voucher	<input checked="" type="checkbox"/>
Final Repair Bill	<input checked="" type="checkbox"/>
Car Rental Invoice	<input checked="" type="checkbox"/>
Towing Invoice	<input type="checkbox"/>
LTA / GIA :	<input checked="" type="checkbox"/>
Medical Bill	<input type="checkbox"/>
PIR	<input type="checkbox"/>
Mandate/Reject Instruction	<input checked="" type="checkbox"/>
LOD	<input checked="" type="checkbox"/>
Payment Breakdown Form	<input type="checkbox"/>
Post-Repair Photos	<input type="checkbox"/>
Others	<input type="checkbox"/>

09-09-18 Email and liability clear.

12-19 FILE THIS TO TPWT TO PREPARE REPORT.

PRELIMINARY ADVICE Date/Time: 10/19 Sent By: [Signature]

FINALIZATION Date/Time: Confirm with: Confirm by: [Signature]

Repair Cost: 4/3 S\$ 6,900 (5 days) Reduction: 34 % Email Call

FINAL SETTLEMENT Date/Time: 01-03-19 Confirm with: BEGGA Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 27 If NO or B 28, Ass. Lia:

Repair Cost: 4/3 S\$ 6,900.00 OI ROAD ENDED TP.

Loss of Rental (LOR): S\$ 600.00 (6 days) x 100

Loss of Use (LOU): S\$ - (3 x days)

Loss of Income (LOI): S\$ - (3 x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search S\$ 31.00

Medical S\$ -

Disbursement: S\$ - (e.g. Tow/Independent)

Legal Cost S\$ -

Total: S\$ 7,586.00 Global Sum S\$:

FINAL PAYMENT Date/Time: 01-03-19 Confirm with: BEGGA Email Call

Payee 1: S\$ 7,586.00 Name 1: FOCUS AUTO PIR LTD

Payee 2: (Str: if N.A.) --- Name 2:

Payee 3: (Dul: if N.A.) --- Name 3:

CLAIM 12/3/19

REP: FWD

ASSIGNMENT

From: Date 7/9/18

Estimated Cost:

OO/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SGG 466 4

at Workshop no: Focus Auto

of 1 kaki Bkt Ave 6 # 02-50

Insured

Policy No.

Claims No.

Sum Insured

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Est. or Market Value: 38

DAC Accident Report

Consistent? : Yes or No

GA / PR Seen: 9

Consistent? : Yes or No

Est. Repairs: 5 days

Res: Yes or No

Lump Sum: 20 %

3 Val: Yes or No

CA / REV / REP. 1-24 HRS (up)

L1A30718

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SGG 4664 Yr Regn: 9 / 11

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAI

Make: Volkswagen Jetta cc 1390

Colour: Se. ge A/C: Insured / Std / NI / NA

Sp. Reading: 145138 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVVZZZ16ZGM004719

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Bin / STD A/Rim or

Tyre Size: F: R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front: 6 mm Rear: 6 mm

R/Bal: 6 mm L/Bal: 6 mm

D.O.A: 5/9/18 D.O.I: 7/9/18

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	net 7281
	1/5 @ 6500 Continental
	RED: + 3,618.21 36%

Date/Time: File Pass to?

: Preli. Report

Days Of Repair:

Date/Time: File Return to?

: Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time: File Return to?

Add Fee: Site Insp (\$)

Transportation

Interview (\$)

3 + RS, SR

Tech. Invs (\$)

Phone

Weekend (\$)

Other

Report Format :

Lump Sum / L.B.t: (\$)

TOTAL

*Disher -
LICK
LOD*

*18/10/2018
WJ
OK
Not about
rent
7/9/18
take the Atteage
Sdy.
4/5 @ 6500*

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT WENGL 620290 AT (URBAN) @ KAKI BUKIT SINGAPORE 417883
TEL: 6886 0067 FAX: 6841 9095 Email: focus-auto@focusauto.com.sg
GST: 2007125001 RCB NO: 201004495R

M/S: FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER FOUR
SINGAPORE 038986
TEL: 6727 5721
ATTN: Motor Claim Department

Estimate No: EST0000700
Date: 06 Sep 2018
Policy No: ga257635 1
Veh Reg No: SGG466U
Make Model: VOLKSWAGEN JETTA 1.4
TSI AT 1623G5
Chassis No: WVWZZ716ZCM004719
Engine No: CAX901645
Reg. Date: 26-09-2011

Your Ref No: SGG466U
Claim Type: Third Party
Accident Date: 05-09-2018
IP Veh Reg No: SLM4453P

*P-7135-83
107
6422.24*

Estimate Repair Cost for Vehicle No :SGG466U

PAGE 1

Description	U-Price	Quantity	List Price SS	Amount SS
VOLKSWAGEN JETTA 1.4 TSI AT 1623G5				
List Price				
1 Rear Bump <i>DS/3uc 1450</i>	1,490.000	1 PC	1,490.00	—
2 Rear Boot Hinge <i>AA</i>	110.0000	2 PC	220.00	X
3 Rear Boot Lock <i>tw</i>	220.0000	1 PC	220.00	—
4 Rear Boot Lock Catch <i>AA</i>	90.0000	1 PC	90.00	X
5 Rear Boot Rubber <i>tw</i>	263.8000	1 PC	263.80	—
6 Rear Boot Emblem (JL FLS) <i>ren 201</i>	35.4000	1 PC	35.40	—
7 Rear Boot Emblem (LSI) <i>ren</i>	35.4000	1 PC	35.40	—
8 Rear Boot Centre Logo <i>ren</i>	120.0000	1 PC	120.00	—
9 Rear Boot Reflector Lamp <i>n/sca o/sca</i>	290.0000	2 PC	580.00	—
10 Rear Boot Inner Cover Board <i>AA</i>	190.0000	1 PC	190.00	X
11 Rear Tail Lamp <i>n/s sca o/s sca</i>	380.0000	2 PC	760.00	—
12 Rear Tail Lamp Inner Side Cover <i>n/s sca 30</i>	54.0000	2 PC	108.00	—
13 Rear End Panel <i>DS 920</i>	980.0000	1 PC	980.00	—
14 Rear End Panel Top Garnish <i>tw</i>	235.0000	1 PC	235.00	—
15 Rear Bumper <i>DS</i>	1,123.700	1 PC	1,123.70	—
16 Rear Bumper Side Reinforce <i>hel</i>	89.5000	2 PC	179.00	—
17 Rear Bumper Reinforcement <i>DS 591.33</i>	640.0000	1 PC	640.00	—
18 Rear Bumper Lower Pad <i>DS/2u</i>	540.0000	1 PC	540.00	—
19 Rear Spare Tyre Top Cover Board <i>AA</i>	240.0000	1 PC	240.00	X
20 Rear Bumper Core Inner Bracket <i>one 115</i>	135.0000	2 PC	270.00	7pc
			8,320.30	
		Less 10%	832.03	7,488.27
Special Net				
21 Rear Number Plate <i>net</i>	50.0000	1 PC	50.00	40
22 Rear Bumper Sensor <i>swtd</i>	300.0000	1 SET	300.00	200
			350.00	350.00
Labour				
23 Panel Beating	1,200.000	1 PC	1,200.00	800
24 Check Wiring	80.0000	1 PC	80.00	30
25 Rust Proofing	80.0000	1 PC	80.00	60

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417003
 TEL: 6886 9097 FAX: 6841 9095 Email: focus.autopthd@yahoo.com.sg
 GST:200712509E RCB NO:201004495R

M/S : FWD SINGAPORE PTE LTD
 6 TEMASEK BOULEVARD
 #18-01 SUNTEC TOWER FOUR
 SINGAPORE 038986
 TEL: 6727 5721
 ATTN: Motor Claim Department

Estimate No: **ES10000700**
 Date: **06 Sep 2018**
 Policy No: **gn257635/1**
 Veh Reg No: **SGG466U**
 Make/Model: **VOLKSWAGEN JETTA 1.4
 TSLAT 1623G5**
 Chassis No: **WVWZZZ16ZC0004719**
 Engine No: **CAX901645**
 Reg. Date: **26-09-2011**

Your Ref No: SGG466U
 Claim Type: Third Party
 Accident Date: 05-09-2018
 TP Veh Reg No: SLM4453P

Estimate Repair Cost for Vehicle No :SGG466U

PAGE:2/2

Description	U/Price	Quantity	List Price	Amount
26 To Remove & Replace Bumper Sensor	80.0000	1 PC	80.00	80.00
27 To Spray Painting	900.0000	1 PC	900.00	900.00
			2,340.00	2,340.00
			Total	SS 10,178.27

TOTAL: SINGAPORE DOLLAR TEN THOUSAND ONE HUNDRED SEVENTY EIGHT AND CENTS TWENTY SEVEN ONLY

For FOCUS AUTO PTE LTD
Focus Auto Pte Ltd
 No 1 Kaki Bukit Ave 6 Auto Bay
 #02-50 Singapore 417003
 AUTHORIZED SIGNATURE

176


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No (illegal modifications) is allowed
- Supplementary (items) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer
 Signatures:
 Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 2741A

Vehicle Details

Vehicle No.: SGG466U
Vehicle to be Exported: No
Intended Deregistration Date: 05 Sep 2018
Vehicle Make: VOLKSWAGEN
Vehicle Model: JETTA 1.4 TSI AT 1623G5
Primary Colour: Gold
Manufacturing Year: 2011
Engine No.: CAX901645
Chassis No.: WVVZZZ16ZCM004719
Maximum Power Output: 90.0 kW (120 bhp)
Open Market Value: \$20,940.00
Original Registration Date: 26 Sep 2011
First Registration Date: 26 Sep 2011
Transfer Count: 0
Actual ARF Paid: \$20,940.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 25 Sep 2021
PARF Rebate Amount: \$13,611.00

Intended COE Rebate Details

COE Expiry Date: 25 Sep 2021
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$55,989.00
COE Rebate Amount: \$17,107.00
Total Rebate Amount: \$30,718.00

The information contained herein is correct as at 05 Sep 2018

OK



Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Oct 2008 Honda CRV 2.4A Selling For \$20k Only.



Good Engine And Gearbox
Condition. Well Maintained
Inside/Out. Nice Dark Blue.
Direct Owner Stocked

ABWIN

[Browse by Category](#)
[« Back \(1 2 \) Next »](#)
[Sort b](#)

25 vehicles

[Advance](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mil
Search Selection	Volkswagen Jetta		Any	Any	2011	Any	
	Volkswagen Jetta Sport 1.4A TSI		\$31,800	\$8,380 /yr	28-Feb-2011	1,390 cc	11
100% Cheapest In The Market, 90% Loan Package Available, Huge Boot Space And Leg Room With Rear Aircon. Best Sp Depreciation. Interior Well Maintained. STA Evaluation Welcome! No ...							
Posted: 07-Sep-2018 Tags: 2011 Volkswagen Jetta, Volkswagen Jetta, Volkswagen, Jetta, Used Volkswagen							
	Volkswagen Jetta Sport 1.4A TSI		\$37,888	\$8,750 /yr	23-Aug-2011	1,390 cc	11
Dont Miss! Selling Cheap! 5k Driveaway. High PARF & COE Rebate At 33 K.Regular Maintained.Accident Free! Flexible Hi Call Now!							
Posted: 06-Sep-2018 Tags: 2011 Volkswagen Jetta, Volkswagen Jetta, Volkswagen, Jetta, Used Volkswagen							
	Volkswagen Jetta Sport 1.4A TSI		\$37,300	\$8,610 /yr	19-Aug-2011	1,390 cc	
Lowest Depreciation In The Market! Warranty 1 Year On Engine, Gearbox. Prevent Buying Consignment W/o Warranty. E Trusted Dealer. Trade In Welcome, Flexible Loan And Insuran...							
Posted: 06-Sep-2018 Tags: 2011 Volkswagen Jetta, Volkswagen Jetta, Volkswagen, Jetta, Used Volkswagen							
	Volkswagen Jetta 1.4A TSI		\$41,123	\$10,040 /yr	26-Jul-2011	1,390 cc	
Nice Sporty Luxurious Sedan Black Unit. Sporty Yet Comfortable. Wear And Tear All Replaced No Cost Spared. Accident F Market Lots Of Modded Goodies. Well Taken Care. No Ab...							
Posted: 05-Sep-2018 Tags: 2011 Volkswagen Jetta, Volkswagen Jetta, Volkswagen, Jetta, Used Volkswagen							

[Car Buying](#)
[Car Selling](#)
[Car Ownership](#)
[Car Aftermarket
Compare](#)
[On The Move](#)
[Lifestyle](#)

Not about
about
7/9/18
take the other
side.

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6841 9095 Email: focus.autoptehd@yahoo.com.sg
GST:200712509E RCB NO:201004495R

M/S : FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER FOUR
SINGAPORE 038986
TEL: 6727 5721
ATTN: Motor Claim Department

Estimate No: EST0000700
Date: 06 Sep 2018
Policy No: ga257635/1
Veh Reg No: SGG466U
Make/Model: VOLKSWAGEN JETTA 1.4
TSI AT 1623G5
Chassis No: WVVZZZ16ZCM004719
Engine No: CAX901645
Reg. Date: 26-09-2011

Your Ref No: SGG466U
Claim Type: Third Party
Accident Date: 05-09-2018
TP Veh Reg No: SLM4453P

Estimate Repair Cost for Vehicle No :SGG466U

PAGE:1/2

Description	U/Price	Quantity	List Price SS	Amount SS
VOLKSWAGEN JETTA 1.4 TSI AT 1623G5				
List Price				
1 Rear Boot <i>DS/3000 1450</i>	1,490.000	1 PC	1,490.00	—
2 Rear Boot Hinge <i>AA</i>	110.0000	2 PC	220.00	X
3 Rear Boot Lock <i>tw</i>	220.0000	1 PC	220.00	—
4 Rear Boot Lock Catch <i>AA</i>	90.0000	1 PC	90.00	X
5 Rear Boot Rubber <i>tw 201</i>	263.8000	1 PC	263.80	—
6 Rear Boot Emblem (JETTA) <i>ren</i>	35.4000	1 PC	35.40	—
7 Rear Boot Emblem (TSI) <i>ren</i>	35.4000	1 PC	35.40	—
8 Rear Boot Centre Logo <i>ren</i>	120.0000	1 PC	120.00	—
9 Rear Boot Reflector Lamp <i>n/s crs o/s scr</i>	290.0000	2 PC	580.00	—
10 Rear Boot Inner Cover Board <i>AA</i>	190.0000	1 PC	190.00	X
11 Rear Tail Lamp <i>n/s crs o/s scr</i>	380.0000	2 PC	760.00	—
12 Rear Tail Lamp Inner Side Cover <i>n/s crs 30</i>	54.0000	2 PC	108.00	4 PC
13 Rear End Panel <i>DS 920</i>	980.0000	1 PC	980.00	—
14 Rear End Panel Top Garnish <i>tw</i>	235.0000	1 PC	235.00	—
15 Rear Bumper <i>Dis</i>	1,123.700	1 PC	1,123.70	—
16 Rear Bumper Side Retainer <i>tw</i>	89.5000	2 PC	179.00	—
17 Rear Bumper Reinforcement <i>DS 591-33</i>	640.0000	1 PC	640.00	—
18 Rear Bumper Lower Pad <i>tw</i>	540.0000	1 PC	540.00	—
19 Rear Spare Tyre Top Cover Board <i>AA</i>	240.0000	1 PC	240.00	X
20 Rear Bumper Core Inner Bracket <i>one 115</i>	135.0000	2 PC	270.00	PA C
			8,320.30	7,135.8
	Less 10%		832.03	7,488.27
Special Net				
21 Rear Number Plate <i>set</i>	50.0000	1 PC	50.00	40
22 Rear Bumper Sensor <i>swad</i>	300.0000	1 SET	300.00	200
			350.00	350.00
Labour				
23 Panel Beating	1,200.000	1 PC	1,200.00	600
24 Check Wiring	80.0000	1 PC	80.00	30
25 Rust Proofing	80.0000	1 PC	80.00	60

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6841 9095 Email: focusautopte Ltd@yahoo.com.sg

GST:200712509E RCB NO:201004495R

M/S : FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER FOUR
SINGAPORE 038986

TEL: 6727 5721

ATTN: Motor Claim Department

Your Ref No: SGG466U
Claim Type: Third Party
Accident Date: 05-09-2018
TP Veh Reg No: SLM4453P

Estimate No: EST0000700
Date: 06 Sep 2018
Policy No: ga257635/1
Veh Reg No: SGG466U
Make/Model: VOLKSWAGEN JETTA 1.4
TSI AT 1623G5
Chassis No: WVVZZZ16ZCM004719
Engine No: CAX901645
Reg. Date: 26-09-2011

Estimate Repair Cost for Vehicle No :SGG466U

PAGE:2/2

Description	U/Price	Quantity	List Price	Amount
26 To Remove & Replace Bumper Sensor	80.0000	1 PC	80.00	80.00
27 To Spray Painting	900.0000	1 PC	900.00	900.00
			2,340.00	2,340.00
			Total	S\$ 10,178.27

TOTAL: SINGAPORE DOLLAR TEN THOUSAND ONE HUNDRED SEVENTY EIGHT AND CENTS TWENTY SEVEN ONLY

For FOCUS AUTO PTE LTD
Focus Auto Pte Ltd
No 1 Kaki Bukit Ave 6 Auto Bay
#02-50 Singapore 417883
AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Josey Loh

Date: 10 Sep 2018

Preliminary Advice

Insured Vehicle No	: SLM4453P	Accident Date	: 05/09/2018
TP Vehicle No	: SGG466U	Assignment Date	: 07/09/2018
Make	: VOLKSWAGEN JETTA	Est. Duration of Repair	: 5 days
Date of Inspection	: 07/09/2018		
Inspection At	: Focus Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #02-48 Autobay Singapore 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesrear... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,178.27
Revised Amount	:S\$	6,641.17
Check Items (Estimated)	:S\$	1,912.50
Total	:S\$	8,553.67

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	07 Sep 2018 14:21	Cim Veh Model Changed	(203946) HONDA VEZEL 1.5 G (A).	[A] HOW MEI KWAN
2	07 Sep 2018 14:21	Cim Created	Reg No: SGG466U. Acct Date: 2018/09/05. Claim Type: TP. Insurer: FWD Singapore Pte. Ltd. (HQ). Workshop: Focus Auto Pte Ltd (HQ)	[A] HOW MEI KWAN
3	07 Sep 2018 14:21	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ); RR Region: FWD - Ext Auto Adj Assignment. Suggested Adj. : Appraisals Associates Pte Ltd.	[A] HOW MEI KWAN
4	07 Sep 2018 14:21	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/09/18	[A] HOW MEI KWAN
5	07 Sep 2018 14:21	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] HOW MEI KWAN
6	07 Sep 2018 14:21	Label Added	(20005):Direct Settlement .	[A] HOW MEI KWAN
7	07 Sep 2018 14:21	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] HOW MEI KWAN
8	07 Sep 2018 14:22	Cim Registration Modified	Pol No:->PNPV2017-00004501-01.	[I] Josey Loh
9	07 Sep 2018 14:22	Cim Registration Modified	Excess: -> 600.00.	[I] Josey Loh
10	07 Sep 2018 14:22	Cim Registration Modified	Acct Time:00:00:00->15:00:00.	[I] Josey Loh
11	10 Sep 2018 15:32	Adj Adjuster Assigned	KENNETH KONG -> MARCUS CHUA	[A] HOW MEI KWAN
12	10 Sep 2018 15:33	Cim Veh Model Changed	(203946) -> (205211) VOLKSWAGEN JETTA 1.4 TSI (A).	[A] HOW MEI KWAN
13	10 Sep 2018 15:37	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/09/18	[A] HOW MEI KWAN
14	01 Feb 2019 17:21	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
15	01 Feb 2019 17:21	Cim Dtl Modified	JPJ Reg. Date: -> 2011/09/26.	[A] JOANNE LEE KHANG MIN
16	01 Feb 2019 17:21	Cim Details Notified		[A] JOANNE LEE KHANG MIN
17	14 Feb 2019 08:51	Adj Mandate Request	Cur.Req:7586.00:LIABILITY: 100% B:27 OI REAR ENDED TP QUANTUM: (a) COR w/GS T: \$6,955.00 + (b) LOR: \$600.00 (6day x \$100) + (c) LTA :\$31.00 Total: a+b+c = \$7,586.00 PLEASE REVERT WITH YOUR APPROVAL / MANDATE / INSTRUCTIONS, IF ANY.	[A] Asher Sng Rong Yi

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1912101	10/09/2018	Motor	LKK Auto	LKK Auto	SGG466U	SLM4453P	10.70

Print Received Message

This mail is associated with :

*SGG466U (1201800011157)
[SLM4453P]

TP

GOH KIA CHENG PATRICK
Sep 5 2018 3:00PM
[MOHAMMAD HAIKEL BIN AHMAD WASHI]
Focus Auto Pte Ltd

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 25/02/2019 17:45 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$7586.00) - SGG466U - Claim Handler: Josey Loh

Approved: 7586.00.

Focus Auto Pte Ltd
Business Reg. No. 201004495R
GST Reg. No. 201004495R
Tel: 6886 9097 Fax: 6481 9095
Email: focus.autopteltd@yahoo.com.sg

Date : 29/10/2018

BY E-MAIL

Your ref: SLM4453P

Our ref: SGG466U

WITHOUT PREJUDICE

M/S FWD Singapore Pte Ltd
6 Temasek Boulevard, #18-01, Suntec Tower 4
Singapore 038986

Dear Sir/Madam,

ACCIDENT INVOLVING : (SGG466U & SLM4453P) ALONG TAMPINES AVE2

DOA: 05/09/2018 TIME: 1500 HOURS

We refer to the above matter and write on behalf of GOH KIA CHENG PATRICK, the registered owner of SGG466U in respect of the above accident.

We are instructed that the above accident was caused by your insured's negligent driving/ or management of your insured vehicle. Your insured's vehicle SLM4453P collided onto the rear portion of our client's vehicle SGG466U. As a result of the accident, our client has been put to loss and expenses, particulars of which are as follows:-

1. Cost of Repair (\$6500 + 7% GST)	\$	6,955.00
2. Loss of Rental (6 days x \$220)	\$	1,320.00
3. Buy 3rd party's GIA report	\$	29.00
4. GIA search	\$	2.00
5. Incidentals	\$	88.00

Total Amount: \$ 8,394.00

Enclosed are the following documents for your perusal.

- 1) Driver's driving license/ Identity card
- 2) Certificate of Insurance
- 3) GIA report
- 4) GIA Search (SLM4453P)
- 5) Original repair claim
- 6) Car Rental Agreement/ Receipt (UL - 3213)

Our company is not the authorized workshop of any of the GIA member companies and we are writing in purely for amicable sake.

The demand herein is in respect of our client's for damages pertaining to his motor vehicle and any settlement following or subsequent to this demand shall not prejudice any claim in respect of personal injuries.

Kindly acknowledge receipt of the above said documents within 7 days and your favourable reply is deeply appreciated.

Yours faithfully,



Laura

LETTER OF AUTHORIZATION

DATE : 06/09/2018

To : _____

RE: ACCIDENT INVOLVING VEHICLE NO. SGG466U & SLM 4453P

ALONG Tampines Ave 2 ON 05/09/2018

I / WE Goh Kia Cheng Patrick of (NRIC / ROC NO.) 50042741A

OF Blk 103 Clementi St 14 #11-25 S (120103)

Owner of vehicle no. SGG466U in consideration of M/S FOCUS AUTO PTE LTD

Repairing my / our vehicle SGG466U at my / our instruction and hereby authorize

FOCUS AUTO PTE LTD to demand claim settle receive whatever amount settled / payable

by the Insurance Company and / or third party or to commence legal proceeding. If necessary, under

my name, for the cost of repairs, car rental and / or loss of use, etc and to their appointing Solicitor to

act for me / us in respect of the said accident / claim and all claimed and / or settled shall belong to

them absolutely.

I further agree and undertake to indemnify them against the above mentioned claim cost which may

arise therewith.

Signature of Owner : _____
(Company's chop - if any)

Name of Owner : Goh Kia Cheng Patrick

NRIC No : 50042741A

Provide always that this discharge of my claim for damages relating to the damage to my vehicle shall not prejudice or affect or preclude me from making a further claim for general and special damages for my personal injuries sustained in the same accident.

RELEASE

Claim Reference:	1201800011157
Surveyor's Reference:	CC4/FWD18016353/Uea3
TP Reference:	SGG 466U

We, **FOCUS AUTO PTE LTD** ("Workshop") hereby agree and confirm that we are authorized by the owner ("Claimant") of motor vehicle **SGG 466U** ("Vehicle") to accept the sum of **\$7,586.00**, being the amount claimed for **\$6,955.00** (repair costs), **\$600.00** (loss of rental/ use), **\$ -** (loss of income), **\$31.00** (search fees) as compensation for the loss of or damage to the Vehicle, as a result of an accident ("Accident") which occurred on **05/09/2018** (date of accident) at / along **TAMPINES AVE 2** (location) involving vehicle no/s. **SGG 466U** and **SLM 4453P**.

This is pursuant to the inspection conducted on **07/09/2018** (date) at the Workshop.

We confirm that this acceptance is in full and final settlement of all claims arising from the damage to the Vehicle (whether now or hereafter to become manifest), to the intent that FWD Singapore Pte. Ltd. and all other persons, in particular the driver of **SLM 4453P** be absolutely and finally exonerated and discharged from all claims of every nature and kind whatsoever which have been made or which may be made in respect of this Accident.

We also declare that we are authorized by the Claimant to receive the above compensation and we have full authority to make the claim as set out above and to settle the matter on behalf of the Claimant in any manner we deem fit.

This settlement is reached on a without prejudice and without admission of liability basis. As such, this Release is not to be construed as an admission of liability on the part of FWD Singapore Pte Ltd, their policyholder and / or authorised driver and shall not be used as evidence in any claims and / or action which may be lodged by any of them.

Dated this 09 day of 03 2019

CLAIMANT



Focus Auto Pte Ltd
No 1 Kaki Bukit Ave 6 Auto Bay
#02-80 Singapore 417883
Tel: 66348895

[Signed by the "Workshop" with Co. Stamp]

For and on behalf of the "Claimant"



CKS

[FWD's appointed surveyor with Co. Stamp]

For and on behalf of FWD Singapore Pte. Ltd.

Focus Auto Pte Ltd

Business Reg. No: 201004495R

GST Reg. No: 201004495R

No 1 Kaki Bukit Ave 6 Autobay

#02-50 Singapore 417883

Date: 29/10/2018

GOH KIA CHENG PATRICK

C/O NO 1 KAKI BUKIT AVENUE 6

AUTOBAY #02-48/50

SINGAPORE 417883

MOTOR VEHICLE NO: SGG466U

VOLKSWAGEN JETTA

REPAIR CLAIM

\$ 6,500.00

LUMP SUM

Sub- total \$ 6,500.00


7% GST: \$ 455.00

Total: \$ 6,955.00

SINGAPORE DOLLARS:

SIX THOUSAND NINE HUNDRED AND FIFTY-FIVE
DOLLARS ONLY


TP-SGG 4664 . VEHICLE RENTAL AGREEMENT No. RA 3213

HIRER'S PARTICULARS		Vehicle No: <u>SJ28806K</u> Replace Veh No:	
Name: <u>Goh Kia Chang Patrick</u>		Mileage Out: _____ Mileage In: _____	
Address: <u>Blk 103 Clementi St 14</u> <u>#11-125</u> <u>Singapore 120103</u>		Make & Model: <u>Volk Jetta</u> Make & Model: _____	
Contact Person: _____ Tel: _____		Auto / Manual: <u>Auto</u> Auto / Manual: _____	
DRIVER'S PARTICULARS		OUT Date: <u>05/09/18</u> OUT Time: <u>5pm</u>	
Name: _____		HIRE EXPIRY: <u>12/9/18</u> TIME EXPIRY: <u>5.30pm</u>	
Address: _____		RENTAL CHARGES	
Tel No: _____ H/P No: _____		Daily: <u>6 day @ \$ 220</u> <u>1,320.00</u>	
P.P. / I.C. No: <u>SP042141A</u> D/L NO: _____		Weekly: @ \$ _____	
Date of Birth: <u>10/02/1952</u> Date of Issue / Expiry: _____		Monthly: @ \$ _____	
Nationality: <u>S'pore</u> Pl. Of Issue: <u>5/9/1973</u>		Hours: @ \$ _____	
Occupation: _____ Driving Exp: _____		Others: @ \$ _____	
Refundable Deposits: _____		CDW: @ \$ _____	
Cash/Nets/Cheque/VISA/MC Cards No.: _____		PAI: @ \$ _____	
(A) - ACCIDENTS (D) - DENTS (S) - SCRATCHES		Delivery Service: _____	
<div style="text-align: center;"> <p>FRONT</p>  </div> <div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;"> <p>LEFT</p>  </div> <div style="text-align: center;">  </div> <div style="text-align: center;"> <p>RIGHT</p>  </div> </div> <div style="text-align: center; margin-top: 10px;"> <p>REAR</p>  </div>		<div style="text-align: center;"> <p>OUT IN</p>  </div> <p>EXTENSION</p> <p>Collection Service: _____</p> <p>Misc: _____</p> <p style="text-align: right;">ESTIMATED TOTAL RENTAL \$ <u>1,320.00</u></p> <p>Sales Person Code: _____</p> <p>Hirer is responsible for the first \$ <u>2,500.00</u> excess for collision / damage to first party. (i.e) ULTIMATE CAR RENTAL Vehicles (including windscreen) and also first \$ <u>2,500.00</u> excess for collision/damage to third party's vehicles for each and every accident / damage <u>Additional Excess loady \$3,500.00</u></p> <p>HIRER's Signature: _____</p> <p>Additional Driver's Signature: _____</p>	

We agree to the terms and conditions above, overleaf and that all information given is true and correct in all respect. My/Our Driving licence(s) is/are current and not disqualified from driving. You may charge all amount due on the rental to my/our credit card.

- IMPORTANT**
- ONLY PERSONS ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE
 - VEHICLES IS STRICTLY FOR SINGAPORE USE ONLY AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY ULTIMATE CAR RENTAL
 - IN THE EVENT OF AN ACCIDENT, THE HIRER OR AUTHORIZED DRIVER:
 - shall report all accidents involving the said vehicle to the Owner immediately
 - shall take immediate steps to complete and sign Form Mar 1 (Motor Accident Report form) and do all other acts required in compliance with the "NON-INJURY MOTOR ACCIDENT REPORT SCHEME" (the form will be made available when the accident is reported to the owner)
 - shall report to the police within 24 hours from the occurrence, the following types of accidents:
 - injury case;
 - non-injury case involving a Government vehicles or damage to Government property;
 - non-injury case involving a foreign vehicle (to obtain their motor insurance, policy, Passport No./Name of the driver, Vehicle number, Log card and Vehicle road tax information);
 - non-injury case involving a pedestrian or cyclist.

RETURN OF VEHICLE - THE HIRER/DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER/DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO ULTIMATE CAR RENTAL AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	DEPOSIT REFUND	SIGNATURE OF HIRER/DRIVER
<u>12/9/18</u>	<u>5.30pm</u>					



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-137907
Date of Request: 06/09/2018

Your Ref No: MSME18115554

Progressive Auto Pte Ltd
No.1 Kaki Bukit Ave 6 #02-48/50
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 05/09/2018
Place of Accident: ALONG TAMPINES AVE 2
Client Vehicle No: SGG466U

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST inclusive)	15.00

Thank You

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

GIRO Cash Cheque



RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-137911
Date of Request: 06/09/2018

Your Ref No: MSME18115554

Progressive Auto Pte Ltd
No.1 Kaki Bukit Ave 6 #02-48/50
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Date of Accident: 05/09/2018
Vehicle No: SGG466U
Place of Accident: ALONG TAMPINES AVE 2
Involving Vehicle No: SLM4453P

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SLM4453P	ALONG TAMPINES AVE 2	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [] Cash [] Cheque



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-137332
Date of Request: 05/09/2018

Your Ref No: Online Purchase

Progressive Auto Pte Ltd
No.1 Kaki Bukit Ave 6 #02-48/50
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 05/09/2018
Enquiry By Chew Wei Keat
TP Vehicle No. SLM4453P
Accident Date 05/09/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

GIRO Cash Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Sep 2018 Edit Reg		06 Sep 2018 00:00 Edit Adj Rpt	S\$6,500.00 Edit Estimates	S\$6,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	MOHAMMAD HAIKEL BIN AHMAD WASHI , ID: S8409297E								
Main Claimant:	GOH KIA CHENG PATRICK , ID: S0042741A								
Vehicle Reg. No.:	SGG466U	Date of Loss:	05/09/2018 15:00 - :59 [83 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201800011157	Policy/Cover Note No.:	PNPV2017-00004501-01 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLM4453P	Policy No. (Claimant):	GA257635						
		Excess:	S\$600.00						
Repairer:	Focus Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #02-48/50 Autobay, 417883 Kaki Bukit - Tel: 68869097								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 18/09/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• FWD_SG (25/02/2019): Alert - Adj Mandate Approved (S\$7586.00) - SGG466U - Claim Handler: Josey Loh									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGG466U (1201800011157)**
[SLM4453P]
TP
GOH KIA CHENG PATRICK
Sep 5 2018 3:00PM
[MOHAMMAD HAIKEL BIN AHMAD WASHI]
Focus Auto Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Letters/Correspondences									
						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail		Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown				1		Edit	
Assessment Reports									
						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail		Print	
1	10/09/18 15:37	Adjuster Immediate Advice				1		Load HTML	
Photos/Images									
						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail		Print	
1	14/02/19 08:50	Odometer Reading				1		Load JPG	
2	14/02/19 08:50	General View				1		Load JPG	
3	14/02/19 08:50	Chassis Number				1		Load JPG	
4	14/02/19 08:50	General View				1		Load JPG	
5	14/02/19 08:50	General View				1		Load JPG	
6	14/02/19 08:50	General View				1		Load JPG	
7	14/02/19 08:50	General View				1		Load JPG	
8	14/02/19 08:50	General View				1		Load JPG	
9	14/02/19 08:50	General View				1		Load JPG	
10	14/02/19 08:50	General View				1		Load JPG	
11	14/02/19 08:50	General View				1		Load JPG	
12	14/02/19 08:50	General View				1		Load JPG	
13	14/02/19 08:50	General View				1		Load JPG	
14	14/02/19 08:50	General View				1		Load JPG	
15	14/02/19 08:50	General View				1		Load JPG	
16	14/02/19 08:50	General View				1		Load JPG	
17	14/02/19 08:50	General View				1		Load JPG	
18	14/02/19 08:50	General View				1		Load JPG	
19	14/02/19 08:50	General View				1		Load JPG	
20	14/02/19 08:50	General View				1		Load JPG	
21	14/02/19 08:50	General View				1		Load JPG	
22	14/02/19 08:50	General View				1		Load JPG	
23	14/02/19 08:50	General View				1		Load JPG	
24	14/02/19 08:50	General View				1		Load JPG	
25	14/02/19 08:50	General View				1		Load JPG	
26	14/02/19 08:50	General View				1		Load JPG	
27	14/02/19 08:50	General View				1		Load JPG	
28	14/02/19 08:50	General View				1		Load JPG	
29	14/02/19 08:50	General View				1		Load JPG	
30	14/02/19 08:50	General View				1		Load JPG	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	14/02/19 08:50	General View		<input checked="" type="checkbox"/>
32	14/02/19 08:50	General View		<input checked="" type="checkbox"/>
33	14/02/19 08:50	General View		<input checked="" type="checkbox"/>
34	14/02/19 08:50	General View		<input checked="" type="checkbox"/>
35	14/02/19 08:50	General View		<input checked="" type="checkbox"/>
36	14/02/19 08:50	General View		<input checked="" type="checkbox"/>
37	14/02/19 08:50	General View		<input checked="" type="checkbox"/>
38	14/02/19 08:50	General View		<input checked="" type="checkbox"/>
39	14/02/19 08:50	General View		<input checked="" type="checkbox"/>
40	14/02/19 08:50	General View		<input checked="" type="checkbox"/>
41	14/02/19 08:50	General View		<input checked="" type="checkbox"/>
42	14/02/19 08:50	General View		<input checked="" type="checkbox"/>
43	14/02/19 08:50	General View		<input checked="" type="checkbox"/>
44	14/02/19 08:50	General View		<input checked="" type="checkbox"/>
45	14/02/19 08:50	General View		<input checked="" type="checkbox"/>
46	14/02/19 08:50	General View		<input checked="" type="checkbox"/>
47	14/02/19 08:50	General View		<input checked="" type="checkbox"/>
48	14/02/19 08:50	General View		<input checked="" type="checkbox"/>
49	14/02/19 08:50	General View		<input checked="" type="checkbox"/>
50	14/02/19 08:50	General View		<input checked="" type="checkbox"/>
51	14/02/19 08:50	General View		<input checked="" type="checkbox"/>
52	14/02/19 08:50	General View		<input checked="" type="checkbox"/>
53	14/02/19 08:50	General View		<input checked="" type="checkbox"/>
54	14/02/19 08:50	General View		<input checked="" type="checkbox"/>
55	14/02/19 08:50	General View		<input checked="" type="checkbox"/>
56	14/02/19 08:50	General View		<input checked="" type="checkbox"/>
57	14/02/19 08:50	General View		<input checked="" type="checkbox"/>
58	14/02/19 08:50	General View		<input checked="" type="checkbox"/>
59	14/02/19 08:50	General View		<input checked="" type="checkbox"/>
60	14/02/19 08:50	Reinspection Photo		<input checked="" type="checkbox"/>
61	14/02/19 08:50	Reinspection Photo		<input checked="" type="checkbox"/>
62	14/02/19 08:50	Reinspection Photo		<input checked="" type="checkbox"/>
63	14/02/19 08:50	Reinspection Photo		<input checked="" type="checkbox"/>
64	14/02/19 08:50	Reinspection Photo		<input checked="" type="checkbox"/>
65	14/02/19 08:50	Reinspection Photo		<input checked="" type="checkbox"/>
66	14/02/19 08:50	Reinspection Photo		<input checked="" type="checkbox"/>
67	14/02/19 08:50	Reinspection Photo		<input checked="" type="checkbox"/>
68	14/02/19 08:50	Reinspection Photo		<input checked="" type="checkbox"/>
69	14/02/19 08:50	Reinspection Photo		<input checked="" type="checkbox"/>
70	14/02/19 08:50	Reinspection Photo		<input checked="" type="checkbox"/>
71	14/02/19 08:50	Reinspection Photo		<input checked="" type="checkbox"/>
72	14/02/19 08:50	Reinspection Photo		<input checked="" type="checkbox"/>
73	14/02/19 08:50	Reinspection Photo		<input checked="" type="checkbox"/>
74	14/02/19 08:50	Reinspection Photo		<input checked="" type="checkbox"/>
75	14/02/19 08:50	Reinspection Photo		<input checked="" type="checkbox"/>
76	14/02/19 08:50	Reinspection Photo		<input checked="" type="checkbox"/>
77	14/02/19 08:50	Reinspection Photo		<input checked="" type="checkbox"/>
78	14/02/19 08:50	Reinspection Photo		<input checked="" type="checkbox"/>
79	14/02/19 08:50	Reinspection Photo		<input checked="" type="checkbox"/>
80	14/02/19 08:50	Reinspection Photo		<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	14/02/19 08:50	Reinspection Photo		<input checked="" type="checkbox"/>
82	14/02/19 08:50	Reinspection Photo		<input checked="" type="checkbox"/>
83	14/02/19 08:50	Reinspection Photo		<input checked="" type="checkbox"/>
84	14/02/19 08:50	Reinspection Photo		<input checked="" type="checkbox"/>
85	14/02/19 08:50	Reinspection Photo		<input checked="" type="checkbox"/>
86	14/02/19 08:50	Reinspection Photo		<input checked="" type="checkbox"/>
87	14/02/19 08:50	Reinspection Photo		<input checked="" type="checkbox"/>
88	14/02/19 08:50	Reinspection Photo		<input checked="" type="checkbox"/>
89	14/02/19 08:50	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/09/18 14:21	ACKNOWLEDGEMENT EMAIL TO FWD DD 06.09.2018		
2	10/09/18 19:27	TP ESTIMATE - MARKED		
3	10/09/18 19:27	TP GIA REPORT		
4	01/02/19 17:30	WORKSHOP INVOICE		
5	01/02/19 17:30	RENTAL RECEIPT		
6	01/02/19 17:30	GIA SEARCH		
7	01/02/19 17:30	LOD		
8	13/03/19 12:25	AUTHORISATION TO ACT FORM		
9	13/03/19 12:25	Release Voucher		
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	07/09/18 14:23	Insured GIA Report		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLM4453P (Insd veh)	Model:	VOLKSWAGEN JETTA 1.4 TSI (A)
	SGG466U (TP veh)		
Date of Accident:	05/09/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	10,890.75
Final Repair Cost	:	\$	6,955.00
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	600.00 6 days
LTA / GIA Search Fee	:	\$	31.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	7,586.00
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Focus Auto Pte Ltd	:	\$ 7,586.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

13 Mar
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD18016353/JEA3Q2
Date: 13/03/2019

REFERENCE

Handling Insurer:	FWD Singapore Pte. Ltd.	Policy No:	PNPV2017-00004501-01
Claimant Vehicle No :	SGG466U	Insured Vehicle No :	SLM4453P
Date of Loss:	05/09/2018	Nature of Claim:	TP
			Claim No: 1201800011157

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGG466U	Engine No:	CAX901645
Make & Model:	VOLKSWAGEN JETTA, 1.4 TSI (A)	Chassis No:	VVVZZZ16ZCM004719
Reg. Date:	26/09/2011 (Man. Year: 2011)	Odometer:	145138 km
Colour:	Beige		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,838.27	6,662.25	1,176.02	15.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,340.00	1,540.00	800.00	34.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,178.27	8,202.25	1,976.02	19.41
Approved Total (Overridden) (S\$)		6,500.00		
	(S\$) 10,178.27	6,500.00	3,678.27	36.14
+ GST 7.00/7.00% (S\$)	712.48	455.00	257.48	36.14
Nett Amount (S\$)	10,890.75	6,955.00	3,935.75	36.14
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		31.00		
Nett Liability (S\$)		7,586.00		

INSPECTION

Date of Assignment:	06/09/2018	
Date Inspected:	07/09/2018	Inspected At: Focus Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #02-48/50 Autobay Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 01 Feb 2019)
Parts: 143	VOLKSWAGEN JETTA 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGG466U)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Dented / Buckled	1,490.00 FL	*1,450.00 FL
2	2		*REAR BOOT HINGE	Not Necessary	220.00 FL	*- FL
3	1		*REAR BOOT LOCK	Twisted	220.00 FL	*220.00 FL
4	1		*REAR BOOT LOCK CATCH	Not Necessary	90.00 FL	*- FL
5	1		*REAR BOOT RUBBER	Twisted	263.80 FL	*201.00 FL
6	1		*REAR BOOT EMBLEM (JETTA)	Necessary	35.40 FL	*35.40 FL
7	1		*REAR BOOT EMBLEM (TSI)	Necessary	35.40 FL	*35.40 FL
8	1		*REAR BOOT CENTRE LOGO	Necessary	120.00 FL	*120.00 FL
9	2		*REAR BOOT REFLECTOR LAMP	N/S Cracked / O/S Scratched	580.00 FL	*580.00 FL
10	1		*REAR BOOT INNER COVER BOARD	Not Necessary	190.00 FL	*- FL
11	2		*REAR TAIL LAMP	N/S Broken / O/S Scratched	760.00 FL	*760.00 FL
12	1		*REAR TAIL LAMP INNER SIDE COVER	N/S Torn	108.00 FL	*30.00 FL
13	1		*REAR END PANEL	Dented	980.00 FL	*920.00 FL
14	1		*REAR END PANEL TOP GARNISH	Twisted	235.00 FL	*235.00 FL
15	1		*REAR BUMPER	Distorted	1,123.70 FL	*1,123.70 FL
16	2		*REAR BUMPER SIDE RETAINER	Bent	179.00 FL	*179.00 FL
17	1		*REAR BUMPER REINFORCEMENT	Dented	640.00 FL	*591.33 FL
18	1		*REAR BUMPER LOWER PAD	Deformed / Twisted	540.00 FL	*540.00 FL
19	1		*REAR SPARE TYRE TOP COVER BOARD	Not Necessary	240.00 FL	*- FL
20	2		*REAR BUMPER CORE INNER BRACKET	Cracked (1 PCS ONLY)	270.00 FL	*115.00 FL
21	1		*REAR NUMBER PLATE	Bent	50.00 FS	*40.00 FS
22	1		*SET REAR BUMPER SENSOR	Shorted	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNetf. L=ListItemDisc.

Sub Total (S\$)	8,670.30	7,375.83
- List Item Discount on L Items 10.00/10.00% (S\$)	832.03	713.58
Total Parts (S\$)	7,838.27	6,662.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	600.00
2	CHECK WIRING	New	80.00	30.00
3	RUST PROOFING	New	80.00	60.00
4	TO REMOVE & REPLACE BUMPER SENSOR	New	80.00	50.00
5	TO SPRAY PAINTING	New	900.00	800.00
Gross Labour Cost (S\$)			2,340.00	1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >