

ASS. REC. BY:

REF: CS/SMO18016370/T1+d3/n2  
Special Instruction:

Surveyor: Taufik Han  
Merimen

ASSIGNMENT (Office)

From (Person): Han cheung Yong of SMO Date/Time: 7/9/18 @ 2:20pm

Estimated Cost: Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKD 2311M Insured: SKW 6765K

at Workshop in/s Performance Motor Tel: 63190174  
of 303 Alexandra Rd

Policy No: D18MTPV01011540 Claim No: CMTD1803810

Sum Insured: Excess:

Make of Veh: D.O.A. 03/09/2018  
(Client's Record)

CA / REV / REP. / REV 24 HRS 'up'

Date/Time: 3:37pm @ 7/9/18 Person Contacted: caroline Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKD 2311M-X
	SKW 6765K-X
4/9-11/10am	revert previ advise via merimen.
	Part by Part \$8088.55, 4 days (led: 3858.75 : 32%)

Signature: *Tan*

REF:

SOMPO

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

\$85K.

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

WP

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

*Amra*

Veh No: SKD2311M Yr. Regn: 2011, Sly

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW X5

C.C. 2771.

Colour: Black

A/C: Insured / Std / NI / NA

Sp. Reading: 108106.

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: \_\_\_\_\_

WBAZV42082 491867

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: \_\_\_\_\_

255 / 50 R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. \_\_\_\_\_

D.O.I. \_\_\_\_\_

7/9/18 @ 4:15pm

Survey held at PMU

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rebate \$64557.

Date / Time Action / Instruction

RECEIVED 03 JAN 2019

Date/Time, File Pass to?

1) 311 Typist

Date/Time, File Return to?

2) \_\_\_\_\_

: Preli. Report

: Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:  Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee.

Transportation: \_\_\_\_\_

Photos

Others

TOTAL

350
10
360

Report Format : TP

Lump Sum / Ins. I: (\$ 8088.55)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18016370/T1td3

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 07-09-2018



Code : SMO

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.		Veh. Inspected	SKD 2311M
Policy No.	D18MTPV01011540	Coverage (\$)	0.00
Claim No.	CMTD1803810	Excess (\$)	0.00
Assign From	MERIMEN (HAN CHEUNG YONG BERNARD)	Assign Date	07/09/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	03/09/2018	Inspection Date	07/09/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Sep 2018		07 Sep 2018 14:20 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>SIM THIAM CHYE</b> , ID: S7734152H, Tel: +6587225678, Email: WILLIAMSIMTC@GMAIL.COM								
Main Claimant:	<b>BART REMES</b> , ID: S2735728H								
Vehicle Reg. No.:	<b>SKD2311M</b>	Date of Loss:	03/09/2018 10:00 - :59						
Claim Type:	<b>TP / CMTD1803810</b>	Policy/Cover Note No.:	D18MTPV01011540 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SKW6765K</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	<b>Sompo Insurance Singapore Pte. Ltd. (HQ)</b> - Tel: 6461 6555 ... [Handled by <b>HAN CHEUNG YONG BERNARD</b> - 6322 4659]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [ <b>Final Rpt due 18/09/2018</b> ]								
Driver/Custodian (Insured):	SIM THIAM CHYE (40 / Male), NRIC: S7734152H, Tel: +6587225678								
Adj Asg. Remarks:	Please assist to survey the vehicle today								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>• SOMPO_SG (07/09/2018): TP SURVEY</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	03/09/2018 17:39
Date Of Accident	03/09/2018 10:00
Exact Location Of Accident	ALONG UPPER CHANGI ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKD2311M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	BART REMES
NRIC No	S2735728H
Email Address	NICOLEREMES@YAHOO.COM
Mobile Phone No	(LOCAL) +65-96882221
Alternative Phone No	OTHERS-96882221
<b>Vehicle Particulars</b>	
Manufacturer	BMW
Model	X5 XDRIVE35I 3.0 AT 4WD 5DR GAS/D NAV SR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA044778
Cover Note Number	18/07/2018 - 17/07/2019
<b>Driver</b>	
Name of Driver	WANG YEN TENG NICOLE REMES
NRIC No	S7343975B
Date Of Birth	22/11/1973
Occupation	INDOOR
Date Of Driving Pass	06/02/2003
Driving Experience	15 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	+65-96882221
Fax Number	
Contact Number	
EMail Address	NICOLEREMES@YAHOO.COM

Address	71 SEAGULL WALK
Postcode	486723
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - U-TURN
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO THE ATTACHED SKETCH PLAN BY DRIVER.

#### Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKW6765K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Date of accident: 03.09.2018 Time: 1000h Location: Upper Changi Road  
 My Vehicle A: SKD2311M Vehicle B: SKW 6765K Vehicle C: -

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Insurance : Sompo Insurance .

Mr. William sim made a sudden U-Turn along Upper Changi Road while driving on the left lane. No signal nothing. just sudden. He did not look in the mirrors and accidentally hit my car that is travelling on the right lane, right behind and next to his lane (right lane).

He asked me to not file any report against him and had agreed to pay for the scratches & damages on the BMW X5 .

1st Workshop details sent to me was Yap Motors Repairs Service : Mr Yap Blk 7 Sin Ming Road Singapore 575642 .

Subsequently, his insurance agent advised him to claim and make the reports accordingly. So, we both filed our reports.

Claim OD/TP at Ah Lim Motor  Claim OD/TP at other workshop  Reporting Only

Remarks : Please forward a copy of my efile accident report to:  
 My workshop : Performance Motors limited  
 Email address : bartremes@yahoo.com ; nicoleremes@yahoo.com  
 & myself :  
 Email address :

Note : Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Romana

Policyholder's Signature  
 Date & Time:

03.09.2018

[Signature]

Driver's Signature  
 (If driver is not the policyholder)

Date & Time: 03.09.2018



Reporting Centre Personnel's Signature

Name:  
 NRIC/FIN No.:

**SKETCH PLAN**


**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature  
 Date & Time:  
 03.09.2018

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time: 03.09.2018

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

To Whom It May Concern,

Accident involving my vehicle no. SKD2311M on 03.09.2018 (date) with  
SKW6765K (other vehicle no) along Upper Changi Road

I, Bart Remes Nric No. S2735728H

Owner of vehicle no. SKD2311M am aware of the accident of my vehicle on  
03.09.2018 (Date) while car was driven by Nicole Wang

Nric No. S7343975B. I hereby, authorise him / her to make the report.

X [Signature] [Signature]

Name Bart Remes / Nicole Wang

Date: 03.09.18

To fill in if there is a OD claim

I am aware of the circumstances and agreeable to claim my own insurance for the  
above accident.

X \_\_\_\_\_

Name

Date:

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159944  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190531/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



*Due 14/9*  
*10/7/2018*  
*ca in*

**GST REG. NO : M2 - 0020081 - X**

**04 SEP 2018**

## ESTIMATE

Estimate No. : <b>b1 48305</b>	Page No. : <b>1 of 5</b>
Date Estimated : <b>04/09/2018</b>	
Prepared By : <b>Chua Kee Sin</b>	

<b>- ESTIMATE REPAIR FOR -</b> <b>Wang Yen Teng Nicole Remes</b> <b>71 Seagull Walk</b>  <b>Singapore 486723</b>	<b>- ACCOUNT - 40000</b> <b>Cash Sales - Service</b> <b>Singapore</b>
--	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SKD2311M</b>	<b>L491869</b>	<b>14/07/2011</b>	<b>X5 xDRIVE35i</b>	<b>0</b>

DESCRIPTION	VALUE
Replace left rear door ,left lower step board and remove attachment etc	<i>1700</i> 2,975.00
Spray painting left rear door	<i>934 752</i> 885.00
To carry out body cavity preservation. (Per panel).	<i>✓ 100</i> 118.00
To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function. (1 door).	<i>✓ 451</i> 531.00
To conduct checks on all doors and bootlid central locking system for proper function.	<i>- 150</i> 177.00
To check steering geometry and conduct wheel alignment according to BMW specification (1x)	<i>- 451</i> 531.00
To replace tyre and wheel rim including balancing. (1x). left rear	<i>- 80</i> 94.00
Sundries.	<i>80 ?</i> 150.00 <i>rec</i>
<b>Total Labour 1: 5,461.00</b>	

DESCRIPTION	QTY	PRIC	VALUE
BLIND RIVET	10	1.10	<i>+</i> 11.00
ALLOY RIM 9JX19 STAR SPK 334	1	1,203.95	<i>✓ int</i> 1,203.95
DOOR REAR LH	1	1,997.10	<i>✓ int</i> 1,997.10
RR LH DOOR MOULDING (SCHWARZ)	1	101.45	<i>✓ int</i> 101.45
REAR DOOR BRAKE	1	91.10	? 91.10
DOOR LOCK REAR LH (SCA)	1	682.80	? 682.80
WINDOW GUIDE WEB COVER LH	1	107.05	? 107.05
COVER WDW FRAME C-COLUMN DOOR RH LH	1	85.15	<i>nn</i> ? 85.15
Seal	1	29.25	? 29.25

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax: 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax: 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : **b1 48305**  
Date Estimated : **04/09/2018**  
Prepared By : **Chua Kee Sin**

Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SKD2311M</b>	<b>L491869</b>	<b>14/07/2011</b>	<b>X5 xDRIVE35i</b>	<b>0</b>

DESCRIPTION	QTY	PRIC	VALUE
Cover	1	92.40	92.40
RR LH DOOR TOP CHROME	1	158.55	158.55
INNER WEATHERSTRIP RR LH DOOR	1	89.70	89.70
WINDOW GUIDE LH REAR DOOR	1	95.55	95.55
WINDOW GUIDE LH REAR DOOR	1	95.55	95.55
GASKET DOOR JOINT ROOF DOOR RR LH	1	132.35	132.35
RR DOOR WEATHERSTRIP	1	180.45	180.45
RR DOOR WEATHERSTRIP	1	180.45	180.45
RR LH WHEEL ARCH COVER	1	205.75	205.75
LEFT DOOR SILL COVER	1	308.30	308.30
CLIP	26	1.15	29.90
EXPANDING RIVET	8	1.35	10.80
INSERT RUNNING BOARD LH	1	27.65	27.65
SUPPORT PIECE FOR DOOR SILL LH	1	154.20	154.20
RUNNING BOARD LH	1	269.80	269.80

Total Parts : **6,340.25**

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_  
Date & Time 7/9/18 @ 1645 Excess S\$ \_\_\_\_\_  
Surveyor's Name Taufik Sign Taufik  
Surveyor's Tel 97475749 Authorised Yes / No \_\_\_\_\_  
Authorised Date \_\_\_\_\_ Time \_\_\_\_\_  
RESURVEY PARTS PHOTO BY SURVEYOR  Yes / No  PML Yes / No   
Surveyor's E-mail taufik@lkkauto.com  
No. of Working Days Recommend 4-5 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

Labour 1	:	<b>5,461.00</b>
Parts	:	<b>6,340.25</b>
Labour 2	:	<b>0.00</b>
Excess	:	<b>0.00</b>
Total GST @ 7%	:	<b>826.09</b>
<b>Grand Total</b>	:	<b>12,627.34</b>

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

11246.30

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : b1 48305  
Date Estimated : 04/09/2018  
Prepared By : Chua Kee Sin

Page No. :

**REPAIR FOR -**  
Wang Yen Teng Nicole Remes  
71 Seagull Walk

**- ACCOUNT - 509**  
Sompo Insurance Singapore Pte Ltd  
50 Raffles Place  
#05-01/06 Singapore Land Tower  
Singapore 048623

Singapore 486723

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKD2311M	L491869	14/07/2011	X5 xDRIVE35i	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To repalce rear LH door and attachments, rear LH wheel arch cover include knocking out dents caused by the accident	1700.00		1,700.00	
* To spray paint rear LH door	934.00		934.00	
To carry out body cavity preservation. (Per panel).	100.00		100.00	
To transfer lock mechanism from old to new door include conducting checks on new door power window system for proper function (1x)	451.00		451.00	
To conduct checks on all doors and boot lid central locking system for proper function	150.00		150.00	
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (1x)	451.00		451.00	
To replace rear LH wheel rim include balancing (1x)	80.00		80.00	
Sundries.	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# FILLISTER HEAD SCREW *	2.15	2.00		4.30 <i>me</i>
# FILLISTER HEAD SCREW *	2.15	8.00		17.20 <i>me</i>
ALLOY RIM 9JX19 STAR SPK 334	1,203.95	1.00		1,203.95
# CRASH REINFORCEMENT LH *	124.05	1.00		124.05 <i>me</i>
DOOR REAR LH	1,997.10	1.00		1,997.10
RR LH DOOR MOULDING (SCHWARZ)	101.45	1.00		101.45
RR DOOR WEATHERSTRIP	180.45	1.00		180.45
RR LH WHEEL ARCH COVER	205.75	1.00		205.75
LEFT DOOR SILL COVER	308.30	1.00		308.30

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## FINAL REPORT

### # SUPPLEMENTARY ITEMS

Total Labour :	3,946.00
Total Parts :	4,142.55
Total Labour & Parts :	8,088.55
Deduction for Excess :	
Total Repair Costs less Excess:	8,088.55
GST @7%:	566.20
Grand Total :	8,654.75

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## SUPPLEMENTARY

Estimate No. : b1 48305  
Date Estimated : 04/09/2018  
Prepared By : Chua Kee Sin

Page No. :

**REPAIR FOR -**  
Wang Yen Teng Nicole Remes  
71 Seagull Walk

**- ACCOUNT - 509**  
Sompo Insurance Singapore Pte Ltd  
50 Raffles Place  
#05-01/06 Singapore Land Tower  
Singapore 048623

Singapore 486723

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKD2311M	L491869	14/07/2011	X5 xDRIVE35i	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
# FILLISTER HEAD SCREW *	2.15	2.00	<i>all</i> 4.30	
# FILLISTER HEAD SCREW *	2.15	8.00	<i>all</i> 17.20	
# CRASH REINFORCEMENT LH *	124.05	1.00	<i>all</i> 124.05	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

Total Labour :	145.55
Total Parts :	
<b>Total Labour &amp; Parts :</b>	<b>145.55</b>

## LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18016370/T1TD3N2

Date: 04/01/2019

#### REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01011540
Claimant Vehicle No :	SKD2311M	Insured Vehicle No :	SKW6765K
Date of Loss:	03/09/2018	Nature of Claim:	TP
		Claim No:	CMTD1803810

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKD2311M	Engine No:	02777746N55B30A
Make & Model:	BMW X5 XDRIVE35I, 3.0 AT 4WD 5DR GAS/D NAV SR (A)	Chassis No:	WBAZV42090L491869
Reg. Date:	14/07/2011 (Man. Year: 2011)	Odometer:	108106 km
Colour:	Black		
Engine Capacity:	2979 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	255/50 R19	Rear Tyre Size:	255/50 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

#### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,635.80	4,222.55	2,413.25	36.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,360.00	3,866.00	1,494.00	27.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>11,995.80</b>	<b>8,088.55</b>	<b>3,907.25</b>	<b>32.57</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>839.71</b>	<b>566.20</b>	<b>273.51</b>	<b>32.57</b>
<b>Nett Amount (S\$)</b>	<b>12,835.51</b>	<b>8,654.75</b>	<b>4,180.76</b>	<b>32.57</b>

#### INSPECTION

Date of Assignment:	07/09/2018	
Date Inspected:	07/09/2018 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 04 Jan 2019)
<b>Parts:</b> M1-SUV	BMW X5 XDRIVE35I 3.0 AT 4WD 5DR GAS/D NAV SR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKD2311M)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	10		*BLIND RIVET	Not Necessary	11.00 FS	*- FS
2	1		*ALLOY RIM 9JX19 STAR SPK 334	Cut	1,203.95 FS	*1,203.95 FS
3	1		*DOOR REAR LH	Bent	1,997.10 FS	*1,997.10 FS
4	1		*RR LH DOOR MOULDING (SCHWARZ)	Cut	101.45 FS	*101.45 FS
5	1		*REAR DOOR BRAKE	Not Necessary	91.10 FS	*- FS
6	1		*DOOR LOCK REAR LH (SCA)	Not Necessary	682.80 FS	*- FS
7	1		*WINDOW GUIDE WEB COVER LH	Not Necessary	107.05 FS	*- FS
8	1		*COVER WDW FRAME C-COLUMN DOOR RH LH	Not Necessary	85.15 FS	*- FS
9	1		*SEAL	Not Necessary	29.25 FS	*- FS
10	1		*COVER	Not Necessary	92.40 FS	*- FS
11	1		*RR LH DOOR TOP CHROME	Not Necessary	158.55 FS	*- FS
12	1		*INNER WEATHERSTRIP RR LH DOOR	Not Necessary	89.70 FS	*- FS
13	1		*WINDOW GUIDE LH REAR DOOR	Not Necessary	95.55 FS	*- FS
14	1		*WINDOW GUIDE LH REAR DOOR	Not Necessary	95.55 FS	*- FS
15	1		*GASKET DOOR JOINT ROOF DOOR RR LH	Not Necessary	132.35 FS	*- FS
16	1		*RR DOOR WEATHERSTRIP	Necessary	180.45 FS	*180.45 FS
17	1		*RR DOOR WEATHERSTRIP	Not Necessary	180.45 FS	*- FS
18	1		*RR LH WHEEL ARCH COVER	Cut	205.75 FS	*205.75 FS
19	1		*LEFT DOOR SILL COVER	Necessary	308.30 FS	*308.30 FS
20	1		*CLIP (26 Pcs)	Not Necessary	29.90 FS	*- FS
21	8		*EXPANDING RIVET	Not Necessary	10.80 FS	*- FS
22	1		*INSERT RUNNING BOARD LH	Not Necessary	27.65 FS	*- FS
23	1		*SUPPORT PIECE FOR DOOR SILL LH	Not Necessary	154.20 FS	*- FS
24	1		*RUNNING BOARD LH	Not Necessary	269.80 FS	*- FS
25	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
26	2		*FILLISTER HEAD SCREW	Necessary	4.30 FS	*4.30 FS
27	8		*FILLISTER HEAD SCREW	Necessary	17.20 FS	*17.20 FS
28	1		*CRASH REINFORCEMENT LH	Bent	124.05 FS	*124.05 FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$)    6,635.80    4,222.55**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACE LEFT REAR DOOR,LEFT LOWER STEP BOARD AND REMOVE ATTACHMENT ETC	New	2,975.00	1,700.00
2	SPRAY PAINTING LEFT REAR DOOR	New	934.00	934.00
3	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
4	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECKS ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION (1 DOOR)	New	531.00	451.00
5	TO CONDUCT CHECKS ON ALL DOORS AND BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	177.00	150.00
6	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION (1X)	New	531.00	451.00
7	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING (1X) LEFT REAR	New	94.00	80.00
<b>Gross Labour Cost (S\$)</b>			<b>5,360.00</b>	<b>3,866.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >