

ASS. REC. BY:

REF: CS3/MSG18016371/Rld312

Special Instruction:

Surveyor:

menmen

ASSIGNMENT (Office)

From (Person): Irene fan of MSIG Date/Time: 07/09/18 @ 1:54pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJU 2112 T Insured: PC 3952C

at Workshop m/s AMA Automotive Tel: 8778 3636

of 36 Joh Guan Rd East #01-36

Policy No: A28610462MCC Claim No: 569411

Sum Insured: Excess:

Make of Veh:

(Client's Record)

D.O.A. 03/09/2018

10/09/2018

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time: 4:12pm @ 7/9/18 Person Contacted: Melvin Vehicle: IN / OUT

Date/Time	Action/Instruction (x) Estimate
	SJU 2112 T - x
	PC 3952C - x
	Dismantle: 11/9/2018
	After repair: 13/9/2018