

NATIONAL Assessment Centre Services

Date In: 07/09/2018 15:07	Job description	Date & Time Completed	Done by
Ref No: NBO/MC80/63744	SAS e-filing		
Veh No: SR 8114 R	E-mail (within 8hrs, Aft 2hrs)		
D.O.A: 07/09/2018 09:10	I-Motor Claim Form	MT/1010531-001	07/09/2018 17:16
OD: TP Reporting Only	I-Motor W/O (Within: OD 2hrs, TP 4hrs)		
	I-Photo Uploaded		
	Assessment/Survey Report		
TP Insurer:	Ass't Report by Fax / Hand to Owner/Wksp		

Preferred Wksp / INC Assign Wksp / QW: (NOVA AUTOMOTIVE)	Tel:	Fax:
TP Particulars:	Veh No: —	INC () / Non-INC ()
Owner / Driver: ()	Tel: ()	
Policy No: ()	Period: ()	Cover Type: ()
Confirmed by: ()	Date: ()	Time: ()
Insured/Driver Liability: ()	[Note-Est. Status (WO): N: 0-20%; P: 21-79%; F: 80-100%]	
Year of Registration: ()	Warranty: YES () / NO ()	
Excess: (\$)	Loading: \$1,000 () / \$2,000 ()	

General Remarks:

() Walk-In Customer: Customer's information strictly Confidential & Strictly NO refer of repairer.

() Total Loss Case: to e-mail Insurer URGENTLY.

Drive-In () / Towed-In (); Invoice: YES () / NO (); Towing Co. ()

Remarks	Date & Time Completed	Done by
1) Apply for Transport Allowance () / Courtesy Car ()		
2) QC Check / Post Repair Inspection ()		
3) Upload Resurvey Photo [Repair Cost > \$3000] ()		

Injury: —

Date/Time	Actions

Claimant's Particulars: Driver/Owner: Contact No: Damaged Portion: QC Checked by (Engr-In-Charge): Auditors' Comments: Date 1: Date 2/3:	Invoice Preparation Checklist 1) AR: Accident Reporting (\$30); 2) DA: Damage Assessment (\$100); INC (\$80) 3) TF: Towing Fee \$40/\$45 4) FT: Follow-Through Survey \$120 5) FT: Follow-Through Survey (Resurvey) \$30 For claiming against INC Only (wef 10 Jan 2005) 6) TR: Re-inspection \$75 7) N1: Idac DA + SMRT Survey \$160 8) NTUC Additional Services:- ON: *N5: Courtesy Car / Tp Allowance \$5 *N6: Repair Co-ordination \$10 *N7: Post Repair Inspection \$25 *N8: DV / Collect Excess Coordination \$5 TP (N11): TP (Non INC) against INC \$20 9) N12: Idac Mobile \$0 Invoice dated Fee Charged
--	---

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/09/2018 15:07
Date Of Accident	07/09/2018 09:10
Exact Location Of Accident	CAPITOL PIAZZA CAR PARK GANTRY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR8114R
Insured/Policyholder	
Name Of Registered Owner	LIM DAW WOEI DAVID
NRIC No	S7627822I
Email Address	DDWLIM@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-91288123
Alternative Phone No	OTHERS-91288123

Vehicle Particulars

Manufacturer	BMW
Model	X1
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5094461869
Cover Note Number	

Driver

Name of Driver	LIM DAW WOEI DAVID
NRIC No	S7627822I
Date Of Birth	24/08/1976
Occupation	INDOOR
Date Of Driving Pass	14/03/2002
Driving Experience	16 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91288123
Fax Number	
Contact Number	OTHERS-91288123
Email Address	DDWLIM@YAHOO.COM.SG

Address	BLK 302A PUNGGOL PLACE #05-247
Postcode	821302
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN (SELF SKIDDED AND TRAFFIC POLICE CAME (A/20180907/0075)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 07/09/18.

Driver's Signature

(If driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN

CAPITOL PIAZZA CARPARK



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

TOTAL ten cars I know affected
Contact available. please call if needed

I was entering the carpark of Capitol Piazza on 07th Sep 2018. Upon clearing the gantry I proceeded to drive down the ramp. Suddenly the car lose control and started to skid. I applied brakes but it did not brake and the car crash on the side right on the side walls. Upon slowly getting into the carpark after I regain control, I came down the car to check the damage. Minutes later, I noted 2 other car owners with their car damage after coming down. Total, 10 cars was damaged in the process of coming down the ramp. Some cars seems to have bang each other. My car just hit the side wall of the carpark. As we went to the management office of Capitol Piazza to speak to Head of Operations Christopher Ang, Head of Operations of Capitol Investment. His number is 6499 1075. Notice: 9455 9201

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 7/9/18.

1515.

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

07/09/2018

Claim Handling

Accident MT/1010531

Policy No.	3094461869	Vehicle No.	SLR8114R	GST Registration No.	
Certificate No.					
Policyholder Name	LIM DAW WOEI DAVID			Policyholder NRIC	S76278221
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	91288123	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	No *
KFK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	50	Private Hire	No
Accident Details					
Report Date	07/09/2018 18:03	Accident Report Within 24 hrs	Yes	Accident Type	Collided into Property
Date of Accident	07/09/2018	Time of Accident (H:M:S)	09:10	Country of Accident	Singapore
Reporting Centre		Orange Force		ICM No.	
Accident Location	CAPITOL PIAZZA CAR PARK GANTRY				
Excess					
Own damage Excess	600.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	800.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		
Benefits					
GST Registered Information					
GST Registered	No	GST Registration Data		Yes	
GST Registration No.		GST Status Verified			
Modification History					
Policyholder Mailing Address					
Address 1	BLK 302A #05-247	Address 2	PUNGGOL PLACE	Address 3	CORALINUS
Address 4	SINGAPORE 821302	Address Type	Singapore address	Post Code	821302
Unit No.		Related Policy Number	3094461869		
DI Driver Info					
Driver Name	DAVID LIM DAW WOEI	Driver Type	Main Driver	Driver DOB	24/06/1976
Unnamed driver Name		Driver NRIC	S76278221	Driving Experience	16
Register Date of Driver License	14/03/2002	Driver Age	42	Contact No.(Home)	
Contact No.(Mobile)	91288123	Contact No.(Office)		Address 3	CORALINUS
Address 1	BLK 302A #05-247	Address 2	PUNGGOL PLACE	Post Code	821302
Address 4	SINGAPORE 821302	Address Type	Singapore address		
Unit No.					
Does he own a Singapore Registered car?	☒ Yes ☐ No	Driver Vehicle No.	SLR8114R	Driver Insurer Company	NTUC
Declaration					
Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☒ No		

Modification History

Claim 001 OD-MX

New

Claim Type *	OD-MX	Insured Name	LIM DAW WOEI DAVID	Insured NRIC	S762
Contact No.(Mobile)	91288123	Contact No.(Home)	65821431	Contact No.(Office)	
Email Address	ddwlim@yahoo.com.sg	OT		TP	
Claim Description	SLR8114R / - ON 7 Sept 2018				
Preferred Workshop		Insured Liability	Not at Fault	GIA report	Received
Workshop No.		Repaired			
Finalisation	Yes	Option	Preferred Workshop, Name unknown		
Date Registered	07/09/2018 17:14	Claim Close Date		Date Received	07/09/2018
Report Taken By	ROSLI WAHAB	Workshop Repairer		Total Loss Out. Repaired	
☒ Print AK letter					

Save Submit

Attachment

Accident No.	MT/1010531	Claim No.	001
Last Doc. Received	☒ Yes ☐ No	Upload Date	07/09/2018 17:16
Path *		Category *	Confidential
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Message Read		Clear	Please Select

Attachment List

Attachment	Uploaded By/Date	Category	Urgency	Description

ASSIGNMENT 1/2017-2018

By Assessor- 1) Vehicle Information

- 1) Vehicle hit Vehicle:
 - a) Motorcycle ()
 - b) Bicycle ()
- 2) Vehicle hit ?
 - a) Pedestrian ()
 - b) Animal ()
- 3) Vehicle hit Road Side Object:
 - a) Govt. Property ()
(Eg: signboard, barrier, etc.)
 - b) Road Work Object ()
 - c) Private Property ()
- 4) Vehicle drop into drain ()
- 5) Damage due to Act of God:
 - a) Fallen Object ()
 - b) Flood ()
 - c) Other, _____
- 6) Parked & Found Damaged:
 - a) Vandalism ()
 - b) Hit by Moving Object ()
- 7) Theft Case
 - a) Stolen ()
 - b) Damage found when recovered ()
- 8) Fire
 - a) Whilst driving ()
 - b) Parked ()
- 9) Accident date more than 24hrs ()

Remarks for internal information

Remarks to appear in Works Order & Assessment report

- 1) Potential Total Loss ()
- 2) SRS Light on ()
- 3) ABS Light on ()

By Assessor- 2) Comments

Veh. No: SLR 8114R Date: APRIL 20/2
 Type: M.Cycle / M.Cycle / Bus / Van / Lorry / Taxi / Private Motor / Truck / Trailer or
 Make & Model: Bmw
 Colour: METALLIC BROWN Transmission Type: Auto / Manual
 Eng. No: A3280144N20320A Sp. Reading: 103878
 C/Nr: WBAVL90090VL60950
 Gen. Cond: Good / Fair / Poor / Burnt or
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: RH / S/Rim / STD A/Rim or
 Tyre Size: F: 225/45 R18
 R: 225/45 R18
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front: 7 mm Rear: 7 mm
 R/Bal. 7 mm L/Bal. 7 mm

Parallel Import: Yes / No Towed-In: Yes / No
 Repair Type: LS / I.B.I Towing Required: Yes / No
 No of Repair Days: 7 Vehicle in Idac: Yes / No
 D.O.I. 10/09/2018 Time: 1600

By Assessor- 2) Comments

- 1) Damages not due to recent accident.
- 2) Damages do not seem hit onto:
 - a. Vehicle () b. Motorcycle () c. Bicycle () d. Pedestrian ()
 - e. Animal () f. Govt. Object () g. Road Work Object ()
 - h. Private Property () i. Drain () j. Road Kerb/Grass Verge ()
- 3) Vehicle does not seem damaged as a result of:
 - a. Fallen Object () b. Flood () c. Vandalism () d. Fire ()
 - e. Moving Object () f. Stolen () g. Stolen & Recovered ()

Time Started: _____ Time completed: _____
 1) CSO _____
 2) ASB _____
 3) Entire Coordination Completed Time: _____

MOTORCAR (Rear)

Vehicle No: SLR 811/R

Rear Portion

NAC	INC	Item	CON	ACQ	QTY
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	/	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NAC	/	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	NAC	/	
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector	RF	7	
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor		7	
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish	7		
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	ACQ	QTY
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	995507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender	DD	RR	
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim	an	/	
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

Rear RH Wheel Rim
Protractor

11/24/2011 (X) 11/24/2011 (Y)
SC: SUR 8714K

NAC	INC	Item	CON	ACQ
1071	992205	Fuse Box		
1072	994011	Relay Box		
1073	995053	Wiper Washer Tank		
1074	993052	Wiper Washer Tank Motor		
1075	990159	Alternator Assy		
1076	990160	Alternator Belt		
1077	992638	Power Steering Pump		
1078	992669	Power Steering Belt		
1079	994431	Power Steering Cooler Pipe		
1080	992692	Power Steering Hose		
1081	990910	ABS Pump Control Unit		
1082	990427	Brake Master Pump Assy		
1083	990403	Brake Booster Pump Assy		
1084	991005	Engine Top Cover		
1085	991011	Engine Under Cover		
1086	990946	Engine Mounting		
1087	990949	Engine Mounting Frt		
1088	990950	Engine Mounting LH		
1089	990952	Engine Mounting RH		
1090	990951	Engine Mounting Rear		
1091	992234	Gear Box Mounting		
1092	991520	Frt LH Chassis Member		
1093	991520	Frt RH Chassis Member		
1094	990728	Frt Vertical Cross Member		
1095	991863	Frt Lower Cross Member		
1096	995070	Frt LH Fender		
1097	995072	Frt LH Fender Inner Panel		
1098	995147	Frt LH Fender Lamp		
1099	995148	Frt LH Fender Protector		
1100	991740	Frt LH Fender Inner Shield		
1101	995179	Frt LH Mudflap		
1102	995170	Frt LH Wheel Rim		
1103	994025	Frt LH Rim Cover		
1104	995065	Frt LH Tyre		
1105	995071	Frt RH Fender	DD	
1106	991739	Frt RH Fender Inner Panel		
1107	991744	Frt RH Fender Lamp		
1108	991752	Frt RH Fender Protector		
1109	991740	Frt RH Fender Inner Shield		
1110	991884	Frt RH Mudflap		
1111	992087	Frt RH Wheel Rim	CD	
1112	994025	Frt RH Rim Cover		
1113	995065	Frt RH Tyre		
1114	992093	Frt Windscreen Glass		
1115	992117	Frt Windscreen Rubber		
1116	992108	Frt Windscreen Moulding		
1117	992098	Frt Windscreen Sealant		
1118	991019	ERP Bracket		
1119	991020	ERP Unit		
1120	992140	Frt Wiper Arm		
1121	992142	Frt Wiper Blade		
1122	995045	Wiper Panel Garnish		
1123	991126	Firewall Panel		
1124	990753	Dashboard Assy		
1125	992282	Glove Box Cover		
1126	992281	Glove Box Compartment		
1127	994483	Steering Wheel Airbag		
1128	994485	Steering Wheel Airbag Sensor		
1129	990745	Dashboard Airbag		
1130	990750	Dashboard Airbag Sensor		
1131	990020	Airbag Control Unit		
1132	990864	Frt Driver Seat		
1133	991932	Frt R/L Seat Belt Assy		
1134	991899	Frt Passenger Seat		
1135	995182	Frt LH Seat Belt Assy		
1136	990247	Sticker		

original copy

Claim Handling

Task Transfer Exit

LOS SAL SLR

Accident MT/1010531

Policy No.	5094461869	Vehicle No.	SLR8114R	GST Registration No.	
Certificate No.					
Policyholder Name	LIM DAW WOEI DAVID			Policyholder NRIC	576278221
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	91288123	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	No *
KFK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	50	Private Hire	No

Accident Details

Report Date	07/09/2018 16:03	Accident Report Within 34 hrs	Yes	Accident Type	Collided Into Property
Date of Accident	07/09/2018	Time of Accident hh:mm	09:10	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTRE	Orange Force	No	ICM No.	
Accident Location	CAPITOL PIAZZA CAR PARK GANTRY				

Excess

Own damage Excess	600.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	600.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		

Benefits

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

Policyholder Mailing Address

Address 1	BLK 302A #05-247	Address 2	PUNGGOL PLACE	Address 3	CORALINUS
Address 4	SINGAPORE 821302	Address Type	Singapore address	Post Code	821302
Unit No.		Related Policy Number	5094461869		

O1 Driver Info

Driver Name	DAVID LIM DAW WOEI	Driver Type	Main Driver	Driver DOB	24/08/1978
Unnamed driver Name		Driver NRIC	576278221	Driving Experience	16
Register Date of Driver License	14/03/2002	Driver Age	42	Contact No.(Home)	
Contact No.(Mobile)	91288123	Contact No.(Office)		Address 3	CORALINUS
Address 1	BLK 302A #05-247	Address 2	PUNGGOL PLACE	Post Code	821302
Address 4	SINGAPORE 821302	Address Type	Singapore address		
Unit No.					
Does he own a Singapore Registered car?	☒ Yes ☐ No	Driver Vehicle No.	SLR8114R	Driver Insurer Company	NTUC

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☒ No
-------------------------------------	------	-------------	---

Modification History

Investigation

Claim 001 OD-MD

Claim Case Officer Tan Siew Choo

LOS SAL SLR

Claim Type	OD-MD	Insured Name	LIM DAW WOEI DAVID	Insured NRIC	576278221
Contact No.(Mobile)	91288123	Contact No. (Home)	63821431	Contact No. (Office)	
Email Address	ddwlim@yahoo.com.sg	O1 Vehicle Number	SLR8114R	TP Vehicle Number	
Claim Description	SLR8114R / - ON 7 Sept 2018			Name of Preferred Workshop	
Preferred Workshop	☒ Yes ☐ No	Preferred Repair Option	☐ Yes ☒ No	Preferred Workshop Name	unknown
Insured Liability report	☐ Insured ☒ Not at fault	07/09/2018 17:19	Claim Close Date	Date Received	11/09/2018 10:44
Report Taken By	ROSLI WAHAB	Workshop Repairer		Total Loss but Repaired	
☒ Print AK letter				OD Excess Collected by Workshop	
Modification History	11/09/2018 08:50 6069588 Modify Claim Type(OD-MD-->OD-MD)				

Special Claim Creation Approval

Approval	Reason
Remarks	

damage assessment Activity Handling Attachment

Vehicle Info

Vehicle Make	BMW	Vehicle Model	X1	Engine Capacity	
Date of Registration	30/04/2012	Classis No.	WBAVL92090VL60950		
Towing Required *	☐ Yes ☒ No	Vehicle in IDAC *	☐ Yes ☒ No	Parallel Import *	☐ Yes ☒ No
Type of Tender	Own Damage	Assessor Name *	ROSLI WAHAB	Survey Current Status	

IDAC/Workshop Name NATIONAL ASSESSMENT CENTRE

IDAC/Workshop Location

51 UBI AVENUE 1 #01-25 PAVA

Windscreen
Parts & Labour
Cost

Total Loss *

☐ Yes ☒ NoMarket
Value(\$)

Scrap Value(\$)

Economic Repair Value(\$)

Remark

OWNER PREFERED MOVA TO BE THE WORKSHOP THANKS.

Remark for
Supplementary

▼ Damage Listing

Find a Part	No.	Part No.	Description	Qty *	Repair Code *	
root						
Not Applicable	1	16000101	BUMPER (FRONT)	1	Repair	☒
ABS	2	16000102	BUMPER (REAR)	1	Replace	☒
ABSORBER	3	16001301	BUMPER BRACKET (FRONT LEFT)	1	Unconfirm	☒
ACCELERATOR	4	16001302	BUMPER BRACKET (FRONT RIGHT)	1	Unconfirm	☒
ACTUATOR	5	16002401	BUMPER CLIPS (FRONT)	1	Replace	☒
ADVERTISEMENT STICKER	6	16002402	BUMPER CLIPS (REAR)	1	Replace	☒
AIR BAG	7	16005102	BUMPER RETAINER (FRONT RIGHT)	1	Replace	☒
AIR BLOWER	8	16005104	BUMPER RETAINER (REAR RIGHT)	1	Replace	☒
AIR BOX	9	16005002	BUMPER REINFORCEMENT (REAR)	1	Unconfirm	☒
AIR CHAMBER BOX	10	16005501	BUMPER SENSOR (FRONT)	1	Unconfirm	☒
AIR CLEANER	11	16002902	BUMPER FOG LAMP COVER (FRONT RIGHT)	1	Replace	☒
AIR COMPRESSOR	12	16004904	BUMPER REFLECTOR (REAR RIGHT)	1	Unconfirm	☒
AIR CON	13	16005502	BUMPER SENSOR (REAR)	1	Unconfirm	☒
AIR CON (VAN)	14	420002	TAIL LAMP GARNISH	1	Unconfirm	☒
AIR COOLER	15	27700102	HEAD LAMP (RIGHT)	1	Replace	☒
AIR DISTRIBUTOR	16	25400103	FENDER (FRONT RIGHT)	1	Replace	☒
AIR FILTER	17	25400106	FENDER (REAR RIGHT)	1	Repair	☒
AIR FLOW	18	25400902	FENDER INNER SHIELD (FRONT RIGHT)	1	Unconfirm	☒
AIR GRILLE	19	25400904	FENDER INNER SHIELD (REAR RIGHT)	1	Unconfirm	☒
AIR HORN	20	448014	WHEEL RIM	2	Replace	☒
AIR INTAKE	21	44800404	WHEEL ARCH PROTECTOR (REAR RIGHT)	1	Replace	☒
AIR RESONATOR BOX	22	43600102	TYRE (FRONT RIGHT)	1	Unconfirm	☒
AIR THROTTLE BODY AND SENSOR	23	43600104	TYRE (REAR RIGHT)	1	Unconfirm	☒
ALARM						
ALTERNATOR						
ALUMINIUM PANEL - SIDE						
AMPLIFIER						
ANTENNA						
ANTI ROLL						
APRON						
ARCH						

ACCIDENT STATEMENT

ACCIDENT DATE: (07/09/2018) (DD/MM/YYYY), TIME: (09:10) (HH:MM)

LOCATION: CAPITAL PLAZA

1. DETAILS OF VEHICLE

- a) VEHICLE NUMBER: SLR 8114R
 b) INSURANCE COMPANY: NTUC
 c) POLICY NUMBER: 8094461869
 d) POLICY TYPE: COMPREHENSIVE THIRD PARTY / THIRD PARTY FIRE & THEFT
 e) MAKE & MODEL: BMW X1 5011R 20i
 f) TYPE: SALOON / COUPE / MPV / VAN / LORRY / MOTORCYCLE / OTHERS
 g) VEHICLE CATEGORY: PRIVATE / COMMERCIAL / MOTORCYCLE
 h) PURPOSE OF USING AT ACCIDENT TIME: PRIVATE USE
 i) ARE YOU CLAIMING UNDER YOUR OWN INSURANCE (YES/NO)
 IF NO, PLEASE STATE THIRD PARTY CLAIM / REPORTING ONLY

2. INSURED / POLICY HOLDER

- a) NAME: DAVID LIM DAW WOEI (MALE / FEMALE)
 b) NRIC/FIN/PASSPORT: 576278222 CONTACT: 91288123
 c) ADDRESS: BLK 302 PUNCEOL PLACE #05-247

* CONTINUE TO 3.d IF DRIVER ALSO POLICY HOLDER

DRIVER

- a) NAME: (MALE / FEMALE)
 b) NRIC/FIN/PASSPORT: CONTACT:
 c) ADDRESS:

* d) DATE OF BIRTH: (24/08/1976) (DD/MM/YYYY)

e) OCCUPATION: INDOOR / OUTDOOR

f) DATE OF DRIVING PASS: 14 MAR 2002

4. WAS DRIVER AN EMPLOYEE OF THE INSURED'S COMPANY? (YES / NO)
 IF NO, RELATIONSHIP OF THE DRIVER WITH INSURED:

5. a) WEATHER CONDITION: CLEAR / RAINING / OTHERS
 b) ROAD SURFACE: DRY / WET / OTHERS

6. WAS ANYBODY INJURED (YES / NO)

7. a) REPORTED TO POLICE (YES / NO)

IF YES, PLEASE STATE WHICH POLICE STATION:

A2018 09 07
 TP CAME. POLICE REF 0075

8. THIRD PARTY VEHICLE

- a) VEHICLE NUMBER: MODEL:
 b) DRIVER'S NAME:
 c) NRIC/FIN/PASSPORT: CONTACT:

9. THIRD PARTY VEHICLE

- d) VEHICLE NUMBER: MODEL:
 e) DRIVER'S NAME:
 f) NRIC/FIN/PASSPORT: CONTACT:

EMAIL =

VIDEO =

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S76278221



Name

DAVID LIM DAW WOEI
(LIN DAOWEI)

林道伟

Race
CHINESE

Date of birth Sex
24-08-1976 M

Country of birth
SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number S76278221

DAVID LIM DAW WOEI
(LIN DAOWEI)

Birth Date: 24 Aug 1976

Issue Date: 29 Jan 2018



3956956

NRIC No. S76278221



Date of issue
09-11-2006

APT BLK 302A PUNGGOL PLACE #05-247
SINGAPORE 621302

NRIC No: S76278221

Date: 08/02/2010

No: 6378337

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor cars with unladen weight $\leq 3000\text{kg}$ with ≤ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq 2500\text{kg}$ 14 Mar 2002

NP 428A



Hello, NAC_BUKIT_MERAH_800676

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.		Date of Accident	07/09/2018 15:05
Vehicle No.(For Motor)	SLR8114R	Certificate Number	
Search			

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☒	5094461869		LIM DAW WOEI DAVID	S7627822I	GPC	drive CLASSIC	SLR8114R	SLR8114R	28/09/2017	29/10/2018

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MUA418116088 Vehicle Registration No: SLR 8114R
Name (as shown in NRIC): Lim Daw Wei David NRIC/FIN/Passport No: S76278221
(*Vehicle Driver / Vehicle Owner) () Please delete as appropriate
Address: _____ Singapore ()
Contact (Tel): _____ Mobile No.: 91288123
Email Address: _____
Date of Accident: _____ Time of Accident: _____
Place of Accident: CARPARK PLAZA CAR PARK GALLERY
Insurance Company: M7UC

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

WHICHVERL CONVENTION SHOULD BE REMINDER & WHT

Policyholder / Driver's Signature
Date:

Reporting Centre Personnel's Signature
Name: Rafael Yip
NRIC/FIN No: 10691248
Date:

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MMAY1816088-01 Vehicle Registration No: SLR 8114R
Name (as shown in NRIC): DAVID LIM DAW WOE NRIC/FIN/Passport No: S7627622J
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address: BLK 302A PINGHOL PLACE #05-247 Singapore 821302
Contact (Tel): - Mobile No.: 91288123
Email Address: ddwlim@yahoo.com.sg
Date of Accident: 7th Sep 2018 Time of Accident: about 0910
Place of Accident: Capitol Pinzee Carpark Ramp down
Insurance Company: NTUC

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

From third party to own damage
claim. To make recovery from
third party.

Prefer Move Workshop to do repair.
Spoken to NTUC Customer Service.
Thanks!

Policyholder / Driver's Signature
Date: 10/09/18

Reporting Centre Personnel's Signature
Name: Rogel Winters
NRIC/FIN No.: 10/09/2018
Date: