

(08/11/13) wef

ASS. DEC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 5728387at Workshop m/s H.

of _____

Insured: SLM 91080Policy No. 29069766 MKFClaims No. 572103

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 5728387 Yr Regn: 1/16Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Honda verel cc 1496Colour: white A/C: Insured / Std / NI / NASp. Reading 119419 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU31110853Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NI / S/Rim / STD A/Rim orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO orFront 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 8/9/18 D.O.I. 10/9/18

Survey held at _____

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop orRear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27A 44202 have LIA11/9/18 Email GIA to Iyanni / Yi Qian28/9/18 4/5 4000 costed at the shop for 15,316,7994/10/18 Send preli revised via merimen

RECEIVED 04 OCT 2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 4/10 - typistDays Of Repair: 4Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

TOTAL

Report Format: merimenLump Sum / I.B.I. (\$) 4000

200

10

210

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Int Auth'es	Status
Main	10 Sep 2018		04 Oct 2018 09:10 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Grab Rentals Pte. Ltd., Co. Reg. No.: 201617200G								
Main Claimant:	LECCA CAR LEASING, Co. Reg. No.: 53247626C								
Vehicle Reg. No.:	SJL838T	Date of Loss:	08/09/2018 09:00 - :59 [31 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 572103	Policy/Cover Note No.:	29069766MKF (Comprehensive) Coverage: 01/02/2018 - 31/01/2019						
Vehicle Reg. No. (Insured):	SLM9108D	Policy No. (Claimant):							
		Excess:							
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by NG CHEN HOW - 6643 1391]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 05/10/2018]								
Adj Asg. Remarks:	direct survey by LKK. survey done on 10.09.2018.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (04/10/2018): Cancellation of Assignment: SJL838T 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAUTO)

From: Low Yi Qian <yiqian_low@sg.msig-asia.com>
Sent: Thursday, 4 October 2018 9:12 AM
To: Veron Chen (LKKAUTO)
Cc: SUR
Subject: RE: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD,DOA: 8/9/2018, SJL 838T (TP VEHICLE), SLM 9108D (OI VEHICLE) Claim Ref: 572103

Hi Veron


Merimen created. Claim No: 572103

FYI, our insured have not reported.

Thank you and have a great day ahead!

Best Regards
Low Yi Qian
Administrative Officer
Claims Services Department
Direct line +65 6594 2525 | Direct fax +65 6225 7402 | yiqian_low@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msig.com.sg | Follow us on  @MSIG_SG

A member of **MS&AD** INSURANCE GROUP

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Thursday, 4 October, 2018 8:38 AM
To: Iryani Amin <iryani_amin@sg.msig-asia.com>; Low Yi Qian <yiqian_low@sg.msig-asia.com>
Cc: SUR <sur@lkkauto.com>
Subject: FW: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD,DOA: 8/9/2018, SJL 838T (TP VEHICLE), SLM 9108D (OI VEHICLE)

Dear Iryani/Yi Qian,

Kindly create claim in merimen for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 11 September 2018 2:49 PM
To: Low Yi Qian <yiqian_low@sg.msig-asia.com>; Iryani_amin@sg.msig-asia.com
Cc: SUR <sur@lkkauto.com>; Accounts (LKKAUTO) <account@lkkauto.com>; KKLau <kklau@lkkauto.com>
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 8/9/2018, SJL 838T (TP VEHICLE), SLM 9108D (OI VEHICLE)

Dear Iryani/Yi Qian,

Please be informed that we had inspected the vehicle SJL 838T M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883 on 10/9/2018

Enclosed herewith a copy of TP's GIA report and estimated cost of repair will forward to you shortly.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 11 September 2018 2:49 PM
To: Low Yi Qian; iryani_amin@sg.msig-asia.com
Cc: SUR; Accounts (LKKAuto); KKLau
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD,DOA: 8/9/2018, SJL 838T (TP VEHICLE), SLM 9108D (OI VEHICLE)
Attachments: GIA.pdf

Dear Iryani/Yi Qian,

Please be informed that we had inspected the vehicle SJL 838T M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6,#01-46/48/50 AUTOBAY SINGAPORE 417883 on 10/9/2018

Enclosed herewith a copy of TP's GIA report and estimated cost of repair will forward to you shortly.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: NG CHEN HOW

Date: 04 Oct 2018

Preliminary Advice

Insured Vehicle No	: SLM9108D		
TP Vehicle No	: SJL838T	Accident Date	: 08/09/2018
Make	: HONDA VEZEL	Assignment Date	: 04/10/2018
Date of Inspection	: 10/09/2018	Est. Duration of Repair	: 4.00
Inspection At	: FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,316.00
Revised Amount	:S\$	4,000.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,000.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(x) The above survey was conducted on a 'without prejudice' basis.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business

Owner ID: 7626C

Vehicle Details

Vehicle No.: SJL838T

Vehicle to be Exported: No

Intended Deregistration Date: 10 Sep 2018

Vehicle Make: HONDA

Vehicle Model: VEZEL 1.5X HYBRID A

Primary Colour: White

Manufacturing Year: 2015

Engine No.: LEB5060862

Chassis No.: RU31110853

Maximum Power Output: 112.0 kW (150 bhp)

Open Market Value: \$22,769.00

Original Registration Date: 19 Jan 2016

First Registration Date: 19 Jan 2016

Transfer Count: 0

Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 18 Jan 2026

PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 18 Jan 2026

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$55,001.00

COE Rebate Amount: \$40,452.00

Total Rebate Amount: \$44,202.00

The information contained herein is correct as at 10 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/09/2018 11:41
Date Of Accident	08/09/2018 09:00
Exact Location Of Accident	ALONG PASIR RIS DRIVE 12
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJL838T
Insured/Policyholder	
Name Of Registered Owner	LECCA CAR LEASING
Co Reg No	53247626C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96176311

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 X HYBRID CVT (A)
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	VCX/P1714235
Cover Note Number	

Driver

Name of Driver	LOH MIN HOE
NRIC No	S1583079D
Date Of Birth	25/07/1963
Occupation	OUTDOOR
Date Of Driving Pass	09/03/1982
Driving Experience	36 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96176311
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 776 PASIR RIS STREET 71 #08-404 SPORE 510776

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions RAINING

Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLM9108D

Vehicle Make/Model/Colour TOYOTA PRIUS HYBRID 1.8 CVT

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be based outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: J. K. N.
NRIC/TPN No.: S82174233311

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 8/4/18 at 9am. I was driving my vehicle A along Park Drive 12. I stop my car at the traffic light. Suddenly vehicle B hit my rear portion.

DECLARATION


I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: J. S. S. S.
NIC/FIN No: 502403772

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 8/9/18 at 9am, I was driving my vehicle A
 along Pasir Ris Drive 12. I stop my car at the traffic
 light. Suddenly vehicle B hit on my rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

LECCA
CAR LEASING



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Date of Accident : 8/9/18 Accident Time: 9am (24-HR-Format)
Accident Place : Along Pasir Ris Drive 12
Vehicle No. (Car Plate No.) : SJL 838T Make/Model: Honda Vezel
Insurance Company : AXA Policy No: P1714235
Owner or Company Name /IC No. : LECCA Car Leasing
Owner or Company Contact No. : _____ Owner's Hp _____ Company Tel _____
DRIVER'S Name / IC No. : Loh Min Hoe /S1583079D
DRIVER'S Date Of Birth : 25/7/1963 DRIVER'S License Pass Date 9/3/1982
Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: _____
DRIVER'S Address : Blk 776 Pasir Ris St 71 #08-404
DRIVER'S Contact No./ Alt No. : 1) 96176311 2) 5510776
DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)
Email Address : _____
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance
Number of Passengers (Including Driver): 1 driver
Was there any video Captured by car camera: YES \ NO
Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose
Any Injury (If YES, Pls state): NO

Other Party Driver's Particular (if any)

Vehicle No: <u>SLM 9108D</u> <u>Casib</u>	Vehicle No: _____
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name Driver: _____	Name Driver: _____
IC No. Driver/Contact: _____	IC No. Driver/Contact: _____

* NEW - Passenger's name & gender:

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

STL 838T

Not Allowed
Star
10/9/18
2/s = 4000
4000

List Item:

1 PCS	REAR WINDSCREEN MOULDING
1 PCS	TAILGATE
1 PCS	TAILGATE OUTER HANDLE GARNISH
1 PCS	TAILGATE 'H' LOGO
2 PCS	TAILGATE REFLECTORS @\$280
1 PCS	TAILGATE 'VEZEL' EMBLEM
1 PCS	TAILGATE INNER LOCK
1 PCS	TAILGATE LOCK STRIKER
1 PCS	TAILGATE INNER TRIM BOARD
1 SET	TAILGATE INNER TRIM BOARD CLIPS
1 PCS	TAILGATE WEATHERSTRIP
1 PCS	TAILGATE KEYLESS SENSOR
1 PCS	REAR BUMPER CENTRE
2 PCS	REAR BUMPER SIDES @\$235.10
2 PCS	REAR BUMPER SIDE RETAINERS @\$35.20
2 PCS	REAR BUMPER SCREW SPACERS @\$12
2 PCS	REAR BUMPER REFLECTORS @\$151.20
2 PCS	TAILLAMPS @\$460.60
2 PCS	TAILLAMP HOUSING PANELS @\$195
1 PCS	REAR END PANEL
1 PCS	REAR END PANEL TOP GARNISH
1 PCS	REAR BUMPER LOWER DIFFUSER
1 SET	REAR BUMPER LOWER DIFFUSER CLIPS
1 PCS	REAR EXHAUST
2 PCS	REAR EXHAUST MOUNTINGS @\$45
1 PCS	REAR EXHAUST HEAT SHIELD
2 PCS	REAR FENDER INNER TRIMS @\$295.30
1 SET	REAR FENDER INNER TRIM CLIPS
2 PCS	REAR FENDER OUTER GARNISH @\$195.80
1 PCS	REAR FLOOR PANEL
1 PCS	REAR FLOOR PANEL TOOLS SPONGE
2 PCS	REAR FENDERS @\$1100

List Item Total:

rec	\$	121.30	—
Body	\$	1,100.90	—
11	\$	285.30	X
11	\$	35.80	X
11	\$	560.00	X
rec	\$	56.20	—
11/11/11	\$	198.50	—
11	\$	25.50	X
2/cu	\$	321.70	—
rec	\$	50.00	—
11/1	\$	135.70	—
cu	\$	180.00	—
11/11	\$	762.70	—
11	\$	470.20	X
11	\$	70.40	X
11	\$	24.00	X
11	\$	302.40	X
11	\$	921.20	X
2	\$	390.00	X
11	\$	514.00	X
11/1	\$	125.00	—
11	\$	348.20	X
11	\$	50.00	X
11	\$	899.20	X
11	\$	90.00	X
11	\$	98.30	X
11	\$	590.60	X
11	\$	50.00	X
2/cu	\$	391.60	—
11	\$	912.30	X
11	\$	685.00	X
11	\$	2,200.00	X
	\$	12,966.00	

207

3296
2636.8

Special Nett Item:

1 SET	REAR BUMPER REVERSER SENSOR
1 PCS	REAR REVERSE CAMERA
1 PCS	REAR WINDSCREEN SEALANT
1 PCS	REAR END PANEL SEALANT
1 PCS	REAR FLOOR PANEL INSULATOPR

Special Nett Total:

shut	\$	280.00	200
shut	\$	500.00	380
rec	\$	50.00	40
11	\$	50.00	X
11	\$	180.00	X
	\$	1,060.00	620

Labour Charge:

TO CHECK WIRING

\$ 80.00 30

TO DISMANTLE & REPLACE REVERSE SENSOR
 TO TRANSFER TAILGATE MECHANISM
 TO DISMANTLE & REFIX REAR WINDSCREEN
 TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY
 TO DISMANTLE & REPLACE REAR EXHAUST
 TO SPRAY RUST PROOFING
 TO MOUNT VEHICLE ON CAR O-LINER
 TO DISMANTLE & REFIX PETROL TANK
 LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS
 TO PUTTY & SPRAY PAINTING
 Labour Charge Total:

\$	80.00	50
\$	100.00	60
\$	150.00	120
\$	150.00	80
1^ \$	100.00	2
\$	150.00	50
1^ \$	380.00	2
1^ \$	100.00	2
\$	2,000.00	600
\$	2,000.00	780
\$	5,290.00	
		1770

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$ 19,316.00

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)











































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Sep 2018		04 Oct 2018 09:10 Edit Adj Rpt	S\$4,000.00 Edit Estimates	S\$4,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: Grab Rentals Pte. Ltd. , Co. Reg. No.: 201617200G									
Main Claimant: LECCA CAR LEASING , Co. Reg. No.: 53247626C									
Vehicle Reg. No.: SJL838T		Date of Loss: 08/09/2018 09:00 - :59 [31 Months and 20 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 572103		Policy/Cover Note No.: 29069766MKF (Comprehensive) Coverage: 01/02/2018 - 31/01/2019							
Vehicle Reg. No. (Insured): SLM9108D		Policy No. (Claimant):							
		Excess:							
Repairer: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by NG CHEN HOW - 6643 1391]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 03/11/2018]									
Adj Asg. Remarks: direct survey by LKK. survey done on 10.09.2018.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (04/10/2018): Cancellation of Assignment: SJL838T 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJL838T (572103)
[SLM9108D]
TP
LECCA CAR LEASING
Sep 8 2018 9:00AM
[Grab Rentals Pte. Ltd.]
Fastech Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Letters/Correspondences									1 per page		<input checked="" type="checkbox"/>			
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail		Print			
1	04/10/18 09:18	Non Reporting Letter to OI									Load HTML			
Assessment Reports									1 per page		<input checked="" type="checkbox"/>			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print			
1	04/10/18 12:28	Adjuster Immediate Advice									Load HTML			
Photos/Images									3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print			
1	04/10/18 12:21	General View									Load JPG			
2	04/10/18 12:21	General View									Load JPG			
3	04/10/18 12:21	General View									Load JPG			
4	04/10/18 12:21	General View									Load JPG			
5	04/10/18 12:21	General View									Load JPG			
6	04/10/18 12:21	General View									Load JPG			
7	04/10/18 12:21	General View									Load JPG			
8	04/10/18 12:21	General View									Load JPG			
9	04/10/18 12:21	General View									Load JPG			
10	04/10/18 12:21	General View									Load JPG			
11	04/10/18 12:21	General View									Load JPG			
12	04/10/18 12:21	General View									Load JPG			
13	04/10/18 12:21	General View									Load JPG			
14	04/10/18 12:21	General View									Load JPG			
15	04/10/18 12:21	General View									Load JPG			
16	04/10/18 12:21	General View									Load JPG			
17	04/10/18 12:21	General View									Load JPG			
18	04/10/18 12:21	General View									Load JPG			
19	04/10/18 12:21	General View									Load JPG			
20	04/10/18 12:21	General View									Load JPG			
21	04/10/18 12:21	General View									Load JPG			
22	04/10/18 12:21	General View									Load JPG			
23	04/10/18 12:21	General View									Load JPG			
24	04/10/18 12:21	General View									Load JPG			
25	04/10/18 12:21	General View									Load JPG			
26	04/10/18 12:21	General View									Load JPG			
27	04/10/18 12:21	General View									Load JPG			
28	04/10/18 12:21	General View									Load JPG			
29	04/10/18 12:21	General View									Load JPG			
30	04/10/18 12:21	General View									Load JPG			

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
31	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
32	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
33	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
34	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
35	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
36	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
37	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
38	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
39	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
40	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
41	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
42	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
43	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
44	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
45	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
46	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
47	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
48	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
49	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
50	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
51	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
52	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
53	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
54	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
55	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
56	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
57	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
58	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
59	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
60	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
61	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
62	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
63	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
64	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
65	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
66	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
67	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
68	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
69	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
70	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
71	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
72	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
73	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
74	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
75	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
76	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
77	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
78	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
79	04/10/18 12:21	General View		<input checked="" type="checkbox"/>
80	04/10/18 12:21	General View		<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
81	04/10/18 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
82	04/10/18 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
83	04/10/18 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
84	04/10/18 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
85	04/10/18 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
86	04/10/18 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
87	04/10/18 12:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	04/10/18 12:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	04/10/18 12:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	04/10/18 12:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	04/10/18 12:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	04/10/18 12:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	04/10/18 12:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	04/10/18 12:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	04/10/18 12:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18016416/UVBE2

Date: 05/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29069766MKF

Claimant Vehicle No: SJL838T

Insured Vehicle No: SLM9108D

Date of Loss: 08/09/2018

Nature of Claim: TP

Claim No: 572103

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJL838T

Make & Model: HONDA VEZEL, 1.5 X HYBRID CVT (A)

Engine No: LEB5060862

Reg. Date: 19/01/2016 (Man. Year: 2015)

Chassis No: RU31110853

Colour: White

Odometer: 119419 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,026.00	3,256.80	10,769.20	76.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,290.00	1,770.00	3,520.00	66.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,316.00	5,026.80	14,289.20	73.98
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	19,316.00	4,000.00	15,316.00	79.29
+ GST 7.00/7.00% (S\$)	1,352.12	280.00	1,072.12	79.29
Nett Amount (S\$)	20,668.12	4,280.00	16,388.12	79.29

INSPECTION

Date of Assignment: 04/10/2018

Date Inspected: 10/09/2018 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Oct 2018)
Parts:	M1-SUV	HONDA VEZEL 1.5 X HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL838T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	121.30 F	*121.30 FL
2	1		*TAILGATE	Badly Dented	1,100.90 F	*953.30 FL
3	1		*TAILGATE OUTER HANDLE GARNISH	Not Necessary	285.30 F	*- FL
4	1		*TAILGATE H LOGO	Not Necessary	35.80 F	*- FL
5	2		*TAILGATE REFLECTORS	Not Necessary	560.00 F	*- FL
6	1		*TAILGATE VEZEL EMBLEM	Necessary	56.20 F	*56.20 FL
7	1		*TAILGATE INNER LOCK	Twisted / Shorted	198.50 F	*198.50 FL
8	1		*TAILGATE LOCK STRIKER	Not Necessary	25.50 F	*- FL
9	1		*TAILGATE INNER TRIM BOARD	Deformed / Cracked	321.70 F	*321.70 FL
10	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
11	1		*TAILGATE WEATHERSTRIP	Twisted	135.70 F	*135.70 FL
12	1		*TAILGATE KEYLESS SENSOR	Cracked	180.00 F	*180.00 FL
13	1		*REAR BUMPER CENTRE	Dented / Deformed	762.70 F	*762.70 FL
14	2		*REAR BUMPER SIDES	Not Necessary	470.20 F	*- FL
15	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	70.40 F	*- FL
16	2		*REAR BUMPER SCREW SPACERS	Not Necessary	24.00 F	*- FL
17	2		*REAR BUMPER REFLECTORS	Not Necessary	302.40 F	*- FL
18	2		*TAILLAMPS	Not Necessary	921.20 F	*- FL
19	2		*TAILLAMP HOUSING PANEL	Repair	390.00 F	*- FL
20	1		*REAR END PANEL	Repair	514.00 F	*- FL
21	1		*REAR END PANEL TOP GARNISH	Twisted	125.00 F	*125.00 FL
22	1		*REAR BUMPER LOWER DIFFUSER	Not Necessary	348.20 F	*- FL
23	1		*SET REAR BUMPER LOWER DIFFUSER CLIPS	Not Necessary	50.00 F	*- FL
24	1		*REAR EXHAUST	Not Necessary	899.20 F	*- FL
25	2		*REAR EXHAUST MOUNTINGS	Not Necessary	90.00 F	*- FL
26	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	98.30 F	*- FL
27	2		*REAR FENDER INNER TRIMS	Not Necessary	590.60 F	*- FL
28	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 F	*- FL
29	2		*REAR FENDER OUTER GARNISH	Deformed / Torn	391.60 F	*391.60 FL
30	1		*REAR FLOOR PANEL	Not Necessary	912.30 F	*- FL
31	1		*REAR FLOOR PANEL TOOLS SPONGE	Not Necessary	685.00 F	*- FL
32	2		*REAR FENDERS	Repair	2,200.00 F	*- FL
33	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
34	1		*SET REAR REVERSE CAMERA	Shorted	500.00 FS	*380.00 FS
35	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
36	1		*REAR END PANEL SEALANT	Not Necessary	50.00 FS	*- FS
37	1		*REAR FLOOR PANEL INSULATOR	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 14,026.00 3,916.00

- List Item Discount on L Items 0.00/20.00% (S\$) 0.00 659.20

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					14,026.00	3,256.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE& REPLACE REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
4	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
5	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY	New	150.00	80.00
6	TO DISMANTLE & REPLACE REAR EXHAUST	New	100.00	0.00
7	TO SPRAY RUST PROOFING	New	150.00	50.00
8	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
9	TO DISMANTLE & REFIX PETROL TANK	New	100.00	0.00
10	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS	New	2,000.00	600.00
11	TO PUTTY & SPRAY PAINTING	New	2,000.00	780.00
Gross Labour Cost (S\$)			5,290.00	1,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >