

ASS. REC. BY:

REF:

CS/AG18016426/ Ugd3/72

Special Instruction:

SURVEY:

ASSIGNMENT (Office) ✓

From (Person):

Mithoo Singh

of

AG

Date/Time:

10/09/18 @ 8:48am

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SV 402P

Insured:

SLT 8886K

at Workshop m/s:

M-Tech Motor

Tel:

9753 4567

of

BLK 9005 Tampines St-93 # 01-252

Policy No:

1700067779

Claim No:

766709819 SSG003

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

03/09/2018

CA / REV / REP. / REV 24 HRS lwp

H.O.D. Endorsement:

Date/Time:

9:55am @ 10/9/18

Person Contacted:

mrchan

Vehicle IN / OUT

Date/Time:

Action/Instruction

(✓)

Estimate

SV 402P - NA / FC11000 413/s/

DoA: 19/01/2010

SLT 8886K - X

REF: **ALG**

ASSIGNMENT

From: **12/9/18**

Estimated Cost:

OD ☒ TP ☐ WS ☐ / TP RES ☐ / OD RES ☐ / EVA ☐ / INV ☐ / MV ☐To Inspect Vehicle No: **SJV 402P**

at Workshop n/s

of **BLK 900S, Tampines St-93 #01-252**Insured: **Tampines Ind. Park A.**

Policy No:

Claims No:


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: **3** days Res: Yes or NoLump Sum: **20** % 3 Val: Yes or No

CA / REV / REP. 1-24 HRS 'up

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: **SJV 402P** Yr Regn: **1 / 10**Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /Truck / Trailer or **CM /**Make: **FIAT DOBLO PANORAMA 136f**Colour: **Blue** A/C: Insured / Std / NI / NASp. Reading: **134933** T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: F:

R: **215-45R17**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **KUMHO**

Front

R/Bal. **6** mmL/Bal. **6** mmD.O.A. **3/9/18**

Survey held at

Rear

R/Bal. **6** mmL/Bal. **6** mmD.O.I. **12/9/18**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: **17/9/18**
Action / Instruction: **LTA 11/10/8**
quely Estimate.**17/9/18 4/5 11/00 confirmed with MR Chan.**
(Red 8 990, 33%)

RECEIVED 18 SEP 2018

Date/Time, File Pass to?

18/9 11/18 ☐ : Preli. Report

Date/Time, File Return to?

21 ☐ : Final Report

Report Format:

Lump Sum / I.B.F. (\$)

MER-TP**1100**Days Of Repair: **3**Resurvey No. of Trip: **1**Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS. SI

) Photos

) Others

TOTAL

250
20**270**

- Pre repair inspection request - SJV402P VS SLT8886K (OI) DOA 03/09/2018

From: Mithoosingh, Aashweenjeetkaur
To: admin-a@lkkauto.com, assignments@lkkauto.com
Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Azlan, Syazairdina, Chan, Yoke Shi
Sent: 10/9/2018 8:48:30 AM
Attachments:  ime-907141640.pdf

Hi,

Please refer to the enclosed request from **Kuru & Co.**

Claim no : 76670981955G003
Case Owner : JACLYN MANIAM KESAVAL

If you have any queries/concerns, please let us know.
Kindly assist to assign Marcus Chua as Single Joint Expert as requested.

Thanks and regards,

Aashweenjeet Kaur (Aashween)
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]
Sent: Friday, September 07, 2018 6:01 PM
To: Chan, Yoke Shi
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Azlan, Syazairdina
Subject: Re: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLT8886K AND SJV402P ON 03/09/2018

Dear Sirs

Our client is agreeable to the following surveyor as the SJE: **Marcus Chua/LKK Auto Consultants Pte Ltd**

Please arrange for your surveyor to survey our client's vehicle at the following address:

M-TECH MOTOR SERVICES

Blk 9005 Tampines St 93 #01-252
Singapore 528839

Tel: 9735 4567/Mr Chan

Please instruct your surveyor to conduct the pre-repair survey **immediately** and complete the pre-repair survey within 2 working days of his appointment.

Kindly let us have the pre-repair and/or post repair survey report upon completion of the survey.

As solicitors on record, our client shall look to you for payment of our legal costs plus disbursements should you reach a direct settlement with our client's repairer.

Regards
Anne
Kuru & Co

150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

From: "Chan, Yoke Shi" <yokeshi.chan@aig.com>
To: Kuru & Co <kurulegal@yahoo.com.sg>
Cc: "Tan, Lily (AIG)" <Lily.Tan@aig.com>; "Fong, Andy-SY" <Andy-SY.Fong@aig.com>; "Kaur, Baljit" <Baljit.Kaur@aig.com>; "Chin, Lee-Ying" <Lee-Ying.Chin@aig.com>; "Abu Kassim, Noor Mariesa" <NoorMariesa.AbuKassim@aig.com>; "Md Ishak, Mohd Imran" <Imran.Ishak@aig.com>; "Lim, Sheng Yang" <ShengYang.Lim@aig.com>; "Mithoosingh, Aashweenjeetkaur" <Aashweenjeetkaur.Mithoosingh@aig.com>; "Azlan, Syazairdina" <Syazairdina.Azlan@aig.com>
Sent: Friday, 7 September 2018, 14:40
Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLT8886K AND SJV402P ON 03/09/2018

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2018-09-14 14:40 +08 to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: yokeshi.chan@aig.com

To: kurulegal@yahoo.com.sg

Cc: Lily.Tan@aig.com, Andy.SY.Fong@aig.com, Baljit.Kaur@aig.com, Lee-

Ying.Chin@aig.com, NoorMariasa.AbuKassim@aig.com, Imran.Ishak@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, Syezairdina.Azlan@aig.com

Subject: aigencrypt - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLT8886K AND SJV402P ON 03/09/2018

Date: Fri, 7 Sep 2018 06:40:33 +0000

Without Prejudice

Your Reference : L 18 1324.AT
Our Reference : 7667098195SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Fong Soon Yee	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Yoke Shi @ Ashley
AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

yokeshi.chan@aig.com | www.aig.com

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]
Sent: Friday, September 07, 2018 2:18 PM
To: Lim, Sheng Yang; Abu Kassim, Noor Mariesa; Fong, Andy-SY
Subject: Our Ref: L18.1324.AT//Your ref: SLT 8886K//PRS

Dear Sirs

ACCIDENT INVOLVING SJV 402P & SLT 8886K ON 03.09.2018

ALONG MCE TUNNEL TOWARDS ECP

NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

We act for **Foong Sun Shipping Pte Ltd**, whose vehicle registration number **SJV 402P** was damaged in the above accident.

A copy of the Accident report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards
Anne
Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	0969N

Vehicle Details

Vehicle No.:	SJV402P
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Sep 2018
Vehicle Make:	FIAT
Vehicle Model:	DOBLO PANORAMA 1.4 M ACTIVE
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	350A10005118293
Chassis No.:	ZFA22300005691543
Maximum Power Output:	57.0 kW (76 bhp)
Open Market Value:	\$15,767.00
Original Registration Date:	07 Jan 2010
First Registration Date:	07 Jan 2010
Transfer Count:	1
Actual ARF Paid:	\$15,767.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Jan 2020
PARF Rebate Amount:	\$8,671.00

Intended COE Rebate Details

COE Expiry Date:	06 Jan 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$6,848.00
COE Rebate Amount:	\$2,437.00
Total Rebate Amount:	\$11,108.00

The information contained herein is correct as at 12 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/09/2018 10:04
Date Of Accident	03/09/2018 17:15
Exact Location Of Accident	ALONG MCE TUNNEL TWDS ECP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJV402P
Insured/Policyholder	
Name Of Registered Owner	FOONG SUN SHIPPING PTE LTD
Co Reg No	198300969N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-63231133

Vehicle Particulars

Manufacturer	FIAT
Model	DOBLO PANORAMA 1.4 M ACTIVE
Exact Purpose for which vehicle was being used at time of accident	

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT20177096
Cover Note Number	07/01/2018 - 06/01/2019

Driver

Name of Driver	NG KWEE KANG
NRIC No	S1589002I
Date Of Birth	25/07/1963
Occupation	OUTDOOR
Date Of Driving Pass	03/06/1986
Driving Experience	32 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85938266
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	5LK 1 PINE CLOSE #08-177
Postcode	390001
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON THE STATED DATE AND TIME, I WAS DRIVING ALONG MCE AT THE EXIT OF ECP. SUDDENLY I FELT AN IMPACT, MY VEHICLE MOVED TO THE FRONT AND I REALIZED VEHICLE B (SLT8886K) HAD HIT ONTO REAR OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLT8886K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ZHANG JIAN
NRIC/Passport Number	S8086734D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) in compliance with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



M-TECH MOTOR SERVICES

Blk 9005 Tampines St.93, #01-252 Tampines Industrial Park A, Singapore 528839
Tel: 6784 0077 Fax: 6788 3025
(Registration No. 269252/00B)

Foong Sun Shipping Pte Ltd

Attention : Motor Claim Department

Estimate : TI030172

Date : 12/09/2018

Vehicle Num. : SJV 402 P

Make/Model : Fiat Doblo

Chassis/Eng# :

Accident Date : 03/09/2018

Claim No. :

Reference : MT/402/2018

Policy No. : MT20177096

not Authorised
LKR
u/s #1100/
3 dy.
12/9/18

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|----|---|----------------------|--|--|
| 1. | 1 | LIST ITEMS : | | |
| 2. | 1 | Rear bumper - centre | | |
| 3. | 1 | Rear bumper-LH | | |
| | | Rear reflector-LH | | |

List Total S\$:

LABOUR :

To respray accident affected parts

To replace rear bumper, repair boot cover

Labour Total S\$:

102

20/22	440.00
22	330.00
320	60.00
	830.00

300	400.00
350	400.00
	800.00

1387

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To spray damaged part(s) during resurvey
- Prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SingDollars : One Thousand Six Hundred Thirty Only

E. & O.E.

Total S\$: 1,630.00

for M-TECH MOTOR SERVICES

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18016426/UQD3N2

Date: 19/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700067219
 Claimant: SJV402P Insured Vehicle No: SLT8886K
 Vehicle No: Date of Loss: 03/09/2018 Nature of Claim: TP Claim No: 7667098195SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJV402P Engine No: 350A10005118293
 Make & Model: FIAT DOBLO PANORAMA, 1.4 Active (M) Chassis No: ZFA22300005691543
 Reg. Date: 07/01/2010 (Man. Year: 2009) Odometer: 134933 km
 Colour: Blue
 Engine Capacity: 1368 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45R17 Rear Tyre Size: 215/45R17
 Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm
 Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	830.00	747.00	83.00	10.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	800.00	650.00	150.00	18.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,630.00	1,397.00	233.00	14.29
Approved Total (Overridden) (S\$)		1,100.00		
Nett Amount (S\$)	1,630.00	1,100.00	530.00	32.52

INSPECTION

Date of Assignment: 10/09/2018

Date Inspected: 12/09/2018 Inspected At:

M-tech Motor Services (HQ)
 BLK 9005 TAMPINES ST 93, #01-252
 TAMPINES INDUSTRIAL PARK A
 Singapore 528839

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER-CENTRE	Deformed/Dented	440.00 F	*440.00 FL
2	1		*REAR BUMPER-LH	Deformed	330.00 F	*330.00 FL
3	1		*REAR REFLECTOR-LH	Broken	60.00 F	*60.00 FL
					Sub Total (S\$)	830.00
					- List Item Discount on L Items 0.00/10.00% (S\$)	83.00
					Total Parts (S\$)	747.00

F=Franchise part, L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RESPRAY ACCIDENT AFFECTED PARTS	New	400.00	300.00
2	TO REPLACE REAR BUMPER,REPAIR BOOT COVER	New	400.00	350.00
Gross Labour Cost (S\$)			800.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >