

ASS. REC. BY: Adrian Ling

REF:

CC3 / A16 / 18016430 / Avb 52

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. 2100349916
 Claims No. _____
 Sum Insured: _____ Excess: 800
 (Client's Record)
 Make of Veh: _____

Veh No: SKK7409X Yr Regn: 2013 August
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Audi A6 c.c. 1984
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 119718 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WAUZZ24 GREN017804
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 225/55R17
 P: 225/55R17

CL AUTO PTE LTD

Please mail to: Bukit Batok Central, P.O. Box 0005, Singapore 916501
 Please mail to: Bukit Batok Central, P.O. Box 0005, Singapore 916501

MV: 83K
 PV: 67.8K
 Nett: 15.2K

offer 14K

SKK7409X - CC3 / A16 / 15000915 / Avj3g2

DDA: 09.01.2015

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 8
 Resurvey No. of Trip: 1

1) _____

2) 23/1 - typist

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee:	
Transportation:	
\$ + RS. SI	
Photos	
Others	
TOTAL	

Report Format: merimen
 Lump Sum / I.B.I. (\$) 7924.36