

22/03/2002

ASS. REC. BY:

REF: CS3 / AIG 18016449 / Gcd3e2

Special Instruction:

Surveyor:

GUO Qiduo

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

10/09/2018 @ 12:23pm

Estimated Cost:

Bill to:

OD

TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLC 6333S

Insured:

SLH 3816J

at Workshop m/s

Eng Shing Mechanical

Tel:

6453 7380

of

160 Sin Ming Drive # 06-21

Policy No:

0999994822

Claim No:

993094357586

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/08/18

CA / REV / REP. / REV 24 HRS

Wp

H.O.D. Endorsement:

Date/Time:

12:38pm @ 10/9/18

Person Contacted:

Mr. Tan

Vehicle

IN/OUT

Date/Time

Action/Instruction (x) Estimate

SLC 6333S - X

Dismantle: 11/9/2018

After repair: 21/9/2018

Surveyor

MS
Xhe

REF: ALY

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Eng ching
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 15 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLC 6333 S Yr Regn: May 16
 Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Jaguar XE C.C. - 1999
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: 40645 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: SAJAB4AG1GA918413
 Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD ☒ Rim or

Tyre Size: F: 225/50R17
 R: 11

BS ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. _____	D.O.I. <u>10092018</u>

Survey held at w/s 3pm
 Des. of Damages ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

~~\$6000~~ \$7000

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee:

Transportation: _____

____ S + RS ____ SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format : DAR

Lump Sum / I.B.I: (\$ _____)

180

20

200



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS3/AIG18016449/Gcd3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 10-09-2018		
		Code : AIG		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SLH 3816J	Veh. Inspected	SLC 6333S	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	CHIN LEE YING	Assign Date	10/09/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	10/08/2018	Inspection Date	10/09/2018	
Survey held at	160 SIN MING DRIVE # 06-21			
Repairer	ENG SHING MECHANICAL WORKS			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying

To: 'assignments', Admin A

Cc: Fong, Andy-SY

Sent: 10/9/2018 12:23:41 PM

Attachments:  [3608193951SG003.tif](#)  [8800 - List of MS 20180907155403.pdf](#)

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Oracle Law Corporation

• Advocates & Solicitors • UEN/GST Reg No. 2009045727

237 Alexandra Road #04-11
The Alexcier, Singapore 159929
Telephone: 6538 6250 Facsimile: 6538 1860
Email: mail@oraclelaw.sg

FACSIMILE TRANSMISSION

To :	AIG Asia Pacific Insurance Pte Ltd	Date :	7 th Sept 2018
Attention :	Motor Claims	From :	Mr Stanley Bay / Miss Pauline Ong
Your Ref. :	Insurer of SLH 3816J	Our Ref. :	SB/PO/Acc/2018-8800
Facsimile :	6835-7416	No. of Pages :	5 (Including this page)

IMMEDIATE ATTENTION

Dear Sirs

PRE-REPAIR INSPECTION

ACCIDENT INVOLVING SLC 6333S & SLH 3816J ALONG TAMPINES AVE 9 ON 10-08-2018 @ 1.35 P.M.


We act for the owners of vehicle registration no. SLC 6333S.

We are instructed by our clients to notify you of the above accident involving our clients' said vehicle and your insured's vehicle registration no. SLH 3816J driven at the material time. A copy of our clients' motor accident report is enclosed herein.

As a result of the above accident, our clients' said vehicle was damaged. Before our clients proceed to repair their damaged vehicle, please let us know within the next (2) working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our clients shall proceed to repair their said vehicle without further reference to you.

Please note that this notification does not in any way prejudice our clients' right nor shall it be deemed as a waiver of any of their rights, as such our clients' rights are expressly reserved.

Yours faithfully



Mr Stanley Bay / Miss Pauline Ong
Enc

Details of Repairers

Eng Shing Mechanical Works
160 Sin Ming Drive
#06-21 Sin Ming Autocity S(575722)
Tel No.: 6453-7380 ; Fax No. 6252-4129

Oracle Law Corporation

• Advocates & Solicitors • UEN/GST Reg No. 200904572Z

237 Alexandra Road #04-11
The Alexcler, Singapore 159929
Telephone: 6538 6250 Facsimile: 6538 1860
Email: mail@oraclelaw.sg

FACSIMILE TRANSMISSION

To	:	AIG Asla Pacific Insurance Pte Ltd	Date	:	7th Sept 2018
Attention	:	Motor Claims	From	:	Mr Stanley Bay / Miss Pauline Ong
Your Ref.	:	Insurer of SLH 3816J	Our Ref.	:	SB/PO/Acc/2018-8800
Facsimile	:	6835-7416	No. of Pages	:	5 (including this page)

IMMEDIATE ATTENTION

Dear Sirs

**PRE-REPAIR INSPECTION
ACCIDENT INVOLVING SLC 6333S & SLH 3816J ALONG TAMPINES AVE 9 ON 10-08-2018 @ 1.35 P.M.**

We act for the owners of vehicle registration no. SLC 6333S.

We are instructed by our clients to notify you of the above accident involving our clients' said vehicle and your insured's vehicle registration no. SLH 3816J driven at the material time. A copy of our clients' motor accident report is enclosed herein.

As a result of the above accident, our clients' said vehicle was damaged. Before our clients proceed to repair their damaged vehicle, please let us know within the next (2) working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our clients shall proceed to repair their said vehicle without further reference to you.

Please note that this notification does not in any way prejudice our clients' right nor shall it be deemed as a waiver of any of their rights, as such our clients' rights are expressly reserved.

Yours faithfully



Mr Stanley Bay / Miss Pauline Ong
Enc

Details of Repairs

Eng Shing Mechanical Works
160 Sin Ming Drive
#06-21 Sin Ming Autocity S(575722)
Tel No.: 6453-7380 ; Fax No. 6252-4129

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SLC6333S		
Vehicle Type :	P10 - Passenger Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	JAGUAR		
Vehicle Model :	XE 2.0 I4P TSS		
Chassis No. :	SAJAB4AG1GA918413		
Propellant :	Petrol		
Engine No. :	015137080423204PT		
Engine Capacity :	1999 cc		
Maximum Power Output :	147.0 kW (197 bhp)		
Maximum Laden Weight :	2120 kg		
Unladen Weight :	1585 kg		
Year Of Manufacture :	2015		
Original Registration Date :	12 May 2016		
Lifespan Expiry Date :	-		
COE Category :	B - Car above 1600cc or 97kW (130bhp)		
Quota Premium :	\$51,010.00		
COE Expiry Date :	11 May 2026		
Road Tax Expiry Date :	11 Nov 2018		
PARF Eligibility Expiry Date :	11 May 2026		
Inspection Due Date :	11 May 2019		
Intended Transfer Date :	11 Sep 2018		
CO2 Emission :	179.00 (g/km)		
CEV/VES Rebate Utilised Amount :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 11 Nov 2018. You may renew the road tax from 12 Aug 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 11 Nov 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 12 Nov 2018 to 11 May 2019)			
	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	606.00	-	606.00
Total Amount Payable :			631.00
Amount Payable (From 12 Nov 2018 to 11 Nov 2019)			

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7710I
Vehicle Details	
Vehicle No.:	SLC6333S
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Sep 2018
Vehicle Make:	JAGUAR
Vehicle Model:	XE 2.0 I4P TSS
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	015137080423204PT
Chassis No.:	SAJAB4AG1GA918413
Maximum Power Output:	147.0 kW (197 bhp)
Open Market Value:	\$45,346.00
Original Registration Date:	12 May 2016
First Registration Date:	12 May 2016
Transfer Count:	1
Actual ARF Paid:	\$55,485.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 May 2026
PARF Rebate Amount:	\$41,613.00
Intended COE Rebate Details	
COE Expiry Date:	11 May 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,010.00
COE Rebate Amount:	\$39,107.00
Total Rebate Amount:	\$80,720.00

The information contained herein is correct as at 11 Sep 2018

OK

MWRA16103382 / Weesine Automotive Pte Ltd - Leng Kee
 ENTRY DATE & TIME: 10/08/2018 16:15
 SUBMITTED BY: Ong Qing Yang Paul

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 10/08/2018 16:15
 Date Of Accident 10/08/2018 13:35
 Exact Location Of Accident ALONG TAMPINES AVE 9
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLC6333S
 Insured/Policyholder
 Name Of Registered Owner TAN JIAN LIANG
 NRIC No S8517710I
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-88099988
 Alternative Phone No OFFICE-88099988

Vehicle Particulars

Manufacturer JAGUAR
 Model XE-2.0 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number

Cover Note Number

Driver

Name of Driver TAN JIAN LIANG
 NRIC No S8517710I
 Date Of Birth 06/06/1985
 Occupation INDOOR
 Date Of Driving Pass 18/11/2013
 Driving Experience 4 YEARS AND 8 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-88099988
 Fax Number
 Contact Number OFFICE-88099988
 Email Address NOEMAIL

Address 216 COMPASSVALE DRIVE
#12-558
Postcode 543216
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of Intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLH3816J
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1


SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to reudate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/PIN No.:

Accident Sketch Plan Pg. 1

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

along Tampines Ave 9

Driving on the left lane on a two-way lane 1 when the other party suddenly swerved into my lane causing me to E-brake and hit ^{myself} against the dashboard. As I was recovering from the daze and ~~into~~ turning ~~into~~ the left into Tampines Ave 2, the other party stopped his vehicle abruptly when there is no obstacle in front. I had to e-brake again but could not stop in time.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

X

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/IN No.:

MOTOR CAR (Frt)

Front Portion

Vehicle No: **SLC 6333 S**

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base	CUT ✓		
1003	991889	Frt Number Plate Garnish	SCR ✓		
1004	991300	Frt Bumper	CR ✓		
1005	992341	Frt Bumper Clips	NEC ✓		
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	AS - 2		
1008	991433	Frt Bumper Reinforcement	DS ✓		
1009	991318	Frt Bumper Beam	CR ✓		
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille	BR ✓		
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor	RH SCR ✓		
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille	BR ✓		
1022	991328	Frt Grille Emblem	BR ✓		
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	DD ✓		
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	CR ✓		
1030	991821	Frt RH Headlamp Assy	CR ✓		
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			
1	LH	Headlight washer lower			
			MIS	✓	

No of Items: **13**

ACCESSION:

TGCin Wm 24/9/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI




























CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Sep 2018 Edit Reg		10 Sep 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LCRF Pte Ltd , Co. Reg. No.: NA, Tel: +6599999999								
Main Claimant:	TAN JIAN LIANG								
Vehicle Reg. No.:	SLC6333S	Date of Loss:	10/08/2018 00:00 - :59 [26 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3608193951SG	Policy/Cover Note No.:	0999994822 (Comprehensive) Coverage: 25/02/2018 - 24/02/2019						
Vehicle Reg. No. (Insured):	SLH3816J	Policy No. (Claimant):							
		Excess:							
Repairer:	Eng Shing Mechanical Works (HQ) 160 Sin Ming Drive, #06-21 Sin Ming Autocity, 575722 Sin Ming - Tel: 64537380								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Boyogan, Joane] Joane.Boyogan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 19/09/2018]								
Claimant's Solicitor:	ORACLE LAW CORPORATION - Tel: 65386250								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (12/09/2018): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLC6333S (3608193951SG)
[SLH3816J]
TP
TAN JIAN LIANG
Aug 10 2018 12:00AM
[LCRF Pte Ltd]
Eng Shing Mechanical Works

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	11/09/18 13:02	General View														Load JPG	<input checked="" type="checkbox"/>	
2	11/09/18 13:02	General View														Load JPG	<input checked="" type="checkbox"/>	
3	11/09/18 13:02	General View														Load JPG	<input checked="" type="checkbox"/>	
4	11/09/18 13:02	General View														Load JPG	<input checked="" type="checkbox"/>	
5	11/09/18 13:02	General View														Load JPG	<input checked="" type="checkbox"/>	
6	11/09/18 13:02	General View														Load JPG	<input checked="" type="checkbox"/>	
7	11/09/18 13:02	General View														Load JPG	<input checked="" type="checkbox"/>	
8	11/09/18 13:02	General View														Load JPG	<input checked="" type="checkbox"/>	
9	11/09/18 13:02	General View														Load JPG	<input checked="" type="checkbox"/>	
10	11/09/18 13:02	General View														Load JPG	<input checked="" type="checkbox"/>	
11	11/09/18 13:02	General View														Load JPG	<input checked="" type="checkbox"/>	
12	11/09/18 13:02	General View														Load JPG	<input checked="" type="checkbox"/>	
13	11/09/18 13:02	General View														Load JPG	<input checked="" type="checkbox"/>	
14	11/09/18 13:02	General View														Load JPG	<input checked="" type="checkbox"/>	
15	11/09/18 13:02	General View														Load JPG	<input checked="" type="checkbox"/>	
16	11/09/18 13:02	General View														Load JPG	<input checked="" type="checkbox"/>	
17	11/09/18 13:02	General View														Load JPG	<input checked="" type="checkbox"/>	
18	11/09/18 13:02	General View														Load JPG	<input checked="" type="checkbox"/>	
19	11/09/18 13:02	General View														Load JPG	<input checked="" type="checkbox"/>	
20	11/09/18 13:02	General View														Load JPG	<input checked="" type="checkbox"/>	
21	11/09/18 13:02	General View														Load JPG	<input checked="" type="checkbox"/>	
22	11/09/18 13:02	General View														Load JPG	<input checked="" type="checkbox"/>	
23	11/09/18 13:02	General View														Load JPG	<input checked="" type="checkbox"/>	
24	11/09/18 13:02	General View														Load JPG	<input checked="" type="checkbox"/>	
25	11/09/18 13:02	General View														Load JPG	<input checked="" type="checkbox"/>	
26	11/09/18 13:02	General View														Load JPG	<input checked="" type="checkbox"/>	
27	11/09/18 13:02	General View														Load JPG	<input checked="" type="checkbox"/>	
28	11/09/18 13:02	General View														Load JPG	<input checked="" type="checkbox"/>	
29	24/09/18 18:21	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
30	24/09/18 18:21	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
31	24/09/18 18:21	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
32	24/09/18 18:21	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
33	24/09/18 18:21	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
34	24/09/18 18:21	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
35	24/09/18 18:21	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
36	24/09/18 18:21	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
37	24/09/18 18:21	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	24/09/18 18:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	24/09/18 18:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	24/09/18 18:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	24/09/18 18:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	24/09/18 18:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	24/09/18 18:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	24/09/18 18:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	24/09/18 18:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	24/09/18 18:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	24/09/18 18:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	24/09/18 18:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	24/09/18 18:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	24/09/18 18:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	24/09/18 18:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	24/09/18 18:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	24/09/18 18:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	24/09/18 18:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	24/09/18 18:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	24/09/18 18:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	24/09/18 18:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	24/09/18 18:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	24/09/18 18:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	24/09/18 18:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	24/09/18 18:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	24/09/18 18:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	24/09/18 18:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	12/09/18 11:05	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div> Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div> <div></div> <div></div> </div> </div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18016449/GCD3E2

Date: 27/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994822
Claimant Vehicle No : SLC6333S **Insured Vehicle No :** SLH3816J
 Date of Loss: 10/08/2018 Nature of Claim: TP Claim No: 3608193951SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLC6333S**
 Make & Model: JAGUAR XE, 2.0 I4P TSS (A) Engine No: 015137080423204PT
 Reg. Date: 12/05/2016 (Man. Year: 2015) Chassis No: SAJAB4AG1GA918413
 Colour: White Odometer: 40645 km
 Engine Capacity: 1999 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 10/09/2018
 Date Inspected: 10/09/2018 Inspected At: Eng Shing Mechanical Works (HQ)
 160 Sin Ming Drive, #06-21 Sin Ming
 Autocity
 Singapore 575722
 Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE BASE	Cut	0.00 F	*- F
2	1		*FRT NUMBER PLATE GARNISH	Scratched	0.00 F	*- F
3	1		*FRT BUMPER	Cracked	0.00 F	*- F
4	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
5	2		*FRT BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
6	1		*FRT BUMPER REINFORCEMENT	Dented	0.00 F	*- F
7	1		*FRT BUMPER BEAM	* Check	0.00 F	*- F
8	1		*FRT BUMPER SPONGE	Cracked	0.00 F	*- F
9	1		*FRT BUMPER GRILLE	Broken	0.00 F	*- F
10	1		*FRT BUMPER SENSOR RH	Scratched	0.00 F	*- F
11	1		*FRT GRILLE	Broken	0.00 F	*- F
12	1		*FRT GRILLE EMBLEM	Broken	0.00 F	*- F
13	1		*FRT SUPPORT PANEL	Dented	0.00 F	*- F
14	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
15	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
16	1		*LH HEADLIGHT WASHER COVER	Missing	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >