

ASS. REC. BY:

REF: CS / CTI 18016456 / GTD30

Special Instruction:

Surveyor: Guo Cheng  
Manmen

ASSIGNMENT (Office)

From (Person): Irene Tay of CTI Date/Time: 7/9/18 @ 4:22pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLK 1831L Insured: SKE 1637A

at Workshop m/s TBS MOTOR Tel: 64845518

of BLK 5035 Amk Ind. Park 2 # 01-357

Policy No: DMPCSN3029911700 Claim No: SNM18D04335C02

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 03/09/2018  
(Client's Record)

CA / REV / REP. / REV 24 HRS <sup>sup</sup> H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 10:13 am @ 10/9/18 Person Contacted: Mrs: oh Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLK 1831L - X</u>
	<u>SKF 1637A - NA / CTI 17022033/13</u> <span style="float: right;"><u>DOA: 16/11/17</u></span>
	<u>Part by Part \$2051.50 (red: 2735.50, 57%)</u>





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18016456/Gtd3

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 10-09-2018



Code : CTI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKE 1637A	Veh. Inspected	SLK 1831L
Policy No.	DMPCSN3029911700	Coverage (\$)	0.00
Claim No.	SNM18D04335C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	10/09/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	03/09/2018	Inspection Date	10/09/2018
Survey held at	T & S MOTOR SERVICE BLK 5035 ANG MO KIO INDUSTRIAL PARK 2 #01-357 . SINGAPORE 569538		

## 5a. Remarks

<p>A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.</p>
--

### ...CLAIM SUBFOLDER...(New Assignment)

**CLAIM SUBFOLDER TRACKING**

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Sep 2018		07 Sep 2018 16:22 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

**CLAIM SUBFOLDER DETAILS**

[Created by insurer]

Insured:	<b>WONG GUORONG(HUANG GUORONG)</b> , ID: S8104310H		
Main Claimant:	<b>HEE ENG WAH</b> , ID: S1688379D		
Vehicle Reg. No.:	<b>SLK1831L</b>	Date of Loss:	03/09/2018 12:00 - :59
Claim Type:	<b>TP / SNM18D04335C02</b>	Policy/Cover Note No.:	DMPCSN3029911700 (Comprehensive)
Vehicle Reg. No. (Insured):	<b>SKE1637A</b>	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	<b>T &amp; S Motor Service - Amk (HQ)</b> Block 5035 Ang Mo Kio Industrial Park 2 #01-357, 569538 Ang Mo Kio - Tel: 64845518		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Irene Tay Hui Ping</b> - 638986192]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [ <b>Final Rpt</b> due 18/09/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

**ASSOCIATED MAIL RECEIVED**

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS**

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	8379D
<b>Vehicle Details</b>	
Vehicle No.:	SLK1831L
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Sep 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C200 A AMG
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	27492030646736
Chassis No.:	WDD2050422R181406
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$40,974.00
Original Registration Date:	09 Jan 2017
First Registration Date:	09 Jan 2017
Transfer Count:	0
Actual ARF Paid:	\$44,364.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Jan 2027
PARF Rebate Amount:	\$33,273.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	08 Jan 2027
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$53,001.00
COE Rebate Amount:	\$43,996.00
<b>Total Rebate Amount:</b>	<b>\$77,269.00</b>

The information contained herein is correct as at 20 Sep 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	04/09/2018 12:40
Date Of Accident	03/09/2018 12:45
Exact Location Of Accident	SINGAPORE CUSTOM TOWARDS MALAYSIA
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK1831L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	HEE ENG WAH
NRIC No	S1688379D
Email Address	HEEWEEEEEB@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-90677399
Alternative Phone No	OTHERS-84289350

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C200 A AMG

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VA1/GA307039
Cover Note Number	

### Driver

Name of Driver	HEE WEI QIAN
NRIC No	S9540255J
Date Of Birth	31/10/1995
Occupation	INDOOR
Date Of Driving Pass	08/11/2016
Driving Experience	1 YEAR AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-84289350
Fax Number	
Contact Number	OTHERS-90677399
EEmail Address	HEEWEEEEEB@HOTMAIL.COM

Address	BLK 215 LORONG 8 TOA PAYOH #19-721
Postcode	310215
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : LIM MUI KHENG GENDER: : FEMALE
Passenger 2	NAME: : LIM MUI TING GENDER: : FEMALE
Passenger 3	NAME: : YAP TIONG SENG GENDER: : MALE

### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

PLEASE REFER TO THE ATTACHMENT

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKE1637A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN GEE KANG
NRIC/Passport Number	S7140715B
Contact Number	84313818

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Accident Sketch Plan & Describe Circumstances Of The Accident

SKETCH PLAN

veh A: SLK 1831 L

B: SKE 1637 A



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Singapore custom

I just cleared the Singapore immigration customs, waiting in queue of the fuel check control station. Traffic situation was standstill. Suddenly, vehicle B SKE 1637 A hit my rear parker.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**T & S MOTOR SERVICE**  
 Blk 5035 Ang Mo Kio Industrial Park 2  
 #01-357 Singapore 569538  
 Tel: 64845518 Fax:64815828

Date : 10/9/2018

China TaiPing Insurance (Singapore) Pte Ltd  
 3 Anson Road #16-00  
 Springleaf Tower  
 Singapore 079909

Re: Estimated repair cost of Mercedes Benz C200 A Amg SLK1831L accident on 3/09/2018

1 pc	Rear bumper.	/ <i>RL</i>	\$	1,907.00	? 1535
1 pc	Rear bumper lower trim	/ <i>cut</i>	\$	251.00	200
1 pc	Rear reinforcement	x <i>YNN</i>	\$	629.00	(735)
1 set	Reverse sensor	x	\$	280.00	
			\$	<u>3,067.00</u>	
	Labour charge for remove and refit and panel beat accident dented parts.		\$	800.00	200
	To putty and spraypainting including touch up all affected areas.		\$	800.00	<del>200</del> 250
	Labour to remove and refit reverse sensor.		\$	120.00	40
	<b>Total:</b>		\$	<u><u>4,787.00</u></u>	2051.5

*One Rep.  
 part by net  
 3 Days.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s)-is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Sep 2018		07 Sep 2018 16:22 <a href="#">Edit Adj Rpt</a>	<b>S\$2,051.50</b> <a href="#">Edit Estimates</a>	<b>S\$2,051.50</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	<b>WONG GUORONG(HUANG GUORONG)</b> , ID: S8104310H		
Main Claimant:	<b>HEE ENG WAH</b> , ID: S1688379D		
Vehicle Reg. No.:	<b>SLK1831L</b>	Date of Loss:	03/09/2018 12:00 - :59 [19 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / SNM18D04335C02</b>	Policy/Cover Note No.:	DMPCSN3029911700 (Comprehensive)
Vehicle Reg. No. (Insured):	<b>SKE1637A</b>	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	<b>T &amp; S Motor Service - Amk (HQ)</b> Block 5035 Ang Mo Kio Industrial Park 2 #01-357, 569538 Ang Mo Kio - Tel: 64845518		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Irene Tay Hui Ping</b> - 638986192]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 18/09/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		

ALL ASSOCIATED TASKS										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

## Claim Documents

\*SLK1831L (SNM18D04335C02)  
 [SKE1637A]  
 TP  
 HEE ENG WAH  
 Sep 3 2018 12:00PM  
 [WONG GUORONG(HUANG GUORONG)]  
 T & S Motor Service - Amk

Upload Documents   Upload Photos   Compose New Letter			View	View in Browser
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	05/09/18 16:40	<b>Accident Statement</b>	Load HTM	<input type="checkbox"/>
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	05/09/18 16:34	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	05/09/18 16:34	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	05/09/18 16:34	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	05/09/18 16:34	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	05/09/18 16:34	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	05/09/18 16:34	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	05/09/18 16:34	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	05/09/18 16:34	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	05/09/18 16:34	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	05/09/18 16:34	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
11	05/09/18 16:34	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/09/18 10:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
2	14/09/18 10:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
3	14/09/18 10:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	14/09/18 10:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	14/09/18 10:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	14/09/18 10:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	14/09/18 10:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	14/09/18 10:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	14/09/18 10:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	14/09/18 10:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	14/09/18 10:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	14/09/18 10:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	14/09/18 10:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	14/09/18 10:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
15	14/09/18 10:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
16	14/09/18 10:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
17	14/09/18 10:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
18	14/09/18 10:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
19	14/09/18 10:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
20	14/09/18 10:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>

  

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/09/18 16:21	<b>PRS WITH TP GIA</b>	Load PDF	
2	07/09/18 16:21	<b>OI GIA</b>	Load PDF	

  

No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	05/09/18 16:33	<b>Accident Sketch Plan</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	05/09/18 16:33	<b>Accident Sketch Plan</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	05/09/18 16:33	<b>Identification Card</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	05/09/18 16:33	<b>Driving Licence</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>

### Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	05/09/18 16:40	<b>Accident Statement</b>	Load HTM	

  

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	05/09/18 16:34	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
2	05/09/18 16:34	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
3	05/09/18 16:34	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
4	05/09/18 16:34	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
5	05/09/18 16:34	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
6	05/09/18 16:34	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
7	05/09/18 16:34	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
8	05/09/18 16:34	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
9	05/09/18 16:34	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
10	05/09/18 16:34	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
11	05/09/18 16:34	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>

  

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	05/09/18 16:33	<b>Accident Sketch Plan</b>	Load JPG	<input checked="" type="checkbox"/>
2	05/09/18 16:33	<b>Accident Sketch Plan</b>	Load JPG	<input checked="" type="checkbox"/>
3	05/09/18 16:33	<b>Identification Card</b>	Load JPG	<input checked="" type="checkbox"/>
4	05/09/18 16:33	<b>Driving Licence</b>	Load JPG	<input checked="" type="checkbox"/>

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

**Show Remarks To:**  Handling Insurer  
Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118016456/GTD3E2

Date: 20/09/2018

## REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN3029911700

Claimant Vehicle No: SLK1831L Insured Vehicle No: SKE1637A

Date of Loss: 03/09/2018 Nature of Claim: TP Claim No: SNM18D04335C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SLK1831L**

Make & Model: MERCEDES-BENZ C200 AMG LINE (R18 LED), 2.0 (A) Engine No: 27492030646736

Reg. Date: 09/01/2017 (Man. Year: 2016) Chassis No: WDD2050422R181406

Colour: White Odometer: 32001 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/45Z R18 Rear Tyre Size: 225/45Z R18

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,067.00	1,561.50	1,505.50	49.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,720.00	490.00	1,230.00	71.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>4,787.00</b>	<b>2,051.50</b>	<b>2,735.50</b>	<b>57.14</b>

## INSPECTION

Date of Assignment: 07/09/2018

Date Inspected: 10/09/2018 Inspected At: T & S Motor Service - Amk (HQ)  
Block 5035 Ang Mo Kio Industrial Park 2  
#01-357  
Singapore 569538

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 20 Sep 2018)	
<b>Parts:</b>	N/A	MERCEDES-BENZ C200 AMG LINE (R18 LED) 2.0 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLK1831L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,907.00 F	*1,535.00 FL
2	1		*REAR BUMPER LOWER TRIM	Cut	251.00 F	*200.00 FL
3	1		*REAR REINFORCEMENT	Not Necessary	629.00 F	*- FL
4	1		*SET REVERSE SENSOR	Not Necessary	280.00 F	*- FL
<b>Sub Total (S\$)</b>					<b>3,067.00</b>	<b>1,735.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (S\$)</b>					0.00	173.50
<b>Total Parts (S\$)</b>					<b>3,067.00</b>	<b>1,561.50</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGE FOR REMOVE AND REFIT AND PANEL BEAT ACCIDENT DENTED PARTS	New	800.00	200.00
2	TO PUTTY AND SPRAYPAINTING INCLUDING TOUCH UP ALL AFFECTED AREAS	New	800.00	250.00
3	LABOUR TO REMOVE AND REFIT REVERSE SENSOR	New	120.00	40.00
			<b>Gross Labour Cost (\$\$)</b>	<b>1,720.00</b>
				<b>490.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >