

AXA INSURANCE PTE LTD

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

8 SHENTON WAY #24-01 AXA TOWERSINGAPORE Date: 26-11-2020

068811

		Ш

CS3/ASM18016461/T1ba3e2

Page No.:1 of 1

ATTI	N : KHONG LYNN		Code: ASM					
1.	1. Policy Particulars :- (THIRD PARTY CLAIM)							
	Insured Veh.	SLP 5342D	Veh. Inspected	SKD 8693X				
	Policy No.	GA220825/1	Coverage (\$)	0.00				
	Claim No.	S8M00UT5	Excess (\$)	0.00				
	Assign From	KHONG LYNN	Assign Date	10/09/2018				
2. Vehicle Particulars & Condition								
	Make & Model	MERCEDES BENZ B200	c.c	2035				
	Engine No.	HIDDEN	Year of Reg.	2010				
	Chassis No.	WDD2452342J536243	Colour	WHITE				
	Odometer	92979 KM	Steering	IN ORDER				
	Brakes	IN ORDER	Modification	SPORTS RIM				
	General	GOOD						
3. Conditions of Tyres								
		Size	Make	Balance				
	R/H Front Tyre	215/45 R17	GOODYEAR	6 mm				
	L/H Front Tyre	215/45 R17	GOODYEAR	6 mm				
	R/H Rear Tyre	215/45 R17	GOODYEAR	6 mm				
	L/H Rear Tyre	215/45 R17	GOODYEAR	6 mm				
4. Description of Damages								
	THE VEHICLE SU	STAINED DAMAGES AT THE N/	S BODY.					
5.	*	Gene	ral Information					

5.	General Information						
	Accident Date	29/08/2018	Inspect Date / Time	12/09/2018 (10:00 AM)			
	Survey held at	LIAN HO HUP KEE SPRAY PAINTING					
		BLK 1001 BT MERAH LANE 3 #01-67 SINGAPORE 159718					

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
- D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days

Report Ref No. CS3/ASM18016461/T1ba3e2

Inspected By

pupin

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A
Automotive Assessor

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.