

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/09/2018 16:06
Date Of Accident	09/09/2018 13:35
Exact Location Of Accident	BLK 525 BEDOK NORTH STREET 3 OPEN SPACE CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV8887Y
Insured/Policyholder	
Name Of Registered Owner	TAN BOON KENG (CHEN WENQING)
NRIC No	S7827522G
Email Address	BOONKENG TAN@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97811080
Alternative Phone No	OTHERS-97811080

Vehicle Particulars

Manufacturer	BMW
Model	116D-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	CAR WAS PARKED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5095114645
Cover Note Number	

Driver

Name of Driver	TAN BOON KENG (CHEN WENQING)
NRIC No	S7827522G
Date Of Birth	17/09/1978
Occupation	INDOOR
Date Of Driving Pass	03/10/2009
Driving Experience	8 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97811080
Fax Number	
Contact Number	OTHERS-97811080
Email Address	BOONKENG TAN@HOTMAIL.COM

Address	79 TAMPINES AVENUE 1 #09-13
Postcode	528684
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	QUEENSTOWN N.P.C
Police Station Address	ROAD: 3 QUEENSWAY #01-03 , POSTCODE: 149073 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4719999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN AND POLICE REPORT T/20180910/2040

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GZ7531T
Vehicle Make/Model/Colour	NISSAN
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GiA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:


10/9/2018 13.00hr.

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

GZ 7531T was reversing backward to adjust ~~before~~ driving his position before heading towards the carpark exit. SLV 8887 was stationary parked in the carpark of BIK 525 / BIK 528.

GZ 7531T reversed and hit on SLV 8887Y's front left headlight and bumper, resulting in cracked headlight and scratched bumper.

GZ 7531T drove off without leaving any contact.

POLICE REPORT 7/20180910/2040

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

10/9/2018 13.50hr.

GMARL V00131PlanForm

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20180910/2040

Police Station Of Origin:
Queenstown N.P.C
3 Queensway #01-03 SINGAPORE 149073
Tel No: 1800-4719999

1 of 3

Report No. T/20180910/2040

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/09/2018 12:33		Vide Report No.:		Station Diary No.: 30
Informant's Particulars				
Name of Informant: TAN BOON KENG		Address: 79 TAMPINES AVENUE 1 #09-13 SINGAPORE 528684		
ID Type / ID No.: NRIC NO / S7827522G		Contact No.: Home/Office: Mobile: 97811080		
Nationality: SINGAPORE CITIZEN		Email: boonkengtan@hotmail.com		
Sex: Male	Age: 39	Date of Birth: 17/09/1978	Type of Informant: Vehicle Owner	
Race: Chinese		Language: English	Institution / School Name:	
Occupation: FINANCE CONTROLLER		Driving Licence Information: Class: 3A		Date of Expiry:

General Information of the Accident

Type of Accident: Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 09/09/2018 13:35	Type of Location: Car Park
Location: Along Road 1 BEDOK NORTH STREET 3			
Open Space Car Park near Blk 525 Bedok North St 3			
Weather: Clear	Road Surface: Wet	Road Speed Limit:	
Traffic Flow: Two Way	Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Moving Vehicle Against - Parked Vehicle		Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GZ7531T	Lorry	NISSAN		Silver		0
SLV8887Y	Car	BMW		White	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

POLICE REPORT



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Queenstown N.P.C
3 Queensway #01-03 SINGAPORE 149073
Tel No: 1800-4719999



T/20180910/2040

2 of 3

Report No. T/20180910/2040

CONTINUATION OF REPORT

Vehicle Owner			
Name	TAN BOON KENG		ID No. S7827522G
Related Vehicle	SLV8887Y (Car)		Contact No. 97811080
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3A Date of Expiry: NIL
Date Treatment	NIL		
No. of Days granted Medical Leave	NIL	Date Discharge	NIL
		Degree of Injury	NIL

Brief Details.

On 09/09/2018, at about 1300hrs, I parked my car SLV8887Y at the open space car park near B/525 Bedok North St 3 as I was visiting my parents who are staying around there. After I parked my car, I then left and that was the last time I saw my car intact.

At about 1430hrs, I returned to my car and I drove it back home without checking the condition. I reached the car park of my home at about 1445hrs. When I alighted and about to leave the car park, I realized the front bumper and the front left headlight were actually damaged. I then went to check my in-built car camera and I found out that at about 1336hrs, a silver Nissan lorry GZ7531T had hit onto my car when reversing. The driver of the lorry had alighted to make a check but he drove off after checking, without leaving a note for me regarding the incident. I also recalled that when I returned to my car, the driver was actually at scene as he was looking at me when I was putting my kids into my car. However, he did not approach me at that time.

I wish to state that the driver of the lorry is a male Chinese in his 60s. He was wearing a yellow polo-tee and a pair of black Bermuda when the incident happened. I have reported to my BMW workshop and they advised me to lodge a police report. My in-built car camera had captured the whole incident and I had saved a copy. I am willing to provide the video footage for police investigation purpose.

POLICE REPORT



SINGAPORE
POLICE FORCE

Police Station Of Origin:
Queenstown N.P.C
3 Queensway #01-03 SINGAPORE 149073
Tel No: 1800-4719999



T/20180910/2040

3 of 3

Report No. T/20180910/2040

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

D /
Staff Sgt TAN WEI JIAN

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
10/09/2018 12:33


Officer In Charge Of Case:

TP / HRT /
SI ABDUL KAREEM BIN ABDUL HAGUE
Contact No.: 65476079

Classification Of Case:

SN 47

Authentication Stamp
NP168



SIGNATURE

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo

