

22/03/2002

ASS. REC. BY:

REF:

CS3 / ICS 18016513 / Tlcbcz

Special Instruction:

Survivor

ASSIGNMENT (Office)

Mehmen

From (Person): Junile Goh

of ICS

Date/Time: 10092018 347pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 9273S

Insured:

GBD 7319R

at Workshop m/s:

Keng Soon Auto

Tel:

9005 3335

of

Bik 9004 Tampines St 93 #01-94

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

05092018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp1

H.O.D. Endorsement:

Date/Time: 11-09-2018 937am

Person Contacted:

Kelvin

Vehicle IN / OUT

Date/Time	Action/Instruction ( X ) Estimate
	SLB 9173S X
	GBD 7319R X
	Dismantle: 12/9/2018.
	After repair: 20/9/2018



**Catherine Chong (LKK Auto)**

---

**From:** Janice Goh Siew Geok (ECICS, Claims) <Janice\_Goh@ecics.com.sg>  
**Sent:** Monday, 10 September, 2018 3:47 PM  
**To:** accident@kscgp.com; assignments  
**Cc:** jiapei@kscgp.com; ECICS Claims  
**Subject:** RE: 2nd Notice to conduct pre-repair inspection Your ref: GBD 7319R; Our Ref: SLB 9273/SK/jp/ps  
**Attachments:** 2nd PRS SK.PDF

Hi Sampu

Thank you for your email.

We are not agreeable with your surveyor list and we will appoint LKK for the SJE.

Aside to LKK

Please assist to arrange survey for TPV.

Thank you.

Regards,  
Janice Goh  
**Claims Division**  
DID: +65 6303 0182  
FAX: +65 6338 9267

**ECICS Limited**  
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to [motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg) directly.

*\*\*Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.\*\**

**From:** accident@kscgp.com [mailto:accident@kscgp.com]  
**Sent:** Monday, 10 September, 2018 2:44 PM  
**To:** Janice Goh Siew Geok (ECICS, Claims)  
**Cc:** jiapei@kscgp.com  
**Subject:** 2nd Notice to conduct pre-repair inspection Your ref: GBD 7319R; Our Ref: SLB 9273/SK/jp/ps

Dear Sirs,

We refer to your email below and subject above.

Please find the enclosed 2nd Notice to Conduct Pre-repair Survey herewith.  
Thank you.

Regards,  
Sampu  
KSCGP Juris LLP  
10 Hoe Chiang Road  
#13-03A Keppel Towers  
Singapore 089315

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

----- Original Message -----

**From:** Janice Goh Siew Geok (ECICS, Claims) [[mailto:Janice\\_Goh@ecics.com.sg](mailto:Janice_Goh@ecics.com.sg)]  
**To:** [accident@kscgp.com](mailto:accident@kscgp.com)  
**Cc:** [claims@ecics.com.sg](mailto:claims@ecics.com.sg)  
**Sent:** Mon, 10 Sep 2018 04:14:43 +0000  
**Subject:**

Without prejudice

Dear Sampu

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. LKK
2. JP knight
3. Formteam
4. Appraisal Associates
5. Autoprobe
6. Raleigh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Thank you.

Regards,  
Janice Goh  
**Claims Division**  
DID: +65 6303 0182

**ECICS Limited**  
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

**WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to [motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg) directly.**

*\*\*Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.\*\**

-----  
--

**From:** accident@kscgp.com [mailto:accident@kscgp.com]  
**Sent:** Monday, 10 September, 2018 11:15 AM  
**To:** enquiries  
**Cc:** jiapei@kscgp.com  
**Subject:** Notice to conduct pre-repair inspection Your ref: GBD 7319R Our Ref: SLB 9273/SK/jp/ps

Dear Sirs,

We refer to the subject matter.

Please find the enclosed Notice to conduct Pre-repair Survey herewith.

Thank you.

Regards,  
Sampu  
KSCGP Juris LLP  
10 Hoe Chiang Road  
#13-03A Keppel Towers  
Singapore 089315  
Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708  
Email: [accident@kscgp.com](mailto:accident@kscgp.com)

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
--------------------------	--------------------------	--------------------------

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Your Ref : GBD 7319R

Our Ref : SLB 9273S.SK.jp.ps

Date : 10 September 2018

Fax : 6538 3708

Tel : 3152 0989

Email : [accident@kscgp.com](mailto:accident@kscgp.com)

ECICS Limited

BY EMAIL ONLY

**DATE OF ACCIDENT: 5 SEPTEMBER 2018**

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS**

We refer to your email on 10 September 2018.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

S/No.	Name of Surveyor	Company Name
1.	Lee Kok Weng	Lee Automobile Appraisal Services
2.	Patrick Ng Kong Beng	Carlink Consultancy
3.	Ang Guea Kiang	CA Appraisal
4.	Philip Foo	Precision Appraisal Services
5.	Ong Ah Keng, Kent	KTO Automobile Assessors
6.	Ong Poh Meng	Aeon Auto Consultants LLP
7.	Chang Fuh Keong, Dave	Sincere Appraisal Services

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which our client will commence repairs thereafter without any further notice or reference to you. Please be informed that the said vehicle can be surveyed / inspected at:

Address : **Keng Soon Auto Pte Ltd**  
Khek Joo Motor Workshop  
Block 9004 Tampines Street 93  
#01-94  
Singapore 528838

Contact Person/Tel : Jane Magsino / Kelvin 9005 3335 / 69333814

Yours faithfully,

*PS*

Your Ref : GBD 7319R

Our Ref : SLB 9273S.SK.jp.ps

Date : 10 September 2018

### Acknowledgement

This is to confirm that I \_\_\_\_\_ *[Full Name of Surveyor]* of  
\_\_\_\_\_ *[Surveyor's Company]* have completed as follows:-

(a) Pre- Repair Survey/Inspection on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:

(b) Pre- Repair Survey/Inspection (during dismantling) on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:

(c) Re-inspection of new replacement part (part by part) on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:

(d) Post – Repair Survey/Inspection on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1812E
Vehicle Details	
Vehicle No.:	SLB9273S
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Sep 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	OUTLANDER 2.4 CVT ABS D/AIRBAG AWD BASIC
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	4B12NY6389
Chassis No.:	JMYXTGF3WFZ001243
Maximum Power Output:	123.0 kW (164 bhp)
Open Market Value:	\$14,835.00
Original Registration Date:	27 Apr 2016
First Registration Date:	27 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$14,835.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Apr 2026
PARF Rebate Amount:	\$11,126.00
Intended COE Rebate Details	
COE Expiry Date:	26 Apr 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,610.00
COE Rebate Amount:	\$29,279.00
<b>Total Rebate Amount:</b>	<b>\$40,405.00</b>

The information contained herein is correct as at 26 Sep 2018

OK



### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	07/09/2018 09:25
Date Of Accident	05/09/2018 20:40
Exact Location Of Accident	BKE TOWARDS WOODLANDS (BEFORE DAIRY FARM RD EXIT)
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB9273S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KENG SOON AUTO PTE LTD
Co Reg No	197701812E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-63377533
<b>Vehicle Particulars</b>	
Manufacturer	MITSUBISHI
Model	OUTLANDER 2.4 CVT ABS D/AIRBAG AWD BASIC
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

#### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-18090222MFZH/83 (TP)
Cover Note Number	

#### Driver

Name of Driver	MOHAMED FARIHIN BIN MOHAMED ZAMRI
NRIC No	S9744787Z
Date Of Birth	22/12/1997
Occupation	OUTDOOR
Date Of Driving Pass	26/10/2016
Driving Experience	1 YEAR AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-99999999
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	BLK 454 CHOA CHU KANG AVE 4 #04-111
Postcode	680454
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ORCHARD NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 51 KILLINEY ROAD , POSTCODE: 239572 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7359999 - FAX NO: 67331934
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH INSURED
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD7319R
Vehicle Make/Model/Colour	TOYOTA DYNA 150 MANUAL
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	MOHAMED FARIHIN BIN MOHAMED ZAMRI
Approximate Age	20
Injuries Sustain	NECK INJURY
Injured person in which vehicle?	SLB9273S
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	


**SKETCH PLAN**


**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:


  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

- 7 SEP 2018

**IDAC KAKI BUKIT (VAL)**  
23 Kaki Bukit Ave 4  
Singapore 415933  
Tel: 67416697 Fax: 67492305  
Email: vorkh@singnet.com.sg  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along BKE towards woodlands.  
 This Lorry GPD 7319R failed to brake in  
 time and hit my rear.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)

Date & Time: -- 7 SEP 2018

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4  
 Singapore 415933  
 Tel: 67416697 Fax: 67492305  
 Email: [vackb@singnet.com.sg](mailto:vackb@singnet.com.sg)

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

## Individual Statement



**SINGAPORE  
POLICE FORCE**



T/20180905/2077

1 of 3

Report No. T/20180905/2077

Police Station Of Origin:  
Orchard N.P.C  
51 Killiney Road SINGAPORE 239572  
Tel No: 1800-7359999

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 08/09/2018 14:34	Video Report No.:	Station Diary No.: 80
--	-------------------	--------------------------

**Informant's Particulars**

Name of Informant: MOHAMED FARIHIN BIN MOHAMED ZAMRI		Address: APT BLK 454 CHOA CHU KANG AVENUE 4 #04-111 SINGAPORE 680454	
ID Type / ID No. NRIC NO / S9744787Z		Contact No.: Home/Office: Mobile: 86188891	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 20	Date of Birth: 22/12/1997	Type of Informant: Driver
Race: Eurasian		Language: English	Institution / School Name:
Occupation: National Service Full Time		Driving Licence Information: Class: 3	Date of Expiry:

**General Information of the Accident**

Type of Accident: Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 05/09/2018 20:40	Type of Location: Straight Road
Location: Along Road 1 BUKIT TIMAH EXPRESSWAY 3rd Lane on BKE just before Dairy Farm exit. Lamp Post Number: 11			
Weather: Clear	Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way	Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
GBD7319R	Motor	TOYOTA	TOYOTA DYNA 150 MANUAL	White	Slightly Damaged	0
SLB9273S	Car	MITSUBISHI	OUTLANDE R 2.4 CVT ABS D/AIRBAG AWD BASIC	White	Seriously Damaged	0





**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Orchard N.P.C  
51 Killiney Road SINGAPORE 239572  
Tel No: 1800-7359999



T/20180906/2077

Report No. T/20180906/2077

**CONTINUATION OF REPORT**

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	MOHAMED FARIHIN BIN MOHAMED ZAMRI	ID No.	S9744767Z
Related Vehicle	SLB9273S (Car)	Contact No.	88188891
Hospital/Clinic	ALEXANDRA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	05/09/2018	Date Discharge	05/09/2018
No. of Days granted Medical Leave	02	Degree of Injury	Slight

**Brief Details.**

On 05/09/2018 at about 08:40pm, I was driving (VRN: SLB9273S) along Bukit Timah Expressway (BKE) on the 3rd lane. While driving, the vehicles in front of me had suddenly stopped as such I had applied my brakes and subsequently there was a loud bang as another vehicle had hit the rear of my vehicle. I subsequently moved my vehicle to the shoulder and stopped. The driver of the lorry (VRN: GBD7318R) who had hit me also stopped by the shoulder.

I made a check on my vehicle and it was badly damaged. A big dent on my rear boot door and it was unable to open after the accident. The back windscreen had also shattered due to the accident. I made a check with the lorry driver (Male, local Chinese about 50 years old) whether he was alright however he was not injured and there was only light scratches on his lorry. I asked him if we could exchange our personal details however he refused to give and I only managed to get his vehicle registration number. The lorry driver was quite aggressive and was scolding me while I was talking to him.

The accident happened near to lamp post 11. The lorry driver subsequently went back to his lorry and drove off. Traffic Police rider then came to make a check on me however, he did not give me any report number or case card on the accident after I told him what happened and I do not know what his name was as he had asked me to leave if I was okay. I later went to Alexandra Hospital to have a check up and was given 2 days of Medical Leave. I am lodging this report for record and investigation purpose as it was a hit and run and the Police did not attend to me properly.

Individual Statement



SINGAPORE  
POLICE FORCE

Police Station Of Origin:  
Orchard N.P.C.  
51 Killiney Road SINGAPORE 239572  
Tel No: 1800-7359999



T/20180906/2277

3 of 3

Report No: T/20180906/2277

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference

Signature Of Officer Recording The Report

E/  
Sgt 3 KHAIRUL ASYRAF BIN MISRI

Signature Of Informant

Signature Of Interpreter:  
Not applicable

Date/Time  
06/09/2018 14:34

Officer In Charge Of Case  
TP / HRT /  
Sr Staff Sgt ESTHER CHONG  
Contact No: 65476368

Classification Of Case:



SN 172

SIGNATURE



**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

### ADDENDUM

**(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:**

Original Report No : \_\_\_\_\_ Vehicle Registration No: SLB A2735  
Name (as shown in NRIC): Mond Parvin bin Mond Zamri NRIC/FIN/Passport No : S 97447872  
(\*Vehicle Driver / Vehicle Owner) (\*) Please delete as appropriate  
Address : \_\_\_\_\_ Singapore ( )  
Contact (Tel) : \_\_\_\_\_ Mobile No. : \_\_\_\_\_  
Email Address : \_\_\_\_\_  
Date of Accident : 5 Sep 2018 Time of Accident : 2040  
Place of Accident : DKE -> Woodlands  
Insurance Company: MS First Capital

**(B) ADDITIONAL INFORMATION / AMENDMENTS:**

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

To attach the police report due to injury.



Policyholder / Driver's Signature  
Date:

- 7 SEP 2018

**IDAC KAKI BUKIT (VAC)**

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492305

Email: [yackb@singnet.com.sg](mailto:yackb@singnet.com.sg)

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Date:

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Midnight Accident

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Oct 2018 08:27 <a href="#">Edit Reg</a>		10 Sep 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: -, Co. Reg. No.: -, Email: EMAIL@EMAIL.COM									
Main Claimant: -									
Vehicle Reg. No.: <b>SLB9273S</b>		Date of Loss: 05/09/2018 00:00 - :59 [28 Months and 9 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / DMCV1800071H</b>		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): <b>GBD7319R</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Keng Soon Auto Pte Ltd (HQ)</b> 104 Prinsep Street #01-00, 188653 Bugis - Tel: 63377533									
Handling Insurer: <b>ECICS Limited (HQ)</b> - Tel: 63374779 /6303 0178 ... [Handled by <b>Janice Goh</b> - 6303 0182]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 21/09/2018]									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

**\*SLB9273S (DMCV1800071H)**  
**[GBD7319R]**






































TP















































-

**Sep 5 2018 12:00AM**

[-]

**Keng Soon Auto Pte Ltd**

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images								3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print
1	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
2	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
3	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
4	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
5	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
6	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
7	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
8	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
9	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
10	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
11	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
12	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
13	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
14	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
15	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
16	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
17	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
18	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
19	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
20	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
21	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
22	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
23	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
24	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
25	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
26	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
27	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
28	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
29	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
30	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
31	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
32	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
33	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
34	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
35	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
36	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>
37	17/09/18 15:04	General View							Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	17/09/18 15:04	General View	 Load JPG	<input checked="" type="checkbox"/>
39	17/09/18 15:04	General View	 Load JPG	<input checked="" type="checkbox"/>
40	17/09/18 15:04	General View	 Load JPG	<input checked="" type="checkbox"/>
41	17/09/18 15:04	General View	 Load JPG	<input checked="" type="checkbox"/>
42	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	17/09/18 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	17/09/18 15:05	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
85	17/09/18 15:05	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
86	17/09/18 15:05	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
87	17/09/18 15:05	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
88	26/09/18 12:15	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
89	26/09/18 12:15	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
90	26/09/18 12:15	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
91	26/09/18 12:15	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
92	26/09/18 12:15	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
93	26/09/18 12:15	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
94	26/09/18 12:15	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
95	26/09/18 12:15	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
96	26/09/18 12:15	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
97	26/09/18 12:15	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
98	26/09/18 12:15	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
99	26/09/18 12:15	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
100	26/09/18 12:15	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
101	26/09/18 12:15	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
102	26/09/18 12:15	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
103	26/09/18 12:15	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/ICS18016512/T1CBE2

Date: 01/10/2018

### REFERENCE

Handling Insurer: ECICS Limited Policy No:  
**Claimant Vehicle No :** SLB9273S **Insured Vehicle No :** GBD7319R  
 Date of Loss: 05/09/2018 Nature of Claim: TP Claim No: DMCV1800071H

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLB9273S**  
 Make & Model: MITSUBISHI OUTLANDER, 2.0 (A) Engine No: 4B12NY6389  
 Reg. Date: 27/04/2016 (Man. Year: 2014) Chassis No: JMYXTGF3WFZ001243  
 Colour: White Odometer: 31728 km  
 Engine Capacity: 2360 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (\$\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18  
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm  
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 10/09/2018  
 Date Inspected: 11/09/2018 Inspected At: Keng Soon Auto Pte Ltd (HQ)  
 BLK 9004 TAMPINES IND. PARK 1  
 #01-94 SINGAPORE 528836  
 Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,800.00 - \$8,300.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 01 Oct 2018)
<b>Parts:</b>	M1-SUV	MITSUBISHI OUTLANDER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLB9273S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >