

22/03/2002

ASS. REC. BY:

REF:

CS3 / ms(1180)16520 / Ucb324

Special Instruction:

Surveyor:

MARUIS

**ASSIGNMENT (Office)**

From (Person):

Pauline Tham

of

msj(-)

Date/Time:

11/09/2018 9:30am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SUU 446UR

Insured:

SFR 1616B

at Workshop m/s:

Z-One Automotive

Tel:

6250 2115.

of

Blk 1 Kaki Bukit Ave 6 #01-87

Policy No:

28629423 9VW

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

09/09/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

11.09.2018 10:39am

Person Contacted:

Yvonne

Vehicle IN / OUT

Date/Time	Action/Instruction ( X ) Estimate
	SUU 446UR - X
	SFR 1616B - X
	Dismantle: 11/9/2018

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLU 4464Rat Workshop m/s 7-ONE

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IBAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: 5 days

Res.: Yes or No

Lum Sum: \_\_\_\_\_ %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 42239

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLU 4464RYr Regn: 11/17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)Make: Toyota Sienta Hybrid1496Colour: Brown

A/C: Insured / Std / NI / NA

Sp. Reading: 32958

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: NHP1707106111Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/60R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 9/9/18D.O.I. 11/9/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

PRS No settled.3500 - 4500

RECEIVED 13 SEP 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

S + RS, SI

Photos

Others

Report Format: PRE

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

TOTAL



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS3/MSG18016520/Ucb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 11-09-2018	
			Code : MSG	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	SFR 1616B	Veh. Inspected	SLU 4464R	
Policy No.	28629423AVW	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	MERIMEN (PAULINE THAM)	Assign Date	11/09/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	09/09/2018	Inspection Date	11/09/2018	
Survey held at	Z-ONE AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVE 6, BLK C, #01-52 AUTOBAY SINGAPORE 417883			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Sep 2018		11 Sep 2018 09:33 Assign				<b>New Assignment</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	Jesse Satria, Oeni, ID: S8428443B		
Main Claimant:	Edition Auto		
Vehicle Reg. No.:	SLU4464R	Date of Loss:	09/09/2018 10:00 - :59 [27 Months and 14 Days From LTA Reg Date (Mon Yr)]
Claim Type:	TP	Policy/Cover Note No.:	28629423AVW (Comprehensive) Coverage: 31/10/2017 - 30/10/2018
Vehicle Reg. No. (Insured):	SFR1616B	Policy No. (Claimant):	
		Excess:	
Repairer:	Z-one Automotive Pte Ltd - Kb (HQ) 1 Kaki Bukit Avenue 6, #01-87/85 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/09/2018]		
Adj Asg. Remarks:	OI not reported, SJE disagree - assign LKK Contact : Yvonne at 6250 2115 or HP 9755 2115		

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MSME18116991 / SME Motor Pte Ltd - Kaki Bukit  
 ENTRY DATE & TIME: 10/09/2018 13:54  
 SUBMITTED BY: Chia Pei Ying

## SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date Of Report	10/09/2018 13:54
Date Of Accident	09/09/2018 10:15
Exact Location Of Accident	CHANGI VILLAGE
Country/State of Loss	SINGAPORE

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU4464R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	EDITION AUTO
Co Reg No	53333433X
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-88585121

## Vehicle Particulars

Manufacturer	TOYOTA
Model	SIENTA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

## Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5096110301
Cover Note Number	

## Driver

Name of Driver	LIM JING RUI JESSIE
NRIC No	S8423499J
Date Of Birth	18/07/1984
Occupation	INDOOR
Date Of Driving Pass	01/12/2006
Driving Experience	11 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-88585121
Fax Number	
Contact Number	
E-Mail Address	JESSELIM,ECG@GMAIL.COM

Address BLK 556 BEDOK NORTH ST 3 #14-940  
 Postcode 460556  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

ON 19/09/2018 AT ABOUT 1015HRS, VEHICLE A WAS DRIVING ALONG CHANGI VILLAGE. VEHICLE IN FRONT OF MY VEHICLE STOPPED AND I FOLLOWED SUIT. SUDDENLY, I FELT A HIT IMPACT FROM MY VEHICLE REAR PORTION. VEHICLE B CANNOT STOP IN TIME AND COLLIDED ONTO MY VEHICLE REAR PORTION.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SFR1616B  
 Vehicle Make/Model/Colour  
 Details Of Properties VEHICLE B  
 Vehicle Category PRIVATE CAR  
 Name of Driver JESSE SATRIA OENI  
 NRIC/Passport Number S8428443B  
 Contact Number 98417009  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name LIM JING RUI JESSIE

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLU4464R

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

## Sketch Plan Pg. 1

## SKETCH PLAN

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (c) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

EDITION AUTO

Policyholder's Name  
Date & Time

Driver's Signature  
Address and Mobile No.  
Date & Time


Police Report Number  
Number  
Date & Time

2 - ONE



## Sketch Plan #2 Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 09/09/2018 at about 1015 hrs, I Vehicle A was driving along  
 Changi Village Vehicle in front of my vehicle stopped and I  
 followed suit. Suddenly, I felt an hit impact from my vehicle  
 rear portion. Vehicle B cannot stop in time and collided on to  
 my vehicle rear portion.

## DECLARATION

No declaration required for this accident report.

EDITION AUTO

Signature of Driver A  
 Date & Time

Signature of Driver B  
 Date & Time

Signature of Driver A  
 Date & Time

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Business

Owner ID: 3433X

**Vehicle Details**

Vehicle No.: SLU4464R

Vehicle to be Exported: No

Intended Deregistration Date: 11 Sep 2018

Vehicle Make: TOYOTA

Vehicle Model: SIENTA HYBRID 1.5X CVT

Primary Colour: Brown

Manufacturing Year: 2017

Engine No.: 1NZ8352045

Chassis No.: NHP1707106111

Maximum Power Output: 73.0 kW (97 bhp)

Open Market Value: \$23,149.00

Original Registration Date: 30 Nov 2017

First Registration Date: 30 Nov 2017

Transfer Count: 0

Actual ARF Paid: \$5,000.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 29 Nov 2027

PARF Rebate Amount: \$3,750.00

**Intended COE Rebate Details**

COE Expiry Date: 29 Nov 2027

COE Category: A - Car up to 1600cc &amp; 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$41,761.00

COE Rebate Amount: \$38,489.00

**Total Rebate Amount: \$42,239.00**

The information contained herein is correct as at 11 Sep 2018

OK

**CHEAPEST CAR**  
**INSURANCE RENEWAL**



Compare  
10+ Insurers

**GET A CHEAPER QUOTE NOW!**

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Honda Stream 1.8A RSZ



\$2000 Downpayment Monthly  
From \$538 Onwards. Lowest  
3.18%P.A@GV Cars Financing  
GV Credit Pte Ltd StarAd



**VALUE FOR MONEY**  
**VALUE FOR TIME**  
**A PEACE OF MIND**

**HOTLINE: 6741 9997**

[view our cars](#)

Browse by Category








Sort by Date Posted

20 results/page

18 vehicles

Toyota Sienta

Advanced Search  Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	Toyota Sienta		Any	Any	2017	Any	Any	Any	Available
	Toyota Sienta	1.5A Elegance	\$84,800	\$8,100 /yr	30-Dec-2017	1,496 cc	7,000 km	MPV	Available
Exclusive 7 Years Warranty With Agent! Well Maintained Car. Fully Serviced At Agent And Very Low Mileage. We Provide Loans Of Up To 85% With Interest Rates As Low As 2.28%! Trade In Welcome. Appointment...									
Posted: 10-Sep-2018 Tags: 2017 Toyota Sienta, Toyota Sienta, Toyota, Sienta, Used Toyota									
	Toyota Sienta	Hybrid 1.5A G	\$97,800	N.A	09-Aug-2017	1,496 cc	-	MPV	Available
<b>Fuel Type:</b> Petrol-Electric									
\$5K Down Payment, Monthly \$1221, Front And Rear Recorder, 3 Free Engine Oil Change At Every 10000Km, Solar Film, Reverse Camera, Rear Parking Sensors, Floor Mat, 5 Years Warranty Or 100000Km Which Eve...									
Posted: 10-Sep-2018 Tags: 2017 Toyota Sienta, Toyota Sienta, Toyota, Sienta, Used Toyota									
	Toyota Sienta	1.5A G	\$82,800	\$9,080 /yr	12-Jan-2017	1,496 cc	28,200 km	MPV	Available
Elegant White, 7 Seaters MPV, One Owner Only, Trade In Welcome, Low Maintenance Cost, Very Well Maintained, Flexible In-house Loan Packages Available.									
Posted: 09-Sep-2018 Tags: 2017 Toyota Sienta, Toyota Sienta, Toyota, Sienta, Used Toyota									
	Toyota Sienta	1.5A G	\$85,800	\$8,940 /yr	14-Jul-2017	1,496 cc	12,000 km	MPV	Available
In House Loan And Trade In Available. Comes With Free IRoad V7 Front And Rear Camera. Hardly Driven With Only 12,000km Done. Very Well Spec'ed With 2 x Auto Sliding Doors And Toyota Safety Sense. Lots...									
Quality Motor Trading Enterprise									
Posted: 09-Sep-2018 Tags: 2017 Toyota Sienta, Toyota Sienta, Toyota, Sienta, Used Toyota									
<div>Car Buying</div> <div>Car Aftermarket</div> <div>Car Selling</div> <div>On The Move</div> <div>Car Ownership</div> <div>Lifestyle</div> <div> <a href="#">Buy Tyres Online!</a>  <a href="#">Latest Special Offers from Tyrepatch</a> </div>									
	Toyota Sienta	1.5A G	\$82,800	\$9,110 /yr	12-Jan-2017	1,496 cc	-	MPV	Available
Elegant Black, 7 Seater MPV, One Owner Only, Low Maintenance Cost, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In House Loan Packages Available.									
Prime Motor & Leasing									
Posted: 08-Sep-2018 Tags: 2017 Toyota Sienta, Toyota Sienta, Toyota, Sienta, Used Toyota									
	Toyota Sienta	Hybrid 1.5A G	\$93,800	\$9,820 /yr	27-Dec-2017	1,496 cc	9,000 km	MPV	Available
<b>Fuel Type:</b> Petrol-Electric									
Brand New Condition, Come With LED Lights, Warranty 3 Years, Loan Up To 90%, Call For Viewing Now!									
Posted: 08-Sep-2018 Tags: 2017 Toyota Sienta, Toyota Sienta, Toyota, Sienta, Used Toyota									
	Toyota Sienta	Hybrid 1.5A G	\$88,000	\$9,360 /yr	30-Oct-2017	1,496 cc	300 km	MPV	Available
<b>Fuel Type:</b> Petrol-Electric									
Elegant MPV, 7 Seaters Unit, Condition Like Brand New, Drive Away With Minimum Down Payment, Flexible In House Loan Package Available.									

Compare

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Sep 2018		11 Sep 2018 09:33 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

Insured:	Jesse Satria, Oeni, ID: S8428443B		
Main Claimant:	Edition Auto		
Vehicle Reg. No.:	SLU4464R	Date of Loss:	09/09/2018 10:00 - :59 [9 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 569815	Policy/Cover Note No.:	28629423AVW (Comprehensive) Coverage: 31/10/2017 - 30/10/2018
Vehicle Reg. No. (Insured):	SFR1616B	Policy No. (Claimant):	
		Excess:	
Repairer:	Z-one Automotive Pte Ltd - Kb (HQ) 1 Kaki Bukit Avenue 6, #01-87/85 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 12/09/2018]		
Adj Asg. Remarks:	Oi not reported, SJE disagree - assign LKK Contact : Yvonne at 6250 2115 or HP 9755 2115		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									


















































## Claim Documents

**\*SLU4464R (569815)**  
**[SFR1616B]**  
**TP**  
**Edition Auto**  
**Sep 9 2018 10:00AM**  
**[Jesse Satria, Oeni]**  
**Z-one Automotive Pte Ltd - Kb**

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/09/18 15:34	Chassis Number	1 Load JPG	✓
2	11/09/18 15:34	Odometer Reading	1 Load JPG	✓
3	11/09/18 15:35	General View	1 Load JPG	✓
4	11/09/18 15:35	General View	1 Load JPG	✓
5	11/09/18 15:35	General View	1 Load JPG	✓
6	11/09/18 15:35	General View	1 Load JPG	✓
7	11/09/18 15:35	General View	1 Load JPG	✓
8	11/09/18 15:35	General View	1 Load JPG	✓
9	11/09/18 15:35	General View	1 Load JPG	✓
10	11/09/18 15:35	General View	1 Load JPG	✓
11	11/09/18 15:35	General View	1 Load JPG	✓
12	11/09/18 15:35	General View	1 Load JPG	✓
13	11/09/18 15:35	General View	1 Load JPG	✓
14	11/09/18 15:35	General View	1 Load JPG	✓
15	11/09/18 15:35	General View	1 Load JPG	✓
16	11/09/18 15:35	General View	1 Load JPG	✓
17	11/09/18 15:35	General View	1 Load JPG	✓
18	11/09/18 15:35	General View	1 Load JPG	✓
19	11/09/18 15:35	General View	1 Load JPG	✓
20	11/09/18 15:35	General View	1 Load JPG	✓
21	11/09/18 15:35	General View	1 Load JPG	✓
22	11/09/18 15:35	General View	1 Load JPG	✓
23	11/09/18 15:35	General View	1 Load JPG	✓
24	11/09/18 15:35	General View	1 Load JPG	✓
25	11/09/18 15:35	General View	1 Load JPG	✓
26	11/09/18 15:35	General View	1 Load JPG	✓
27	11/09/18 15:35	General View	1 Load JPG	✓
28	11/09/18 15:35	General View	1 Load JPG	✓
29	11/09/18 15:35	General View	1 Load JPG	✓
30	11/09/18 15:35	General View	1 Load JPG	✓
31	11/09/18 15:35	General View	1 Load JPG	✓
32	11/09/18 15:35	General View	1 Load JPG	✓
33	11/09/18 15:35	General View	1 Load JPG	✓
34	11/09/18 15:35	General View	1 Load JPG	✓
35	11/09/18 15:35	General View	1 Load JPG	✓

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	11/09/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
37	11/09/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
38	11/09/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
39	11/09/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
40	11/09/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
41	11/09/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
42	11/09/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
43	11/09/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
44	11/09/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
45	11/09/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
46	11/09/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
47	11/09/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
48	11/09/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
49	11/09/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
50	11/09/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
51	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	11/09/18 15:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	11/09/18 15:35	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▾	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
85	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
86	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
Documentation			1 per page ▾	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/09/18 16:02	Pri from Crossborders LLC	 Load PDF	
2	10/09/18 16:02	Survey Disagree on SJE - assign LKK	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer  
Note: Remarks are private unless you show it to other parties.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/MSG18016520/UCBS2  
**Date:** 14/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 28629423AVW  
**Claimant Vehicle No :** SLU4464R **Insured Vehicle No :** SFR1616B  
**Date of Loss:** 09/09/2018 **Nature of Claim:** TP **Claim No:** 569815

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU4464R**  
 Make & Model: TOYOTA SIENTA, 1.5 G CVT (A) Engine No: 1NZ8352045  
 Reg. Date: 30/11/2017 (Man. Year: 2017) Chassis No: NHP1707106111  
 Colour: Brown Odometer: 32958 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60R15 Rear Tyre Size: 195/60R15  
 Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm  
 Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment: 11/09/2018  
 Date Inspected: 11/09/2018 Inspected At: Z-one Automotive Pte Ltd - Kb (HQ)  
 1 Kaki Bukit Avenue 6, #01-87/85 Autobay @ Kaki  
 Bukit  
 Singapore 417883  
 Estimated Period of Repair: 0.0 days

**Adjuster:** MARCUS CHUA**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500.00 - \$4,500.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 14 Sep 2018)
<b>Parts:</b>	M1-MPV	TOYOTA SIENTA 1.5 G CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLU4464R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >